

ASS. REC. BY:

REF:

CS / SMO1800-736 / Agbn2

Special Instruction:

Survivor:

Adrian

ASSIGNMENT (Office)

From (Person):

Graue Ted

of

SMD

Date/Time: 26/04/2018 3:07pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 9296R

Insured:

YL 5465A

at Workshop m/s

Premium Carz

Tel:

6636 9100

of

Blk 1 Kaki Bukit Ave 6 #01-90

Policy No:

Claim No: CMTD1801695 / THE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/04/2018

CA / REV / REP. / REV 24 HRS wpi

27-04-2018

H.O.D. Endorsement:

Date/Time:

26/04/2018 3:41pm

Person Contacted:

Aun Teng

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (☒) Estimate

SLW 9296R - X

YL 5465A - X

30/4/18 @

3:08pm Informed Thebus, we are pending for estimate from repairer.

28/6/18 @

1:42pm Verised to Thebus Chao by email.

US \$ 4200, 3 days. (Red B 1303.25, 247.7)

REF: SMO

ASSIGNMENT

From:

Date: 27/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 9296R

at Workshop m/s

Premium Carz

of

Blk 1 Kaki Bukit Ave 6 #01-90

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 9296R.

Yr Regn:

2015, June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Alphard

C.C. 2493

Colour:

White.

A/C: Insured / Std / NI / NA

Sp. Reading

75073

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

AGH 300007044.

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/50R18

R:

235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

27/04/18

Survey held at

Premium Carz

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Somp.

RECEIVED 29 JUN 2018

Date/Time, File Pass to?

☐

: Preli. Report

11/29/6 11/15/17

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

250

Report Format:

7P

Lump Sum / I.B.A. (\$)

4200

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1801695/THE

Date: 28th June 2018

Our Ref: CS/SMO18007736/Aqb

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLW 9296R .


We thank you for the instruction on 26/04/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/04/2018 at the premises of M/s PREMIUM CARZ and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,503.25</u> .
Revised Estimate Amount	: S\$ <u>4,200.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 day.

We have not authorized repair.

Yours faithfully

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 26 April, 2018 3:07 PM
To: Aunteng; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma; Ye, Yong Kang Melvin
Subject: CMTD1801695/THE - SUV(LKK)/LIA/ YL5465A & SLW9296R ACC ON 17/04/2018
Attachments: SLW9296R report.pdf

Our Claim Reference: CMTD1801695/THE
Your Reference: SLW9296R

Hi Aun Teng,

We acknowledged receipt of your claim documents.

Please be informed that Thelma Choo the handler of this case.

We have appointed **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SLW9296R.

Aside to Thelma,

Please advise on the liability request from Premium Carz Services Pte Ltd.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Aunteng [mailto:aunteng@premiumcarz.com.sg]

Sent: Thursday, April 26, 2018 2:03 PM

To: Claims - Motor Survey

Subject: Pre-repair survey! Accident involving SLW9296R & YL5465A on 17/04/2018

Dear Officer-in-charge

We refer to the above matter.

Attached our client's accident report for you to create a third party file.

Your insured's vehicle is YL5465A.

Our client's vehicle is ready for survey.

A copy estimate will be ready and made available to surveyor upon site inspection at our workshop. Please indicate whether you are sending your surveyor to our workshop.

In the meantime, please advise us on the liability.

Regards

Aun Teng

Tel: 6636 9100 Fax: 6636 9113

1 Kaki Bukit Avenue 6

#01-90 Autobay@Kaki Bukit

Singapore 417883

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 June 2018 1:42 PM
To: 'Teo, Grace'; assignments; 'Choo, Thelma'
Cc: 'Ye, Yong Kang Melvin'; SUR
Subject: RE: CMTD1801695/THE - SUV(LKK)/LIA/ YL5465A & SLW9296R ACC ON 17/04/2018
Attachments: CSSMO18007736Aqb.pdf

Dear Thelma,

Enclosed herewith preliminary advice of SLW 9296R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 30 April 2018 3:08 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Choo, Thelma' <thelma.choo@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801695/THE - SUV(LKK)/LIA/ YL5465A & SLW9296R ACC ON 17/04/2018

Dear Thelma,

Please be informed that we have inspected the vehicle SLW 9296R on 27/04/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 26 April 2018 3:43 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Choo, Thelma' <thelma.choo@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801695/THE - SUV(LKK)/LIA/ YL5465A & SLW9296R ACC ON 17/04/2018

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 30 April 2018 3:08 PM
To: 'Teo, Grace'; assignments
Cc: 'Choo, Thelma'; 'Ye, Yong Kang Melvin'; SUR
Subject: RE: CMTD1801695/THE - SUV(LKK)/LIA/ YL5465A & SLW9296R ACC ON 17/04/2018

Dear Thelma,

Please be informed that we have inspected the vehicle SLW 9296R on 27/04/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 26 April 2018 3:43 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Choo, Thelma' <thelma.choo@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801695/THE - SUV(LKK)/LIA/ YL5465A & SLW9296R ACC ON 17/04/2018

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Thursday, 26 April, 2018 3:07 PM
To: Aunteng <aunteng@premiumcarz.com.sg>; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1801695/THE - SUV(LKK)/LIA/ YL5465A & SLW9296R ACC ON 17/04/2018

Our Claim Reference: CMTD1801695/THE
Your Reference: SLW9296R

Hi Aun Teng,

We acknowledged receipt of your claim documents.

Please be informed that Thelma Choo the handler of this case.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/04/2018 14:24
Date Of Accident	17/04/2018 16:30
Exact Location Of Accident	60 ALPS AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW9296R
Insured/Policyholder	
Name Of Registered Owner	LENS MODE PRIVATE LIMITED
Co Reg No	200301316G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90906263
Alternative Phone No	OFFICE-90906263

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALPHARD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098819110
Cover Note Number	

Driver

Name of Driver	NARABAYASHI ETSURO
Passport No/FIN	G6022036R
Date Of Birth	04/10/1975
Occupation	INDOOR
Date Of Driving Pass	24/11/2011
Driving Experience	6 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90906263
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 60 ALPS AVENUE #05-03
 Postcode 498815
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YL5465A
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver LI SHOUFANG
 NRIC/Passport Number G6941830P
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was entering carpark of 60 Alps Ave, suddenly
front car reverse and hit onto my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Date : 26/04/2018

TO: Sompso Insurance (Singapore) Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Our Customer : Lens Mode Private Limited
Vehicle No : SLW9296R
Model : Toyota Alphard 2.5SA CVT ABS
Manufacture Year : 2015
Date of Accident : 17/04/2018

Total Estimate Repair Days : 6
Total Pages : 1

Attn : Motor Claims Department
Fax : 6221 3147

Re: Repair Estimate For Third Party Claim against YLS465A

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper <i>Painted</i>	1	\$1,950.00	\$1,950.00	✓ 1859.
2	Front bumper clip <i>new</i>	10	\$5.00	\$50.00	30
3	Front bumper side retainer LH <i>new</i>	1	\$115.00	\$115.00	✓
4	Front bumper tow hook cover <i>new</i>	1		\$0.00	+
5	Front sensor LH <i>new</i>	1	\$381.00	\$381.00	+
6	Front grille base w/chrome <i>cut</i>	1	\$855.00	\$855.00	✓
7	Front grille "Alphard" logo <i>new</i>	1	\$178.00	\$178.00	✓
8	Fog lamp LH <i>Painted</i>	1	\$280.00	\$280.00	+
9	Fog lamp garnish w/chrome LH <i>Painted</i>	1	\$222.00	\$222.00	+
10	Headlamp LH <i>Painted</i>	1	3518	3518 \$0.00	✓ 3104
11	Headlamp garnish LH <i>cut</i>	1	71	71 \$0.00	✓
12	Headlamp lower bracket RH <i>new</i>	1		\$0.00	+
13	Support panel <i>new</i>	1		\$0.00	+
14	Front fender LH <i>new</i>	1	repair	repair	+
			Total	\$4,031.00	
			Less 25%	\$1,007.75	
			Sub-total 1	\$3,023.25	
A	Spare Parts (S/Nett)				
1	Coolant <i>new</i>	1	\$80.00	\$80.00	+
			Sub-Total 2	\$80.00	
			Total for Parts	\$3,103.25	
B.	Labour				
1	To check wiring and re-focus headlamp.			\$90.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,000.00	300
3	Spray painting all affected parts & areas.			\$800.00	250
4	To spray anti-rust undercoat.			\$60.00	+
5	To program headlamp LH.			\$450.00	+
			Total Labour	\$2,400.00	
			Total Repair Cost	\$5,503.25	

LKK Auto Consultants (Singapore) Pte Ltd
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

total: 5239 8195
h/s: A. L. C.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO18007736/Aqbn2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 02-07-2018	
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 5465A	Veh. Inspected	SLW 9296R	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801695/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	26/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALPHARD	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	AGH300007044	Colour	WHITE	
Odometer	75073	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	MICHELIN	6 mm	
L/H Front Tyre	235/50 R18	MICHELIN	6 mm	
R/H Rear Tyre	235/50 R18	MICHELIN	6 mm	
L/H Rear Tyre	235/50 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/04/2018	Inspection Date	27/04/2018	
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 9296R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,950.00	1,859.00
10	FRONT BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	115.00	115.00
1	FRONT BUMPER TOW HOOK COVER (NPA)	NOT NECESSARY	-	-
1	FRONT SENSOR LH	NOT NECESSARY	381.00	-
1	FRONT GRILLE BASE W/CHROME	CUT	855.00	855.00
1	FRONT GRILLE "ALPHARD" LOGO	NECESSARY	178.00	178.00
1	FOG LAMP LH	NOT NECESSARY	280.00	-
1	FOG LAMP GARNISH W/CHROME LH	NOT NECESSARY	222.00	-
1	HEADLAMP LH	CRACKED	3,518.00	3,104.00
1	HEADLAMP GARNISH LH	CUT	71.00	71.00
1	HEADLAMP LOWER BRACKET RH (NPA)	NOT NECESSARY	-	-
1	SUPPORT PANEL (NPA)	NOT NECESSARY	-	-
1	FRONT FENDER LH (NPA)	NOT NECESSARY	-	-
	LESS 25% DISCOUNT		-1,905.00	-1,553.00
			5,715.00	4,659.00
	<u>SPECIAL NETT ITEMS</u>			
1	COOLANT (SN)	NOT NECESSARY	80.00	-
			80.00	-
	<u>LABOUR</u>			
	TO CHECK WIRING AND RE-FOCUS HEADLAMP.		90.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.		1,000.00	300.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		800.00	250.00
	TO SPRAY ANTI-RUST UNDERCOAT.	NOT NECESSARY	60.00	-
	TO PROGRAM HEADLAMP LH.	NOT NECESSARY	450.00	-
	-		-	-
	-		-	-
	-		-	-
			2,400.00	580.00
	GRAND TOTAL		8,195.00	5,239.00

Report Ref No. CS/SMO18007736/Aqbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00
---	--	--	-----------------

Report Ref No. CS/SMO18007736/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.