

Surveyor:

REF: CS3 / ASM18001079 / T1 v6-1⁰²

Special Instruction:

US: \$ 1600.00

Third Parties:

Claimant:

Surveyor: Prominent Appraiser.

Workshop: Gold Autoworks

From (Person): Tan Jun Hong of ASM Date/Time: 24042018

Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJW 909P Insured: SLG 546M

at Workshop m/s Gold Autoworks Tel: 48 Toh Guan Rd East #01-119

Policy No: Claim No: S8M006YQMC / NPS

Sum Insured: Excess:

Make of Veh: D.O.A. 08012018

(Client's Record)

27-04-2018 (Friday) @ 2pm

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 16 days)

Date/Time: 8/6/18 Submit Final Fig 45/13,850, 14 days (Red \$ 4350 / 27 %; Original days)

LS: \$ 11,950 12 days

Date/Time	Action/Instruction
	Kee Yong Automobile - 160 Sin Ming Drive #03-09
	SJW 909P - CS3 / ASM18001079 / R1be2
	SLG 546M - x
	Tau-fick.
8/6/18	Submit report in SMART claim
	Pls see my remarks

[Signature]
25/5/2018.

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 08 JUN 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

200
200

- | | | | |
|--------------|--------------|--------------|----------------|
| 1) Date/Time | File Pass to | 2) Date/Time | File Return to |
| 3) Date/Time | File Pass to | 4) Date/Time | File Return to |
| 5) Date/Time | File Pass to | 6) Date/Time | File Return to |

Surveyor

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SSW909P Yr Regn: 2015, 2nd

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz GLA200 c.c. 1595

Colour: Grey A/C: Insured / Std / NI / NA

Sp.Reading: — T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC156.9432.5103908

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: 4 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 27/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : S+RS, \$ _____

☐ : Interview (\$ _____)

☐ : Photos

☐ : Tech. Invs (\$ _____)

☐ : Others

☐ : Weekend (\$ _____)

☐ : _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

Catherine Chong (LKK Auto)

From: sophia@satwantlaw.com
Sent: Tuesday, 24 April, 2018 6:12 PM
To: assignments@lkkauto.com
Subject: Fwd: Re: Acknowledgement Your ref: PD/DL/1800521 (ml) Our ref : S8M006YQMC/NPS

Importance: High

Hi Sirs

Kindly make the arrangement for the re-inspection.

Our client vehicle is SJW 909P.

Kindly confirm the said re-inspection.

Rdgs
Sophia Tan
Satwant & Associates

----- Original Message -----

Subject: Fwd: Re: Acknowledgement Your ref: PD/DL/1800521 (ml) Our ref : S8M006YQMC/NPS
Date: 2018-04-24 20:06
From: sophia@satwantlaw.com
To: junhong.tan@axa.com.sg

Hi Jun Hong

Kindly note the re-inspection date and revert with your confirmation and name of surveyor.

Thanks
Sophia Tan
Satwant & Associates

----- Original Message -----

Subject: Re: Acknowledgement Your ref: PD/DL/1800521 (ml) Our ref : S8M006YQMC/NPS
Date: 2018-04-24 12:10
From: claims@goldautoworks.com.sg
To: Margaret Lim <MargaretLim@satwantlaw.com.sg>
Cc: sophia@satwantlaw.com

Hi Sophie/Margaret,

Kindly inform AXA that the Re-Inspection will take place at the following address on this coming Friday, 27.4.2018; 14:00hrs;-

Venue: KEE YONG AUTOMOBILE SERVICE
160 SIN MING DRIVE
#03-09 SIN MING AUTOCITY
SINGAPORE 575722

Please cc LKK @ assignments@lkk.com in the email as well.

Thank you.

Warmest Regards,
Jess Chua
Gold Autoworks Pte Ltd

Quoting claims@goldautoworks.com.sg:

> Hi Margaret,
>
> We refer to your email dated 19.4.2018.
>
> Our client will only be free tomorrow, 20.5.2018 (Friday) at 1700hrs
> at the following address for the re-inspection;-
>
> Venue: KEE YONG AUTOMOBILE SERVICE
> 160 SIN MING DRIVE
> #03-09 SIN MING AUTOCITY
> SINGAPORE 575722
>
> Kindly confirm soonest possible.
>
> Thank you.
>
>
> Warmest Regards,
> Jess Chua
> Gold Autoworks Pte Ltd
>
>
> Quoting Margaret Lim <MargaretLim@satwantlaw.com.sg>:
>
>> Hi Zoron and Jess,
>>
>>
>> AXA would like to re-inspect SJW909P as per their email below.
>>
>>
>> Kindly let us have the suitable date, time and venue asap. Thank you.
>>
>>
>>
>> Thank you & Best Regards
>>
>> Margaret Lim (Branch Office)
>>
>> Secretary
>>
>>
>> For and on behalf of
>>
>> SATWANT & ASSOCIATES

>>
>> Advocates & Solicitors | Notary Public | Commissioner for Oaths Main
>> Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 |
>> fax: 6299 5541
>>
>> Branch Office: 450 Lorong 6 Toa Payoh #02-03 Hersing Centre
>> Singapore
>> 319394 | tel: 6221 6114 | fax: 6266 6925
>>
>>
>>
>> Email Confidentiality Warning:
>>
>> This message contains information which is subject to legal
>> professional privilege and/or is confidential. If you are not the
>> intended recipient, you are notified that any unauthorised
>> disclosure, copying, distribution or use of this information is
>> strictly prohibited. If you have received this message in error,
>> please notify us by e-mailing us at
>> [margaretlim@satwantlaw.com.sg<mailto:salleha@satwantlaw.com.sg>]
>> and delete it from your system. Unless the contents of this email
>> relate to matters within the scope of the firm's engagement, any
>> opinions, views and other information are expressed in the sender's
>> personal capacity. You should scan this email and any file attached
>> for viruses. We take no responsibility for any loss or damage,
>> whether caused by our own negligence or not, that results from a
>> computer virus or a defect in the transmission of this email or any
>> attached file
>>
>>
>> _____
>> From: KADRI Mateen <mateen.kadri@axa.com.sg>
>> Sent: Monday, April 9, 2018 4:11 PM
>> To: Margaret Lim
>> Cc: CHIA Mary; NG Stacey
>> Subject: Acknowledgement Your ref: PD/DL/1800521 (ml) Our ref :
>> S8M006YQMC/NPS
>>
>>
>> ACCIDENT INVOLVING SLG546M AND SJW909P ON 08/01/2018
>>
>>
>>
>>
>>
>> Without Prejudice
>>
>>
>>
>> We acknowledge receipt of your letter dated 05/04/2018 and the
>> enclosures on 06/04/2018.
>>
>>
>>
>> We would like to conduct a re-inspection of your client's vehicle
>> SJW909P. Please let us know a suitable date and time.

>>
>>
>>
>> We would appreciate that in letting us know the date, your client
>> could allow us at least 10 days of lead-time. This is to allow us to
>> co-ordinate with the surveyor concerning the re-inspection date and
>> time .
>>
>>
>>
>> May we hear from you in due course.
>>
>>
>>
>> For future correspondence, please reply to NG Stacey at
>> stacey.ng@axa.com.sg<mailto:stacey.ng@axa.com.sg>
>>
>>
>>
>>
>>
>> Regards,
>>
>> Mateen Kadri
>>
>>
>>
>> [cid:image001.jpg@01D012BC.290D3F30]
>>
>>
>>
>>
>>
>>
>>
>>
>>
>>
>> -----Disclaimer-----
>> This message may contain confidential information intended solely
>> for the use of the named addressee. If you are not the intended
>> recipient, you should not read, use, disclose or reproduce the
>> content of this message. If you have received this message by
>> mistake, please notify the sender immediately. Any views or opinions
>> presented in this message are solely those of the author and do not
>> necessarily represent those of AXA Singapore - Externals or any
>> other entity of the AXA Group, unless otherwise stated by the sender
>> and duly authorized by the said companies.
>> _____
>>
>> Satwant & Associates
>> Advocates & Solicitors | Notary Public | Commissioner for Oaths Main
>> Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 |
>> fax: 6299 5541
>> Conveyancing: Blk 186 Toa Payoh Central #02-420, Singapore 310186 |
>> tel: 6635 7493 | fax: 6635 7494
>>

>> The information contained in this communication is confidential and
>> may be legally privileged. It is intended solely for the use of the
>> individual or entity to whom it is addressed and others authorised
>> to receive it. If you are not the intended recipient you are hereby
>> notified that any disclosure, copying, distribution or taking any
>> action with respect to the content of this information is strictly
>> prohibited and may be unlawful, and kindly inform the sender via
>> email or call SATWANT & ASSOCIATES at (65) 6 2999 470 immediately
>> and destroy all copies. SATWANT & ASSOCIATES is neither liable for
>> the proper and complete transmission of the information contained in
>> this communication nor for any delay in its receipt.

Satwant Singh
Danny Teo Kim Soon
Pritam Singh
Tan Shu Hua, Vanessa
Khong Zi-Wei

SATWANT & ASSOCIATES

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS • NOTARY PUBLIC

CONVEYANCING OFFICE:
450 Lorong 6 Toa Payoh
#02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114
Fax: 6266 6925
www.satwantlaw.com.sg
(Fax not for service
of documents)

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying)
Your Ref: To be advised
Our Ref: PD/DL/1806521 (ml) – Toa Payoh Office
(margaretlim@satwantlaw.com.sg)

61153522
3019359232

05 April 2018

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811



WITHOUT PREJUDICE

BY HAND & EMAIL

Attention: Motor Claims Department

Dear Sirs,

**ACCIDENT INVOLVING SJW909P & SLG546M ALONG PIE TOWARDS TOA PAYOH
EXIT (TUAS/JURONG) ON 08/01/2018 @ 18:30**

We act for Ms Lee Linda, whose motor vehicle No. SJW909P was damaged in the above accident
by your insured motor vehicle No. SLG546M.

Our investigation reveals that you are the Insurers of motor vehicle No. SLG546M at the material
time of the accident and that the said accident was caused solely by the negligence of the driver of
your insured motor vehicle.

We enclose herewith copy each of the following: -

1. Motor Accident Statement Report;
2. LTA searches;
3. Repair Bill;
4. Surveyor Report and invoice;
5. Rental Invoice.

We are instructed to claim the following: -

1. Cost of Repairs (Lump Sum)	\$16,300.00
2. Rental (\$200.00 x 24 days)	\$ 4,800.00
3. GIA search and report fees	\$ 30.00
4. LTA search	\$ 8.00
5. Surveyor Report fees	\$ 842.00
6. Costs (at this stage)	\$ 1,000.00

Total: \$22,980.00



MAIN OFFICE:

3 Jalan Bingka
Singapore 588896
Tel: 6299 9470 Fax: 6299 5541

CONVEYANCING BRANCH OFFICE:


450 Lorong 6 Toa Payoh #02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114 Fax: 6266 6925

This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to
legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

Kindly let us know whether you are prepared to settle our client's claim amicably by 19 April 2018, failing which we shall commence legal proceedings without further reference to you as instructed.

We look forward to hearing from you.

Yours faithfully,



SATWANT & ASSOCIATES
(Danny Teo)

encs

cc. client

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available a/cresaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2018 18:08
Date Of Accident	08/01/2018 18:30
Exact Location Of Accident	PIE TOWARDS TOA PAYOH EXIT (TUAS/JURONG)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW909P
Insured/Policyholder	
Name Of Registered Owner	LEE LINDA
NRIC No	S7804166H
Email Address	URBANITE.DENIS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97437585
Alternative Phone No	OFFICE-97437585

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLA200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA042716
Cover Note Number	

Driver

Name of Driver	NG YONG NGEE
NRIC No	S7627836I
Date Of Birth	04/09/1976
Occupation	INDOOR
Date Of Driving Pass	11/11/2008
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90062242

Fax Number

Contact Number

Email Address URBANITE.DENIS@GMAIL.COM

Address	B_K 90 DAWSON ROAD #23-14
Postcode	142090
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG546M
Vehicle Make/Model/Colour	MERCEDES BENZ E250
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIN JUN XIAN
NRIC/Passport Number	S8509461J
Contact Number	91882242
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLB2826T
Vehicle Make/Model/Colour	MAZDA 3

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	LUAY MING TONG JEFFREY
NRIC/Passport Number	S8202737H
Contact Number	90932017
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	NG YONG NGEE
Approximate Age	
Injuries Sustain	HEADACHE AND ASTHMATIC
Injured person in which vehicle?	SJW909P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 1 January 2018, 6.30pm affected driver / CAR A was driving along PIE expressway to township on the extreme right lane. During driving along the lane, CAR A was being hit from the rear / back by CAR B after CAR A ^{has} fully stopped his car. Prior to CAR B ~~hit~~ hitting the rear bumper of CAR A when CAR A has fully stopped.

The impact from the crash from CAR B hitting on ^{the rear of} CAR A has inflicted to CAR A hitting the rear of CAR C when CAR A is fully stopped.

Repair at other workshop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

(X)

Policyholder's Signature
Date & Time:
Company Chop (if applicable)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

INVOICE

Ms Lee Linda
90 Dawson Road
#23-14
Singapore 142090

Invoice No. : HA/1803-29

Date : 17/03/2018

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 842.00
SGD Dollar : Eight Hundred Forty Two Dollars Only.	
Our Reference : PAS/TP/0190118	
Vehicle No. : SJW909P	
Make & Model : M/Benz GLA200	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0190118

Date of Report : 17/03/2018

To : Ms Lee Linda
90 Dawson Road
#23-14
Singapore 142090

Date of Assignment : 10/01/2018
Report requested by : Ms Lee Linda
Date of Accident : 08/01/2018
Date of Inspection : 10/01/2018
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SJW909P
Make & Model : M/Benz GLA200
Date of Registration : 05/06/2015
Colour : Frozen Grey

Engine Capacity (cc) : 1595cc
Mileage (km) : 73457km
Chassis / Frame No. : WDC1569432J103908
Engine No. : 27091030607659

TYRE CONDITION

Front LH : 6 mm
Make : Pirelli

Front RH : 6 mm
Make : Pirelli

Rear LH : 6 mm
Make : Pirelli

Rear RH : 6 mm
Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Gold Autoworks Pte Ltd
48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586

ASSESSMENT

Repairer's Estimate : \$ 23,934.10
Revised Amount : \$ 20,384.70
Less Excess : \$ -
Recommended Reserve : \$ 16,300.00 (Lump Sum)

Estimated Normal Period of Repairs : 16 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SJW909P

Report No. : PAS/TP/0190118

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Gold Autoworks Pte Ltd, 48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front and rear portions.

DAMAGES

The bonnet, front support panel, front chassis members, front bumpers, headlamps, front grilles, tailgate, rear bumpers, rear end panel, rear floor panel, rear chassis members, rear fenders, rear exhaust silencer, taillamps, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$20,384.70.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$16,300.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile. 9295 2204 Fax: 6722 8508 Email. pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJW909P

Report No. : PAS/TP/0190118

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	2 pcs	Headlamp assy R/L	Cracked/Broken	RA \$ 2,479.00	\$ 4,958.00	\$ 4,958.00 <i>LH-X#0</i>
2	1 pc	Frt grille assy (w/moulding,trim)	Dented/Cracked		\$ 730.00	\$ 730.00
3	1 pc	Frt grille emblem assy (w/bracket)	Dented/Cracked		\$ 222.00	\$ 222.00
4	1 pc	Frt bumper	Dented		\$ 1,165.00	\$ 1,165.00
5	1 pc	Frt bumper no.plate garnish	Dented/Deformed		\$ 66.00	\$ 66.00
6	1 pc	Frt bumper lower trim chrome	Dented/Cracked		\$ 605.00	\$ 605.00
7	4 pcs	Frt bumper park sensor	Dented/Damaged	\$ 188.00	\$ 752.00	3pcs \$ 564.00
8	1 pc	Frt bumper lower grille	Cracked		\$ 127.00	\$ 127.00
9	1 pc	Frt bumper reinforcement	Refit		\$ 416.00	\$ -
10	1 pc	Frt support assy	Dented/Repair		\$ 632.00	\$ -
11	1 pc	Tailgate	Dented/Distorted		\$ 1,698.00	\$ 1,698.00 <i>✓2</i>
12	1 pc	Tailgate emblem (Logo)	Necessary		\$ 55.00	\$ 55.00
13	1 pc	Tailgate emblem (AMG)	Necessary		\$ 205.00	\$ 205.00
14	1 pc	Tailgate chrome moulding	Necessary		\$ 138.00	\$ 138.00
15	2 pcs	Tailgate reflector lamp R/L	Refit	\$ 577.00	\$ 1,154.00	\$ -
16	1 pc	Tailgate inner trim	Cracked/Deformed		\$ 240.00	\$ 240.00 <i>XUB</i>
17	1 pc	Tailgate lock assy	Bent/Damaged		\$ 305.00	\$ 305.00 <i>XUB</i>
18	1 pc	Tailgate weatherstrip	Torn/Necessary		\$ 207.00	\$ 207.00
19	2 pcs	Taillamp R/L	Cracked	RA LH-X#X \$ 580.00	\$ 1,160.00	\$ 1,160.00 <i>580 Δ</i>
20	1 pc	Rr bumper	Dented		\$ 1,128.00	\$ 1,128.00
21	1 pc	Rr bumper top sill plate	Dented/Cracked		\$ 168.00	\$ 168.00
22	4 pcs	Rr bumper reverse sensor	Dented/Damaged	\$ 188.00	\$ 752.00	2pcs \$ 376.00
23	1 pc	Rr bumper lower cover	Dented/Deformed		\$ 425.00	\$ 425.00
24	1 pc	Rr bumper lower cover chrome	Dented/Deformed		\$ 785.00	\$ 785.00
25	1 pc	Rr bumper center guide	Dented/Cracked		\$ 48.00	\$ 48.00
26	2 pcs	Rr bumper side guide R/L	Cracked/Necessary	\$ 25.00	\$ 50.00	\$ 50.00
27	2 pcs	Rr bumper side bracket R/L	Dented/Necessary	\$ 55.00	\$ 110.00	\$ 110.00
28	1 pc	Rr bumper reinforcement	Dented		\$ 486.00	\$ 486.00
29	1 pc	Rr end panel	Dented/Distorted		\$ 890.00	\$ 890.00 <i>RX Δ</i>
30	1 pc	Rr end panel garnish	Cracked/Deformed		\$ 142.00	\$ 142.00
31	1 pc	Rr exhaust muffler heat shield	Dented		\$ 130.00	\$ 130.00
					\$ 19,949.00	\$ 17,183.00 <i>14940</i>
Less Discount : 10%					\$ 1,994.90	10% \$ 1,718.30
List Parts Sub-Total :					\$ 17,954.10	\$ 15,464.70 <i>13446</i>
1	1 set	Frt no.plate (3D, w/bracket)	Dented/Cracked	S/N	\$ 120.00	\$ 120.00
2	1 pc	Rr windscreen sealant	Necessary	S/N	\$ 40.00	\$ 40.00
2	1 pc	Rr end panel sealant	Necessary	S/N	\$ 40.00	\$ 40.00
Special Nett Sub-Total :					\$ 200.00	\$ 200.00 <i>160</i>
Parts Total :					\$ 18,154.10	\$ 15,664.70



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJW909P

Report No. : PAS/TP/0190118

S/No.	Labour Descriptions	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	To check electrical system and calibrate/focus headlamp.	\$ 80.00	\$ 60.00 ³⁰
2	To remove, replace and/or transfer front parking sensors to new bumper.	\$ 60.00	\$ 40.00 ³⁰
3	To straighten, repair, realign on front affected area and replace damaged parts.	\$ 800.00	\$ 550.00 ⁴⁰⁰
4	To spray Frozen Grey painting, blending on front affected and adjacent area.	\$ 600.00	\$ 500.00 ⁴⁰⁰
5	To check rear electrical wiring system.	\$ 80.00	\$ 60.00 ³⁰
6	To transfer tailgate component parts to new tailgate.	\$ 120.00	\$ 100.00 ⁶⁰
7	To transfer rear windscreen to new tailgate.	\$ 120.00	\$ 120.00 -
8	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 140.00	\$ 120.00 ⁸⁰
9	To straighten, repair and realign rear exhaust silencer.	\$ 80.00	\$ 60.00 -
10	To remove, replace and/or transfer rear parking sensors to new bumper. (Include reset front and rear parking sensor control unit)	\$ 200.00	\$ 160.00 ¹⁰⁰
11	To straighten, repair, realign on rear affected area and replace damaged parts.	\$ 1,000.00	\$ 880.00 ⁷⁰⁰
12	To spray Frozen Grey painting, blending on rear affected and adjacent area.	\$ 1,500.00	\$ 1,200.00 ⁹⁰⁰
13	To spray anti-rust coating on new and affected panels.	\$ 250.00	\$ 120.00 ⁸⁰
14	To reapply ceramic coating on front and rear new and affected portions.	\$ 750.00	\$ 750.00 ⁴⁰⁰ ^Δ
Labour Total :		\$ 5,780.00	\$ 4,720.00 ³⁷⁴⁰
Total (Parts & Labour) :		\$ 23,934.10	\$ 20,384.70

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 16,300.00

Under normal circumstances, the repairs should be completed within a reasonable period of 16 Working Days.

172 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.