

22/03/2002

ASS. REC. BY:

REF: C93 / CTT18007764 / 71241ber

Special Instruction:



SUPERVISOR:

Tawfik

ASSIGNMENT (Office)

From (Person):

Angie Foo

of

CTL

Date/Time: 27042018 910am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 6973H

Insured:

SJL 8730S

at Workshop m/s

Hiap Lek

Tel:

9660 1347

of

160 Sin Ming Drive #05-17

Policy No:

DMPCSN 8031861708

Claim No:

SNM18D 02046C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19042018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

27042018 1033am

Person Contacted:

Wan Wei

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

GBD 6973H - NA/INC 13005452/d2

DIA: 3082015

SJL 8730S - X

REF: Tanpin

REF:

CT1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

4

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: G6D6973H Yr Regn: 2014 May
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NV350

C.C. 2488

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 132 332

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1MC 2E 26 2000 2166

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195 K15

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Queen - map

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A. _____

D.O.I. 27/4/18 @ 1445

Survey held at Hiap Lek 160 Siming Dr #10

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt w/s

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Estimated repair range \$2,000 - \$2,500

07/18 Submit PRS report.

5/7/2018

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) S + PR \$

1) Photos

1) Others

1)

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

150

150

22/03/2003

ASS. REC. BY:

REF: CS3 / CTT18007764 / 712462

Special Instruction:



SUPERVISOR

MURPHY

Tatfich

ASSIGNMENT (Office)

From (Person):

Angie Foo

of

CTL

Date/Time:

27042018 910am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 6973H

Insured:

SJL 8730S

at Workshop m/s

Hiap Lek

Tel:

9660 1347

of

160 Sin Ming Drive #05-17

Policy No:

DMPCSN 3031861708

Claim No:

SNM16D02046C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19042018

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

27042018 1033am

Person Contacted:

Wan Wei

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBD 6973H - NA/INC 13005452/d2
	SJL 8730S - X

DIA: 30032015

REF: *Taufik*

REF:

CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G6D6973H Yr Regn: 2014 May
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Nu350

C.C. 2488

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 132 332

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1MC 2E 26 Z 000 2166

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 195 K15

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Queen - map

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 27/4/18 @ 1445

Survey held at Hiap Lek 660 Siming Dr #10

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt w/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$2,000 - \$2,500

07/18 Submit PRS Report.

[Signature]
5/7/2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1) S + PS \$

2) Photos

3) Other

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Insp (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

150

Catherine Chong (LKK Auto)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Friday, 27 April, 2018 9:10 AM
To: roynpartners
Cc: Jowyn Tay; assignments@lkkauto.com; 'SUR'; Admin A
Subject: RE: OUR REF: PRS/SNM18D02046C02/0 & YR REF: MKR/104/7889/2018/AS.WL -TO CONDUCT PRE REPAIR SURVEY -GBD6973H
Attachments: PRS FAX LTR.pdf

Without Prejudice

Save As To Costs

Dear Ashely,

We refer to your email of 26th April 2018.

We are objecting to your list of surveyors and shall be appointing M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Marcus/Kalvin/Simon,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Adeline Chng 6389 6155

Best Regards,

Angie Foo

Claims Executive

Claims Department – Motor Division

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6186

Fax (65) 6224 7175 / 6224 7478

Email: angie.foo@sg.cntaiping.com

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: roynpartners [mailto:roynpartners@roynpartners.com.sg]

Sent: Thursday, 26 April, 2018 6:00 PM

To: Angie Foo

Cc: Jowyn Tay

Subject: RE: OUR REF: PRS/SNM18D02046C02/0 & YR REF: MKR/104/7889/2018/AS.WL -TO CONDUCT PRE REPAIR SURVEY -GBD6973H

Importance: High

Dear Angie,

We refer to your email of 26th April 2018.

Our client reject your list of proposed motor surveyors and propose their list of surveyors as follows :-

1. PAR Automotive Consultancy
Contact Person: Mr. Loi Boon Juan
2. United Appraisal and Management Pte Ltd
Contact Person: Mr. Marc
3. Oh Appraisal Services
Contact Person: Mr. Oh Han Cheong
4. SK Auto Consultants
Contact Person: Mr. Kuma
5. Lee Automobile Appraisers Services
Contact Person: Mr. Lee K. W.
6. CM Automotive Consultancy
Contact Person: Mr. Ng Cheng Meng
7. ISP Management Pte Ltd
Contact Person: Mr. Zali Saidi
8. Auto Performance Appraisal
Contact Person: Mr. Lek Boon Hwee

Pursuant to the new NIMA protocol, kindly let us know within 2 working days of receipt of our letter whether you agree or has any objections to any of the motor surveyors proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors listed by our client.

BCC – Client – For your information
(Ref: GBD 6973H)

Thanks & regards,

Ashley Su (Mr)

Legal Executive

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : ashley@roynpartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

From: Angie Foo [mailto:angie.foo@sg.cntaiping.com]

Sent: Thursday, 26 April, 2018 5:21 PM

To: roynpartners <roynpartners@roynpartners.com.sg>

Cc: Jowyn Tay <jowyn.tay@sg.cntaiping.com>

Subject: OUR REF: PRS/SNM18D02046C02/0 & YR REF: MKR/104/7889/2018/AS.WL -TO CONDUCT PRE REPAIR SURVEY -GBD6973H

WITHOUT PREJUDICE

SAVE AS TO COSTS

Dear Sirs/Mdm,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Jowyn Tay 6389 6174.

Best Regards,

Angie Foo

Claims Executive

Claims Department – Motor Division

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6186

Fax (65) 6224 7175 / 6224 7478

Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Virus-free. www.avg.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Vehicle Details			
Vehicle No. :	GBD6973H		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	NV350 PANEL VAN 2.5 5MT 5DR EURO V		
Chassis No. :	JN1MC2E26Z0002166		
Propellant :	Diesel		
Engine No. :	YD25350002A		
Engine Capacity :	2488 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3300 kg		
Unladen Weight :	1800 kg		
Year Of Manufacture :	2014		
Original Registration Date :	30 May 2014		
Lifespan Expiry Date :	29 May 2034		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$32,890.00		
COE Expiry Date :	29 May 2024		
Road Tax Expiry Date :	29 Nov 2018		
Inspection Due Date :	29 May 2019		
Intended Transfer Date :	05 Jul 2018		
CO2 Emission :	232.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$103.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0913N
Vehicle Details	
Vehicle No.:	GBD6973H
Vehicle to be Exported:	No
Intended De-registration Date:	05 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	YD25350002A
Chassis No.:	JN1MC2E26Z0002166
Maximum Power Output:	-
Open Market Value:	\$23,804.00
Original Registration Date:	30 May 2014
First Registration Date:	30 May 2014
Transfer Count:	0
Actual ARF Paid:	\$1,191.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$32,890.00
COE Rebate Amount:	\$19,398.00
Total Rebate Amount:	\$19,398.00

The information contained herein is correct as at 05 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/04/2018 09:57
Date Of Accident	19/04/2018 23:15
Exact Location Of Accident	QUEEN STREET CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD6973H
Insured/Policyholder	
Name Of Registered Owner	STAR PEST CONTROL PTE LTD
Co Reg No	ENV200000913N
Email Address	ADRIAN_RAJOO@STARPEST.SG
Mobile Phone No	
Alternative Phone No	OFFICE-84689445

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ17-002290
Cover Note Number	

Driver

Name of Driver	MUHAMMAD IZWAN BIN MESABAN
NRIC No	S8834183Z
Date Of Birth	16/09/1988
Occupation	OUTDOOR
Date Of Driving Pass	01/04/2013
Driving Experience	5 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84689445
Fax Number	
Contact Number	
Email Address	ADRIAN_RAJOO@STARPEST.SG

Address	BLK 443B BUKIT BATOK WEST AVENUE #04-811
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL8730S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE JIN QUAN
NRIC/Passport Number	S9133895E
Contact Number	91597404
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 19/4/18 AT ABOUT 2315HRS, ACCIDENT HAPPEN AT QUEEN STREET OPEN CARPARK OPPOSITE BUGIS PLUS MALL. I WAS IN VEHICLE GBD6973 H ABOUT TO LEAVE THE CARPARK ~~AND~~ WHEN I SAW VEHICLE SJL 8730 S CAME TO PARK ON THE LEFT SIDE OF ~~BY~~ MY VEHICLE AS THERE WAS TWO EMPTY LOTS ON MY LEFT SIDE VEHICLE SJL 8730 S WAS REVERSING TO THE PARKING LOT AND ACCIDENTALLY HIT MY FRONT LEFT OF VEHICLE AND CAUSE SCRATCHES.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No: _____

21/4/18
0930 hrs

SKETCH PLAN


SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/4/18
0930HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:
























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Apr 2018		27 Apr 2018 16:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SOH GWEK WAH , Co. Reg. No.: -								
Main Claimant:	STAR PEST CONTROL PTE LTD , Co. Reg. No.: ENV200000913N								
Vehicle Reg. No.:	GBD6973H	Date of Loss:	19/04/2018 23:00 - :59 [46 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02046C02	Policy/Cover Note No.:	DMPCSN3031861708						
Vehicle Reg. No. (Insured):	SJL8730S	Policy No. (Claimant):	DMCPHQ17-002290						
		Excess:	S\$0.00						
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/05/2018]								
Adj Asg. Remarks:	PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR SURVEY								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBD6973H (SNM18D02046C02)
[SJL8730S]
TP
STAR PEST CONTROL PTE LTD
Apr 19 2018 11:00PM
[SOH GWEK WAH]
Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	21/04/18 11:20	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	21/04/18 11:13	THIRD PARTY [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	21/04/18 11:13	THIRD PARTY [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	21/04/18 11:13	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 11:05	General View	 Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/04/18 16:31	INSURED SAS REPORT SJL8730S	 Load PDF	
2	27/04/18 16:31	THIRD PARTY GBD6973H -FR ROY & PARTNERS -PRS LTR AND SAS REPORT	 Load PDF	
3	27/04/18 16:31	THIRD PARTY GBD6973H -PRS EMAIL BTW CIC AND ROY & PARTNERS	 Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	21/04/18 11:19	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	21/04/18 11:19	INSURANCE [Linked Accident Report Documents]	 Load TIF	
3	21/04/18 11:19	SKETCH PLAN [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	21/04/18 11:19	DRIVER IC [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	21/04/18 11:20	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	21/04/18 11:13	THIRD PARTY	 Load JPG	<input checked="" type="checkbox"/>
9	21/04/18 11:13	THIRD PARTY	 Load JPG	<input checked="" type="checkbox"/>
10	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	21/04/18 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	21/04/18 11:19	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	21/04/18 11:19	INSURANCE	 Load TIF	
3	21/04/18 11:19	SKETCH PLAN	 Load JPG	<input checked="" type="checkbox"/>
4	21/04/18 11:19	DRIVER IC	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118007764/T1Z4BE2

Date: 09/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3031861708

Claimant Vehicle
No : GBD6973HInsured Vehicle
No : SJL8730S

Date of Loss: 19/04/2018

Nature of Claim: TP

Claim
No: SNM18D02046C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD6973H

Make & Model: NISSAN NV350, 2.5 (A)

Reg. Date: 30/05/2014 (Man. Year: 2014)

Colour: Black

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: YD25350002A

Chassis No: JN1MC2E26Z0002166

Odometer: 132332 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: GREEN-MAX 6 mm

Rear Left Side: GREEN-MAX 6 mm

Front Right Side: GREEN-MAX 6 mm

Rear Right Side: GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/04/2018

Date Inspected: 27/04/2018 Inspected At:

 Hiap Lek Automobile Trading (HQ)
 160 Sin Ming Drive, #05-17 Sin Ming
 Autocity
 Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$2,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Jul 2018)

Parts: N/A NISSAN NV350 2.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBD6973H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >