

2/19/2003

A REC. BY:

REF:

CS3 / ALH18007767 / SZ4157

Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

Mrimen.

From (Person):

Winnie Tan

of

ALH

Date/Time:

27042018 1108am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FS 3758G

Insured:

SLQ 6767A

at Workshop m/s

Soon Hin

Tel:

9619 1882

of

Blk 1018 Yishun Ind Park A #01-342

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

27042018 1134am

Person Contacted:

Isaac

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

FS 3758G - X

SLQ 6767A - X

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Sec:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

3/5/18

Submit DAR Report.

RECEIVED 04 MAY 2018

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Workshop (\$)

Survey Fee:
Transportation.

) \$ + RS. \$

: Photos

: Others

TOTAL

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Rear

R/Bal.

L/Bal.

D.O.I.

mm

mm

mm

Soon Hin.

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO
SLQ6767A AND FS3758G ON 19 APRIL 2018**

From: Fan, Winnie-LW

To:

Cc: Fong, Andy-SY, Chin, Lee-Ying

Sent: Friday, 27 April, 2018 11:08:28 AM

Attachments:  SLQ6767A - 26 APRIL.TIF

Hi LKK,

Kindly assist to survey.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Fax +(65) 6835 7416

winnie-lw.fan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/04/2018 14:12
Date Of Accident	19/04/2018 13:00
Exact Location Of Accident	ALONG RD 1 YISHUN AVE 9 (INFRONT ESSO)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FS3758G
Insured/Policyholder	
Name Of Registered Owner	ZULFIQAR BIN MAHMOOD
NRIC No	S9515038A
Email Address	ZULMAHMOOD95@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-84288854
Alternative Phone No	OFFICE-84288854

Vehicle Particulars

Manufacturer	YAMAHA
Model	RXZ
Exact Purpose for which vehicle was being used at time of accident	MOTORCYCLE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	PNMC2017-00000623
Cover Note Number	

Driver

Name of Driver	ZULFIQAR BIN MAHMOOD
NRIC No	S9515038A
Date Of Birth	09/05/1995
Occupation	INDOOR
Date Of Driving Pass	08/05/2014
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84288854
Fax Number	
Contact Number	OFFICE-84288854
Email Address	ZULMAHMOOD95@OUTLOOK.COM

Address	APT BLK 762 YISHUN STREET 72 #09-418 SINGAPORE 760762
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	YISHUN NORTH N.P.C.
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO: T/20180419/2178 LODGED AT YISHUN NORTH N.P.C. ON 19/04/2018 AT ABOUT 1300HRS, I WAS RIDING A MOTORCYCLE WITH THE REGISTRATION NUMBER (FS3758G) ALONG YISHUN AVENUE 9 BESIDE ESSO STATION TOWARDS YISHUN RING ROAD ALONG 2-LANE ROAD. I WAS TRAVELLING ON THE MOST RIGHT LANE. AFTER I RODE PASS THE TRAFFIC LIGHT ON THE T-JUNCTION, SUDDENLY THERE'S A WHITE COLORED VEHICLE WITH THE VEHICLE REGISTRATION NUMBER (SLQ6767A) HIT ME FROM THE BACK AND CAUSES ME TO FAIL AND CAUSES SOME INJURES ON MY LEFT ARM AND LEFT LEG. THE DRIVER (SLQ6767A) THEN STOPPED HIS VEHICLE ON THE SIDE AND HE PROVIDE ME HIS NAME AND CONTACT NUMBER AND DROVE OFF. DURING THE ACCIDENT THERE'S A DRIVER BEHIND ME HAPPENED TO WITNESS THE WHOLE ACCIDENT AND PROVIDED ME A VIDEO OF THE ACCIDENT. THE VIDEO FOOTAGE SHOWED THAT THE VEHICLE (SLQ6767A) WHILE CHANGING LANE FROM THE LEFT LANE TO THE RIGHT LANE. THE VEHICLE SIDE SWEEP MY VEHICLE FROM THE REAR LEFT AND CAUSES ME TO FAIL. I HAD CONSULTED A DOCTOR AT YISHUN ONE FAMILY CLINIC AND THE DOCTOR DIAGNOSED THAT I HAVE A ABRASION ON MY LEFT ARM AND LEFT LEG AND I WAS GIVEN 3 DAYS OF MEDICAL CERTIFICATE FROM DR CHUNG KIAN WEE FROM 19/04/2018 TO 21/04/2018. THE DRIVER (SLQ6767A) INFORMED THAT THERE'S SOME DAMAGES ON HIS REAR RIGHT SIDE AND MY MOTOR VEHICLE (FS3758G) HAD SOME DAMAGES ON THE SIDE MIRROR, CLUTCH LEVER, FRONT FORK SUSPENSION AND HANDLE BAR. DURING THE ACCIDENT THERE'S NO AMBULANCE AND TRAFFIC POLICE WAS CALLED UPON TO THE SCENE. WITNESS: XIANG - CHINESE / 82586498 / 6773 3116 DRIVER: SLQ6767A - DANNY 40'S / 88698933

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	XIANG
Phone Number	82586498
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ6767A
Vehicle Make/Model/Colour	PEUGEOT/RCZ 1.6 TURBO AUTO/WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DANNY
NRIC/Passport Number	
Contact Number	88698933
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ZULFIQAR BIN MAHMOOD
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FS3758G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to as insurer(s) who have insured the vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/ may not be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHD FADZLY BIN ISMAIL

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personal

Sketch Plan



POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180419/2178

1 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No: T/20180419/2178

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/04/2018 23:09		Vide Report No.:		Station Diary No.: 160	
Informant's Particulars					
Name of Informant: ZULFIQAR BIN MAHMOOD		Address: APT BLK 762 YISHUN STREET 72 #09-418 SINGAPORE 760762			
ID Type / ID No.: NRIC NO / S9515038A		Contact No.: Home/Office:		Mobile: 84288854	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 22	Date of Birth: 09/05/1995	Type of Informant: Rider		
Race: Boyanese		Language:		Institution / School Name:	
Occupation: National Service Full Time		Driving Licence Information: Class: 2B, 2A		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/04/2018 13:00	Type of Location: T-Junction
Location: Along Road 1 YISHUN AVENUE 9				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FS3758G	Motorcycle	YAMAHA	RXZ	Blue	Seriously Damaged	0
SLQ6767A	Car	PEUGEOT	RCZ 1.6 TURBO AUTO	White	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180419/2178

2 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20180419/2178

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FS3758G	FWD Singapore Pte. Ltd	PNMC2017-00000623	19/07/2017	18/07/2018

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Rider			
Name	ZULFIQAR BIN MAHMOOD	ID No.	S9515038A
Related Vehicle	F53758G (Motorcycle)	Contact No.	84288854
Hospital/Clinic	YISHUN ONE FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 2B, 2A Date of Expiry: NIL
Date Treatment	19/04/2018	Date Discharge	19/04/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 19/04/2018 at about 1300hrs, I was riding a motorcycle with the registration number (FS3758G) along Yishun Avenue 9 beside ESSO Station towards Yishun Ring Road along a 2-lane road. I was travelling on the most right lane. After I rode pass the traffic light on the T-Junction, suddenly there's a white colored vehicle with the registration number (SLQ6767A) hit me from the back and causes me to fall and causes some injuries on my left arm and left leg. The driver (SLQ6767A) then stopped his vehicle on the side and he provide me his name and contact number and drove off. During the accident there's a driver behind me happened to witness the whole accident and provided me a video of the accident. The video footage showed that the vehicle (SLQ6767A) while changing lane from the left lane to the right lane, the vehicle side sweep my vehicle from the rear left and causes me to fall.

I had consulted a doctor at YishunOne Family clinic and the doctor diagnosed that I have abrasion on my left arm and left leg and I was given 3 days of medical certificate from DR Chung Kian Wee from 19/04/2018 to 21/04/2018. The driver (SLQ6767A) informed that there's some damages on his rear right side and my motor vehicle (FS3758G) had some damages on the side mirror, clutch lever, front fork suspension and handle bar. During the accident there's no ambulance and traffic police was called upon to the scene.

Witness : Xiang - Chinese / 8258 6498 / 6773 3116.
Driver : SLQ6767A - Danny 40's / 8869 8933.

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180419/2178

3 of 3

Report No. T/20180419/2178

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F/
Sgt 1 GAN WEI LEONG, ALASTAIR

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
19/04/2018 23:09

Officer In Charge Of Case:
TP / AEIT /
Sgt 2 YEO KIA HUAT
Contact No : 65476326

Classification Of Case:

Authentication Stamp
NF108

FOR MOTORCYCLE

Motorcycle

Vehicle No: FS 3758 G

NAC	INC	Item	CON	AC	Qty
3001	991336	Front Number Plate			
3001	991065	Front Tyre			
3002	991095	Front Rim			
3003	991372	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	SCR	✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	SCR	✓	
3015	992357	Front Headlamp Bracket			
3016	992345	Front Headlamp Faring			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror	SCR	✓	
3019	992245	Front LH Signal Lamp	SCR	✓	
3020	992246	Front RH Signal Lamp	SCR	✓	
3021	992556	Meter Casing	SCR	✓	
3022	992553	Meter Assy	CUT	✓	
3023	991019	ERP Bracket			
3024	991020	ERP Unit			
3025	992446	Ignition Switch			
3026	992442	Ignition Key Assy			
3027	990706	Cowling Stay			
3028	994470	Steering Stem			
3029	994427	Steering Cone			
3030	992299	Handle Bar	CUT	✓	
3031	992312	Handle Bar Switch			
3032	992310	Handle Bar Grip			
3033	995184	Handle Bar Balancer LH			
3034	992300	Handle Bar Balancer RH	CUT	✓	
3035	992179	Fuel Tank			
3036	990438	Brake Reservoir			
3037	990621	Clutch Lever			
3038	992293	Hand Brake Lever			
3039	991119	Side Faring	CUT	✓	
3040	994220	Side Faring Top Garnish			
3041	994219	Side Faring Inner Garnish			
3042	991118	Faring Shield			
3043	992047	Front Top Faring Inner Garnish			
3044	991123	Faring Top Garnish			
3045	990538	Center Faring	SCR	✓	
3046	991378	Rear Faring			
3047	991124	Faring Stopper			
3048	991117	Faring Lower			

NAC	INC	Item	CON	AC	Qty
3049	995074	Radiator			
3050	992738	Radiator Cowling			
3051	994146	Seat Assy			
3052	990915	Engine Crash Bar			
3053	990928	Engine Guard			
3054	990219	Battery			
3055	990224	Battery Cover			
3056	990223	Battery Bracket			
3057	991144	Foot Brake	SCR	✓	
3058	991154	Front Foot Rest			
3059	991779	Front Foot Rest Bracket			
3060	994269	Side Stand			
3061	992549	Main Stand			
3062	990615	Clutch Engine Cover			
3063	992478	Kick Starter Rubber			
3064	992477	Kick Starter Lever			
3065	991145	Foot Gear Shifter			
3066	993500	Rear Foot Rest	CUT	✓	
3067	993501	Rear Foot Rest Bracket			
3068	992581	Exhaust Muffler Heat Shield			
3069	991058	Exhaust Muffler Assy	DD	✓	
3070	993719	Rear LH Shock Absorber			
3071	993720	Rear RH Shock Absorber			
3072	995065	Rear Tyre			
3073	991200	Rear Rim			
3074	994872	Rear Tyre Rim Spoke			
3075	993474	Rear Fender Wheel Guard			
3076	993443	Rear Fender Mudflap			
3077	992940	Rear Brake Disc			
3078	992936	Rear Brake Caliper			
3079	995236	Rear Spocket			
3080	990585	Chain			
3081	990580	Chain Guard			
3082	994530	Swing Arm			
3083	993819	Rear Sub frame			
3084	995245	Rear LH Signal Lamp			
3085	995246	Rear RH Signal Lamp			
3086	995251	Rear Taillamp			
3087	993626	Rear Number Plate			
3088	994192	Side Box			
3089	992927	Rear Box	CUT	✓	
3090	992928	Rear Box Bracket	Defam	✓	
3091	991328	Emblem			
3092	990247	Sticker			

* 3 days

No of Items:

Assessed:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018 Edit Reg		27 Apr 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MADLINE TURYA MAMALA , ID: S7285573F		
Main Claimant:	ZULFIQAR BIN MAHMOOD , ID: S9515038A		
Vehicle Reg. No.:	FS3758G	Date of Loss:	19/04/2018 13:00 - :59 [213 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3594917206SG	Policy/Cover Note No.:	1700031790 (Comprehensive)
Vehicle Reg. No. (Insured):	SLQ6767A	Policy No. (Claimant):	
		Excess:	
Repairer:	Soon Hin Motor (HQ) BLK 1018 YISHUN INDUSTRIAL PARK A #01-342, 768760 Yishun - Tel: 67524893		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 10/05/2018]		
Claimant's Solicitor:	LEGAL OPTIONS LLC - Tel: 64388039		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------



































No results.































Claim Documents

***FS3758G (3594917206SG)
[SLQ6767A]**

TP

**ZULFIQAR BIN MAHMOOD
Apr 19 2018 1:00PM
[MADELINE TURYA MAMALA]
Soon Hin Motor**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
2	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
3	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/05/18 09:52	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	02/05/18 09:52	General View	 Load JPG	✓
37	02/05/18 09:52	General View	 Load JPG	✓
38	02/05/18 09:52	General View	 Load JPG	✓
39	02/05/18 09:52	General View	 Load JPG	✓
40	02/05/18 09:52	General View	 Load JPG	✓
41	02/05/18 09:52	General View	 Load JPG	✓
42	02/05/18 09:52	General View	 Load JPG	✓
43	02/05/18 09:52	General View	 Load JPG	✓
44	02/05/18 09:52	General View	 Load JPG	✓
45	02/05/18 09:52	General View	 Load JPG	✓
46	02/05/18 09:52	General View	 Load JPG	✓
47	02/05/18 09:52	General View	 Load JPG	✓
48	02/05/18 09:52	General View	 Load JPG	✓
49	02/05/18 09:52	General View	 Load JPG	✓
50	02/05/18 09:52	General View	 Load JPG	✓
51	02/05/18 09:52	General View	 Load JPG	✓
52	02/05/18 09:52	General View	 Load JPG	✓
53	02/05/18 09:52	General View	 Load JPG	✓
54	02/05/18 09:52	General View	 Load JPG	✓
55	02/05/18 09:52	General View	 Load JPG	✓
56	02/05/18 09:52	General View	 Load JPG	✓
57	02/05/18 09:52	General View	 Load JPG	✓
58	02/05/18 09:52	General View	 Load JPG	✓
59	02/05/18 09:52	General View	 Load JPG	✓
60	02/05/18 09:52	General View	 Load JPG	✓
61	02/05/18 09:52	General View	 Load JPG	✓
62	02/05/18 09:52	General View	 Load JPG	✓
63	02/05/18 09:52	General View	 Load JPG	✓
64	02/05/18 09:52	General View	 Load JPG	✓
65	02/05/18 09:52	General View	 Load JPG	✓
66	02/05/18 09:52	General View	 Load JPG	✓
67	02/05/18 09:52	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/05/18 12:57	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18007767/SZ4BS2

Date: 09/05/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700031790
Claimant Vehicle No :	FS3758G	Insured Vehicle No :	SLQ6767A
Date of Loss:	19/04/2018	Nature of Claim:	TP
		Claim No:	3594917206SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FS3758G	Engine No:	3BS253702
Make & Model:	YAMAHA RXZ, 133cc (M)	Chassis No:	ZMC253702
Reg. Date:	17/07/2000 (Man. Year: 2000)	Odometer:	827038 km
Colour:	Red/White		
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	2.75/18	Rear Tyre Size:	90/90-18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/04/2018	Soon Hin Motor (HQ)
Date Inspected:	27/04/2018	Inspected At: BLK 1018 YISHUN INDUSTRIAL PARK A #01-342
Estimated Period of Repair:	3.0 days	Singapore 768760

Adjuster: Sebastian Yeang Wai Keen

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
2	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
3	1		*FRONT WING MIRROR	Scratched	0.00 F	*- F
4	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
5	1		*FRONT RH SIGNAL LAMP	Scratched	0.00 F	*- F
6	1		*METER CASING	Cut	0.00 F	*- F
7	1		*HANDLE BAR	Cut	0.00 F	*- F
8	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
9	1		*SIDE FAIRING	Cut	0.00 F	*- F
10	1		*CENTER FAIRING	Scratched	0.00 F	*- F
11	1		*FOOT BRAKE	Scratched	0.00 F	*- F
12	1		*REAR FOOT REST	Cut	0.00 F	*- F
13	1		*EXHAUST MUFFLER ASSY	Dented	0.00 F	*- F
14	1		*REAR BOX	Cut	0.00 F	*- F
15	1		*REAR BOX BRACKET	Deformed	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >