

ASS. REC. BY:

REF: CS/MS/18007770/DB⁵²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Maximilien Elaine Ngu of MSU Date/Time: 27042018 938am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GZ 9469C Insured: ET 1500C

at Workshop m/s Teamwork Tel: 6844 2475

of 53 ubi Ave 1 #01-24

Policy No: B27713971SMP Claim No: 556649

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20042018
(Client's Record)

CA / REV / REP. / REV 24 HRS up

H.O.D. Et fornement: _____

Date/Time: 27042018 11:18am Person Contacted: Darren Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	GZ 9469C - NA/MS/18007453/zk	Dat: 200418
	ET 1500C - CS/MS/18007453/Rqd	Dat: 270809
	Dismantle Part: 1505 2018	
	After repair: 1805 2018	

Surveys

REF:


ASSIGNMENT

COR Nov 2021

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G2 9469C Yr Regn: 2006 / HLV
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2982
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 209075 T/Radio: Insured / Std / NI / NA

Eng/No: 1K71528817
 C/No: 55A5TFAT35Y003000131

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/75 R15
 R: 155 R12C (double)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5/5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5/5</u> mm

D.O.A. 20/04/18 D.O.I. 14/05/2018 @ 1130am

Survey held at Teamwork Page Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

H/S Front y H/S Body y H/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MSG BT 1500C ?R8</u>
	<u>regr range 2.5K 3K</u>
	<u>3.5K to 4K with 5 days of in</u>
	<u>Vehicle travelled about 2K mileage after the accident to time of</u>
	<u>Survey. Underwriga items unlikely to be damaged.</u>
	<u>MV 21K</u>
	<u>LTA 15K HL 6K</u>

Date/Time, File Pass to?

1) 30-10-2018

Date/Time, File Return to?

2)

Report Format: PRS.

Lump Sum / I.B.I: (\$ _____)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$ _____

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Apr 2018		27 Apr 2018 09:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHANG YANG FA, ID: S2000158E, Tel: +6596382311, Email: YANGFACHANG@GMAIL.COM								
Main Claimant:	TECHTUNE, Co. Reg. No.: 53191252C								
Vehicle Reg. No.:	GZ9469C	Date of Loss:	20/04/2018 13:00 - :59 [136 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556649	Policy/Cover Note No.:	B27713971SMP (Comprehensive) Coverage: 16/05/2017 - 15/05/2018						
Vehicle Reg. No. (Insured):	ET1500C	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/04/2018]								
Driver/Custodian (Insured):	CHANG YANG FA (68 / Male), NRIC: S2000158E, Tel: +6596382311								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2018 16:49
Date Of Accident	20/04/2018 13:30
Exact Location Of Accident	ALONG SELETAR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ9469C
Insured/Policyholder	
Name Of Registered Owner	TECHTUNE
Co Reg No	53191252C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 MANUAL
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	A29050172MKC
Cover Note Number	

Driver

Name of Driver	CHEW KOK CHEANG (ZHOU GUOQIANG)
NRIC No	S7201160J
Date Of Birth	04/01/1972
Occupation	OUTDOOR
Date Of Driving Pass	17/07/1990
Driving Experience	27 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93363518
Fax Number	
Contact Number	OFFICE-93363518
Email Address	NOEMAIL

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Apr 2018		27 Apr 2018 09:38 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHANG YANG FA, ID: S2000158E, Tel: +6596382311, Email: YANGFACHANG@GMAIL.COM		
Main Claimant:	TECHTUNE, Co. Reg. No.: 53191252C		
Vehicle Reg. No.:	GZ9469C	Date of Loss:	20/04/2018 13:00 - :59 [136 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 556649	Policy/Cover Note No.:	B27713971SMP (Comprehensive) Coverage: 16/05/2017 - 15/05/2018
Vehicle Reg. No. (Insured):	ET1500C	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Imm.Advice due 28/04/2018]		
Driver/Custodian (Insured):	CHANG YANG FA (68 / Male), NRIC: S2000158E, Tel: +6596382311		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (30/10/2018): Surveyor report-urgent

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results,									

Claim Documents

***GZ9469C (556649)**
[ET1500C]
TP
TECHTUNE
Apr 20 2018 1:00PM
[CHANG YANG FA]
Teamwork Garage Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View

View in Browser ▼

Assessment Reports

1 per page ▼



No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/04/18 09:37	Accident Statement From: SC - Reg. No: ET1500C, Claimant: CHANG YANG FA	 Load HTM	☐

Photos/Images

3 per page ▼



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 11:52	Rear View Right	 Load JPG	☒
2	30/10/18 11:52	Rear View Left	 Load JPG	☒
3	30/10/18 11:52	General View	 Load JPG	☒
4	30/10/18 11:52	General View	 Load JPG	☒
5	30/10/18 11:52	General View	 Load JPG	☒
6	30/10/18 11:52	General View	 Load JPG	☒
7	30/10/18 11:52	General View	 Load JPG	☒
8	30/10/18 11:52	General View	 Load JPG	☒
9	30/10/18 11:52	General View	 Load JPG	☒
10	30/10/18 11:52	General View	 Load JPG	☒
11	30/10/18 11:52	General View	 Load JPG	☒
12	30/10/18 11:52	General View	 Load JPG	☒
13	30/10/18 11:52	General View	 Load JPG	☒
14	30/10/18 11:52	General View	 Load JPG	☒
15	30/10/18 11:52	General View	 Load JPG	☒
16	30/10/18 11:52	General View	 Load JPG	☒
17	30/10/18 11:52	General View	 Load JPG	☒
18	30/10/18 11:52	General View	 Load JPG	☒
19	30/10/18 11:52	General View	 Load JPG	☒
20	30/10/18 11:52	General View	 Load JPG	☒
21	30/10/18 11:52	General View	 Load JPG	☒
22	30/10/18 11:52	General View	 Load JPG	☒
23	30/10/18 11:52	General View	 Load JPG	☒
24	30/10/18 11:52	General View	 Load JPG	☒
25	30/10/18 11:52	General View	 Load JPG	☒
26	30/10/18 11:52	General View	 Load JPG	☒
27	30/10/18 11:52	General View	 Load JPG	☒
28	30/10/18 11:52	General View	 Load JPG	☒
29	30/10/18 11:52	Odometer Reading	 Load JPG	☒
30	30/10/18 11:52	Chassis Number	 Load JPG	☒
31	30/10/18 11:53	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
32	30/10/18 11:53	Reinspection Photo		Load JPG	☒
33	30/10/18 11:53	Reinspection Photo		Load JPG	☒
34	30/10/18 11:53	Reinspection Photo		Load JPG	☒
35	30/10/18 11:53	Reinspection Photo		Load JPG	☒
36	30/10/18 11:53	Reinspection Photo		Load JPG	☒
37	30/10/18 11:53	Reinspection Photo		Load JPG	☒
38	30/10/18 11:53	Reinspection Photo		Load JPG	☒
39	30/10/18 11:53	Reinspection Photo		Load JPG	☒
40	30/10/18 11:53	Reinspection Photo		Load JPG	☒
41	30/10/18 11:53	Reinspection Photo		Load JPG	☒
42	30/10/18 11:53	Reinspection Photo		Load JPG	☒
43	30/10/18 11:53	Reinspection Photo		Load JPG	☒
44	30/10/18 11:53	Reinspection Photo		Load JPG	☒
45	30/10/18 11:53	Reinspection Photo		Load JPG	☒
46	30/10/18 11:53	Reinspection Photo		Load JPG	☒
47	30/10/18 11:53	Reinspection Photo		Load JPG	☒
48	30/10/18 11:53	Reinspection Photo		Load JPG	☒
49	30/10/18 11:53	Reinspection Photo		Load JPG	☒
50	30/10/18 11:53	Reinspection Photo		Load JPG	☒
51	30/10/18 11:53	Reinspection Photo		Load JPG	☒
52	30/10/18 11:53	Reinspection Photo		Load JPG	☒
53	30/10/18 11:53	Reinspection Photo		Load JPG	☒
54	30/10/18 11:53	Reinspection Photo		Load JPG	☒
55	30/10/18 11:53	Reinspection Photo		Load JPG	☒
56	30/10/18 11:53	Reinspection Photo		Load JPG	☒
57	30/10/18 11:53	Reinspection Photo		Load JPG	☒
58	30/10/18 11:53	Reinspection Photo		Load JPG	☒
59	30/10/18 11:53	Reinspection Photo		Load JPG	☒
60	30/10/18 11:53	Reinspection Photo		Load JPG	☒
61	30/10/18 11:53	Reinspection Photo		Load JPG	☒
62	30/10/18 11:53	Reinspection Photo		Load JPG	☒
63	30/10/18 11:53	Reinspection Photo		Load JPG	☒
64	30/10/18 11:53	Reinspection Photo		Load JPG	☒
65	30/10/18 11:53	Reinspection Photo		Load JPG	☒
66	30/10/18 11:53	Reinspection Photo		Load JPG	☒
67	30/10/18 11:53	Reinspection Photo		Load JPG	☒
68	30/10/18 11:53	Reinspection Photo		Load JPG	☒
69	30/10/18 11:53	Finishing Photo		Load JPG	☒
70	30/10/18 11:53	Finishing Photo		Load JPG	☒
71	30/10/18 11:53	Finishing Photo		Load JPG	☒
72	30/10/18 11:53	Finishing Photo		Load JPG	☒
73	30/10/18 11:53	Finishing Photo		Load JPG	☒
74	30/10/18 11:53	Finishing Photo		Load JPG	☒
75	30/10/18 11:53	Finishing Photo		Load JPG	☒
76	30/10/18 11:53	Finishing Photo		Load JPG	☒
77	30/10/18 11:53	Finishing Photo		Load JPG	☒
78	30/10/18 11:53	Finishing Photo		Load JPG	☒
79	30/10/18 11:53	Finishing Photo		Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	30/10/18 11:53	Finishing Photo	 Load JPG	✓
81	30/10/18 11:53	Finishing Photo	 Load JPG	✓
82	30/10/18 11:53	Finishing Photo	 Load JPG	✓
83	30/10/18 11:53	Finishing Photo	 Load JPG	✓
84	30/10/18 11:53	Finishing Photo	 Load JPG	✓
85	30/10/18 11:53	Finishing Photo	 Load JPG	✓
86	30/10/18 11:53	Finishing Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/04/18 09:36	TPD GZ9469C GIA REPORT.pdf	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18007770/DBS2

Date: 02/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B27713971SMP

Claimant Vehicle No : GZ9469C

Insured Vehicle No : ET1500C

Date of Loss: 20/04/2018

Nature of Claim: TP

Claim No: 556649

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GZ9469C

Make & Model: TOYOTA DYNA 1.5T, 3.0 (M)

Engine No: 1KD1528817

Reg. Date: 30/11/2006 (Man. Year: 2006)

Chassis No: JTFAT35Y003000131

Colour: White

Odometer: 209075 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75R15

Rear Tyre Size: 155 R12C (D)

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5/5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/04/2018

Date Inspected: 14/05/2018 Inspected At:

Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park

Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

11/2/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Nov 2018)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ9469C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >