

REC. BY:

REF: 09/CTAU8007794 / Utbnz

Special Instruction:

Survivor: MARVIS ASSIGNMENT (Office)

From (Person): Kelvina of GAL Date/Time: 27042018 153pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBA 8511K Insured: Gx 7485D

at Workshop m/s liu's Brother Tel: 6741 1730

of Blk 1 Kaki Bukit Ave 6 #01-01

Policy No: _____ Claim No: CLMOMVLC000003188

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16042018
(Client's Record)

CA / REV / REP. / REV 24 HRS WPI 30042018 H.O.D. Endorsement: _____

Date/Time: 27042018 352pm Person Contacted: Susan Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBA 8511K - NGA / INC 09001194 / K1
	Gx 7485D - x

DA: 14012009

REF: GML

ASSIGNMENT

From: Date: 30042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBT 8511K
at Workshop m/s: Liu's Brother
of: Blk 1 Kaki Bukit Ave 6 #01-01

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 30

IDAC Accident Rpt: Consistent? : Yes or No

GLA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1196N

Vehicle: IN / OUT

Date: Person Contacted: 3/1/2018

Veh No: GBA 811K Yr Regn: 208

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: NISSAN URVAN c.c 2953

Colour: yellow A/C: Insured / Std / NI / NA

Sp. Reading: 45288 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1M64E2520780709

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Locked / Jammed / Leaked / Burnt or

Brake: In/Order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front: R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 16/4/18 D.O.I. 30/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rtd o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/5/18 conf. met 4/5 @ 5100 with Suben (Red: 5570-10 : 52%)

RECEIVED 13 JUN 2018

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 5

13/6/18 Typist

: Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee:

Transportation

2)

Add Fee: : Site Insp (\$)

) S-RS SI

: Interview (\$)

) Photos

: Tech. Invs (\$)

) Others

: Weekend (\$)

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 5100)

350

Catherine Chong (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Friday, 27 April, 2018 1:53 PM
To: Catherine Chong (LKK Auto); SUR
Subject: Re: Request for 3rd party survey GBA8511K Claims against GX7485D
Attachments: GBA8511K180416.pdf, GX7485D.pdf

Dear team

Please conduct TP survey

Thanks
Kelvyna

From: Susan Low <liusbro@ymail.com>
Sent: Friday, April 27, 2018 12:47 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Re: Request for 3rd party survey GBA8511K Claims against GX7485D

We did liked to chose as follow

5. LKK Auto Consultants

Kindly arrange

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

Nissan Urvan

Price Range ▾

Depreciation ▾

> 10 year(s) ▾

Vehicle Type ▾

Home » Used Cars » ABWIN (1994) Pte Ltd » Nissan Urvan (COE till 12/2022)

Resources

Car Buying

Car Selling


Car Ownership

Car Aftermarket

On The Move

Lifestyle

Tyres



Nissan Urvan (COE till 12/2022)

Overview

Financial

Accessories

Similar

Research

Photos

Map

ABWIN 論輝

YOUR FIRST CHOICE AUTOMOTIVE SERVICE

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$31,800	
Depreciation	\$6,820 /yr	?
Reg Date	28-Dec-2007 (4yrs 7mths 27days COE left)	
Lifespan	27-Dec-2027	
Manufactured	2007	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,953 cc	
Curb Weight	1,760 kg	?
Fuel type	Diesel	
Features	-	
Accessories	New Paint, New Seat, Servicing Done.	
Description	Most Popular Japan-made Goods Van. Long Wheel Based. Pristine Condition. Call Now To View!	
COE	\$25,536	?
OMV	\$25,360	?
Dereg Value	\$23,815 as of today (change)	?
No. of Owners	2	?
Type of Veh	Van	



Seller Infor

Company

Compare



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 26 Apr 2018 / 10:47:06

Receipt Date/Time : 26 Apr 2018 / 10:47:06

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180426-000513

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GX7485D				
As at 16 Apr 2018/11:30:00				
Insurance Co: GREAT AMERICAN INSURANCE COMPANY				
1	Insurance Enquiry - GX7485D Enquiry Fee 20180426104551451425	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 1196N

Vehicle Details

Vehicle No.: GBA8511K
Vehicle to be Exported: No
Intended De-registration Date: 26 Apr 2018
Vehicle Make: NISSAN
Vehicle Model: URVAN PANEL LWB 3.0 5DR 5MT AIRBAG 2WD
Primary Colour: Blue
Manufacturing Year: 2008
Engine No.: ZD30158157K
Chassis No.: JN1MG4E25Z0780709
Maximum Power Output: -
Open Market Value: \$25,572.00
Original Registration Date: 01 Feb 2008
First Registration Date: 01 Feb 2008
Transfer Count: 3
Actual ARF Paid: \$1,279.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Dec 2022
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$25,536.00
COE Rebate Amount: \$23,902.00
Total Rebate Amount: \$23,902.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.
The information contained herein is correct as at 26 Apr 2018.

OK

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	1196N

Vehicle Details

Vehicle No.:	GBA8511K
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	NISSAN
Vehicle Model:	URVAN PANEL LWB 3.0 5DR 5MT AIRBAG 2WD
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	ZD30158157K
Chassis No.:	JN1MG4E25Z0780709
Maximum Power Output:	-
Open Market Value:	\$25,572.00
Original Registration Date:	01 Feb 2008
First Registration Date:	01 Feb 2008
Transfer Count:	3
Actual ARF Paid:	\$1,279.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Dec 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$25,536.00
COE Rebate Amount:	\$23,833.00
Total Rebate Amount:	\$23,833.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 30 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2018 00:20
Date Of Accident	16/04/2018 11:30
Exact Location Of Accident	30 TUAS LINK 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA8511K
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942897
Vehicle Particulars	
Manufacturer	NISSAN
Model	USED NISSAN URVAN PANEL VAN
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087422MFCV
Cover Note Number	N.A.
Driver	
Name of Driver	MUHAMMAD AZAHAR BIN MOHD SARWI
NRIC No	S8429246Z
Date Of Birth	02/09/1984
Occupation	OUTDOOR
Date Of Driving Pass	06/10/2017
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97101775
Fax Number	
Contact Number	OFFICE-97101775
EMail Address	NOEMAIL

Address NIL
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes,Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes,against whom?

Circumstances of Accident

My vehicle was stationary at the said location when vehicle B GX7485D reversed. I sounded my horn but the said vehicle did not slow down. As such, vehicle collided into the front right portion of my vehicle.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GX7485D
 Vehicle Make/Model/Colour NISSAN/URVAN-WHITE
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver OH HWEI SIONG
 NRIC/Passport Number S7437324J
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


Fill in and report correctly the details of the accident to speed up the claims process. This Form must be completed by the Policyholder and/or the Authorised Driver. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may result in the insurance companies to repudiate policy liability. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies. Any false reporting may be referred to the Police for investigation. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

I understand, acknowledge, agree and consent that:
 (i) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers who have insured vehicles involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 (ii) investigating the accident and/or my claims;
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 (ii) All insurers who have insured vehicles involved in this accident and the insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 (iii) My Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore for one or more of the above Purposes.

VERIFIED BY AJAX MARS
 REPORTING OFFICER
 MOHAMAD HELMY BIN
 ALEHAM

Policyholder's Signature: Date & Time: Driver's Signature (if driver is not the policyholder): Date & Time: Witnessed by Reporting Centre Personnel

Sketch Plan



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

My vehicle was stationary at the said location when vehicle B GX7485D reversed. I sounded my horn but the said vehicle did not slow down. As such, vehicle collided into the front right portion of my vehicle.

Taxi Voucher No.

Are you claiming your own insurance policy for the repair of your vehicle?


No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMAD HELMY BIN ALEHAM

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 00101 Auto Bay @ Kaki Bukit Singapore 417003

ROB No: 55291703 | Tel: 6744-1707/731 | Fax: 6744-5746 Email: info@lba.com

Invoice/Ref No: GBA8511K180416

GBA8511

Estimate

Customer		
Name: Great American Insurance Company		Date: 29-04-18
Address: Motor Claims Department		Vehicle No: GBA8511K
3 Temasek Avenue #16-01		Model/Make: Nissan Urvan Panel
Centennial Tower	Singapore 039190	LWB 3.0 5DR 5MT Airbag 2WD

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Panel <i>pp/bent</i>	\$ 1,229.60	
2	Panel "DHL" Sticker <i>neu</i>	\$ 400.00	SN 1005.~
3	Front windscreen Moulding <i>neu</i>	\$ 133.00	N ✓
4	Front Grille <i>RA</i>	\$ 432.00	N ✓
5	Grille "Nissan" Logo Motif <i>AA</i>	\$ 64.60	N X
6	Grille Clips 1 set <i>7.1</i>	\$ 50.00	SN X
7	Corner Panel <i>ofs</i> <i>Boots</i> <i>pp</i> <i>403</i>	\$ 535.50	
8	Head Lamp <i>ofs</i> <i>BAO</i>	\$ 475.00	N ✓
9	Bumper <i>pis</i>	\$ 685.00	
10	Bumper Beam	\$ 325.60	X ✓
11	Bumper Side Holder <i>neu</i>	\$ 92.00	
12	Bumper Clip 1 set <i>neu</i>	\$ 48.00	SN 305.~
13	Fog Lamp <i>AA</i>	\$ 328.00	SN X
14	Fog Lamp Garnish <i>neu</i>	\$ 131.00	X ✓
15	Inter Cooler <i>pp/ppu</i>	\$ 1,320.00	X ✓
16	Door <i>ofs</i> <i>neu</i>	\$ 1,782.80	
17	Door "ROC" Sticker 1 set <i>neu</i>	\$ 48.00	SN 305.~
18	Windscreen Glass Sealant <i>neu</i>	\$ 50.00	SN 405.~
	To check all wiring & electrical component for proper function.	\$ 50.00	- 30
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 120.00	- 100
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc...	\$ 300.00	- 160
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 150.00	- 100
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 900.00	- 700
	To putty & spray painting & including touch up paint on accident affected areas	\$ 900.00	- 750
	To apply Rust Proofing . reseal tuff-coating treatment on accident area	\$ 120.00	- 50

Total Parts & Labour of estimate for damaged vehicle \$ 10,670.10

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$

SDLS:



M/s Liu's Brother Auto Engrg Ws

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorized
Wen
1/585100
Sdy.

p-4769.6
107
4292.64
S.V - 200
labur - 1890
6382.64
5106



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY Ref : CS/GAI18007794/Utbn2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 18-06-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 7485D	Veh. Inspected	GBA 8511K
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003188	Excess (\$)	0.00
Assign From	KELVYNA	Assign Date	27/04/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN URVAN (M)	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JN1MG4E25Z0780709	Colour	YELLOW
Odometer	452858	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	TRIANGLE	6 mm
L/H Front Tyre	195 R15	TRIANGLE	6 mm
R/H Rear Tyre	195 R15	TRIANGLE	6 mm
L/H Rear Tyre	195 R15	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/04/2018	Inspection Date	30/04/2018
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 8511K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT PANEL (N)	DENTED / BENT	1,229.60	1,229.60
1	FRT WINDSCREEN MOULDING (N)	NECESSARY	133.00	133.00
1	FRT GRILLE (N)	CRACKED	432.00	432.00
1	FRT GRILLE "NISSAN" LOGO MOTIF (N)	NOT NECESSARY	64.60	-
1	FRT CORNER PANEL O/S (N)	BADLY DENTED	535.50	403.00
1	FRT HEAD LAMP (N)	BROKEN	475.00	475.00
1	FRT BUMPER (N)	DISTORTED	685.00	685.00
1	FRT BUMPER BEAM (N)	TO REPAIR SEE LABOUR	325.60	-
1	FRT BUMPER SIDE HOLDER (N)	CRACKED	92.00	92.00
1	FRT FOG LAMP GARNISH (N)	TO REPAIR SEE LABOUR	131.00	-
1	FRT INTER COOLER (N)	DENTED / PUNCTURE	1,320.00	1,320.00
1	FRT DOOR O/S (N)	TO REPAIR SEE LABOUR	1,782.80	-
	LESS 10% DISCOUNT		-	-476.96
			7,206.10	4,292.64
<u>SPECIAL NETT ITEMS</u>				
1	PANEL "DHL" STICKER (SN)	NECESSARY	400.00	100.00
1	SET FRT GRILE CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRT BUMPER CLIP (SN)	NECESSARY	48.00	30.00
1	FRT FOG LAMP (SN)	NOT NECESSARY	328.00	-
1	SET FRT DOOR "ROC" STICKER (SN)	NECESSARY	48.00	30.00
1	FRT WINDSCREEN GLASS SEALANT (SN)	NECESSARY	50.00	40.00
			924.00	200.00
<u>LABOUR</u>				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		50.00	30.00
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST.		120.00	100.00
	REMOVE & REINSTALL DASHBOARD, METER INSTRUMENTS, DISCONNECT WIRING & ETCS.		300.00	160.00
	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES.		150.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. :2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF FRT BUMPER BEAM,FRT FOG LAMP GARNISH AND FRT DOOR O/S.		900.00	700.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		900.00	750.00
	TO APPLY RUST PROOFING,RESEAL TUFF COATING TREATMENT ON ACCIDENT AREA.		120.00	50.00
			2,540.00	1,890.00
	GRAND TOTAL		10,670.10	6,382.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,100.00

Report Ref No. CS/GAI18007794/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.