

100/100  
Sur: Kelvin

REF: NS/INC18007807/KIRb02

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate Cost

OD/TP INS/TP RES/OD RES/EVA/INV/MV

To Insp Vehicle No: \_\_\_\_\_

at Work Shop No: \_\_\_\_\_

of \_\_\_\_\_

Insured: EM 3928B

Policy No: 5051880084-06 061117-051118

Claims No: MT 10992340 - 001

Sum Ins Used: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 5617M Yr Regn: 3<sup>rd</sup> Apr, 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Sonata c.c. 1991

Colour: Blue A/C: Insured / Std / Nil / NA

Sp. Reading: 663767 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: KM HET41VMB 810108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 215/60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 26/4/8

D.O.I. 27/4/8

Survey held at

CDGE (Layang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHA 3617M - <u>CC3 / ATG15014462 / H106392</u>
	EM 3928B - <u>x</u>
<u>30/4/11</u>	<u>Contract 4/5 \$1450 / 2 Rep.</u>
	<u>Red: \$1162.10, 441</u>

RECEIVED 02 MAY 2010

Date/Time, File Passb?

☐ : Prell. Report

1) typist

☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Other

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Ins. (\$ \_\_\_\_\_)

Date/Time: \_\_\_\_\_

7P  
L/S: \$1450.00



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007807/K1rb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 27-04-2018  
189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EM 3928B	Veh. Inspected	SHA 5617M
Policy No.	5051880084-06	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/04/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	26/04/2018	Inspection Date	27/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5051880084-06	LIM AH CHAY	S0233911J	GPC	Third Party, Fire & Theft	EM3928B	EM3928B	06/11/2017	05/11/2018

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0992340-001	Comfort Transportation	SHA 5617M	EM 3928B	26/4/2018
2	MT/0992344-001	Comfort Transportation	SH 6997S	SIL 3515E	26/4/2018
3	MT/0986118-002	SMRT BUSES LTD	SMB 148T	SJM 5462E	12/3/2018
4	MT/0991797-002	CityCab	SHC 7718G	XD 8343C	24/4/2018
5	MT/0986118-002	SMRT BUSES LTD	SMB 148T	SJM 5462E	12/3/2018
6	MT/0992112-002	Comfort Transportation	SH8003Y	FBK 528M	26/4/2018
7	MT/0992351-001	Comfort Transportation	SH 6751J	GY 4005X	23/4/2018

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/04/2018 09:04
Date Of Accident	26/04/2018 22:00
Exact Location Of Accident	THOMSON ROAD TWDS BALESTIER SLIP ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA5617M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	YAHYA B ABU HASSAN
NRIC No	S1553091Z
Date Of Birth	23/10/1962
Occupation	OUTDOOR
Date Of Driving Pass	02/11/1984
Driving Experience	33 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

BLK 159 WOODLANDS STREET 13  
#04-669

Postcode

730159

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle

-  
-  
-  
-  
-  
-

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME: : -

GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

REFER ATTACHED

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

-

Was there any audio recorded?

NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

EM3928B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN

NRIC/Passport Number

S8527677H

Contact Number

96192226

Address

Postcode

Insurance Company Name

UNSURE

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	YAHYA B ABU HASSAN
Approximate Age	GIDDY
Injuries Sustain	SHA5617M
Injured person in which vehicle?	YES
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Teo Yen Yee  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan Pg. 2

SKETCH PLAN

Slip Rd to Balesier Rd



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Teo Yen Yee

**Describe Circumstances of the Accident.**

On 26/04/2018 at about 22:00hrs, I was driving along Thomson Road towards Balestier slip road.

As I approached the slip Road, the front car SLQ6564T braked and stopped thus I braked and stopped as well. Suddenly a few seconds later a car EM3928B came from behind collided onto the rear of my taxi.

01 male passenger on board my taxi. No injury reported at the point of the accident.


### Declaration




I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature/Date &  
Time

Driver's Signature (If driver is not the policyholder)/Date  
& Time

  
Teo Yen Yee  
Witnessed by Reporting  
Centre Personnel



A member of COMFORTDELGRO

Date/Time: 27.04.2018 10:06 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305153991

CUSTOMER  
NAME COMFORT TRANSPORTATION PTE LTD  
CUSTOMER NO 7010045  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755 (R) (P) (Q)

REGN NO	SHA5617M	MILEAGE
MAKE	HYUNDAI	FUEL
MODEL	SONATA	DATE/TIME IN
YR OF MANU	30.04.2011	TARGET DATE
CHASSIS CODE	KMHET41VMB810104	COMPLETION DATE/TIME

NTUC

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 26.04.2018  
NATURE: 3P 26.04.2018

S/NO LABOR CODE DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA5617M LIKE

Vehicle No.: SHA5617M

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHA 5617M

DATE 27/4/2018 10:21

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <del>xxxx</del> <i>defend</i>			\$ 578.40
	Rear Bumper Reinforcement <i>2 cm</i>			\$ 483.30
	Rear Bumper Clip <i>2</i>			\$ 22.00
	Rear Bumper Sponge <i>2</i>			\$ 137.40
	Rear Bumper Under Cover <i>2</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>x repair</i>		\$ 38.00	\$ 76.00
	Rear Panel <i>x 5</i>			\$ 391.80
	Rear Panel Garnish <i>x 5</i>			\$ 95.80
	<b>SUB TOTAL</b>			<b>\$ 1,970.50</b>
	<b>LESS 20%</b>			<b>\$ 394.10</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,576.40</b>
	Rear Bumper Reverse Sensor <i>1</i> <i>should</i>			\$ 135.70 <b>Nett</b>
	Rear Bumper Advertisement Logo <i>1</i> <i>me</i>			\$ 50.00 <b>Nett</b>
	Rear Fender Advertisement Logo (LH/RH) <i>1</i> <i>me</i>		\$ 100.00	\$ 200.00 <b>Nett</b>
				<b>\$ 385.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>280.00</del> <i>200</i>
	Spray Painting Charge			\$ <del>200.00</del> <i>200</i>
	Wiring Charge			\$ <del>50.00</del> <i>x 1</i>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <i>20</i>
	<b>TOTAL LABOUR</b>			<b>\$ 650.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,612.10</b>

*Kahin 1 U/K*  
*27/4/18 11:00 hrs*  
*2 Days*  
*4/5*  
*After Repair ph*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305153991  
Date : 28/04/18

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK  
Attn : Mr KALVIN ANG  
Vehicle Reg No : SHA5617M CTPL

Fax :  
26.04.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- EM3928B
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost
  - (c) Lumpsum Repair (if applicable)
 


Total for Lumpsum repair cost after Less:	20%	\$1,450.00
Final Lumpsum Repair cost		\$1,450.00


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM KWOK ENG  
Tel : 62148316  
Fax : 65468156

Signature :   
Name : KALVIN ANG  
Date : 30/4/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:





Thatcham describe

## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007807/K1rbn2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 08-05-2018  
189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EM 3928B	Veh. Inspected	SHA 5617M
Policy No.	5051880084-06	Coverage (\$)	0.00
Claim No.	MT/0992340-001	Excess (\$)	0.00
Assign From		Assign Date	27/04/2018

### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHET41VMB810104	Colour	BLUE
Odometer	663767	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	HANKOOK	7 mm
L/H Front Tyre	215/60 R16	HANKOOK	7 mm
R/H Rear Tyre	215/60 R16	HANKOOK	7 mm
L/H Rear Tyre	215/60 R16	HANKOOK	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	26/04/2018	Inspection Date	27/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5617M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	CRACKED	483.30	483.30
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	TORN	137.40	137.40
1	REAR BUMPER UNDER COVER	SERVICEABLE	185.80	-
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	TO REPAIR	76.00	-
1	REAR PANEL	SERVICEABLE	391.80	-
1	REAR PANEL GARNISH	SERVICEABLE	95.80	-
	LESS 20% DISCOUNT		-394.10	-244.22
			1,576.40	976.88
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
			385.70	385.70
<b>LABOUR</b>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		450.00	220.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		200.00	200.00
			650.00	420.00
			2,612.10	1,782.58
<b>GRAND TOTAL</b>				
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				1,450.00

Report Ref No. NS/INC18007807/K1rbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.