

ASS. REC BY:

REF:

CS/SMD18007883/Us3bn2

Special Instruction:

SUPERVISOR

MARCUS

ASSIGNMENT (Office)

From (Person):

Grace Tao

of

SMD

Date/Time:

30042018 10:39am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 6023A

Insured:

PC 3036Y

at Workshop m/s

Fastech Auto

Tel:

6746 5405

of

1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

CMTD1801815/THE

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30042018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

30042018 11:19am

Person Contacted:

Nany

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBD 6023A - X

PC 3036Y - CCB / AXA 18007347 / MY4032

DEN: 240418

08/06/18 (\$45,045.37 - \$17,000/-) - Reduction = 62%

(08/11/13) wef

ASS. REC. BY: Mar

REF:

Smo

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: GRD 6023A

at Workshop m/s Rp.

of _____

Insured: PC 30314

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 586.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: See Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3016/c

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GRD 6023A Yr Regn: 1214

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Car

Make: Toyota Dyna c.c. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: Settling fly T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35/60K 204003

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15 m/c

R: 155-R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 2.1/4/18

Survey held at

Rear

R/Bal. 6/6 mm

L/Bal. 6/6 mm

D.O.I. 30/4/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R/L N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rep 8600 L74 40617 Gys. 6ml. net 17383

7/6/18 1/5 @ 17.000 confirmed with Aler.

RECEIVED 06 JUN 2018

Date/Time, File Pass to?

02/06/18

1) Fast

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 15

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS, \$ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 45 \$17,000/-)

450

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 30 April, 2018 10:39 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Nancy Lam; Choo, Thelma; Ye, Yong Kang Melvin
Subject: CMTD1801815/THE - SUV(LKK)/ PC3036Y & GBD6023A ACC ON 28.04.18

Our Reference: CMTD1801815/THE

Dear LKK AUTO,

Please make arrangement to conduct the survey for GBD6023A.

Please be informed that Thelma Choo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]

Sent: Monday, April 30, 2018 10:27 AM

To: Teo, Grace

Cc: Choo, Thelma; Ye, Yong Kang Melvin

Subject: RE: CMTD1801815/THE - PRI/ PC3036Y & GBD6023A ACC ON 28.04.18

Dear Grace

Please arrange LKK Auto Consultants to survey the car.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Monday, April 30, 2018 10:26 AM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1801815/THE - PRI/ PC3036Y & GBD6023A ACC ON 28.04.18

Our Reference: CMTD1801815/THE
Your Reference: GBD6023A

Without Prejudice

Date: 30th April 2018

Attention:
M/S FASTECH AUTO PTE LTD

Dear Nancy,

ACCIDENT INVOLVING PC3036Y & GBD6023A ON 28.04.2018

We refer to your Notice of Accident dated 30/04/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Saturday, April 28, 2018 11:49 AM

To: Claims - Motor Survey

Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBD6023A

Hi Sir

My client claiming your insured PC 3036Y.

Please kindly arrange PRS for GBD 6023A.

Date of accident 28.04.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520



Toyota Dyna

Price Range

Depreciation

2014

Vehicle Type



Submit

Advanced Search

Home > Used Cars > Think One Automobile & Trading > Toyota Dyna 150

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Dyna 150

Overview

Financial

Accessories

Similar

Research

Photos

Map



Think One Automobile



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$57,800

Depreciation \$8,670 /yr

View models with similar depreciation

Reg Date 29-Dec-2014

(6yrs 7mths 28days COE left)

Manufactured 2014

Mileage 54,105 km (16.2k /yr)

Transmission Manual

Engine Cap 2,982 cc

Curb Weight 1,800 kg

Fuel type Diesel

Features -

Accessories -

Description Best Selling 10 Foot Lorry, Book Now While Stock Last. Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!

COE \$49,889

OMV \$31,390

ARF \$1,570

Dereg Value \$33,268 as of today (change)

No. of Owners 1

Type of Veh Truck

Category -

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 23-Apr-2018 | Last Updated on: 23-Apr-2018

Tags: Toyota Dyna, 2014 Toyota Dyna, Toyota, Dyna, Used Toyota

Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$5,780 (change)

Maximum 90% Loan



Location Map



Price Analysis

Seller Information

Company

Think One Automobile & Trading

» dealer's pricelist

» 81 vehs sold | 165 vehs available

Address

20 Ubi Road 4

Search cars nearby this location

Location

Think One Building

Office No

65553300

Contact Person(s)

Dylan	83532939
Eric	91638879
Liza	97769403

Commercial Vehicle



Club Med amazing you

FLASH SALE

SAVE UP TO 45% + MYR500 PER ADULT



USE CODE: AVSALE

BOOK ONLINE

Compare



Toyota Dyna

Price Range

Depreciation

2014

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Athical Pte Ltd » Toyota Dyna 150

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres

Club Med
amazing youFLASH SALE
SAVE UP TO 45%
+ MYR500 PER ADULT

USE CODE: AVSALE

BOOK ONLINE

Compare

Toyota Dyna 150

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$60,800**Depreciation** \$9,360 /yr

View models with similar depreciation

Reg Date 28-Oct-2014

(6yrs 5mths 27days COE left)

Manufactured 2014**Mileage** -**Transmission** Manual**Engine Cap** 2,982 cc**Curb Weight** 2,120 kg**Fuel type** Diesel**Features** -**Accessories** Tailgate! Full Checker Plates!**Description** Very Rare Toyota Dyna 10FT Lorry With Tailgate & Full Checker Plate! High Trade In For All Vehicles! Call Now For Appointment!**COE** \$29,974**OMV** \$31,722**ARF** \$1,587**Dereg Value** \$19,479 as of today (change)**No. of Owners** 2**Type of Veh** Truck**Category** Premium Ad Car**Availability** Available

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 14-Apr-2018 | Last Updated on: 14-Apr-2018

Tags: Toyota Dyna, 2014 Toyota Dyna, Toyota, Dyna, Used Toyota

Upfront Payment

* more Financial info

Transfer Fee \$25**Down Payment** \$6,080 (change)

Maximum 90% Loan

1st Instalment \$866**Total Upfront Payment** \$6,971 (excluding insurance)

Estimates based on 90% loan at 3.4% interest rate. Check with seller for exact figure.

Items for Toyota Dyna

* View All



Seller Information

Company	Athical Pte Ltd	
	* dealer's pricelist	
	* 0 vehs sold 2 vehs available	
Address	23 New Industrial Road #04-08	
Location	Solstice Business Center	
Contact Person(s)	Mr Lee	91115811

Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3016K

Vehicle Details

Vehicle No.: GBD6023A

Vehicle to be Exported: No

Intended De-registration Date: 30 Apr 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA DYNA 150 MANUAL

Primary Colour: White

Manufacturing Year: 2014

Engine No.: 1KD2467411

Chassis No.: JTFAT35Y60K204003

Maximum Power Output: -

Open Market Value: \$27,856.00

Original Registration Date: 29 Dec 2014

First Registration Date: 29 Dec 2014

Transfer Count: 0

Actual ARF Paid: \$1,393.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Dec 2024

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$61,000.00

COE Rebate Amount: \$40,617.00

Total Rebate Amount: \$40,617.00

The information contained herein is correct as at 30 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2018 14:19
Date Of Accident	28/04/2018 08:00
Exact Location Of Accident	AYE TWDS TUAS AFTER LOWER DELTA LAMP POST 229
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD6023A
Insured/Policyholder	
Name Of Registered Owner	TEMPUR SINGAPORE PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98179853

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100397453-03
Cover Note Number	-

Driver

Name of Driver	THAM WAI MUN JEFFREY(TAN WEIMING JEFFREY)
NRIC No	S7438547H
Date Of Birth	13/11/1974
Occupation	OUTDOOR
Date Of Driving Pass	11/02/2004
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91112252
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 57 HAVELOCK RD #13-156
Postcode	161057
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC3036Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	THAM WAI MUN JEFFREY(TAN WEIMING JEFFREY)
Approximate Age	
Injuries Sustain	RIGHT SIDE OF BODY & ARMS
Injured person in which vehicle?	GBD6023A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180428/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180428/7001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/04/2018 10:25		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: THAM WAI MUN JEFFREY			Address: APT BLK 57 HAVELOCK ROAD #13-156 SINGAPORE 161057		
ID Type / ID No.: NRIC NO / S7438547H			Contact No.: Home/Office: Mobile: 91112252		
Nationality: SINGAPORE CITIZEN			Email: eileenlee0712@gmail.com		
Sex: Male	Age: 43	Date of Birth: 13/11/1974	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: DELIVERY DRIVER			Driving Licence Information: Class: 2B,3 Date of Expiry: 28/04/2018		

General Information of the Accident

Type of Accident:	Injury Government Property	Drink Drive: No	Date/Time of Accident: 28/04/2018 08:00	Type of Location: Straight Road
Location: AYER RAJAH EXPRESSWAY				
Lamp Post Number: 229				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD6023A	Lorry				Seriously Damaged	0
PC3036Y			Mini Bus	Silver	Seriously Damaged	3

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
GBD6023A	AIG ASIA PACIFIC INSURANCE PTE. LTD.			



**SINGAPORE
POLICE FORCE**



T/20180428/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180428/7001

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	THAM WAI MUN JEFFREY	ID No.	S7438547H
Related Vehicle	GBD6023A (Lorry)	Contact No.	91112252
Hospital/Clinic	24 HOUR WALK-IN CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: 28/04/2018
Date Treatment	28/04/2018	Date Discharge	28/04/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the stated date & time i was driving on the stated venue . I was in the 3rd lane & driving at 50km/hr speed. Out of Sudden, Vehicle B (GBD6023 A) that was driving behind me suddenly hit onto my rear portion of my vehicle. The Great Impact pushes my Vehicle to swerve to hit onto the Railing along the expressway, the great impact causes pain to my right side of body & arms



**SINGAPORE
POLICE FORCE**



T/20180428/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180428/7001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
ANG YI TING, STEPHANIE
Contact No.: 65476414

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
28/04/2018 10:25

Classification Of Case:

Date of Accident : 28/4/18 Accident Time: 8 00am (24-HR-Format)
 Accident Place : AYE towards Tuas after Lower Delta
 Vehicle No. (Car Plate No.) : 6B06023A Make/Model: Toyota Dyna
 Insurance Company : AIG Policy No: 2100397453-03
 Owner or Company Name /IC No. : Tempur Singapore Pte Ltd.
 Owner or Company Contact No. : T Owner's Hp 98179853 Company Tel
 DRIVER'S Name / IC No. : Tham Wat Mun Jeffrey
 DRIVER'S Date Of Birth : 15/11/74 DRIVER'S License Pass Date 03 Nov 2003
 Relationship of Owner & Driver : Spouse | Parents | Children | Sibling | Employee | Others:
 DRIVER'S Address : Blk 57 Harlock Rd #12-156
 DRIVER'S Contact No. / Alt No. : 1) ~~9311~~ 91112352 2)
 DRIVER'S Occupation : INDOOR | OUTDOOR (e.g. working inside or outside office)
 Email Address : shermyn.tang@tempursealy.com
 Weather & Road Surface : CLEAR & DRY | RAINING & WET | AFTER RAIN & WET
 Reporting Type : Reporting Only | Claim Other Party | Claim Own Insurance
 Number of Passengers (Including Driver): 1
 Was there any video Captured by car camera: YES | NO
 Exact purpose for which vehicle was being used at the time of accident: Private use | Work purpose
 Any Injury (If YES, Pls state): Yes

Other Party Driver's Particular (if any)

Vehicle No: <u>PL 30264 (Somp)</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: <u>88111994</u>	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

9/19/11

Diagram showing two rectangular blocks, B and A, connected by a horizontal line. Block B is on the left and block A is on the right. Both blocks have a diagonal line drawn across them from the top-left to the bottom-right.

A - GR06022
B - PL30364

As per police report.

I/We declare the foregoing particulars are true in every respect.



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180428/7001

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20180428/7001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/04/2018 10:25	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: THAM WAI MUN JEFFREY		Address: APT BLK 57 HAVELOCK ROAD #13-156 SINGAPORE 161057	
ID Type / ID No.: NRIC NO / S7438547H		Contact No.: Home/Office: Mobile: 91112252	
Nationality: SINGAPORE CITIZEN		Email: eileenlee0712@gmail.com	
Sex: Male	Age: 43	Date of Birth: 13/11/1974	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: DELIVERY DRIVER		Driving Licence Information: Class: 2B,3 Date of Expiry: 28/04/2018	

General Information of the Accident				
Type of Accident:	Injury: Government Property	Drink Drive: No	Date/Time of Accident: 28/04/2018 08:00	Type of Location: Straight Road
Location: AYER RAJAH EXPRESSWAY				
Lamp Post Number: 229				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD6023A	Lorry				Seriously Damaged	0
PC3036Y			Mini Bus	Silver	Seriously Damaged	3

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
GBD6023A	AIG ASIA PACIFIC INSURANCE PTE. LTD.			

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180428/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No: T/20180428/7001

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	THAM WAI MUN JEFFREY	ID No.	S7438547H
Related Vehicle	GBD6023A (Lorry)	Contact No.	91112252
Hospital/Clinic	24 HOUR WALK-IN CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: 28/04/2018
Date Treatment	28/04/2018	Date Discharge	28/04/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details

On the stated date & time i was driving on the stated venue . I was in the 3rd lane & driving at 50km/hr speed. Out of Sudden, Vehicle B (GBD6023 A) that was driving behind me suddenly hit onto my rear portion of my vehicle. The Great Impact pushes my Vehicle to swerve to hit onto the Railing along the expressway, the great impact causes pain to my right side of body & arms

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180428/7001

3 of 3

Report No. T/20180428/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP1B /
ANG YI TING, STEPHANIE
Contact No : 65476414

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
28/04/2018 10:25

Classification Of Case:

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6
#01-46/48/50 Autobay
SINGAPORE 417883

VEHICLE NO: GBD 6023A

Surveys must be notified
in advance of the following:
• Parts to be replaced: spray painting
• Supply damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Addressed
Hill
4/5 @ 17.000
15dy.
30/4/18

QTY	PARTICULAR	AMOUNT
1 PCS	REAR LICENCE PLATE BRACKET	Bent \$119.50
1 PCS	REAR CARGO DECK LOWER MEMBER	Bent \$566.10
1 PCS	REAR SPARE TYRE BRACKET & CHAIN	Tw/1/2m \$392.40
1 PCS	REAR TAILLAMP O/S	3/20 \$285.30
1 PCS	REAR TAILLAMP BRACKET O/S	Dis \$119.20
1 PCS	REAR EXHAUST PIPE	429.10
1 PCS	REAR EXHAUST PIPE MOUNTING	DD/Bent \$585.20
1 PCS	REAR CHASSIS FRAME O/S	twi \$112.00
1 PCS	FRONT PANEL	n \$1,800.00 X
1 PCS	FRONT PANEL 'DYN' EMBLEM	DD/Bent \$1,245.10
1 PCS	FRONT GRILLE	ru \$66.20
1 PCS	FRONT GRILLE LOGO	one \$867.92
1 PCS	FRONT BUMPER	ru \$56.90
1 PCS	FRONT BUMPER BRACKET N/S	Bent \$898.90
1 PCS	FRONT CORNER PANEL N/S	Bent \$195.27
2 PCS	HEADLAMPS @\$899.10	twi \$243.50
2 PCS	FRONT CABIN MOUNTINGS @\$285.00	699.10 x 2 = 1398.20 w/53w o/s one \$1,798.20
2 PCS	FRONT CABIN REAR PILLARS @\$485.10	17 \$570.00 X
1 PCS	FRONT DOOR N/S	n \$970.20 X
1 PCS	FRONT DOOR OUTER PILLARS N/S	Bent/Bul \$1,957.31
1 PCS	FRONT DOOR WHEEL ARCH PANEL N/S	DD/Bul \$899.30
1 PCS	FRONT DOOR RUBBER N/S	Bul \$545.10
1 PCS	FRONT DOOR INNER LOCK N/S	Tw-1 \$122.30
1 PCS	FRONT DOOR INNER TRIM BOARD N/S	17 \$261.20 X
1 PCS	FRONT DOOR LOWER RUBBER N/S	Def/one \$645.10
2 PCS	FRONT DOOR HINGES @\$79.50	tw-1 \$88.20
1 PCS	FRONT DOOR GLASS N/S	twi \$159.00
1 PCS	FRONT DOOR GLASS REGULATOR N/S	17 \$650.10 X
1 PCS	FRONT WINDSCREEN	SUC \$233.20 X
1 PCS	FRONT WINDSCREEN MOULDING	SUC \$1,987.92 X
1 PCS	FRONT STEP GARNISH N/S	ru \$247.69
1 PCS	FRONT FLOOR PANEL	one \$241.10
1 PCS	FRONT DASHBOARD	n \$1,650.10 X
		17 \$928.86 X

2570

1 PCS	AIR CON BLOWER	Cne	\$1,098.70	✓
1 PCS	AIR CON HEATER ASSY	17	\$1,855.10	X
2 PCS	FRONT CABIN REAR PILLAR EMBLEMS @\$45.50	als	\$91.00	122
1 PCS	AIR CON CONDENSER	3w/7w	\$1,261.30	✓
1 PCS	AIR CON ELECTRIC FAN ASSY	Cne/Jm	\$641.50	✓
1 PCS	AIR CON CONDENSER BRACKET	3w	\$195.40	✓
1 PCS	FRONT LOWER ARM N/S 188.20	3w/3w	\$688.20	✓
1 PCS	FRONT SHOCK ABSORBER N/S	tw	\$195.30	✓
1 PCS	FRONT WHEEL HUB N/S 645-10	Dye	\$845.10	✓
1 PCS	FRONT CROSS MEMBER	su	\$1,150.50	X
1 PCS	FRONT BALL JOINT N/S	tw	\$211.30	✓
1 PCS	FRONT STEERING ASSY	su	\$1,866.20	X
1 PCS	RADIATOR ASSY	17	\$899.20	✓
			\$32,507.17	
			LESS 25%	\$24,380.37

S.NETT

2 PCS	REAR CARGO BOX REAR DOORS @\$1800.00	3w/cw	\$3,600.00	2400
2 PCS	REAR CARGO BOX REAR DOOR LOCK BARS @\$600.00	3w	\$1,200.00	500
2 PCS	REAR CARGO BOX REAR DOOR INNER WOODENS @\$680.00	3w/cw	\$1,360.00	500
1 PCS	REAR CARGO BOX LOWER HINGES O/S	su	\$115.00	X
1 PCS	REAR 70KM/H STICKER	su	\$20.00	10
1 PCS	REAR LICENCE PLATE	3w	\$20.00	14
1 SET	REAR REVERSE SENSOR	3w/3w	\$280.00	200
1 PCS	REAR CARGO BOX REAR PILLAR O/S	3w	\$1,100.00	600
1 PCS	REAR CARGO BOX INNER FLOOR WOODEN	R	\$1,800.00	X
1 PCS	REAR CARGO BOX FRONT PANEL	R	\$1,200.00	X
1 SET	REAR CARGO BOX REAR CORPORATE STICKER	su	\$1,100.00	600
1 SET	FRONT BUMPER STICKER	17	\$180.00	X
1 PCS	FRONT DOOR 'ROC' STICKER N/S	su	\$50.00	30
1 SET	FRONT DOOR CORPORATE STICKER	su	\$100.00	90
1 SET	FRONT FLOOR PANEL INSULATOR	su	\$200.00	100

LABOUR CHARGES:

TOWING CHARGE	\$120.00	60
TO CHECK WIRING	\$80.00	30
TO DISMENTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMENTLE & REPLACING REAR EXHAUST	\$80.00	60
TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE	\$280.00	120
TO CONDUCT WHEEL ALIGNMENT	\$150.00	60
TO DISMENTLE & REFIX FRONT DASHBOARD	\$300.00	160
TO DISMENTLE & REFIX FRONT WINDSCREEN	\$120.00	80

TO DISMENTLE & REFIX DOOR MECHANISM
TO SPRAY RUST PROOFING
TO MOUNT VEHICLE ON CAR O-LINER
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$100.00 60
\$200.00 100
11 \$380.00 X
\$150.00 100
\$3,800.00 1800
\$2,500.00 1500

TOTAL \$45,045.37



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18007883/Usbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 08-06-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 3036Y	Veh. Inspected	GBD 6023A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801815/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	30/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTFAT35Y60K204003	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	YOKOHAMA	6 mm
L/H Front Tyre	195 R15	YOKOHAMA	6 mm
R/H Rear Tyre	155 R12 (D)	YOKOHAMA	6/6 mm
L/H Rear Tyre	155 R12 (D)	YOKOHAMA	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT N/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/04/2018	Inspection Date	30/04/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 6023A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR LICENCE PLATE BRACKET	BENT	119.50	119.50
1	REAR CARGO DECK LOWER MEMBER	BADLY DENTED	566.10	566.10
1	REAR SPARE TYRE BRACKET & CHAIN	TWISTED / JAMMED	392.40	392.40
1	REAR TAILLAMP O/S	BROKEN	285.30	285.30
1	REAR TAILLAMP BRACKET O/S	DISTORTED	119.20	119.20
1	REAR EXHAUST BOX	DENTED / BENT	585.20	429.10
1	REAR EXHAUST BOX MOUNTING	TWISTED	112.00	112.00
1	REAR CHASSIS FRAME O/S	TO REPAIR SEE LABOUR	1,800.00	-
1	FRONT PANEL	DENTED / BENT	1,245.10	1,245.10
1	FRONT PANEL "DYNA" EMBLEM	NECESSARY	66.20	66.20
1	FRONT GRILLE	CRACKED	867.92	867.92
1	FRONT GRILLE LOGO	NECESSARY	56.90	56.90
1	FRONT BUMPER	BENT	898.90	898.90
1	FRONT BUMPER BRACKET N/S	BENT	195.27	195.27
1	FRONT CORNER PANEL N/S	TWISTED	243.50	243.50
2	HEADLAMPS @\$899.10	N/S BROKEN / O/S CRACKED	1,798.20	1,398.20
2	FRONT CABIN MOUNTINGS @\$285.00	NOT NECESSARY	570.00	-
2	FRONT CABIN REAR PILLARS @\$485.10	TO REPAIR SEE LABOUR	970.20	-
1	FRONT DOOR N/S	BENT / BUCKLED	1,957.31	1,957.31
1	FRONT DOOR OUTER PILLAR N/S	DENTED / BENT	899.30	899.30
1	FRONT DOOR WHEEL ARCH PANEL N/S	BUCKLED	545.10	545.10
1	FRONT DOOR RUBBER N/S	TORN	122.30	122.30
1	FRONT DOOR INNER LOCK N/S	NOT NECESSARY	261.20	-
1	FRONT DOOR INNER TRIM BOARD N/S	DEFORMED / CRACKED	645.10	645.10
1	FRONT DOOR LOWER RUBBER N/S	TORN	88.20	88.20
2	FRONT DOOR HINGES @\$79.50	TWISTED	159.00	159.00
1	FRONT DOOR GLASS N/S	NOT NECESSARY	650.10	-
1	FRONT DOOR GLASS REGULATOR N/S	SERVICEABLE	233.20	-
1	FRONT WINDSCREEN	SERVICEABLE	1,987.92	-
1	FRONT WINDSCREEN MOULDING	NECESSARY	247.69	247.69
1	FRONT STEP GARNISH N/S	CRACKED	241.10	241.10

Report Ref No. CS/SMO18007883/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FLOOR PANEL	TO REPAIR SEE LABOUR	1,650.10	-
1	FRONT DASHBOARD	NOT NECESSARY	928.86	-
1	AIR CON BLOWER	CRACKED	1,098.70	1,098.70
1	AIR CON HEATER ASSY	NOT NECESSARY	1,855.10	-
2	FRONT CABIN REAR PILLAR EMBLEMS @\$45.50	N/S NECESSARY	91.00	45.50
1	AIR CON CONDENSER	BENT / TWISTED	1,261.30	1,261.30
1	AIR CON ELECTRIC FAN ASSY	CRACKED / JAMMED	641.50	641.50
1	AIR CON CONDENSER BRACKET	BENT	195.40	195.40
1	FRONT LOWER ARM N/S	DENTED / BENT	688.20	588.20
1	FRONT SHOCK ABSORBER N/S	TWISTED	195.30	195.30
1	FRONT WHEEL HUB N/S	DAMAGED	845.10	645.10
1	FRONT CROSS MEMBER	SERVICEABLE	1,150.50	-
1	FRONT BALL JOINT N/S	TWISTED	211.30	211.30
1	FRONT STEERING ASSY	SERVICEABLE	1,866.20	-
1	RADIATOR ASSY	NOT NECESSARY	899.20	-
	LESS 25% DISCOUNT		-8,126.80	-4,195.75
			24,380.37	12,587.24
	<u>SPECIAL NETT ITEMS</u>			
2	REAR CARGO BOX REAR DOORS @\$1800.00 (SN)	BENT / CRACKED	3,600.00	2,400.00
2	REAR CARGO BOX REAR DOOR LOCK BARS @\$600.00 (SN)	BENT	1,200.00	500.00
2	REAR CARGO BOX REAR DOOR INNER WOODENS @\$680.00 (SN)	BENT / CRACKED	1,360.00	500.00
1	REAR CARGO BOX LOWER HINGES O/S (SN)	SERVICEABLE	115.00	-
1	REAR 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	REAR LICENCE PLATE (SN)	BENT	20.00	14.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR CARGO BOX REAR PILLAR O/S (SN)	DENTED	1,100.00	600.00
1	REAR CARGO BOX INNER FLOOR WOODEN (SN)	TO REPAIR SEE LABOUR	1,800.00	-
1	REAR CARGO BOX FRONT PANEL (SN)	TO REPAIR SEE LABOUR	1,200.00	-
1	SET REAR CARGO BOX REAR CORPORATE STICKER (SN)	NECESSARY	1,100.00	600.00
1	SET FRONT BUMPER STICKER (SN)	NOT NECESSARY	180.00	-
1	FRONT DOOR "ROC" STICKER N/S (SN)	NECESSARY	50.00	30.00

Report Ref No. CS/SMO18007883/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT DOOR CORPORATE STICKER (SN)	NECESSARY	100.00	90.00
1	SET FRONT FLOOR PANEL INSULATOR (SN)	NECESSARY	200.00	100.00
			12,325.00	5,044.00
	LABOUR			
	TOWING CHARGE.		120.00	60.00
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMENTLE & REPLACING REAR EXHAUST.		80.00	60.00
	TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE.		280.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO DISMENTLE & REFIX FRONT DASHBOARD.		300.00	160.00
	TO DISMENTLE & REFIX FRONT WINDSCREEN.		120.00	80.00
	TO DISMENTLE & REFIX DOOR MECHANISM.		100.00	60.00
	TO SPRAY RUST PROOFING.		200.00	100.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO REFILL AIR CON GAS.		150.00	100.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR CHASSIS FRAME O/S,FRONT CABIN REAR PILLARS,FRONT FLOOR PANEL,REAR CARGO BOX INNER FLOOR WOODEN AND REAR CARGO BOX FRONT PANEL.		3,800.00	1,800.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,500.00
			8,340.00	4,180.00
	GRAND TOTAL		45,045.37	21,811.24
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,000.00

Report Ref No. CS/SMO18007883/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.