

ASS. REC. BY:

REF:

CS/CTU18007929 / Kvbnz

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Irene Tay of CTL Date/Time: 30/04/2018 3:06pm
 Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 3599 R Insured: SLJ 302867

at Workshop in/s City Auto Tel: 6453 1235

of 160 Sin Ming Drive # 05-01

Policy No: Claim No: SNM18002101002

Sum Insured: Excess:

Make of Veh: D.O.A. 24/04/2018
 (Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 30/04/2018 3:07pm

Person Contacted:

Vronica

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKN 3599 R - X
	SLJ 302867 - X
14/8/18	@ 3:30pm Vronica said waiting Kenneth to finalise
22/10 @ 3:58pm	✓ 1 Lr @ 1900 email confirmed with Vronica (Red 1231-66, 391)

ASS. REC. BY:

REF: C121

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

15/5 Pk pass to Coroner

RECEIVED 23 OCT 2010

Veh No:

SKN 3599Rr Regn: 06114

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Alfa Romeo Giulietta 1368

Colour:

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

79992

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

EAR940000.07158660

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

225/40 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

R/Bal.

mm

mm

L/Bal.

L/Bal.

mm

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

22/10 - typist

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

merimen

1900p

TOTAL

220

Catherine Chong (LKK Auto)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Monday, 30 April, 2018 3:06 PM
To: City Auto
Cc: Irene Tay; assignments@lkkauto.com; 'SUR'; Admin A
Subject: OUR REF: SNM18D02101C02/8 & YR REF:SKN3599R -TO CONDUCT PRE REPAIR SURVEY -SKN3599R

Without Prejudice

Dear Vronica,

We refer to your email on even date.

We have appointed M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Marcus/Simon/Kalvin,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Irene Tay 6389 617

Best Regards,

Angie Foo

Claims Executive

Claims Department – Motor Division

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6186

Fax (65) 6224 7175 / 6224 7478

Email: angie.foo@sg.cntaiping.com

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: City Auto [mailto:cityauto@singnet.com.sg]
Sent: Monday, 30 April, 2018 9:42 AM
To: Claims Dept of CTI
Subject: Arrange survey of SKN3599R D.O.A: 24/04/2018

Dear Arrangement survey dept,

Kindly arrange **LKK AUTO CONSULTANTS PTE LTD** survey on following vehicle:

Survey TP,

Your vehicle : SLJ3028G

Our vehicle : SKN3599R

D.O.A : 24/04/2018

LOCATION : BLK 160, Sing Ming Drive, Sin Ming Auto City #05-01 Singapore 575722

Thank you.

Best Regards,

Vronica Law
City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate,
#01-60/62 Sin Ming Road,
Singapore 575643
Tel : 6453 1235
Fax : 6453 7944

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	1004E

Vehicle Details

Vehicle No.:	SKN3599R
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Oct 2018
Vehicle Make:	ALFA ROMEO
Vehicle Model:	GIULIETTA 1.4 TURBO TCT SMT ABS D/AB
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	940A20001744125
Chassis No.:	ZAR94000007158660
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$27,672.00
Original Registration Date:	04 Jun 2014
First Registration Date:	04 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$20,741.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jun 2024
PARF Rebate Amount:	\$15,555.00

Intended COE Rebate Details

COE Expiry Date:	03 Jun 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$67,290.00
COE Rebate Amount:	\$37,789.00
Total Rebate Amount:	\$53,344.00

The information contained herein is correct as at 22 Oct 2018

OK



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

CHINA TAIPING INSURANCE (S) PTE LTD

3
ANSON RD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
Attention: Lee Jia Min
Contact : 94871217

Fax No. : 62247175

Estimate : QUOT201804-000655(00)

Date : 30/04/2018
Vehicle No. : SKN3599R
Make/Model : ALFA ROMEO GIULIETTA 1.4
TURBO TCT SMT ABS D/AB
Mileage (km) : 0
Chassis No. : ZAR94000007158660
Accident Date : 24/04/2018 00:00:00
Claim No. : SLJ3028G
Reference : SKN3599R
Policy No. : VCX/P1514693

*Not Authorized
61 hrs & 1900k
Resurvey After Paint*

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	Rear bumper	1.0	1,561.06	1,561.06
2	Rear bumper red reflector	1.0	118.04	118.04
3	Rear bumper garnish	1.0	610.47	610.47

List Total :

20% Discount S\$

2,289.57

457.91

1,831.66

SPECIAL NET :

1	Reverse sensor	1.0	250.00	250.00
---	----------------	-----	--------	--------

SPECIAL NET Total S\$:

250.00

LABOUR :

- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts
- Spray painting on affected & replace parts

450.00 450.00

600.00 600.00

1,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

E & O.E.

Date:

Total S\$ 3,131.66

GST 7% S\$ 219.22

Amount Due S\$ 3,350.88

N/A

for CITY AUTO PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007929/KVBN2

Date: 25/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3018701700
Claimant Vehicle No :	SKN3599R	Insured Vehicle No :	SLJ3028G
Date of Loss:	24/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D02101C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN3599R		
Make & Model:	ALFA ROMEO GIULIETTA, 1.4 TURBO TCT SMT ABS D/AB (A)	Engine No:	940A20001744125
Reg. Date:	04/06/2014 (Man. Year: 2012)	Chassis No:	ZAR94000007158660
Colour:	Metallic Black	Odometer:	79992 km
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40ZR17	Rear Tyre Size:	225/40ZR17
Front Left Side:	Nexen 4 mm	Rear Left Side:	Nexen 4 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,081.66	1,937.22	144.44	6.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	470.00	580.00	55.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,131.66	2,407.22	724.44	23.13
Approved Total (Overridden) (\$\$)		1,900.00		
(\$\$)	3,131.66	1,900.00	1,231.66	39.33
+ GST 7.00/7.00% (\$\$)	219.22	133.00	86.22	39.33
Nett Amount (\$\$)	3,350.88	2,033.00	1,317.88	39.33

INSPECTION

Date of Assignment:	02/05/2018	
Date Inspected:	14/05/2018 Inspected At:	160 Sin Ming Drive #05-01 Repairer: City Auto Pte Ltd (Sin Ming) (HQ)
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2018)
Parts:	144	ALFA ROMEO GIULIETTA 1.4 TURBO TCT SMT ABS D/AB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN3599R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,561.06 FL	*1,561.06 FL
2	1		*REAR BUMPER RED REFLECTOR	Serviceable	118.04 FL	*- FL
3	1		*REAR BUMPER GARNISH	Dented/Cut	610.47 FL	*610.47 FL
4	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
					Sub Total (S\$)	2,539.57
					- List Item Discount on L Items 20.00/20.00% (S\$)	457.91
					Total Parts (S\$)	1,937.22

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN.REFIX AND TO RENEW ACCIDENT PARTS	New	450.00	250.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	600.00	220.00
Gross Labour Cost (\$\$)			1,050.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >