

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2018 11:08
Date Of Accident	01/05/2018 14:00
Exact Location Of Accident	JUNCTION OF CLARKE QUAY AND RIVER VALLEY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD5700S
Insured/Policyholder	
Name Of Registered Owner	DAPHNE NG CHIA LI (DAPHNE HUANG JIALI)
NRIC No	S8028886G
Email Address	DAFNIE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96876908
Alternative Phone No	OTHERS-96876908

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5081507196-01
Cover Note Number	

Driver

Name of Driver	DAPHNE NG CHIA LI (DAPHNE HUANG JIALI)
NRIC No	S8028886G
Date Of Birth	27/07/1980
Occupation	INDOOR
Date Of Driving Pass	03/05/2005
Driving Experience	12 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96876908
Fax Number	
Contact Number	OTHERS-96876908
Email Address	DAFNIE@GMAIL.COM

Address	54 NEW UPPER CHANGI ROAD #04-1462
Postcode	461054
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN (TYPE OF COLLISION IS HEAD TO SIDE)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CAPTURED WRONG DIRECTION
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PZ24E
Vehicle Make/Model/Colour	MAN
Details Of Properties	
Vehicle Category	BUS
Name of Driver	LI GUIDONG
NRIC/Passport Number	O57601167
Contact Number	96549580
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

ASSIGNMENT (IDAC)

By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Motorcar ()
 - b) Motorcycle ()
 - c) Bicycle ()
- 2) Vehicle hit ??
 - a) Pedestrian ()
 - b) Animal ()
- 3) Vehicle hit Road Side Objects:
 - a) Govt. Property ()
(Eg: signboard, barrier, tree etc)
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other, _____
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case
 - a) Stolen ()
 - b) Damage found when recovered, ()
- 8) Fire
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SLD J7005 Yr Regn: Jun / 2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MPV / Truck / Trailer or _____
 Make & Model: Honda Vezel 1.5X CVT 1496
 Colour: WHITE Transmission Type: Auto / Manual
 Eng/No: L15B4036755 Sp. Reading: 28292
 C/No: 211116750
 Gen. Cond: Good / Fair / Poor / Burnt or _____
 Steering: Order / Jammed / Leaked / Burnt or _____
 Brake: Order / Jammed / Leaked / Burnt or _____
 Modi: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60 R16
 R: 215/60 R16
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm

Parallel Import: Yes / No Towed-In: Yes / No
 Repair Type: LS / I.B.I Towing Required: Yes / No
 No of Repair Days: _____ Vehicle in Idac: Yes / No
 D.O.I. 11/05/2018 Time: 1400hrs

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 - e. Animal () f. Govrn Object () g. Road Work Object ()
 - h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 - e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started: _____ Time completed: _____

- 1) CSO
- 2) ASS
- 3) Entire Operation Completed Time:

Condition Legend

(1) Assembled (2) Damaged (3) Discontinued (4) Cracked (5) Cured (6) Scratched (7) Deformed (8) Stretched (9) Bubbled (10) Broken (11) Necessary (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (Frt)

Actions/AC

(1) Replace (✓) (2) Repair (X) (3) Check (✓) (4) Not Consistent (NC)

Aug 2005

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR		
1005	992341	Frt Bumper Clips	NAC		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NAC		
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt RH Bumper Fog Lamp MIRROR	SCR		
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	SCR		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BT		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: **SLD 5700S**

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BT		
1106	991739	Frt RH Fender Inner Panel	BT		
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector	OK		2
1109	991740	Frt RH Fender Inner Shield	OK		
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim	OK		
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Frt RH Door	BT		
		Rear RH Door	SCR		

No of Items: _____

Accessories: _____

original copy

AUTOR CARIQ

\$ 505700 S

ITEM	QTY	ITEM	CON	ACT
1272	995165	Frt LH Shock Absorber		
1273	991944	Frt LH Shock Absorber Mounting		
1274	990632	Frt LH Coil Spring		
1275	995198	Frt LH Knuckle Arm		
1276	995199	Frt LH Knuckle Arm Bearing		
1277	995174	Frt LH Lower Arm		
1278	995169	Frt LH Upper Arm		
1279	995183	Frt LH Tie Rod		
1280	995143	Frt LH Drive Shaft		
1281	990661	Frt LH Control Arm		
1282	992062	Frt LH Trailing Arm		
1283	991848	Frt LH Leaf Spring		
1284	991293	Frt LH Brake Disc Rotor		
1285	991281	Frt LH Brake Caliper		
1286	991292	Frt LH Brake Pipe		
1287	991287	Frt LH Brake Hose		
1288	991295	Frt LH Brake Sensor Wire		
1289	991989	Frt Stay Bar Bracket		
1290	994455	Steering Rack & Pinion		
1291	994435	Steering Cross Member		
1292	994519	Frt Sub Frame		
1293	992093	Frt Sub Frame Mounting		
1294	991217	Frt Anti Roll Bar		
1295	991219	Frt Anti Roll Bar Linkage		
1296	990887	Engine Block		
1297	990890	Engine Block Gasket		
1298	990972	Engine Oil Sump		
1299	990960	Engine Oil *		
1300	992224	Gear Box Assy		
1301	992229	Gear Box Gasket		
1302	992241	Gear Box Oil Sump		
1303	992257	Gear Oil		
1304	990534	Centre Exhaust Pipe Assy		
1305	990532	Centre Exhaust Mounting		
1306	991134	Floor Panel		
1307	993719	Rear LH Shock Absorber		
1308	993723	Rear LH Shock Absorber Mounting		
1309	993170	Rear LH Coil Spring		
1310	993550	Rear LH Knuckle Arm		
1311	993551	Rear LH Knuckle Arm Bearing		
1312	993597	Rear LH Lower Arm		
1313	993884	Rear LH Upper Arm		
1314	995161	Rear LH Drive Shaft		
1315	995216	Rear LH Control Arm		
1316	993881	Rear LH Trailing Arm		
1317	993573	Rear LH Leaf Spring		
1318	992941	Rear LH Brake Disc Rotor		
1319	992937	Rear LH Brake Caliper Assy		
1320	990434	Rear LH Brake Pipe		
1321	992946	Rear LH Brake Hose		
1322	993819	Rear Sub Frame		
1323	993820	Rear Sub Frame Mounting		
1324	992813	Rear Anti Roll Bar		
1325	990168	Rear Anti Roll Bar Linkage		
1326	990202	Axle Beam		
1327	990170	Rear Axle Panhard Rod		
1328	990810	Differential Assy		
1329	992706	Propeller Shaft		

ITEM	QTY	ITEM	CON	ACT
1330	991935	Frt RH Shock Absorber		
1331	991944	Frt RH Shock Absorber Mounting		
1332	990632	Frt RH Coil Spring		
1333	991844	Frt RH Knuckle Arm		
1334	991845	Frt RH Knuckle Arm Bearing		
1335	991851	Frt RH Lower Arm		
1336	992061	Frt RH Upper Arm		
1337	992040	Frt RH Tie Rod		
1338	991692	Frt RH Drive Shaft		
1339	990661	Frt RH Control Arm		
1340	992062	Frt RH Trailing Arm		
1341	991848	Frt RH Leaf Spring		
1342	991293	Frt RH Brake Disc Rotor		
1343	991281	Frt RH Brake Caliper		
1344	991292	Frt RH Brake Pipe		
1345	991287	Frt RH Brake Hose		
1346	991295	Frt RH Brake Sensor Wire		
1347	993720	Rear RH Shock Absorber		
1348	993723	Rear RH Shock Absorber Mounting		
1349	993173	Rear RH Coil Spring		
1350	993550	Rear RH Knuckle Arm		
1351	993551	Rear RH Knuckle Arm Bearing		
1352	993601	Rear RH Lower Arm		
1353	993885	Rear RH Upper Arm		
1354	993322	Rear RH Drive Shaft		
1355	993178	Rear RH Control Arm		
1356	995117	Rear RH Trailing Arm		
1357	995110	Rear RH Leaf Spring		
1358	992942	Rear RH Brake Disc Rotor		
1359	992938	Rear RH Brake Caliper Assy		
1360	990434	Rear RH Brake Pipe		
1361	992947	Rear RH Brake Hose		

No of Items: _____ Assessor: _____

Original copy

Claim Handling

Task Transfer Exit

Accident MT/0992566

LOS SAL SUB

Policy No.	5081507196-01	Vehicle No.	SLD57005	GST Registration No.	
Policyholder Name	DAHPNE NG CHIA LI (DAHPNE HUANG JIALI)			Policyholder NRIC	S8028886G
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	96876908	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☐ No ☒ Yes	TCA	☐ No ☒ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	10	Private Hire	No

Accident Details

Report Date	02/05/2018 12:08	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Major/Minor Road
Date of Accident	01/05/2018	Time of Accident hh:mm	14:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTRE	Orange Force	No	ICM No.	
Accident Location	JUNCTION OF CLARKE QUAY AND RIVER VALLEY ROAD				

Benefits

Excess

Own damage Excess	600.00	Additional Excess	0.00	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 54 #04-1462	Address 2	NEW UPPER CHANGI ROAD	Address 3	SINGAPORE 461054
Address 4		Address Type	Singapore address	Post Code	461054
Unit No.		Related Policy Number	5081507196-01		

OI Driver Info

Driver Name	DAHPNE NG CHIA LI	Driver Type	Main Driver	Driver DOB	27/09/1980
Unnamed driver Name		Driver NRIC	S8028886G	Driving Experience	12
Register Date of Driver License	03/05/2005	Driver Age	37	Contact No.(Home)	
Contact No.(Mobile)	96876908	Contact No.(Office)		Address 3	SINGAPORE 461054
Address 1	BLK 54 #04-1462	Address 2	NEW UPPER CHANGI ROAD	Post Code	461054
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.	SLD57005	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes ☐ No ☒
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Chop

LOS SAL SUB

Claim Type	OD-MD	Insured Name	DAHPNE NG CHIA LI (DAHPNE HUANG JIALI)	Insured NRIC	S8028886G
Contact No.(Mobile)	96876908	Contact No.(Home)	64483990	Contact No.(Office)	
Email Address	dahnie@gmail.com	OT Vehicle Number	SLD57005	TP Vehicle Number	P224E
Claim Description	SLD57005 / P224E ON 1 May 2018	Insured Liability	Not at Fault	Name of Preferred Workshop	
Preferred Workshop Contact No.		Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Received
Require Finalisation	Yes	Claim Close Date		Date Received	11/05/2018 17:09
Date Registered	02/05/2018 12:33	Workshop Repairer		Total Loss but Repaired	
Report Taken By	ROSLI WAHAB			OD Excess Collected by Workshop	
Print AK letter					

Modification History 11/05/2018 17:09 s069568 Modify Claim Type(OD-MX-->OD-MD)

Special Claim Creation Approval

Approval	Reason
----------	--------

Remarks

damage assessment Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	VEZEL	Engine Capacity	
Date of Registration	21/06/2016	Class No.	BU11116750	Parallel Import	☐ Yes ☒ No
Towing Required	☐ Yes ☒ No	Vehicle in IDAC	☐ Yes ☒ No	Survey Current Status	
Type of Tender	Please Select	Assessor Name	ROSLI WAHAB		
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTRE	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen		Total Loss	☐ Yes ☒ No		
Parts & Labour					

5/11/2018

Claim Handling (damage assessment Claim Task MT/0992566 / Claim 001 OD-MD)

Cost

Market
Value(\$)

Scrap Value(\$)

Economical Repair Value(\$)

Remark

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
next						
Not Applicable	1	39600602	SHOCK ABSORBER MOUNTING (FRONT RIGHT)	1	Unconfirm	X
ABS	2	36600102	SHOCK ABSORBER (FRONT RIGHT)	1	Unconfirm	X
ABSORBER	3	30000102	KNUCKLE ARM (FRONT RIGHT)	1	Unconfirm	X
ACCELERATOR	4	30000202	KNUCKLE ARM BEARING (FRONT RIGHT)	1	Unconfirm	X
ACTUATOR	5	30500102	LOWER ARM (FRONT RIGHT)	1	Unconfirm	X
ADVERTISEMENT STICKER	6	16000101	BUMPER (FRONT)	1	Replace	X
	7	16002401	BUMPER CLIPS (FRONT)	1	Replace	X
	8	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
	9	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
	10	31700102	MIRROR (RIGHT)	1	Repair	X
	11	27700101	HEAD LAMP (LEFT)	1	Unconfirm	X
	12	27700102	HEAD LAMP (RIGHT)	1	Replace	X
	13	148001	BONNET	1	Repair	X
	14	25400103	FENDER (FRONT RIGHT)	1	Replace	X
	15	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Repair	X
	16	25401301	FENDER LOWER PROTECTOR (FRONT LEFT)	1	Replace	X
	17	25401302	FENDER LOWER PROTECTOR (FRONT RIGHT)	1	Replace	X
	18	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
	19	448014	WHEEL RIM	1	Replace	X
	20	23300202	DOOR (FRONT RIGHT)	1	Replace	X
	21	23300204	DOOR (REAR RIGHT)	1	Repair	X

Save Submit

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MNA418056973-02 Vehicle Registration No: SLD5700S
Name (as shown in NRIC): DAPHNE NA CHIA LI NRIC/FIN/Passport No: S8028886G
(* ~~Vehicle Driver~~ / Vehicle Owner) (*) Please delete as appropriate
Address: 54 NEW UPPER CHANGI ROAD #04-1462 Singapore 461054
Contact (Tel): _____ Mobile No.: 96876908
Email Address: dafnie@gmail.com
Date of Accident: 01/05/2018 Time of Accident: 14:00
Place of Accident: River Valley Road
Insurance Company: NTUC INCOME

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To change from claiming against third party to
my own insurance policy.

Policyholder / Driver's Signature: 

Date: 11/5/2018

Reporting Centre Personnel's Signature: 

Name: _____

NRIC/FIN No.: _____

Date: 11/05/2018

From: Tan Siew Choo <siewchoo.tan@income.com.sg>
Sent: Monday, 14 May, 2018 3:02 PM
To: Lee Sheng Motor
Cc: NAC-Bukit Merah
Subject: SLD5700S, OD claim no : MT/0992566

Importance: High

Dear Lee Sheng,

Veh is still with owner Ms Daphne Ng (tel : 96876908), pls assist to liaise with her directly.

OD excess of \$600/- is applicable

Survey required, pls arrange personally at mtsurvey@income.com.sg

FOR PAYMENT: Please forward the Invoice & Discharge Voucher within 14 days after the repair has been done/ finalized with Surveyor to my email, cc a copy to Yap Chee Ling at cheeling.yap@income.com.sg

Regards.

Without Prejudice

Tan Siew Choo
Senior Claims Executive
Motor Insurance
T +65 6430 7882
www.income.com.sg



Our Ref: MT/CA/OD/051/0992566-001/TSC

14 May 2018

LEE SHENG AUTO PTE. LTD.

1 KAKI BUKIT AVENUE 6

BLK C #01-58 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

Dear Sir

CLAIM NUMBER: MT/0992566-001

REPAIR OF VEHICLE NUMBER: SLD5700S

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 14 May 2018

Make: HONDA

Model: VEZEL

Estimated Repair Days: 7

Location: NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)

Address: BLK 1007 #01-11 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE INDUSTRIAL ESTATE SINGAPORE

• 159721

Benefits Applicable: N/A

• Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at motor@income.com.sg.

Yours sincerely

Low Choo Mee

Senior Manager

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.