

22/03/2002

ASS. REC. BY:

REF: CS/CT118007960/RLS b02

Special Instruction:

Surveyor
Insurer

Rasul

ASSIGNMENT (Office)

From (Person):

Shawn Han

of

CTI

Date/Time: 02/05/2018 11:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 7305Z

Insured:

SKS 39J

at Workshop m/s

Borneo Motor

Tel:

of

2 Pandan Crescent

Policy No:

DMP CN303612180Z

Claim No:

SNM18 D02213C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/04/2018

CA / REV / REP. / REV 24 HRS wpi

03052018

H.O.D. Endorsement:

Date/Time:

02/05/2018 12:11pm

Person Contacted:

Thomas

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SKW 7305Z - CS/msh17023233/Rlgbnz	DAF: 22.11.17
	SKS 39J - CC3 / ALH16005664 / Khg3ga	DAF: 23/03/16

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

D.O.A. 28/04/18

D.O.I.

03/05/18

Survey held at

Borneo Motor

Des. of Damages: Frt / Rear / O/S / N/B / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	P/P \$14,491.70
	\$30,571.12 - \$14,491.70 (Reduc - 52%)

Date/Time, File Pass to?

17/05/18

1) Typist

Date/Time, File Return to?

2) .

☐ : Preli. Report☒ : Final Report

Days Of Repair:

10

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$

P/P \$14,491.70

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$