

ASS. REC. BY:

REF: 09/FCL18007973/Avb n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): WS Hung Yin Min of FCL Date/Time: 02052018 2.12pm

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 9748D Insured: SMA 98156

at Workshop m/s: Premium Carz Tel: 636 9100

of Bik i Kaki Bukit Ave 6 #01-90

Policy No: _____ Claim No: 018003374MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27042018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: _____

Date/Time: 02052018 2.16pm Person Contacted: Aun Teng Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLW 9748D - x</u>
	<u>SMA 98156 - NB/INC17017350/ Kijahz</u> <u>Dat: 041017</u>
<u>3/5/18</u>	<u>Email FCI informed pending for repairer est</u>
<u>27/6/18</u>	<u>Adrian confirmed \$ 947 (Real 120, 119)</u>
<u>28/6/18</u>	<u>Email preli revised to FCI</u>

CLASS. REC. BY: Adrian King

REF: _____

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLW974817 Yr Regn: 2018, March
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Wish c.c. 1798
 Colour: Orange A/C: Insured / Std / NI / NA
 Sp. Reading: 24220 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDG620W50J008230
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Tyre Size: F: 195/65R15
 R: 195/65R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 02/05/18
 Survey held at Premium Carz
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
	RECEIVED 28 JUN 2018
	<u>28/6/2018</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) 28/6 - typist
 Report Format : TP
 Lump Sum / I.B.J.: (\$) 947 / 2

Days Of Repair: 2
 Resurvey No. of Trip: -
 Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee:	<u>100</u>
Transportation:	<u>50</u>
\$ + RS. SI	
Photos	<u>7</u>
Others	
TOTAL	<u>157</u>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: D18003374MFSH
Our ref: CS/FCII8007973/Avb

Date : 28/6/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLW 9748D


We thank you for your instruction on 2/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/5/2018 at the premises of M/s PREMIUM CARZ and have the following to report:-

Workshop Estimate Amount	: S\$1,067.00
Revised Estimate Amount	: S\$947.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	30-04-2018	Our Ref No. D18003374MFSH
Accident Date	27-04-2018	Claim Type. Third Party
Insured Vehicle	SHA9815G	Third Party Vehicle. SLW9748D
Survey Location	1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT	
Contact Person.	AUN TENG	
Contact No.	66369100/ 66369100	Fax No. 66369113
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM CARZ SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 28 June 2018 8:58 AM
To: 'Claim Workflow System'
Cc: 'AUNGYINMIN@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18003374MFSH/1, SLW 9748D
Attachments: SLW 9748D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLW 9748D
Date of survey: 2/5/2018
Number of days :2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 3 May 2018 12:07 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003374MFSH/1, SLW 9748D

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLW 9748D on 2/5/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 2 May 2018 2:16 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003374MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 2 May, 2018 2:12 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18003374MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Friday, 11 May 2018 11:59 AM
To: 'Claim Workflow System'; SUR
Cc: assignments
Subject: RE: SURVEYOR APPOINTED; OUR REF : D18003374MFSH ; YOUR REF: SLW9748D

Dear Sir / Madam,

Thank you for your email.

Dear Veron,

FYNA. Our Ref: CS/FCI18007973/Avb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 11 May, 2018 11:54 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: cwsmotorclaims@msfirstcapital.com.sg
Subject: RE: SURVEYOR APPOINTED; OUR REF : D18003374MFSH ; YOUR REF: SLW9748D

Dear Sirs,
Please refer to our email below.

Thanks & Regards,
Motor Claims Department
MS First Capital Insurance Ltd
cwsmotorclaims@msfirstcapital.com.sg

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, May 11, 2018 9:21 AM
To: aunteng@premiumcarz.com.sg
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; ASSIGNMENTS@LKKAUTO.COM;
cwsmotorclaims@msfirstcapital.com.sg
Subject: RE: SURVEYOR APPOINTED; OUR REF : D18003374MFSH ; YOUR REF: SLW9748D

Dear Sirs,

Having reviewed the matter, we wish to confirm that we admit liability subject to quantum to be agreed later.

You may liaise with our appointed surveyor accordingly.

Thanks & Regards,

Motor Claims Department

MS First Capital Insurance Ltd

cwsmotorclaims@msfirstcapital.com.sg

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 3 May 2018 12:07 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003374MFSH/1, SLW 9748D

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLW 9748D on 2/5/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 2 May 2018 2:16 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003374MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 2 May, 2018 2:12 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003374MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Date : 27/04/2018

TO: MS First Capital Insurance Ltd
 36 Robinson Road
 #16-01 City House
 Singapore 068877

Veron

Our Customer : Thian Chee Seng
 Vehicle No : SLW9748D
 Model : Toyota Wish 1.8CVT
 Manufacture Year : 2017
 Date of Accident : 13/03/2018
 Total Estimate Repair Days : 1
 Total Pages : 1

Attn : Motor Claim Department
 Fax : 6507 3849

Re: Repair Estimate For Third Party Claim against SHA9815G

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Side mirror mechanism RH	1	\$956.00	\$956.00	✓
2	Side mirror cover RH	1			
3	Side mirror signal lamp RH	1			
			Sub Total	\$956.00	
			Less 25%	\$239.00	
			Total for Parts	\$717.00	
B.	Labour				
1	To check wiring.			\$50.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$150.00	100 230
3	Spray painting all affected parts & areas.			\$150.00	100.
			Total Labour	\$350.00	
			Total Repair Cost	\$1,067.00	

*total: 947.
 (P/P)*

*Adrian Lij
 P/P 02/05/18
 02 days.*

Yours faithfully,

Aun Teng
 f Premium Carz Services Pte Ltd

Insurance consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007973/Avbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9815G	Veh. Inspected	SLW 9748D
Policy No.		Coverage (\$)	0.00
Claim No.	D18003374MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	02/05/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDGG20W50J008230	Colour	ORANGE
Odometer	2422	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/04/2018	Inspection Date	02/05/2018
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 9748D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE MIRROR COVER RH }	CRACKED	956.00	956.00
1	SIDE MIRROR MECHANISM RH }	CRACKED	-	-
1	SIDE MIRROR SIGNAL LAMP RH }	CRACKED	-	-
	LESS 25% DISCOUNT		-239.00	-239.00
			717.00	717.00
	LABOUR			
	TO CHECK WIRING.		50.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE ALL AFFECTED PARTS & AREAS.		150.00	100.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		150.00	100.00
			350.00	230.00
	GRAND TOTAL		1,067.00	947.00
	RECOMMENDED COST OF REPAIRS			947.00

Report Ref No. CS/FC118007973/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.