

ASS. REC. BY:

REF:

CS3/II 18007978 / G24b57

Special Instruction:

SURVIVAL

meimen

G2

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

02052018 9.49am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBG 9643A

Insured:

SHC 84724

at Workshop m/s

Tel:

8380 2233

of

10 Kaki Bukit Rd 2 #01-16

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06042018

(Client's Record)

CA / REV / REP. / REV 24 HRS wp.

H.O.D. Endorsement:

Date/Time:

0205 2018 1057am

Person Contacted:

Jacky

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (X) Estimate
	FBG 9643A - X
	SHC 84724 - CS3/II 16010582 / Kpubn2
	Dismantle: 3/5/2018
	After repair: 14/5/2018

Ref: 060446

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. _____

at Workshop n/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **FBG 9643A** Yr Regn: _____

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **PGD TR3 150** C.C. **148**Colour: **Red** A/C: _____ Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **120 / 70-12**R: **130 / 70-12**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **5** mm R/Bal. **5** mm

L/Bal. mm L/Bal. mm

D.O.A. **06042018** D.O.I. **02052018 @ 638pm**Survey held at **Blk 10 Kaki Bukit Rd 2 #01-16**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/7	Submit PRS report

RECEIVED 24 JUL 2018

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS SI

) Photos

) Other

Report Format: **PRE**

Lump Sum / I.B.I. / \$

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Insp (\$☐ Weekend (\$

TOTAL

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 2 May, 2018 9:49 AM
To: Weng Kit; 'sur@lkkauto.com'; Nivitha (LKK Auto)
Cc: Sherini Pillai
Subject: RE: Our Ref: FBG 9643A (wk) PRE-REPAIR INSPECTION NOTICE ACCIDENT INVOLVING FBG 9643A & SHC 8472H ALONG 110 SELETAR AEROSPACE VIEW ON 6 APRIL 2018
Attachments: 20180427145900705.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : FBG9643A
III INSURED VEHICLE NO. : SHC8472H
DATE OF LOSS : 06.04.18

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Sherini.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Weng Kit [mailto:wengkit@chiaarul.com]

Sent: 30 April, 2018 5:18 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: RE: Our Ref: FBG 9643A (wk) PRE-REPAIR INSPECTION NOTICE ACCIDENT INVOLVING FBG 9643A & SHC 8472H ALONG 110 SELETAR AEROSPACE VIEW ON 6 APRIL 2018

Dear Sirs,

We refer to your email below.

Our client is not agreeable to your motor surveyor.

We are instructed by our client to propose the list of their surveyor as the mutual surveyor / single joint expert for your consideration as follows:-

<u>S/N</u>	<u>Surveyor</u>	<u>Surveyor Firm</u>
1.	Mr. Sebastian Lim Yong Tian	Constant Appraiser Services
2.	Mr. B J Loi	Par Automotive Consultancy
3.	Mr. Patrick Ng	CarLink Consultancy
4.	Mr. How Andrew	Prominent Appraiser Services
5.	Mr. Ong Ah Heng Kent	KTO Automobile Assessors
6.	Mr. Phillip Foo	Precision Appraisal Services
7.	Mr. Lee Kok Weng	Lee Automobile Appraiser Services
8.	Mr. Danny Ho Joo Loong	HJL Auto Appraiser Services
9.	Mr. Thor Teck Soon David	JAS Appraisal Services
10.	Mr. Dave Chang Fuh Keong	Sincere Appraisal Services

Please let us have your favourable response soonest possible.

Best Regards,

Mr Weng Kit
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Monday, April 30, 2018 8:57 AM

To: Weng Kit

Subject: RE: Our Ref: FBG 9643A (wk) PRE-REPAIR INSPECTION NOTICE ACCIDENT INVOLVING FBG 9643A & SHC 8472H ALONG 110 SELETAR AEROSPACE VIEW ON 6 APRIL 2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

From: Weng Kit [<mailto:wengkit@chiaarul.com>]
Sent: 27 April, 2018 3:00 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Our Ref: FBG 9643A (wk) PRE-REPAIR INSPECTION NOTICE ACCIDENT INVOLVING FBG 9643A & SHC 8472H
ALONG 110 SELETAR AEROSPACE VIEW ON 6 APRIL 2018

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair inspection notice 27 April 2018 for your attention.

Best Regards,

Mr Weng Kit
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : FBG 9643A (wk)

Your Ref : -

27 April 2018

India International Insurance Pte Ltd
64 Cecil Street
#04/06-00 IOB Building
Singapore 049711

BY EMAIL

Dear Sir,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : MA CHEE TUAN
ACCIDENT INVOLVING FBG 9643A & SHC 8472H ALONG 110 SELETAR
AEROSPACE VIEW ON 6 APRIL 2018
PRE-REPAIR INSPECTION NOTICE

1. We act for Ma Chee Tuan, the owner of motor cycle no FBG 9643A, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SHC 8472H damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor cycle at **10 Kaki Bukit Road 2 #01-16 First East Centre Singapore 417868 (Mr. Jacky Siah - 8380 2233)**.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.

Yours faithfully,

MR ARULCHELVAN S

cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

Enquire Vehicle & Owner Information (Vehicle No. SHC8472H As At 06 Apr 2018 / 18:05:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: FBG9643A

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHC8472H
Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Insurance Company Name: INDIA INT'L INS PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	17 Jul 2018 Edit Reg		02 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	FBG9643A	Date of Loss:	06/04/2018 00:00 - :59 [339 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHC8472H	Policy No. (Claimant):	
		Excess:	
Repairer:	Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/07/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBG9643A
[SHC8472H]
TP
-

Apr 6 2018 12:00AM
[-]
Ong Motor Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 14:18	General View	Load PDF	
2	24/07/18 14:18	Photographs of Damaged Parts	Load PDF	
3	24/07/18 14:19	Photo After Spray	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 08:44	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18007978/GZ4BS2
 Date: 25/07/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	FBG9643A	Insured Vehicle No :	SHC8472H
Date of Loss:	06/04/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG9643A	Engine No:	HIDDEN
Make & Model:	PGO TR3, 148cc 150	Chassis No:	0
Reg. Date:	01/01/1990 (Man. Year: 1990)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	148 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-12	Rear Tyre Size:	130/70-12
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/05/2018	Inspected At:	10 KAKI BUKIT RD 2 #01-16
Date Inspected:	02/05/2018		
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Jul 2018)	
Parts:	N/A	PGO TR3 148cc 150 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG9643A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >