

22/03/2002

ASS. REC. BY:

REF: C83/ALH 18007997 / Szilber

Special Instruction:

SUPERVISOR:

Sebastian

ASSIGNMENT (Office)

From (Person):

Mwamin

Mohd Imran

of

Alh

Date/Time:

30042018 531pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FS 8494J

Insured:

SLM 3048H

at Workshop m/s

360 motor city

Tel:

9813 3997

of

780 Woodlands Ind E5 #04-22

Policy No:

Claim No:

724605804556-003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19042018

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

02052018 931am

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate	
	FS 8494J - RCL ALH 1700780 / RHC 39	D.O.A. 211116
	SLM 3048H - NA/MS/17015947 / K4	D.O.A. 050317

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FS 8494J Yr Regn: \_\_\_\_\_ /  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_ C.C. \_\_\_\_\_

Colour: Black A/C: Insured / Std / NI / NASp. Reading: 967988 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: kmv548 BLS 9C 0000/6Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: 17 / S/Rim / STD A/Rim orTyre Size: F: 120/70-13 MaxxisR: 140/60-13 Mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 2/5/18Survey held at 360 motor CityDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>4/5/18</u>	<u>No Estimate / GIA</u>

<u>7/5/18</u>	<u>Submit DAR Report.</u>
---------------	---------------------------

RECEIVED 23:3

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)

180

20

200

# FOR REPAIR CYCLE

## Motorcycle

Vehicle No: **FS 8494J**

NAC	INC	Item	CON	AC	Qty	NAC	INC	Item	CON	AC	Qty
1001	991336	Front Number Plate				1001	991074	Radiator			
1001	991065	Front Tyre				1001	991138	Radiator Cowling			
1002	991095	Front Rim				1006	991146	Seat Assy	TN	✓	
1003	991372	Front Tyre Rim Spoke				1007	990915	Engine Crank Pin			
1004	991171	Front Fender Wheel Guard	CUT	✓		1008	990928	Engine Guard	CUT	✓	
1005	991283	Front Brake Disc				1009	990219	Battery			
1006	991281	Front Brake Caliper				1010	990224	Battery Cover			
1007	991155	Front Fork Assy				1011	990223	Battery Bracket			
1008	991157	Front Fork Inner Tube				1012	991144	Foot Brake			
1009	991159	Front Fork Outer Tube				1013	991154	Front Foot Rest	CUT	✓	
1010	991167	Front Fork Bracket				1014	991779	Front Foot Rest Bracket			
1011	991132	Front Fork Oil Seal				1015	991269	Side Stand	SCR	✓	
1012	991174	Front Fork Garnish				1016	992549	Main Stand	CUT	✓	
1013	992346	Front Headlamp Rim				1017	990615	Clutch Engine Cover			
1014	992348	Front Headlamp	SCR	✓		1018	992478	Kick Starter Rubber			
1015	992337	Front Headlamp Bracket				1019	992477	Kick Starter Lever			
1016	992345	Front Headlamp Fitting				1020	991145	Foot Gear Shifter			
1017	992130	Front Windshield				1021	993500	Rear Foot Rest	SCR	✓	
1018	992131	Front Wing Mirror	SCR	✓		1022	993501	Rear Foot Rest Bracket	BR	✓	
1019	992135	Front LH Signal Lamp	BR	✓		1023	992581	Exhaust Muffler Heat Shield			
1020	992146	Front RH Signal Lamp	BR	✓		1024	991058	Exhaust Muffler Assy			
1021	992556	Meter Clamp				1025	993719	Rear LH Shock Absorber			
1022	992553	Meter Assy				1026	993720	Rear RH Shock Absorber			
1023	991019	ERP Bracket				1027	995065	Rear Tyre			
1024	991020	ERP Unit				1028	991200	Rear Rim			
1025	992446	Ignition Switch				1029	994872	Rear Tyre Rim Spoke			
1026	992442	Ignition Key Assy				1030	993474	Rear Fender Wheel Guard			
1027	990706	Cowling Stay				1031	993443	Rear Fender Mudflap			
1028	994370	Steering Stem				1032	992940	Rear Brake Disc			
1029	994427	Steering Cone				1033	992936	Rear Brake Caliper			
1030	992299	Handle Bar				1034	995236	Rear Spocket			
1031	992317	Handle Bar Switch				1035	990585	Chain			
1032	992310	Handle Bar Grip				1036	990580	Chain Guard			
1033	995183	Handle Bar Balancer LH				1037	991530	Swing Arm			
1034	992300	Handle Bar Balancer RH				1038	993819	Rear Sub frame			
1035	992179	Fuel Tank				1039	995245	Rear LH Signal Lamp			
1036	990438	Brake Reservoir	SCR	✓		1040	995246	Rear RH Signal Lamp			
1037	990621	Clutch Lever				1041	995251	Rear Taillamp			
1038	992293	Hand Brake Lever				1042	993626	Rear Number Plate			
1039	991119	Side Faring				1043	994192	Side Box			
1040	994220	Side Faring Top Garnish				1044	992927	Rear Box			
1041	994219	Side Faring Inner Garnish				1045	992928	Rear Box Bracket	Rebrm	✓	
1042	991118	Faring Shield				1046	991328	Emblem			
1043	992047	Front Top Faring Inner Garnish				1047	990247	Sticker			
1044	991123	Faring Top Garnish						Engine Cover	BR	✓	
1045	990548	Center Faring									
1046	991178	Rear Faring									
1047	991121	Faring Goggles									
1048	991117	Faring Lower									

\* 3 days

Part of Item:

Assessor:


**-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM3048H AND FS8494J ON 19/04/2018**

From: Md Ishak, Mohd Imran

To: assignments@lkkauto.com, admin-a@lkkauto.com

Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Lim, Sheng Yang, Chan, Yoke Shi, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Fan, Winnie-LW, Supramaniam, Darshene

Sent: Monday, 30 April, 2018 5:31:14 PM

Attachments:  20180430082517591.pdf

---

**WITHOUT PREJUDICE**

Hi,

Please refer to the enclosed request from M/s Chia S Arul LLC

Claim no : 7246058045SG-003

Case Owner : ANGIE

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto

Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

[imran.ishak@aig.com](mailto:imran.ishak@aig.com) | [www.aig.com](http://www.aig.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

---

From: kelly@chiaarul.com

To: Imran.Ishak@aig.com

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM3048H AND FS8494J ON 19/04/2018

Date: Mon, 30 Apr 2018 09:11:57 +0000

yes

Regards,

**Ms Kelley Choong**

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 5183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com) <<http://chiaarul.com/>>. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

On 30 Apr 2018, at 16:18, Md Ishak, Mohd Imran <[imran.ishak@aig.com](mailto:imran.ishak@aig.com)> wrote:

Dear Kelley

Please confirm whether you agree to appoint Kenneth Kong from LKK as asingle joint expert

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto

Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)  
Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

[imran.ishak@aig.com](mailto:imran.ishak@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Md Ishak, Mohd Imran  
**Sent:** Monday, April 30, 2018 2:23 PM  
**To:** Kelley Choong  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Supramaniam, Darshene  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM3048H AND FS8494J ON 19/04/2018

Dear Kelley

Please confirm whether you agree to the appointment of any of these motor surveyors below as a single joint expert

Thank you

Sincerely,

Imran

**Mohd Imran Md Ishak**  
AIG  
Express Claims Adjuster II, FNOL SG Claims Operations - Auto  
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)  
Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

[imran.ishak@aig.com](mailto:imran.ishak@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Kelley Choong [<mailto:kelley@chiaarul.com>]  
**Sent:** Monday, April 30, 2018 12:39 PM  
**To:** Md Ishak, Mohd Imran  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Supramaniam, Darshene  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM3048H AND FS8494J ON 19/04/2018

Dear Imran,

Our client is agreeable to your surveyor Kenneth Kong from LKK.

Regards,  
**Ms Kelley Choong**  
M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Md Ishak, Mohd Imran [<mailto:imran.ishak@aig.com>]  
**Sent:** Monday, April 30, 2018 9:12 AM  
**To:** 'Kelley Choong' <[kelley@chiaarul.com](mailto:kelley@chiaarul.com)>  
**Cc:** Tan, Lily (AIG) <[Lily.Tan@aig.com](mailto:Lily.Tan@aig.com)>; Fong, Andy-SY <[Andy-SY.Fong@aig.com](mailto:Andy-SY.Fong@aig.com)>; Kaur, Baljit <[Baljit.Kaur@aig.com](mailto:Baljit.Kaur@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>; Chan, Yoke Shi <[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)>; Chin, Lee-Ying <[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com)>; Abu Kassim, Noor Mariesa <[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com)>; Fan, Winnie-LW <[Winnie-LW.Fan@aig.com](mailto:Winnie-LW.Fan@aig.com)>; Supramaniam, Darshene <[Darshene.Supramaniam@aig.com](mailto:Darshene.Supramaniam@aig.com)>  
**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM3048H AND FS8494J ON 19/04/2018

**WITHOUT PREJUDICE**

Your Reference : FS8494J(kc)  
Our Reference : 7246058045SG-003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto  
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)  
Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

[imran.ishak@aig.com](mailto:imran.ishak@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Kelley Choong [<mailto:kelley@chiaarul.com>]

**Sent:** Monday, April 30, 2018 8:28 AM

**To:** Lim, Sheng Yang; 'Mohd Fitri'

**Subject:** PRE-INSPECTION OF FS 8494J (kc)

Dear Sirs,

Enclosed for your attention.

Regards,

**Ms Kelley Choong**

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**CHIA S ARUL LLC**  
**ADVOCATES & SOLICITORS**  
UEN 201330709H

ARULCHELVAN S

---

Our Ref : FS8494J (kc)

Your Ref :

30 April 2018

AIG  
Singapore

BY EMAIL

Dear Sir,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : YEOW KIN WENG, EDWIN**  
**ACCIDENT INVOLVING FS 8494J & SLM 3048H ALONG TANJONG KATONG**  
**ROAD ON 19/4/18**  
**PRE-REPAIR INSPECTION NOTICE**

1. We act for Yeow Kin Weng, Edwin, the owner of motor vehicle FS 8494J, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SLM 3048H damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor cycle at 360 Motor City of 280 Woodlands Industrial E5 Harvest #04-22 Singapore 757322 (T: 98133997).
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.

Yours faithfully,



**MR ARULCHELVAN S**

cc: Client



5/4/2018

E-FILE

MSI118055050 / STA INSPECTION PTE LTD - Sin Ming  
ENTRY DATE & TIME: 26/04/2018 15:49  
SUBMITTED BY: Wong Lip Yong

**Your NCD will be affected due to late reporting**  
**Actual e-Filing Submission Date & Time: 26/04/2018 16:00**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 26/04/2018 15:49  
Date Of Accident 19/04/2018 20:00  
Exact Location Of Accident ALONG TANJONG KATONG ROAD TOWARDS DUNMAN ROAD  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number FS8494J  
**Insured/Policyholder**  
Name Of Registered Owner YEOW KIN WENG, EDWIN (YOU JIANRONG, EDWIN)  
NRIC No S8325411D  
Email Address EYKW1983@GMAIL.COM  
Mobile Phone No (LOCAL) +65-98432596  
Alternative Phone No Others-98432596

### Vehicle Particulars

Manufacturer DAELIM  
Model B-BONE  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category MOTORCYCLE

### Insurance Company

Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD  
Type Of Coverage THIRD PARTY  
Fleet Policy NO  
Policy Number MC/00365392/01  
Cover Note Number

### Driver

Name of Driver YEOW KIN WENG, EDWIN (YOU JIANRONG, EDWIN)  
NRIC No S8325411D  
Date Of Birth 12/08/1983  
Occupation OUTDOOR  
Date Of Driving Pass 15/09/2004

5/4/2018

E-FILE

Driving Experience	13 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98432596
Fax Number	
Contact Number	OTHERS-98432596
E-Mail Address	EYKW1983@GMAIL.COM
Address	BLK 131 GEYLANG EAST AVE 1 #01-279 SINGAPORE
Postcode	380131
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

**General Information of the Accident**

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4529999 - FAX NO: 6 5535740
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

5/4/2018

E-FILE

Vehicle Registration Number

SLM3048H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

YEOW KIN WENG, EDWIN (YOU JIANRONG, EDWIN)

Approximate Age

Injuries Sustain

REFER POLICE REPORT

Injured person in which vehicle?

FS8494J

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

5/4/2018

E-FILE

**Sketch Plan**


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

### Sketch Plan #2

### SKETCH PLAN

Refer Attache d

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Red & Blue Report.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

5/4/2018

E-FILE

**Sketch Plan #3**





## Accident Sketch Plan



**SINGAPORE  
POLICE FORCE**



T/20180426/2089

1 of 3

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

Report No. T/20180426/2089

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/04/2018 14:52		Vide Report No.:		Station Diary No.: 42	
<b>Informant's Particulars</b>					
Name of Informant: YEOW KIN WENG, EDWIN			Address: APT BLK 131 GEYLANG EAST AVENUE 1 #01-279 SINGAPORE 380131		
ID Type / ID No.: NRIC NO / S8325411D			Contact No.: Home/Office: Mobile: 98432596		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 34	Date of Birth: 12/08/1983	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 2B,3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/04/2018 00:00	Type of Location: Straight Road
Location: Along Road 1 TANJONG KATONG ROAD  Along Tanjong Katong road towards Dunman road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FS8494J	Motorcycle	DAELIM	B-BONE AUTO	Black	Seriously Damaged	0
SLM3048H	Car	HONDA	VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD	Silver	Slightly Damaged	0

5/4/2018

E-FILE

**Accident Sketch Plan**



**SINGAPORE  
POLICE FORCE**



T/20180426/2089

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

2 of 3

Report No. T/20180426/2089

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FS8494J	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00365392/01	10/02/2017	07/12/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	YEOW KIN WENG, EDWIN	ID No.	S8325411D
Related Vehicle	FS8494J (Motorcycle)	Contact No.	98432596
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	19/04/2018	Date Discharge	19/04/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

**Brief Details.**

On 19/04/2018 at about 2000hrs, I was riding my motorcycle FS8494J on the right lane of Tanjong Katong towards Dunman road at a speed of about 50kmh. At that time vehicle SLM3048H was travelling in the same direction directly to my left. While we were passing the CDAC building, vehicle SLM3048H suddenly swung right into my path without signaling causing me and my motorcycle to fall to the right, crossing the center divider onto the opposite side of the road. Luckily there was no oncoming vehicle at that moment otherwise the result will be unthinkable. I sustained bodily injury and required medical assistance. The driver of vehicle SLM3048H called for an ambulance which arrived approx 20 minutes which took me to Tan Tock Seng Hospital. A police patrol car happened to pass by and gave assistance. I overheard the driver of vehicle SLM3048H telling the police officer that he attempted to make a U-turn from the left lane thus collided into me.

I wish to state while I was in Tan Tock Seng Hospital was given 5 days mc from 19/04/2018 till 23/04/2018. However after my MC ended on 23/04/2018 I still suffer pain on my left ankle and left underarm as such I went to see doctor at Geylang polyclinic and was given 3days mc from 24/04/2018 till 26/04/2018.

## Accident Sketch Plan

SINGAPORE  
POLICE FORCE

T/20180426/2089

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

3 of 3




Report No. T/20180426/2089

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 JEFFREY LOIS 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 26/04/2018 14:52
Officer In Charge Of Case: TP / AEIT / Staff Sgt TANG SIEW PING Contact No: 65478430 POLICE FORCE SN 070	Classification Of Case:
Authentication Stamp NP168  FIRE	

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Apr 2018 <a href="#">Edit Reg</a>		30 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

























Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>LCRF PTE LTD</b> , Co. Reg. No.: 201604597K									
Main Claimant: -									
Vehicle Reg. No.: <b>FS8494J</b>		Date of Loss: 19/04/2018 00:00 - :59 [100 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 7246058045SG</b>		Policy/Cover Note No.: 999995174 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SLM3048H</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>360 Motorcity Pte Ltd (HQ)</b> 280 Woodlands Industrial ES, #04-22 Woodlands @harvest, 757322 Woodlands - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Gan, Angle-GL</b> ] Angiegeokling.Gan@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sebastian Yeang Wai Keen</b> ] ... [Final Rpt due 15/05/2018]									
Claimant's Solicitor: <b>CHIA S ARUL &amp; LLC</b> - Tel: 67334647									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (07/05/2018): &lt; No subject &gt;</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*FS8494J (7246058045SG)**  
**[SLM3048H]**  
**TP**

**-**  
**Apr 19 2018 12:00AM**  
**[LCRF PTE LTD]**  
**360 Motorcity Pte Ltd**

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<a href="#">View</a>			<a href="#">View in Browser</a>		
<b>Photos/Images</b>															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
2	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
3	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
4	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
5	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
6	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
7	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
8	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
9	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
10	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
11	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
12	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
13	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
14	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
15	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
16	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
17	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
18	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
19	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
20	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
21	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
22	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
23	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
24	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
25	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
26	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
27	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
28	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
29	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
30	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
31	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
32	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
33	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
34	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
35	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
36	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			
37	04/05/18 14:30	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
56	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
57	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
58	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
59	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
60	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
61	04/05/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG18007997/SZ4BE2**Date:** 09/05/2018REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 999995174  
**Claimant Vehicle No :** FS8494J **Insured Vehicle No :** SLM3048H  
**Date of Loss:** 19/04/2018 **Nature of Claim:** TP **Claim No:** 7246058045SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** FS8494J  
**Make & Model:** DAELIM B-BONE, 125cc (A) **Engine No:** SN125E1002679  
**Reg. Date:** 08/12/2009 (Man. Year: 2008) **Chassis No:** KMYSA8BLS9C000016  
**Colour:** Black **Odometer:** 967988 km  
**Engine Capacity:** 125 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

**Front Tyre Size:** 120/70-13 **Rear Tyre Size:** 140/60-13  
**Front Left Side:** Maxxis 6 mm **Rear Left Side:** Michelin 6 mm  
**Front Right Side:** 0 mm **Rear Right Side:** 0 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

**Date of Assignment:** 30/04/2018  
**Date Inspected:** 02/05/2018 **Inspected At:** 360 Motorcity Pte Ltd (HQ)  
280 Woodlands Industrial E5, #04-22  
Woodlands @harvest  
Singapore 757322  
**Estimated Period of Repair:** 3.0 days

**Adjuster:** Sebastian Yeang Wai Keen**Manager:** Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
3	1		*FRONT WING MIRROR	Scratched	0.00 F	*- F
4	1		*FRONT LH SIGNAL LAMP	Broken	0.00 F	*- F
5	1		*FRONT RH SIGNAL LAMP	Broken	0.00 F	*- F
6	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
7	1		*SEAL ASSY	Torn	0.00 F	*- F
8	1		*ENGINE GUARD	Cut	0.00 F	*- F
9	1		*FRONT FOOT REST	Cut	0.00 F	*- F
10	1		*SIDE STAND	Scratched	0.00 F	*- F
11	1		*MAIN STAND	Cut	0.00 F	*- F
12	1		*REAR FOOT REST	Scratched	0.00 F	*- F
13	1		*REAR FOOT REST BRACKET	Broken	0.00 F	*- F
14	1		*REAR BOX BRACKET	Deformed	0.00 F	*- F
15	1		*ENGINE COVER	Broken	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >