

winne

CC4 / AXA1800 8000, R2 6/3/18

LKK
IDAC

Surveyor:

Rasul

DOI:

ASSIGNMENT

1/5/18

Date / Time:

1/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKR 2377A

Name of Insured:

BENJAMIN LAY HONG FOH

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

26/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE YEN - NEE ADRIANA

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8MD00ELA / 42623

Policy No.:

VPA / P103339

Make / Model:

TOYOTA

Place of Accident:

EXIT OUT FROM P15 TUNNEL
TOWS IN TUNNEL

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKR 4086m



INSRS:

WSP:

Tel:

Liability:

RMKS:

WIKSWAHN



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

3/5/18

Agree ✓

gmaruda.m

3.3.18 @ 3.13pm UNABLE TO LOCATE NO RESPONSE, LEAVE SENT TO OI.

@ 357 OI BENJAMIN CALLED
CALL HIM @ 9649-4267

Email WSP. Heavy Case

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

R/S SP. 420.85

(12 days)

Reduction:

75 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 3/5/18

Confirm with SNA 9/8

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

W/L 167

SS 13,355.91

O/D REPR ENDED TP

Loss of Rental (LOR):

W/L 167

SS 1,926.00

(18 days) x +100

Loss of Use (LOU):

SS -

(\$ x days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 15,281.91

Global Sum SS:

FINAL PAYMENT

Date/Time: 3/5/18

Confirm with: SNA 9/8

Email ☒ Call ☐

Payee 1:

SS 15,281.91

Name 1:

WIKSWAHN (OFFICE SINGAPORE)

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +350

COPY SENT
6/5/180126
2/5/18

Surveyor Rafael

REF:

2

39940

06/04/2023

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKK 4086M
 at Workshop mis: Volkswagen Tux
 of 17 Tux mtr
 Insured: AXA Jap
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 58 K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKK 4086M Yr Regn: 2013 July
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Volkswagen Jetta 1.4 cc 1390
 Colour: Grey A/C Insured / Std / NI / NA
 Sp. Reading: 93577 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 Cr/No: WVWZZZ1KZDM083061

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/45 R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 28/04/18 D.O.I: 02/05/18

Survey held at: Volkswagen Tux
 Des. of Damages: Frt / Front / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

03/05/18 refer to email

P/P: 12,480.55 (RSD: 10,199.91 45%)

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. SI

Phone

Others

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18008000/R1eb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 02-05-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 2377A	Veh. Inspected	SKK 4086M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/04/2018	Inspection Date		
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



DISCHARGE VOUCHER

I/We Yi He FA Enterprises Pte Ltd (Passport No. 1982037940) the
owner of vehicle number SKK4086M hereby accept from
AXA (Insurance Company) the sum of
_____ (total repair cost) in full and final settlement for the cost of repairs
arising from the loss damage of property as a result of the accident involving
SKK4086M & SKR2377A along Slip Road of Toh Tuck Ave.
on 28/4/18.

Please pay to Volkswagen Group Singapore Pte Ltd who is authorized to receive
only on the total cost of repair on my/our behalf.

The lost of use (transport/allowance / rental receipts) to be payable to

VOLKSWAGEN GROUP SINGAPORE PTE LTD.

Dated this on 6/6/18 (DD/MM/YYYY)

YI HE FA ENTERPRISES PTE LTD
60, Kaki Bukit Place
#01-01, Eunos Techpark
Singapore 415979
Tel: 6741 6155 Fax: 6742 9155
(Signature of owner / Company stamp)

Name :

NRIC No. :

Date :

Service Order Confirmation

SERVICE ORDER NO.: 18IP1144

CUSTOMER NO.: CV022591

CUSTOMER NAME: YI HE FA ENTERPRISES PTE. LTD.

TELEPHONE NO.:

 ADDRESS: 60 KAKI BUKIT PLACE #01-01 EUNOS TECHPARK
 Singapore

VEH No.: SKK4086M

Order Date: 04/30/18

Reg Date: 07/09/13

KM: 84,464

VIN NO.: VVVWZZZ16ZDM063061

ENGINE NO.:

SA: Tang Shu Shi

MODEL: JETTA A6 1.4 TSI DSG 90KW TL MODEL NO.: 1622G5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P TOWING	156	TU	1.25		195
2	B&P MECH	1	TU	280		280
3	B&P DIAG	1	TU	480		480
4	EXTD0037	1	UNIT	0		0
5	B&P MACP LABOUR	8	UNIT	840		6720
6	B&P MACP PAINT	5	UNIT	800		4000
7	B&P MACP LABOUR	1	UNIT	840		840
8	B&P MACP LABOUR	1	UNIT	840		840
9	B&P NUMBER PLATE	1	ST	80		80
10	B&P SENSOR	1	PCS	400		400
Item						
11	5C6827025A	1	PCS	1,796.25		1,796.25
12	5C6827705A 5AP	1	PCS	252.81		252.81
13	5C6827301E	1	PCS	94.92		94.92
14	5C6827302D	1	PCS	94.92		94.92
15	5C6827505G	1	PCS	193.80		193.80
16	5C6827520	1	PCS	16.30		16.30
17	5C6827507B	1	PCS	51.46		51.46
18	N 90766702	2	PCS	1.66		3.32
19	8D0653419D	1	PCS	9.74		9.74
20	5C6853630E ULM	1	PCS	93.67		93.67
21	1K9853667A 739	1	PCS	55.80		55.80
22	1K9853675B GQF	1	PCS	52.53		52.53
23	5C6867605A 986	1	PCS	279.93		279.93
24	5C6807421 GRU	1	PCS	1,061.34		1,061.34
25	5C6807433	1	PCS	511.00		511.00
26	5C6807305	1	PCS	514.20		514.20
27	5C6807863	1	PCS	77.46		77.46
28	5C6807390A	1	PCS	83.43		83.43

195 ✓
 280 ✓ 193.20
 480 ✓ 331.20
 0
 6720 5040 4620
 4000 3000 2760
 840 420 579.60
 840 420 579.60
 80 84 36
 400 276
 1,796.25 808.31
 252.81 115.78
 94.92 X
 94.92 X
 193.80 8
 16.30 16.30 +
 51.46 *
 3.32 3.32 +
 9.74 9.74
 93.67 93.67
 55.80 55.80
 52.53 52.53
 279.93 279.93
 1,061.34 1,061.34
 511.00 511.00
 514.20 514.20
 77.46 77.46
 83.43 83.43

Service Order Confirmation

SERVICE ORDER NO: 18IP1144
CUSTOMER NO.: CV022581
CUSTOMER NAME: VI HE FA ENTERPRISES PTE. LTD.
TELEPHONE NO.:
ADDRESS: 60 KAKI BUKIT PLACE #01-01 EUNOS TECHPARK
Singapore

VEH No.: SKK4086M

Order Date: 04/30/16
Reg Date: 07/09/13 KM: 84,484
VIN NO.: VVVWZZZ16ZDM083081 ENGINE NO:
MODEL: JETTA AE 1.4 TSI DSG 90KW TL MODEL NO.: 1622GS

SA: Tang Shu Shi

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	5C6807394A TAILLIGHT LOWER BRACKET RH	1	PCS	60.84		60.84 <i>30% 27.38</i>
30	5C6807393B BUMPER SIDE BRACKET LH	1	PCS	115.65		115.65 <i>30% 81.00</i>
31	5C6807394B BUMPER SIDE BRACKET RH	1	PCS	104.08		104.08 <i>30% 72.86</i>
32	5C6845095E TAILLIGHT OUTER LH	1	PCS	498.60		498.60 <i>30% 349.02</i>
33	5C6845095E TAILLIGHT OUTER RH	1	PCS	498.60		498.60 <i>30% 349.02</i>
34	5C6845093 TAILLIGHT INNER LH	1	PCS	310.51		310.51 <i>30% 217.36</i>
35	5C6845094A TAILLIGHT INNER RH	1	PCS	310.51		310.51 <i>30% 217.36</i>
36	N 10621301 NUT	8	PCS	1.43		11.44 <i>30% 7.91</i>
37	5C6813301 END PANEL	1	PCS	1,282.33		1,282.33 <i>30% 897.63</i>
38	D 007600A1 INOXSPRAY	1	PCS	52.29		52.29 <i>30% 36.60</i>
39	D 180003M2 2KADHESIV	1	PCS	220.16		220.16 <i>30% 154.11</i>
40	D 476KD1M2 SEALANT	1	PCS	59.53		59.53 <i>30% 41.67</i>
41	5C6863455A 988 END PANEL TRIM COVER	1	PCS	77.89		77.89 <i>30% 54.52</i>

Remarks: AXA DIRECT SETTLEMENT

DOA: 26/04/2016

TP VEHICLE: SKR2377A

SURVEY BY:

(A) 1827 2 pcs + 250 55% + 237.16



Service Order Confirmation

SERVICE ORDER NO: 18IP1144
CUSTOMER NO.: CV022591
CUSTOMER NAME: VI HE FA ENTERPRISES PTE. LTD.
TELEPHONE NO.:
ADDRESS: 60 KAKI BUKIT PLACE #01-01 EUNOS TECHPARK
Singapore

VEH No.: SKK4086M

Order Date: 04/30/18
Reg Date: 07/09/13 KM: 84,484
VIN NO.: WWWZZZ16ZDM083061 ENGINE NO:
MODEL: JETTA A6 1.4 TSI DSG 100KW TL MODEL NO.: 162205

SA: Tang Shu Shi

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
#12 days
02/05/18 @ 1450
Resurvey by paint

TOTAL	22,680.31
GST AMOUNT	1,567.62
TOTAL AMOUNT	24,247.93



Authorized Signature

Certified Goods/Service received:

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	3994D
Vehicle Details	
Vehicle No.:	SKK4086M
Vehicle to be Exported:	No
Intended De-registration Date:	03 May 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1622G5
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	CAXD38959
Chassis No.:	WVWZZZ16ZDM083061
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,289.00
Original Registration Date:	09 Jul 2013
First Registration Date:	09 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$9,289.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jul 2023
PARF Rebate Amount:	\$6,966.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$73,100.00
COE Rebate Amount:	\$37,866.00
Total Rebate Amount:	\$44,832.00

The information contained herein is correct as at 03 May 2018

OK

58,000
44,832
13,168

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 3 May, 2018 9:36 AM
To: 'Ong, Germaine (VWG Singapore)'
Cc: Oh, Aik Seong (VWG Singapore)
Subject: SKK 4086M DOA : 28/04/18

Hi Germaine,

Kindly take note, the NETT amount to repair this vehicle is 4K only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Service Order Confirmation

SERVICE ORDER NO.: 18IP1144
 CUSTOMER NO.: CV022581
 CUSTOMER NAME: YI HE FA ENTERPRISES PTE. LTD.
 TELEPHONE NO.:
 ADDRESS: 60 KAKI BUKIT PLACE #01-01 EUNOS TECHPARK
 Singapore

VEH No.: SKK4086M

Order Date: 30/04/18
 Reg Date: 09/07/13 KM: 84,484
 VIN NO.: WYVZZZ16ZDM063061 ENGINE NO:
 MODEL: JETTA A6 1.4 TSI DSG 90KW TL MODEL NO.: 1622G5
 SA: Tang Shu Shi

No.	DESCRIPTION		QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor							
1	B&P TOWING	B&P TOWING CHARGES	158	TU	1.25		195
2	B&P MECH	CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280	31	193.2
3	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	1	TU	480	31	331.2
4	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0		0
5	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0		0
6	B&P MACP LABOUR	LABOUR	8	UNIT	840	31	4,836.8
7	B&P MACP PAINT	SPRAY PAINT	3	UNIT	800	31	2,760
8	B&P MACP LABOUR	R&R REAR LUGGAGE	1	UNIT	840	31	579.6
9	B&P MACP LABOUR	R&R TRANSFER BOOTLID MECHANISM	1	UNIT	840	31	579.6
10	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	ST	80	55	36
11	B&P SENSOR	SUPPLY & INSTALL REVERSE SENSOR	1	PCS	400	31	276
Item							
12	5C68Z7025A	RR BOOT LID	1	PCS	1,796.25	55	808.31
13	5C68Z7705A 5AP	WEATHER STRIP	1	PCS	252.81	55	113.76
14	WHT007341	NUT	2	PCS	2.52	55	2.27
15	8D0853419D	RR NUMBER PLATE PACKING	1	PCS	9.74	55	4.38
16	5C6853630E ULM	VW SIGN	1	PCS	93.67	55	42.15
17	1K9853687A 739	JETTA NAME PLATE	1	PCS	55.80	55	25.11
18	1K9853675B GGF	TSI NAME PLATE	1	PCS	52.53	55	23.84
19	5C6807421 GRU	RR BUMPER	1	PCS	1,061.34	55	477.60
20	5C6807433	SPOILER	1	PCS	511.00	55	229.95
21	5C6807863	RR CTR BRACKET	1	PCS	77.46	55	34.86
22	5C6807393A	TAILLIGHT LOWER BRACKET LH	1	PCS	83.43	55	37.54
23	5C6807394A	TAILLIGHT LOWER BRACKET RH	1	PCS	60.84	55	27.38
24	5C6945095E	TAILLIGHT OUTER LH	1	PCS	498.60	55	224.37
25	5C6945096E	TAILLIGHT OUTER RH	1	PCS	498.60	55	224.37
26	N 10621301	NUT	8	PCS	1.43	55	5.15
27	5C6813301	END PANEL	1	PCS	1,292.33	55	577.05
28	5C6863458A 9B9	END PANEL TRIM COVER	1	PCS	77.89	55	36.05

Service Order Confirmation

SERVICE ORDER NO.: 18IP1144
CUSTOMER NO.: CV022581
CUSTOMER NAME: YI HE FA ENTERPRISES PTE. LTD.
TELEPHONE NO.:
ADDRESS: 68 KAKI BUKIT PLACE #01-01 EUNOS TECHPARK
Singapore

VEH No.: SKK4086M

Order Date: 30/04/18
Reg Date: 09/07/13 KM: 84,484
VIN NO.: WVGWZZ16ZDM083061 ENGINE NO: SA: Tang Shu Shi
MODEL: JETTA A8 1.4 TSI DSG 90KW TL MODEL NO.: 162205

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Remarks : AXA DIRECT SETTLEMENT						
DOA: 28/04/2019						
TP VEHICLE: SKK12377A						
SURVEY BY: RASUL						

TOTAL	12,480.35
GST AMOUNT	873.62
TOTAL AMOUNT	13,353.97

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



LETTER OF DEMAND

Your Ref: SKR2377A

Our Ref: SKK4086M

To: AXA

Dear Sirs,

ACCIDENT INVOLVING SKK4086M & SKR2377A ON 28.4.2018

We are claiming on behalf of our client Yi He Fa Enterprises P.L owner of

vehicle number SKK4086M involved in accident on 28.4.2018

with vehicle SKR2377A along/at Slip Rd of Toh Tuck Ave.

Description of claims:

Cost of Repairs \$ 12,480.35 + 7% GST = \$ 13,353.97

Loss of Use/Rental \$ 120 + 7% GST X 18 Days = \$ 2160

Medical Fee \$ _____ + 7% GST = \$ _____

Search Fee \$ 2 + 7% GST = \$ 2

TOTAL \$ _____

We are claiming in full and final settlement of \$ 15,515.97

Cost of repair & search fee \$ 13,355.97 to be payable to Volkswagen Group Singapore Pte Ltd.

Loss of use/Rental amount/Medical fee of \$ 2160 to be payable to

Yi He Fa Enterprises Pte Ltd.

Kindly send us a written acknowledgement within 14 days from receipt of this document. Please note that finalization/settlement offer of this claim should be within 8 weeks from the date of this document. Please email all settlement offers to shushi.tang@vw.com.sg

Dated this _____

VOLKSWAGEN GROUP SINGAPORE
81030002

06 JUN 2018

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 21 May 2018 10:35 AM
To: 'BENADRI@GMAIL.COM'
Subject: ACCIDENT INVOLVING SKR 2377A AND SKK 4086M ALONG EXIT OUT FROM PIE TUAS TWDS TOH TUCK AVE ON 28/04/2018

21 MAY 2018

BENJAMIN LAU HONG KOH

Dear Sir/ Mdm

OUR REF : CC4/ASM18008000/R1eb3

YOUR REF : SKR 2377A

ACCIDENT INVOLVING SKR 2377A AND SKK 4086M ALONG EXIT OUT FROM PIE TUAS TWDS TOH TUCK AVE ON 28/04/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s VOLKSWAGEN CENTRE SINGAPORE acting on behalf of the owner of SKK 4086M against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SKK 4086M. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Volkswagen Centre Singapore



Biz Reg. No. 53103069E
GST No. M20098505-2

LETTER OF AUTHORITY

ACCIDENT INVOLVING SKK 4086 m and SICR2377A on 28/4/18
along Slip Road of Toh Tuck Ave.
Own vehicle's number Other vehicle's number Date of accident
Accident location

BY THE LETTER OF AUTHORITY, I/we, Yi He Fa Enterprises Pte. Ltd.
of 1982059940
Name of Policy Holder & IC / Passport number
owner of Vehicle Registration

Number SKK 4086 m hereby irrevocable appoint **Volkswagen Centre Singapore**
Own vehicle's number

(hereinafter refer to VGS), a company incorporated in Singapore and having its registered office at **247 Alexandra Road, Singapore 159934**, its agents or any person authorized by VGS to be *my / our Attorney and in *my / our name(s) on *my / our behalf to do all or any of the following:

1. To submit, resolve and make any claim(s) (including the commencement of legal proceedings) which *I/we may have against the other *party/parties to the Accident and under the insurance *policy/policies taken up by such *party/parties or **alternatively** under Insurance Policy number _____ taken up by *me/us and pay the **compulsory excess** in respect of the cost repairs suffered by *me/us arising from the Accident (loss and damage)/.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favour of **Volkswagen Centre Singapore** and give a valid receipt and discharge therefore.
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever in relation thereto.
4. Generally do all such acts as it shall deem necessary for the purpose of settling such claim.

*I/We hereby declare that all acts, instruments and documents done by virtue of this letter of authority on *my/our behalf by the Attorney, its agents or any person authorized by VGS in that behalf shall be as good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by *me/us in *my/our own proper person(s) and *I/we hereby ratify and confirm, all acts, instruments and documents done or executed by virtue of the authority and powers hereby conferred.

*I/We hereby further declare that the **letter of authority hereby conferred shall remain irrevocable.**

*I/We further confirm that the acceptance by VGS of the settlement amount in respect of such constitute the full discharge of *my/our claim(s) in respect of such loss and damage.

IN WITNESS WHEREOF, *I/we have hereunto to set *my/our hand and sign this 6 of the month
6 Year 18

Signed & Delivered By: **YI HE FA ENTERPRISES PTE LTD**

60, Kaki Bukit Place
#01-01, Eunos Techpark
Singapore 415979

Tel: 6741 6155 Fax: 6742 9155

Witness By: [Signature]
Policy Holder





redefining / insurance

CLAIM REF : S8M00FLA
INSURED : BENJAMIN LAU HONG KOH

DISCHARGE VOUCHER

We/I [YI HE FA ENTERPRISES PTE LTD, NRIC NO. 198203994D] hereby agree to accept the sum of dollars [FIFTEEN THOUSAND TWO HUNDRED EIGHTY ONE AND CENTS NINETY SEVEN ONLY.] [\$\$15,281.97] paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SKR 2377A] as a result of an accident along [SLIP ROAD OF TOH TUCK AVE] on [28/04/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SKK 4086M].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SKR 2377A] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SKR 2377A].

Dated this 31 day of JULY 2018

Claimant's Signature

TAN CHEE SENG 温和益金堂私人有限公司
NRIC no./ Company Stamp : S1293880C YI HE FA ENTERPRISES PTE. LTD.

Occupation/ Business

Director

Address

60 Kaki Bt. Place #01-01 Sunar Techpark
5415979

Telephone No.

67416155

Witness's Name

TAN SIOK HOON

Witness's Signature

[Signature]

Witness's NRIC No.

S1436015H

Volkswagen Centre Singapore



Service Tax Invoice No. SV18P23306

Reg. No. 5310306PE
GST No. M20098505-2

SERVICE ORDER NO: 18IP1144

SERVICE CUSTOMER NO.: CV000066

SERVICE CUSTOMER NAME: AXA INSURANCE SINGAPORE P.L.

TELEPHONE NO.:

ADDRESS: 6 SHENTON WAY
#27-01 AXA TOWER
Singapore

Post Code: 068811

VEH NO.: SKK4086M

DATE: 25/05/18

Pickup:

VIN NO.: WVVZZZ16ZDM063061

KM: 93,577

GEARBOX CODE:

Engine No.:

MODEL: JETTA A6 1.4 TSI DSG 90KW TL

SA: Tang Shu Shi

Next Appointment Date :

Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
AXA DIRECT SETTLEMENT					
DOA: 28/04/2018					
TP VEHICLE: SKR2377A					
SURVEY BY: RASUL					
REPAIR LIMIT @\$12,500					
Labor					
1	LABOUR	8.00	UNIT	840.00	4,836.80
2	R&R REAR LUGGAGE	1.00	UNIT	840.00	579.60
3	R&R TRANSFER BOOTLID MECHANISM	1.00	UNIT	840.00	579.60
4	SPRAY PAINT	3.00	UNIT	800.00	2,760.00
5	B&P NUMBER PLATE-NETT	1.00	ST	60.00	36.00
6	SUPPLY & INSTALL REVERSE SENSOR	1.00	PCS	400.00	276.00
7	Tow SVC- Quality Recovery Services	1.00	UNIT		
8	Tow SVC- Quality Recovery Services	1.00	UNIT		
9	PROGRAMMING & CALIBRATION- NETT	1.00	TU	480.00	331.20
10	CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1.00	TU	280.00	193.20
11	B&P TOWING CHARGES	156.00	TU	1.25	195.00
Rem					
12	TSI NAME PLATE	1.00	PCS	52.83	23.84
13	JETTA NAME PLATE	1.00	PCS	55.80	25.11

Volkswagen Centre Singapore



Service Tax Invoice No. SV18P23306

Biz Reg. No. 521030696
GST No. M20098505-2

SERVICE ORDER NO: 18IP1144

SERVICE CUSTOMER NO: CVD00066

SERVICE CUSTOMER NAME: AXA INSURANCE SINGAPORE PL

TELEPHONE NO:

ADDRESS: 8 SHENTON WAY
#27-01 AXA TOWER
Singapore

Post Code: 068811

VEH NO.: SKK4086M

DATE: 25/05/18

Pickup:

VIN NO: WVVWZZZ16ZDM083061

KM: 93,577

GEARBOX CODE:

Engine No.:

MODEL: JETTA A5 1.4 TSI DSG 90KW TL

SA: Tang Shu Shi

Next Appointment Date :

Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
14	TAILLIGHT LOWER BRACKET LH	1.00	PCS	83.43	37.54
15	TAILLIGHT LOWER BRACKET RH	1.00	PCS	80.84	27.38
16	RR BUMPER	1.00	PCS	1,061.34	477.80
17	SPOILER	1.00	PCS	511.00	229.55
18	RR CTR BRACKET	1.00	PCS	77.46	34.86
19	END PANEL	1.00	PCS	1,282.33	577.05
20	RR BOOT LID	1.00	PCS	1,796.25	808.31
21	WEATHER STRIP	1.00	PCS	252.81	113.77
22	VW SIGN	1.00	PCS	93.67	42.15
23	END PANEL TRIM COVER	1.00	PCS	77.89	35.05
24	TAILLIGHT OUTER LH	1.00	PCS	498.60	224.37
25	TAILLIGHT OUTER RH	1.00	PCS	498.60	224.37
26	RR NUMBER PLATE PACKING	1.00	PCS	9.74	4.38
27	NUT	8.00	PCS	1.43	5.15
28	NUT	2.00	PCS	2.52	2.27

Sub Total 12,480.35
GST (7%) AMOUNT 873.62
TOTAL AMOUNT 13,353.97

for Volkswagen Group Singapore Pte Ltd

06 JUN 2018

Customer

Phone : Fax :



Authorised Signatory

400 ORCHARD ROAD #15-06 ORCHARD TOWER SINGAPORE 238875, SINGAPORE 238875
Tel: 6333 6333 Fax: 6416 8555

RCB : 199904194N GST : 199904194N

PO NO : RA03235

RECEIVED
30 APR 2018
BY: VOB CC #360

TOTAL S\$	360.00
-----------	--------



Authorised Signature

400 ORCHARD ROAD #15-06 ORCHARD TOWER, SINGAPORE 238875
Tel: 6333 6333 Fax: 6416 8555

RCB - 199904194N GST - 199904194N

BLOCK 117 BUKIT BATOK WEST AVENUE 6 #24-242
SINGAPORE 650117

PO NO : RA03235

RECEIVED
18 MAY 2016
BY: UOB CC \$1800

Please issue cheque payable to **SKYWAY MOTOR PTE LTD** and send us a copy of cheque image then bank in to our **DBS Bank Ltd**. Current A/C No. 003-947-267-6.

SUB TOTAL	1,682.24
GST 7%	117.76
TOTAL \$	1,800.00

Authorized Signature



MOTOR PTE LTD

SKYWAY MOTOR PTE LTD

400 Orchard Road #15-06

Singapore 238875

Tel : 6333 6333 Email : rental@skyway.com.sg

Company Reg. No. 199904194N

GST Reg. No. 199904194N

RENTAL AGREEMENT

NO. 03235

ORIGINAL COPY

W1

HIRER'S PARTICULARS

Owner's Vehicle No.: **SKK 4086M**

Model: **Jetta**

Name: **Tan Siok Hoon**

Address: **B/K 117 Bukit Batok West Ave 6
#24-242 Spore 650117.**

Office Tel:

Residence Tel:

Occupation

Hp / Pgr No: **82338135**

P.P / LC No.: **S14360/SH**

Nationality: **Spore**

Date of Birth: **20/3/1960**

Place of Birth:

Dr. Licence No.

Date of Issue:

Country of Issue:

ADDITIONAL DRIVER'S PARTICULARS

Name:

Address:

Office Tel:

Residence Tel:

Occupation

Hp / Pgr No:

P.P / LC No.:

Nationality:

Date of Birth:

Place of Birth:

Dr. Licence No.

Date of Issue:

Country of Issue:

IMPORTANT: The vehicle will not be insured after the expiry of the hire period and in case of any accident the Hirer will be liable for all consequences.

RENTAL VEHICLE PARTICULARS

Rental Vehicle No.: **3LJ 9685P**

Model: **Jetta**

Collection Out

Date & Time

Mileage Out

30/4/18 @ 10:30am 25363

Return In

Date & Time

Mileage In

18/5/18 @ 4:10pm 26580



RENTAL CHARGES

Months @ \$ per month

Weeks @ \$ per week

3 Days @ \$ 120 per day 360 00

Hours @ \$ per hour

+ 15 day @ \$120/day 1800

ADDITIONAL CHARGES




PETROL TOP-UP CHARGES

MISC

TOTAL CHARGES (incl 7% GST)

PAYMENT MODE

- ☐ Master : _____
- ☐ VISA : _____
- ☐ Cash : _____
- ☐ Others : _____



Remarks:

CHECKED OUT BY

CHECKED IN BY

[Signature]

SKYWAY MOTOR PTE LTD

YI HE FA ENTERPRISES PTE LTD

60, Kaki Bukit Place

#01-01, Eunos Technopark

Singapore 415938

Tel: 6741 6155 Fax: 6742 9155

CUSTOMER'S SIGNATURE



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-064695

Date of Request: 30/04/2018

Your Ref No:

Online Purchase

Volkswagen Centre Singapore
247 Alexandra Road
Singapore 159934

Dear Sir/Madam,

Enquiry Date 30/04/2018
Enquiry By Tang Shu Shi
TP Vehicle No. SKR2377A
Accident Date 28/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKR2377A	AXA Insurance Pte Ltd	27/01/2018-26/01/2020	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-064695

Date of Request: 30/04/2018

Your Ref No: Online Purchase

Volkswagen Centre Singapore
247 Alexandra Road
Singapore 159934

Dear Sir/Madam,

Enquiry Date: 30/04/2018
Enquiry By: Tang Shu Shi
TP Vehicle No: SKR2377A
Accident Date: 28/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Service Request Details

Claim

SIMMOFLA

Reference

CC4/ASM1000000/R1eb3a2

Loss Date

28 April 2018

Request Date

30 April 2018

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SKK428AM

Make

TPND VOLKSWAGEN

Model

JETTA

Service Address

...

Primary Contact/Insured

LAU HONG HOH BENJAMIN
53 JURONG EAST AVENUE 1, #12-01, 609783, Singapore
BENADRI@GMAIL.COM

Claim Handler

HO Winnie
656804833
winnie.ho@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions

NON-REPORTING

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Melimen	
LKXInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	24 September 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown SKK 4086M.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018
 LDD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POM / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018
 Work Chart.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 June 2018
 FINAL REPORT.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	29 June 2018
 LTA PART COE Rebate Details.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2018
 Immediate Advice with Mandate.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2018
 LKK Survey Photo.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2018
 LKK Resurvey Photo.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2018
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2018
 RENTAL.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 June 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Immediate Advice.pdf	Reports & Statement	Estimate / Quotation	UXK AUTO CONSULTANTS PTE LTD (TP)	8 May 2018
 TP ESTIMATE - MABKED.pdf	Reports & Statement	Estimate / Quotation	UXK AUTO CONSULTANTS PTE LTD (TP)	3 May 2018
 EMAIL FROM WORKSHOP WITH TP GA.mig	Forms / Claim Documents	Others	KUMAR Shalendra	30 April 2018

Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT		SIR NO	QUAN TITY	MATERIAL	SIZE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPIL/ ETHRS	DISC DUNT'S	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE	
		1	1			S&P NUMBER PLATE			Bent	36		0		36	Approve		
		2	1			RR BOOT LID			Bent	808.31		0		808.31	Approve		
		3	1			WEATHER STRIP			Necessary	113.77		0		113.77	Approve		
		4	1			HINGE LH			Serviceable	0	0	0	0	0	Deny		
		5	1			HINGE RH			Serviceable	0	0	0	0	0	Deny		
		6	1			LOCK			Serviceable	0	0	0	0	0	Deny		
		7	1			LOCK COVER			Serviceable	0	0	0	0	0	Deny		
		8	1			LATCH			Serviceable	0	0	0	0	0	Deny		
		9	2			NUT REAR BOOT			Serviceable	0	0	0	0	0	Deny		
		10	1			RR NUMBER PLATE PACKING			Necessary	4.38		0		4.38	Approve		
		11	1			VW SIGN			Necessary	42.15		0		42.15	Approve		
		12	1			JETTA NAME PLATE			Necessary	25.11		0		25.11	Approve		
		13	1			TSI NAME PLATE			Necessary	23.64		0		23.64	Approve		
		14	1			RR BOOT LID TRIM PANEL			Serviceable	0	0	0	0	0	Deny		
		15	1			RR BUMPER			Deformed	477.6		0		477.6	Approve		
		16	1			SPOILER			Damaged	229.95		0		229.95	Approve		

EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LBRT PRICE	DEPRL/ BTTYS	DISC QUNTYS	SALY AGES	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	17	1			REINFORCEMENT			Serviceable	0	0	0	0	0	Deny	
	18	1			RR CTR. BRACKET			Cracked	34.86		0		34.86	Approve	
	19	1			TAILLIGHT LOWER BRACKET LH			Cracked	37.54		0		37.54	Approve	
	20	1			TAILLIGHT LOWER BRACKET RH			Cracked	27.38		0		27.38	Approve	
	21	1			BUMPER SIDE BRACKET LH			Serviceable	0	0	0	0	0	Deny	
	22	1			BUMPER SIDE BRACKET RH			Serviceable	0	0	0	0	0	Deny	
	23	1			TAILLIGHT OUTER LH			Damaged	224.37		0		224.37	Approve	
	24	1			TAILLIGHT OUTER RH			Damaged	224.37		0		224.37	Approve	
	25	1			TAILLIGHT INNER LH			Serviceable	0	0	0	0	0	Deny	
	26	1			TAILLIGHT INNER RH			Serviceable	0	0	0	0	0	Deny	
	27	1			NUT			Necessary	5.15		0		5.15	Approve	
	28	1			END PANEL			Bent	577.05		0		577.05	Approve	
	29	1			INOXSPRAY			Serviceable	0	0	0	0	0	Deny	
	30	1			2KADHESIV			Serviceable	0	0	0	0	0	Deny	
	31	1			SEALANT			Serviceable	0	0	0	0	0	Deny	
	32	1			END PANEL TRIM COVER			Deformed	35.05		0		35.05	Approve	
	33	1			NUT			Necessary	2.27		0		2.27	Approve	

Labour

Auto

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR REAR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		B&P TOWING CHARGES	195	0	0	Approve		
	2		CHECK WIRE HARNESS ECU SENSOR SOCKET	193.2	0	0	Approve		
	3		PROGRAMMING & CALIBRATION	331.2	0	0	Approve		
	4		LABOUR	4636.8	0	0	Approve		
	5		SPRAY PAINT	2768	0	0	Approve		
	6		R&R REAR LUGGAGE	579.4	0	0	Approve		
	7		R&R TRANSFER BOOTLID MECHANISM	579.4	0	0	Approve		
	8		SUPPLY & INSTALL REVERSE SENSOR	276	0	0	Approve		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Parts Parts & Labour Miscellaneous Summary

Add		Approved	Cherry	By Email Ad		
EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR 12 DAYS	Approve			

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$12,480.35

Claim Amount

\$12,480.35

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$2,528.95

\$2,528.95

Labour

\$9,551.40

\$9,551.40

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKR 2377A (Insd veh)	Model:	TPVD VOLKSWAGEN
	SKK 4086M (TP veh)		JETTA
Date of Accident:	28/04/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	24,270.36
Final Repair Cost	:	\$	13,353.97
Loss of Token Sum	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,926.00 18 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	15,281.97

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	VOLKSWAGEN CENTRE SINGAPORE	:	\$ 15,281.97

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

24/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))