

22/03/2002

ASS. REC. BY:

REF: CS3 / SM018008008 / Gzthbz

Special Instruction:

Surveyor

GZ

ASSIGNMENT (Office)

From (Person):

Grove Tco

of

SMO

Date/Time:

02052018 336pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JPX 1425

Insured:

FR 5006K

at Workshop m/s

Carz Auto

Tel:

9861 5313

of

Blk 1 Kaki Bukit Ave 6 #01-35

Policy No:

Claim No:

OMTD1801860 / GPL

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23042018

(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>Wp</sup>

H.O.D. Endorsement:

Date/Time: 02052018 143pm

Person Contacted:

Wilson

Vehicle IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

JPX 1425 - X

FR 5006K - CS / INC / 0011243 / Bbg1

Order repair: 9/5/2018.

DA: 20122010


REF: 14725

REF: 14725

No Logcard.

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



Veh No: JPX 14725 Yr Regn: - /  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Yamaha C.C. -  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 84564 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: \_\_\_\_\_  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 70/90-17  
 R: 80/90-17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Maxxis  
 Front 5 mm Rear 5 mm  
 R/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 26042018 D.O.I. 03052018 @ 4:30pm  
 Survey held at Carz Auto 6pm  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
Estimate repair @ range \$4000 - \$5,000. (Bryan)

RECEIVED 17 JUL 2018

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 5  
 Resurvey No. of Trip: 1

Date/Time, File Return to?

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee.	100
Transportation	60
S + RS	
Photos	
Others	
TOTAL	160

Report Format : PRQ  
 Lump Sum / I.B.I: (\$)

**Catherine Chong (LKK Auto)**

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Wednesday, 2 May, 2018 3:36 PM  
**To:** Huiling; admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Gnoh, Pau Loong; Ye, Yong Kang Melvin  
**Subject:** CMTD1801860/GPL - SUV(LKK)/ ACCIDENT INVOLVING FR5006K & JPX1425 ON 25.04.2018  
**Attachments:** CARZ.pdf

Our Reference : CMTD1801860/GPL  
Your Reference: JPX1425 (V) CARZ AUTO

**Without Prejudice**

Date: 2<sup>nd</sup> May 2018

**Attention:**  
**M/S RIAZ LLC**

Dear Hui Ling,

**ACCIDENT INVOLVING FR5006K & JPX1425 ON 25.04.2018**

We refer to your email reply dated 02/05/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards  
**Grace Teo**  
Claims Division  
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing  
**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Huiling [mailto:riaz@justice.com.sg]

**Sent:** Wednesday, May 02, 2018 2:27 PM

**To:** Teo, Grace

**Cc:** Gnoh, Pau Loong; Ye, Yong Kang Melvin

**Subject:** RE: \*\*\*SPAM\*\*\* CMTD1801860/GPL - PRI/ ACCIDENT INVOLVING FR5006K & JPX1425 ON 25.04.2018

**WITHOUT PREJUDICE**

Dear Grace,

We refer to your below email.

We disagree with your list of surveyor and shall proceed with appoint independent surveyor for this matter

Thanks and Best Regards,

HUILING

RIAZ LLC

133 NEW BRIDGE ROAD

# 09-09 CHINATOWN POINT

SINGAPORE 059413

TEL : 6534-0110 FAX : 6534-0220

\*\*\*\* DISCLAIMER\*\*\*\*

THIS EMAIL AND ANY FILES TRANSMITTED WITH IT ARE CONFIDENTIAL AND SUBJECT TO LEGAL PROFESSIONAL PRIVILEGE AND INTENDED SOLELY FOR THE USE OF THE INDIVIDUAL OR ENTITY TO WHO THEY ARE ADDRESSED. IF YOU HAVE RECEIVED THIS EMAIL IN ERROR PLEASE NOTIFY THE SYSTEM MANAGER. THIS MESSAGE CONTAINS CONFIDENTIAL INFORMATION AND IS INTENDED ONLY FOR THE INDIVIDUAL NAMED. IF YOU ARE NOT THE NAMED ADDRESSEE YOU SHOULD NOT DISSEMINATE, DISTRIBUTE OR COPY THIS EMAIL. PLEASE NOTIFY THE SENDER IMMEDIATELY BY EMAIL IF YOU HAVE RECEIVED THIS EMAIL BY MISTAKE AND DELETE THIS EMAIL FROM YOUR SYSTEM. IF YOU ARE NOT THE INTENDED RECIPIENT YOU ARE NOTIFIED THAT DISCLOSING, COPYING, DISTRIBUTING OR TAKING ANY ACTION IN RELIANCE ON THE CONTENTS OF THIS INFORMATION IS STRICTLY PROHIBITED.

---

**From:** Teo, Grace [mailto:grace.teo@sompo.com.sg]

**Sent:** Wednesday, 2 May, 2018 2:06 PM

**To:** RIAZ@JUSTICE.COM.SG

**Cc:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

**Subject:** \*\*\*SPAM\*\*\* CMTD1801860/GPL - PRI/ ACCIDENT INVOLVING FR5006K & JPX1425 ON 25.04.2018

Our Reference : CMTD1801860/GPL

Your Reference: JPX1425 (V) CARZ AUTO

Date: 2<sup>nd</sup> May 2018

**Without Prejudice**  
**EMAIL ONLY**

**Attention:**  
**M/S RIAZ LLC**

Dear Sir/ Madam,

**ACCIDENT INVOLVING FR5006K & JPX1425 ON 25.04.2018**

We refer to your Notice of Accident dated 02/05/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18008008/Gz4be2		
50 RAFFLES PLACE #05-01/06		Date: 18-07-2018		
SINGAPORE LAND TOWERSINGAPORE 048623				
Code: SMO				
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	FR 5006K	Veh. Inspected	JPX 1425	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801860/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	BLACK	
Odometer	84564 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	70/90-17	MAXXIS	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-17	MAXXIS	5 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.				
<b>5. General Information</b>				
Accident Date	25/04/2018	Inspect Date / Time	03/05/2018 ( 06:00 PM )	
Survey held at	CARZ AUTO SERVICES PTE LTD 1 KAKI BUKIT AVE 6 #02-35 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/SMO18008008/Gz4be2

**Inspected By**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.