

ASS. REC. BY:

REF:

CS/MSL/3008009/Rlvbz

(Special Instruction)

Surveyor
Merimen

Rasu

ASSIGNMENT (Office)

From (Person):

Clara Mitali Yeo

of

MSLH

Date/Time:

02/05/2018 4:23pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SK8 1458R

Insured:

at Workshop m/s

Performance

Tel:

91165600

of

303 Alexander Rd

Policy No:

770979255MP

Claim No:

557056

Sum Insured:

Excess:

\$1000.00

500

Make of Veh:

D.O.A.

27042018

(Client's Record)

CA / KEY / REP. / REV 24 HRS

03/05/2018 @ 10am

H.O.D. Endorsement:

Date/Time:

02/05/2018 4:38pm

Person Contacted:

Kevin

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SK8. 1458R - x

3/5/18

Report by merimen

3/5/18

Recd approved from Chen How by merimen

3/5/18

Informed Kevin C/A ex \$1000 by email

9/5/18

Excess amend to \$500

25/5/18

Final fig \$ 7863.15 (Ref 2506.10, 2490) confirmed by email

Cityvale
Merimen

Ref: MSH

REF: MSH

2519E

ASSIGNMENT

From: Date: 03/05/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKB 1458R

at Workshop m/s Performance

of 303 Alexandra Rd

Insured

Policy No.

Claims No.

Sum Insured: Excess: \$1000.00

(Client's Record)

Make of Veh: Kevin

(Policy Condition) 10am

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 49K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKB 1458R Yr Regn: 2011 / APR

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 318I 2.0 AT c.c 1995

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 072261 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDA PF72000 FG900 28

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: -

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 25/04/18

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 30 MAY 2018

25/5/2018

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1)

Date/Time, File Return to?

2) 20/5 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

1 \$ + RS. \$

1 Photo

1 Other

1

TOTAL

200

10

210

Report Format: merimen

Lump Sum / I.B.I. (\$ 7863.15

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2018		02 May 2018 16:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	DAMODARAN UNNIKRISHNAN, ID: S7282519E, Tel: +6592379070,		Email: NOEMAIL																					
Vehicle Reg. No.:	SKB1458R	Date of Loss:	29/04/2018 10:00 - :59 [84 Months From LTA Reg Date (Man Yr)]																					
Claim Type:	OD / 557056	Policy/Cover Note No.:	270979255MP (Comprehensive) Coverage: 29/04/2018 - 28/04/2019																					
		Excess:	S\$1,000.00																					
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/05/2018]																							
Driver/Custodian:	DAMODARAN UNNIKRISHNAN (45 / Male), NRIC: S7282519E, Tel: +6592379070																							
Adj Asg. Remarks:	URGENT. Car in, survey and revert. Please contact us ASAP if you are not able to attend this assignment.																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
ALL ASSOCIATED TASKS																								
View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

View Received Message

This mail is associated with :

***SKB1458R (557056)**

OD

Apr 29 2018 10:00AM

[DAMODARAN UNNIKRIISHNAN]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 28/05/2018 17:09 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$7863.15) - SKB1458R - Claim Handler: Clara Milah Yeo

Approved:7863.15.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Clara Milah Yeo	Date: 25 May 2018
<u>Preliminary Advice</u>	

Vehicle No	: SKB1458R	Accident Date	: 29/04/2018
Make	: BMW 318I	Policy No.	: 27097925SMP
Assignment Date	: 02/05/2018	Excess	: S\$1,000.00
Date of Inspection	: 03/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,369.25	(incl.supplementary \$4.15)
Revised Amount	:S\$	7,863.15	(incl.supplementary \$4.15)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	7,863.15	
Lump Sum Repair	:S\$		
Total Loss Consideration			
New for Old Value	:S\$		
Pre-Accident Value	:S\$	49,000.00	
COE / PARF Rebate	:S\$	35,439.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	13,561.00	

Remarks
☒ (X) The vehicle is economical for repair.

☐ () The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 9 May 2018 12:05 PM
To: SUR; kevin.leong.waikit@simedarby.com.sg
Subject: RE: SKB 1458R-DOA: 29/4/18 (MSIG OD)

Dear Kevin,

Please be informed that vehicle excess is \$500/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 3 May 2018 5:06 PM
To: SUR <sur@lkkauto.com>; 'kevin.leong.waikit@simedarby.com.sg' <kevin.leong.waikit@simedarby.com.sg>
Subject: SKB 1458R-DOA: 29/4/18 (MSIG OD)

Dear Kevin,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SKB 1458R (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 9 May 2018 12:04 PM
To: 'Clara Milah Yeo'
Cc: SUR
Subject: RE: OD claim - SKB1458R (doa: 29/04/2018) - revision of excess

Dear Milah,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Clara Milah Yeo [mailto:Milah@sg.msig-asia.com]
Sent: Wednesday, 9 May 2018 11:52 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: OD claim - SKB1458R (doa: 29/04/2018) - revision of excess

Dear Veron,

Please note that there's a revision of excess for the above claim.

Please help to inform the workshop the same.

Thank you.

Sincerely,

Clara Milah Yeo
Senior Admin Officer, Claims Services (Motor)
Direct line +65 6594 2560 | Direct fax +65 6225 7402 | milah@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 3 May 2018 5:06 PM
To: SUR; 'kevin.leong.waikit@simedarby.com.sg'
Subject: SKB 1458R-DOA: 29/4/18 (MSIG OD)

Dear Kevin,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SKB 1458R (Excess \$1000/-)**).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 03 May 2018

Preliminary Advice

Vehicle No	: SKB1458R	Accident Date	: 29/04/2018
Make	: BMW 318i	Policy No.	: 27097925SMP
Assignment Date	: 02/05/2018	Excess	: S\$1,000.00
Date of Inspection	: 03/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,365.10
Revised Amount	:S\$	7,044.65
Check Items (Estimated)	:S\$	1,302.45
Total	:S\$	8,347.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	49,000.00
COE / PARF Rebate	:S\$	35,439.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,561.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2519E
Vehicle Details	
Vehicle No.:	SKB1458R
Vehicle to be Exported:	No
Intended De-registration Date:	03 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	318I 2.0 AT D/AB 2WD 4DR GAS/D SR DRL
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	B374I877N46B20BZ
Chassis No.:	WBAPF72000FG90025
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,694.00
Original Registration Date:	29 Apr 2011
First Registration Date:	29 Apr 2011
Transfer Count:	0
Actual ARF Paid:	\$31,694.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2021
PARF Rebate Amount:	\$19,016.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,100.00
COE Rebate Amount:	\$16,423.00
Total Rebate Amount:	\$35,439.00

The information contained herein is correct as at 03 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2018 12:49
Date Of Accident	29/04/2018 10:20
Exact Location Of Accident	JURONG EAST ST 24 TO JURONG EAST AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB1458R
Insured/Policyholder	
Name Of Registered Owner	DAMODARAN UNNIKRISHNAN
NRIC No	S7282519E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92379070
Alternative Phone No	OFFICE-92379070

Vehicle Particulars

Manufacturer	BMW
Model	318
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	10118179

Driver

Name of Driver	DAMODARAN UNNIKRISHNAN
NRIC No	S7282519E
Date Of Birth	01/06/1972
Occupation	INDOOR
Date Of Driving Pass	16/03/2011
Driving Experience	7 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92379070
Fax Number	
Contact Number	OFFICE-92379070
Email Address	NOEMAIL

Address	27 WEST COAST CRESCENT #17-23
Postcode	128048
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ854K
Vehicle Make/Model/Colour	KIA FORTE WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIEW WENG HONG
NRIC/Passport Number	S1279073B
Contact Number	90263103
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29th April I was driving my car through the leftmost lane on Turong East St 24 turning left into Turong East Ave 1. The car in front had turned into the Turong East Ave 1, I was following. The car in front suddenly stopped. I could not stop in time and hit the car on the back side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

A/RG/FFV No.

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401339W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

Car In

ESTIMATE

Estimate No. : b1 46777
Date Estimated : 30/04/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Damodaran Unnikrishnan
39C West Coast Park
#05-07 The Infiniti

Singapore 127714

- ACCOUNT -

66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB1458R	FG90025	29/04/2011	318i/4 (A)	0

DESCRIPTION

To replace front bumper, front left side panel, RH headlight bracket and all attachments cause by accident.

✓ 1700 ~~3,480.00~~

Painting on front bumper & front left side panel

✓ 1730 ~~1,923.00~~

To check electrical wiring systems at the front section for proper function.

✓ 150 ~~177.00~~

To replace left headlight including program and conduct tests for proper function.

✓ 451 ~~531.00~~

To carry out body cavity preservation.
(Per panel).

✓ 100 ~~118.00~~

Sundries.

✓ 150.00

Total Labour 1: 6,299.00

DESCRIPTION

FRT LH FENDER
Set of mount
FRT BUMPER LH SUPPORT BKT
FRT BUMPER LH INSERT
FRT BUMPER LH CLOSED GRID
FRT BUMPER CARRIER
BRACKET FOR HEADLIGHT ARM LH
FRT BUMPER RH FINISHER ROD
FRT BUMPER CTR GRID
FRT BUMPER (PRIMED)
Support
LH HEADLAMP LOWER BRACE BKT
FRT LH FENDER INNER COVERING
COVER LH
FRT LH FENDER BOTTOM COVERING
FRT BUMPER TOP GASKET
HEADLIGHT LH

QTY PRICE

1	648.35
1	78.15
1	8.45
1	11.45
1	50.95
1	550.30
1	27.15
1	29.65
1	59.60
1	898.50
1	5.95
1	71.95
1	112.10
1	16.55
1	112.10
1	18.10
1	1,108.65

VALUE

✓	648.35
✓	78.15
✓	8.45
✓	11.45
✓	50.95
✓	550.30
✓	27.15
✓	29.65
✓	59.60
✓	898.50
✓	5.95
✓	71.95
✓	112.10
✓	16.55
✓	112.10
✓	18.10
✓	1,108.65



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449775

313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190520 (AfterSales)
63190533/330 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46777
Date Estimated : 30/04/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB1458R	FG90025	29/04/2011	318i/4 (A)	0

DESCRIPTION
LH FOGLAMP

QTY	PRIC	VALUE
1	258.15	258.15
Total Parts :		4,066.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims On / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 03/05/18 @ 1030 Excess S\$ 1000

Surveyor's Name Raul Sign _____

Surveyor's Tel 90010068 Authorised Yes ☒ No ☐ Remark

Authorised Date _____ Time _____

RESURVEY PARTS - PHOTO YES / NO YES / NO PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 4-5 days

10,369.25

Labour 1	:	6,299.00
Parts	:	4,066.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	725.56
Grand Total	:	11,090.66

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 25 May 2018 12:16 PM
To: PBSP; SUR
Subject: RE: FINAL REPORT / SKB1458R

Hi Caroline,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Friday, 18 May, 2018 5:10 PM

To: Rasul (LKKAUTO); SUR

Subject: FINAL REPORT / SKB1458R

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,211.00

Total Parts : 3,652.15

Total Labour & Parts : 7,863.15

Repair days: 5

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 191401088M, GST Reg. No. M2-0020011-8



FINAL REPORT

Estimate No. : b1 46777
Date Estimated : 30/04/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Damodaran Unnikrishnan
39C West Coast Park
#05-07 The Infiniti

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 127714

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKB1458R	FG90025	29/04/2011	318i/4 (A)	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front LH fender and attachments include knocking out dents caused by the accident	1700.00		1,700.00
To spray paint front bumper and front LH fender	1730.00		1,730.00
To check electrical wiring systems at the front section for proper function include adjustment of headlights	150.00		150.00
To replace LH headlight include programming and conducting tests for proper function	451.00		451.00
To carry out body cavity preservation. (Per panel).	100.00		100.00
Sundries.	80.00		80.00

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.40	2.00		2.80
FRT LH FENDER	648.35	1.00		648.35
FRT BUMPER CARRIER	550.30	1.00		550.30
FRT BUMPER (PRIMED)	898.50	1.00		898.50
# RIVET *	0.45	3.00		1.35
LH HEADLAMP LOWER BRACE BKT	71.95	1.00		71.95
FRT LH FENDER BOTTOM COVERING	112.10	1.00		112.10
HEADLIGHT LH	1,108.65	1.00		1,108.65
LH FOGLAMP	258.15	1.00		258.15

SUPPLEMENTARY ITEMS

Total Labour :	4,211.00
Total Parts :	3,652.15
Total Labour & Parts :	7,863.15
Deduction for Excess :	500.00
Total Repair Costs less Excess:	7,363.15
GST @7%:	515.42
Grand Total :	7,878.57

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401589W. GST Reg. No. M2-0020081-X.



SUPPLEMENTARY

Estimate No. : b1 46777
Date Estimated : 30/04/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Damodaran Unnikrishnan
39C West Coast Park
#05-07 The Infiniti

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 127714

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKB1458R	FG90025	29/04/2011	318i/4 (A)	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.40	2.00		2.80
# RIVET *	0.45	3.00		1.35

Total Labour :	
Total Parts :	4.15
Total Labour & Parts :	4.15

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2018		02 May 2018 16:23 Edit Adj Rpt	\$7,863.15 Edit Estimates	\$7,863.15 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: DAMODARAN UNNIKRISHNAN , ID: S7282519E, Tel: +6592379070, Email: NOEMAIL									
Vehicle Reg. No.: SKB1458R		Date of Loss: 29/04/2018 10:00 - :59 [84 Months From LTA Reg Date (Man Yr)]							
Claim Type: OD / 557056		Policy/Cover Note No.: 27097925SMP (Comprehensive) Coverage: 29/04/2018 - 28/04/2019 Excess: S\$500.00							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Derby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/06/2018]									
Driver/Custodian: DAMODARAN UNNIKRISHNAN (45 / Male) , NRIC: S7282519E, Tel: +6592379070									
Adj Asg. Remarks: URGENT . Car in, survey and revert. Please contact us ASAP if you are not able to attend this assignment.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (28/05/2018): Alert - Adj Mandate Approved (\$7863.15) - SKB1458R - Claim Handler: Clara Milah... - MSIG_SG (03/05/2018): Alert - Adj Mandate Approved (\$7044.65) - SKB1458R - Claim Handler: Clara Milah...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB1458R (557056)
OD
Apr 29 2018 10:00AM
[DAMODARAN UNNIKRISHNAN]
Performance Motors Limited

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	30/04/18 15:08	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/05/18 13:37	Adjuster Immediate Advice		Load HTM	
2	25/05/18 12:38	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/05/18 12:07	General View		Load JPG	☒
2	07/05/18 12:07	General View		Load JPG	☒
3	07/05/18 12:07	General View		Load JPG	☒
4	07/05/18 12:07	General View		Load JPG	☒
5	07/05/18 12:07	General View		Load JPG	☒
6	07/05/18 12:07	General View		Load JPG	☒
7	07/05/18 12:07	General View		Load JPG	☒
8	07/05/18 12:07	General View		Load JPG	☒
9	07/05/18 12:07	General View		Load JPG	☒
10	07/05/18 12:07	General View		Load JPG	☒
11	07/05/18 12:07	General View		Load JPG	☒
12	07/05/18 12:07	General View		Load JPG	☒
13	07/05/18 12:07	General View		Load JPG	☒
14	07/05/18 12:07	General View		Load JPG	☒
15	07/05/18 12:07	General View		Load JPG	☒
16	07/05/18 12:07	General View		Load JPG	☒
17	07/05/18 12:07	General View		Load JPG	☒
18	07/05/18 12:07	General View		Load JPG	☒
19	07/05/18 12:07	General View		Load JPG	☒
20	07/05/18 12:07	General View		Load JPG	☒
21	07/05/18 12:07	General View		Load JPG	☒
22	07/05/18 12:07	General View		Load JPG	☒
23	07/05/18 12:07	General View		Load JPG	☒
24	07/05/18 12:07	General View		Load JPG	☒
25	07/05/18 12:07	General View		Load JPG	☒
26	07/05/18 12:07	General View		Load JPG	☒
27	07/05/18 12:07	General View		Load JPG	☒
28	07/05/18 12:07	General View		Load JPG	☒
29	07/05/18 12:07	General View		Load JPG	☒
30	07/05/18 12:07	General View		Load JPG	☒
31	07/05/18 12:07	General View		Load JPG	☒
32	07/05/18 12:07	General View		Load JPG	☒
33	25/05/18 12:21	Reinspection Photo		Load JPG	

Assessment Reports				1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
					☒
34	25/05/18 12:21	Reinspection Photo	1	Load JPG	☒
35	25/05/18 12:21	Reinspection Photo	1	Load JPG	☒
36	25/05/18 12:21	Reinspection Photo	1	Load JPG	☒
37	25/05/18 12:21	Reinspection Photo	1	Load JPG	☒
38	25/05/18 12:21	Reinspection Photo	1	Load JPG	☒
39	25/05/18 12:21	Reinspection Photo	1	Load JPG	☒
40	25/05/18 12:21	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	M5IG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/04/18 17:38	Repair Estimate	1	Load PDF	
2	30/04/18 17:42	Email from w/shop to request for survey	1	Load PDF	
3	02/05/18 10:09	SKZ854K - 3P REPORT	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/05/18 13:37	MARK ESTIMATE	1	Load PDF	
2	25/05/18 12:39	1ST MARK ESTIMATE	1	Load PDF	
3	25/05/18 12:39	SUPPLEMENTARY	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	30/04/18 15:08	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	30/04/18 15:05	Accident Photo	1	Load JPG	☒
2	30/04/18 15:05	Accident Photo	1	Load JPG	☒
3	30/04/18 15:05	Accident Photo	1	Load JPG	☒
4	30/04/18 15:05	Accident Photo	1	Load JPG	☒
5	30/04/18 15:05	Accident Photo	1	Load JPG	☒
6	30/04/18 15:05	Accident Photo	1	Load JPG	☒
7	30/04/18 15:05	Accident Photo	1	Load JPG	☒
8	30/04/18 15:05	Accident Photo	1	Load JPG	☒
9	30/04/18 15:05	Accident Photo	1	Load JPG	☒
10	30/04/18 15:05	Accident Photo	1	Load JPG	☒
11	30/04/18 15:05	Accident Photo	1	Load JPG	☒
12	30/04/18 15:05	Accident Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	30/04/18 12:53	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18008009/R1VBE2

Date: 01/06/2018

REFERENCE

Insured/Claimant: DAMODARAN UNNIKRISHNAN

Policy No: 27097925SMP

Date of Loss: 29/04/2018

Nature of Claim: OD

Claim No: 557056

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB1458R**

Make & Model: BMW 318i, 2.0 (A)

Engine No: B374I877N46B20BZ

Reg. Date: 29/04/2011 (Man. Year: 2010)

Chassis No: WBAPF72000FG90025

Colour: Grey

Odometer: 72261 km

Engine Capacity: 1995 cc

Market Value/New Car Price: S\$49,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,220.25	3,732.15	488.10	11.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,149.00	4,131.00	2,018.00	32.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,369.25	7,863.15	2,506.10	24.17
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	9,869.25	7,363.15	2,506.10	25.39
+ GST 7.00/7.00% (S\$)	690.85	515.42	175.43	25.39
Nett Amount (S\$)	10,560.10	7,878.57	2,681.53	25.39

INSPECTION

Date of Assignment: 02/05/2018

Date Inspected: 03/05/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2018)
Parts:	143	BMW 318i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB1458R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRT LH FENDER	Buckled	648.35 FS	*648.35 FS
3	1		*SET OF MOUNT	Serviceable	78.15 FS	*- FS
4	1		*FRT BUMPER LH SUPPORT BKT	Serviceable	8.45 FS	*- FS
5	1		*FRT BUMPER LH INSERT	Serviceable	11.45 FS	*- FS
6	1		*FRT BUMPER LH CLOSED GRID	Serviceable	50.95 FS	*- FS
7	1		*FRT BUMPER CARRIER	Broken	550.30 FS	*550.30 FS
8	1		*BRACKET FOR HEADLIGHT ARM LH	Serviceable	27.15 FS	*- FS
9	1		*FRT BUMPER RH FINISHER ROD	Serviceable	29.65 FS	*- FS
10	1		*FRT BUMPER CTR GRID	Serviceable	59.60 FS	*- FS
11	1		*FRT BUMPER (PRIMED)	Deformed	898.50 FS	*898.50 FS
12	1		*SUPPORT	Serviceable	5.95 FS	*- FS
13	1		*LH HEADLAMP LOWER BRACE BKT	Bent	71.95 FS	*71.95 FS
14	1		*FRT LH FENDER INNER COVERING	Cut	112.10 FS	*112.10 FS
15	1		*COVER LH	Serviceable	16.55 FS	*- FS
16	1		*FRT BUMPER TOP GASKET	Serviceable	18.10 FS	*- FS
17	1		*HEADLIGHT LH	Cracked	1,108.65 FS	*1,108.65 FS
18	1		*LH FOGLAMP	Scratched	258.15 FS	*258.15 FS
19	2		*BLIND RIVET	Necessary	2.80 FS	*2.80 FS
20	3		*RIVET	Necessary	1.35 FS	*1.35 FS
21	1		*FRT LH FENDER BOTTOM COVERING	Serviceable	112.10 FS	*- FS
Total Parts (S\$)					4,220.25	3,732.15

F=Franchise part. S=SpcNetl.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER, FRONT LEFT SIDE PANEL, RH HEADLIGHT BRACKET AND ALL ATTACHMENTS CAUSE BY ACCIDENT	New	3,400.00	1,700.00
2	PAINTING ON FRONT BUMPER & FRONT LEFT SIDE PANEL	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REPLACE LEFT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			6,149.00	4,131.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >