

ASS. REC. BY:

REF: CS/MS/18008020 / Tiz4ber

Special Instructions:

Surveyor:

Tuzilch

McIntosh

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MS16

Estimated Cost:

Date/Time: 02052018 4:54pm

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 39815

Insured:

FS 3796X

at Workshop m/s

Empire Image

Tel:

6777 5463

of

Blk 4 Pandan Loop (Blk 1 / Blk 2)

Policy No:

MSD/VMT/17-36 3912 - CA

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

71042018

CA / REV / REP. / REV 24 HRS w/p

03052018

Date/Time:

02052018 5:18pm

Person Contacted:

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SKE 39815 - CS/CTU/7005789/Hirbm2

D.O.A. 03032017

FS 3796X - X

PRs
Surrender
M/M/11/11

REF: msh

ASSIGNMENT

From: Date: 01/02/08

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE 39815

at Workshop m/s

of Empire Image
Blk 4 Pandan Larp (Blk 1 / Blk K)

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKE 39815

Yr Regr: /

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Saguar XF

C.C.

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

76982

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

S4JA105120C1F535430

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

255/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 3/5/180/1530

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No GIA.

* Estimate repair : S\$ 4500 - 5500

* 3 days

7/5/10

Submit PRS report

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		02 May 2018 16:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GOH MAI KEL, ID: S8282682C								
Main Claimant:	KOH CHIANG LIANG, ID: S7707647F								
Vehicle Reg. No.:	SKE3981S	Date of Loss:	27/04/2018 19:00 - :59 [73 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/17-363912-CA Coverage: 06/05/2017 - 05/05/2018						
Vehicle Reg. No. (Insured):	F53796X	Policy No. (Claimant):							
		Excess:							
Repairer:	Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018		02 May 2018 16:54 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: GOH MAI KEL , ID: S8282682C									
Main Claimant: KOH CHIANG LIANG , ID: S7707647F									
Vehicle Reg. No.: SKE3981S		Date of Loss: 27/04/2018 19:00 - :59 [73 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000626		Policy/Cover Note No.: MSD/VMT/17-363912-CA Coverage: 06/05/2017 - 05/05/2018							
Vehicle Reg. No. (Insured): FS3796X		Policy No. (Claimant):							
		Excess:							
Repairer: Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 03/05/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE3981S (MSC/V/18-000626)
[FS3796X]
TP
KOH CHIANG LIANG
Apr 27 2018 7:00PM
[GOH MAI KEL]
Empire Image

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	04/05/18 14:20	General View								Load JPG	☒	
2	04/05/18 14:20	General View								Load JPG	☒	
3	04/05/18 14:20	General View								Load JPG	☒	
4	04/05/18 14:20	General View								Load JPG	☒	
5	04/05/18 14:20	General View								Load JPG	☒	
6	04/05/18 14:20	General View								Load JPG	☒	
7	04/05/18 14:20	General View								Load JPG	☒	
8	04/05/18 14:20	General View								Load JPG	☒	
9	04/05/18 14:20	General View								Load JPG	☒	
10	04/05/18 14:20	General View								Load JPG	☒	
11	04/05/18 14:20	General View								Load JPG	☒	
12	04/05/18 14:20	General View								Load JPG	☒	
13	04/05/18 14:20	General View								Load JPG	☒	
14	04/05/18 14:20	General View								Load JPG	☒	
15	04/05/18 14:20	General View								Load JPG	☒	
16	04/05/18 14:20	General View								Load JPG	☒	
Documentation									1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print	
1	02/05/18 12:05	TP PRI Request Email								Load PDF		
2	02/05/18 12:07	TP PRI Request and GIA Report								Load PDF		
3	02/05/18 16:54	TP reject SJE- assign LKK								Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008020/T1Z4BE2

Date: 09/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/17-363912-CA
Claimant Vehicle No :	SKE3981S	Insured Vehicle No :	FS3796X
Date of Loss:	27/04/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000626

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE3981S	Engine No:	602791334FC
Make & Model:	JAGUAR XF, 3.0 V6 LUXURY (A)	Chassis No:	SAJAC05D0CFS35430
Reg. Date:	28/02/2012 (Man. Year: 2011)	Odometer:	76982 km
Colour:	Black		
Engine Capacity:	2967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R20	Rear Tyre Size:	255/35 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/05/2018	
Date Inspected:	03/05/2018	Inspected At: Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K) Singapore 128222
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 -\$5,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2018)
Parts: 143	JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE3981S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >