

ASS. REC. BY:

REF: CS3 / MSC18008021 / T24bez | Special Instruction:

SURVAYOR: Taufiqh ASSIGNMENT (Office)

From (Person): Monica Chung of msllh Date/Time: 02052018 458pm

Estimated Cost: Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 8204A Insured: GBA 1188G

at Workshop m/s: Sin Song Hong Tel: 9617 8521

of: 81k 3022A Ubi Rd 1 #01-53

Policy No: 29067855MKC Claim No: 557167

Sum Insured: Excess:

Make of Veh: D.O.A. 26042018
(Client's Record)

CA / REV / REP. / REV 24 HRS wpr H.O.D. Endorsement:

Date/Time: 02052018 5:12pm Person Contacted: Andy Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SJK 8204A - KIA / MSC18007837 / ZH DUA: 26042018
	GBA 1188G - NA / INC12009411 / W1el DUA: 09152012

Tan Jiah

REF: MSLH

ASSIGNMENT

From: _____ Date: 08052018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJK 8204A

at Workshop n/s: Sin Leng Hong

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJK 8204A Regn: 908 Nov

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi Lancer c.c. 1584

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 127100 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: July SNC S31794 001935

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size: F: 205/45 R16
R: - -

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A.	D.O.I. 8/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* Repair Estimate : S\$ 10,000 - 11,000
	* 4 days
16/5/18	Submit PRS Report.

RECEIVED 17 MAY 2018

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.f: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S+RS: _____

Photos: _____

Others: _____

TOTAL: _____

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

120
10
130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018		02 May 2018 16:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ACOUSTIC & LIGHTING SYSTEM PTE LTD, Co. Reg. No.: 200311031M								
Main Claimant:	ALEX TEO HEUI SIN, ID: S78371172								
Vehicle Reg. No.:	SJK8204A	Date of Loss: 26/04/2018 17:00 - :59 [113 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 557167	Policy/Cover Note No.: 29067855MKC (Comprehensive) Coverage: 17/01/2018 - 16/01/2019							
Vehicle Reg. No. (Insured):	GBA1188G	Policy No. (Claimant): Excess: S\$500.00							
Repairer:	Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/05/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7117Z
Vehicle Details	
Vehicle No.:	SJK8204A
Vehicle to be Exported:	No
Intended De-registration Date:	08 May 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	4G18JY9302
Chassis No.:	JMYSNCS3A9U001933
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,919.00
Original Registration Date:	05 Nov 2008
First Registration Date:	05 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$11,919.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Nov 2018
PARF Rebate Amount:	\$5,959.00
Intended COE Rebate Details	
COE Expiry Date:	04 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,989.00
COE Rebate Amount:	\$538.00
Total Rebate Amount:	\$6,497.00

The information contained herein is correct as at 08 May 2018

OK



Mitsubishi Lancer 1.6 Price Range Depreciation 2008 Vehicle Type Search Advanced Search

Home » Used Cars » Ken Garage Pte Ltd » Mitsubishi Lancer 1.6M GLX

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Commercial Vehicle

WORLD UNIVERSITY EXPO

Friday Only 11 MAY 3-9pm
SUNTEC CONVENTION LEVEL 3 CONCOURSE

Mitsubishi Lancer 1.6M GLX

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$13,899
Depreciation	-
Reg Date	05-Nov-2008 (Smiths 27days COE left)
Manufactured	2008
Mileage	98,000 km (10.3k /yr)
Transmission	Manual
Engine Cap	1,584 cc
Road Tax	\$734 /yr
Power	79.0 kW (105 bhp) View specs of the Mitsubishi Lancer (2006-2008)
Curb Weight	1,162 kg
Features	Fuel Efficient And Responsive 1.6 Inline 4 Cylinder 16 Valve Engine With 105 BHP.
Accessories	Leather Upholstery, Factory Fitted Sports Rims, Single Din Audio System, Immobilizer, Solar Film, Parking Sensor.
Description	Elegant And Sporty Grey! Only 1 Owner! Zero Modifications! Very Much Cheaper Than Car Rental! Best For Short Terms Driving Buy With Trust And Confidence Only At Ken Garage A13.
COE	\$12,001
OMV	\$11,955
ARF	\$11,955
Dereg Value	\$6,569 as of today (change)
No. of Owners	1
Type of Veh	Mid Size Sedan
Category	PARF Car
Availability	Available

Add to Shortlist Add to Compare Add a Note

Posted on: 10-Mar-2018 | Last Updated on: 05-May-2018

Tags: Mitsubishi Lancer, 2008 Mitsubishi Lancer, Mitsubishi Lancer, Used Mitsubishi

Upfront Payment » more Financial info

Transfer Fee	\$25	
Down Payment	\$4,170 (change)	Maximum 70% Loan
1st Instalment	\$1,970	
Total Upfront Payment	\$6,165 (excluding insurance)	

Estimates based on 70% ban at 2.98% interest rate. Check with seller for exact figure.

Items for Mitsubishi Lancer » View All

	LED Rear Bumper Reflector Lamp \$140		2 Din Console Compartment \$80
--	--	--	--



[Location Map](#) [Price Analysis](#)

Seller Information

Company	Ken Garage Pte Ltd » Dealer's pricelist » 54 vehs sold 40 vehs available
Address	210 Turf Club Road Lot A13 Search cars nearby this location
Location	Car Mall @ The Grandstand
Office No	64637008
Contact Person(s)	Ken 85699983 Koh 81181378 Dennis 92722615 Kenny 94559991

Useful Services

STA Make sure of this car condition with STA Evaluation.
Vehicle Evaluation

Free Valuation Find out the market value for your car. Get a free Car Valuation.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/04/2018 13:36
Date Of Accident	26/04/2018 17:30
Exact Location Of Accident	BLK 301 UBI AVE 1 OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK8204A
Insured/Policyholder	
Name Of Registered Owner	ALEX TEO HEUI SIN
NRIC No	S7837117Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92233133
Alternative Phone No	OFFICE-92233133

Vehicle Particulars

Manufacturer	MINI
Model	LANCER 1.6 M
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80445311QMX
Cover Note Number	

Driver

Name of Driver	ALEX TEO HEUI SIN
NRIC No	S7837117Z
Date Of Birth	10/12/1978
Occupation	INDOOR
Date Of Driving Pass	07/11/1997
Driving Experience	20 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92233133
Fax Number	
Contact Number	OFFICE-92233133
E-Mail Address	NOEMAIL

Address	BLK 175D PUNGGOL FIELD #03-537
Postcode	824175
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180427/2005.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA1188G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This report must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The withdrawal or cessation of tort claims by insurance companies is not an admission of policy liability on the part of the insurance company.
5. **Any false reporting may be referred to the Police for investigation**.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. Upon judgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I, the undersigned, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided to me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law, in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Insured's Signature
(Date & Time)

Driver's Signature
(If driver is not the policyholder)
(Date & Time)

Reporting Centre Personnel's Signature
Name
NRIC/TIN No.



**SINGAPORE
POLICE FORCE**



T/20180427/2005

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 3

Report No: T/20180427/2005

CONTINUATION OF REPORT

Driver			
Name	ALEX TEO HEUI SIN	ID No.	S7837117Z
Related Vehicle	SJK8204A (Car)	Contact No.	92233133
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 26/04/2018 at about 1000hrs, I parked my vehicle registration number SJK8204A at Block 301 Ubi Avenue 1 open carpark and left for work. At that point of time, nothing was amiss. .

On the same day at about 1930hrs, I retrieved my vehicle and drove back home. I parked my vehicle and alighted. I noticed a dent at the front right bumper near to the headlight. As such, I took the memory card from my in built car camera and viewed it at home. The footage shows that on the same day at about 1732hrs, a van registration number GBA1188G that was parked beside me have hit onto my vehicle's front bumper when he is driving out from his lot.

I wish to inform that I still have the footage in my memory card.



SINGAPORE
POLICE FORCE



T/20180427/2005

3 of 3

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No: T/20180427/2005

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 TAN XIAO HUI

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
27/04/2018 00:59

Officer In Charge Of Case:
TP / HRT /
SI TAN LEE HWANG DAWN
Contact No: 65476215

Classification Of Case:

Authentication Stamp
SP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018		02 May 2018 16:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ACOUSTIC & LIGHTING SYSTEM PTE LTD , Co. Reg. No.: 200311031M								
Main Claimant:	ALEX TEO HEUI SIN , ID: S7837117Z								
Vehicle Reg. No.:	SJK8204A	Date of Loss:	26/04/2018 17:00 - :59 [113 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557167	Policy/Cover Note No.:	29067855MKC (Comprehensive) Coverage: 17/01/2018 - 16/01/2019						
Vehicle Reg. No. (Insured):	GBA1188G	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 03/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJK8204A (557167)**
[GBA1188G]
TP
ALEX TEO HEUI SIN
Apr 26 2018 5:00PM
[ACOUSTIC & LIGHTING SYSTEM PTE LTD]
Sin Seng Hong Spray Painting & Service

Upload Documents Upload Photos Compose New Letter		View View in Browser		
Letters/Correspondences		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/18 15:50	Non Reporting Letter to OI	Load HTM	<input type="checkbox"/>
Photos/Images		3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
2	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
3	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
11	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
12	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
13	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
14	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
15	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
16	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
17	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
18	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
19	11/05/18 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/18 15:46	TPD SJK8204A GIA REPORT	Load PDF	<input type="checkbox"/>
2	02/05/18 15:48	TPD SJK8204A - PRI	Load PDF	<input type="checkbox"/>
3	02/05/18 16:58	Reply email from TP Lawyer & appoint LKK AUTO	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008021/T1Z4BE2
Date: 17/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 29067855MKC
Claimant Vehicle No : SJK8204A	Insured Vehicle No : GBA1188G
Date of Loss: 26/04/2018	Nature of Claim: TP Claim No: 557167

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK8204A	Engine No: 4G18JY9302
Make & Model: MITSUBISHI LANCER, 1.6 (M)	Chassis No: JMYSNCS3A9U001933
Reg. Date: 05/11/2008 (Man. Year: 2008)	Odometer: 127100 km
Colour: Grey	
Engine Capacity: 1584 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R16	Rear Tyre Size: 205/45 R16
Front Left Side: Bridgestone 6 mm	Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm	Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/05/2018	
Date Inspected: 08/05/2018	Inspected At: Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53 Singapore 408716

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 - \$11,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2018)
Parts: 143	MITSUBISHI LANCER 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJK8204A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >