

ASS. REC. BY:

REF:

CS/ASM18008102/Atbstr

Special Instruction:

Smart claim

From (Person):

Richard Ang

ASSIGNMENT (Office)

of ASM

Date/Time: 02052018 4:33 pm

Estimated Cost:

Bill to:

DI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDV 271H

Insured:

at Workshop m/s

McWell Ventures

Tel:

90625745 / 91060030

of

51 Ubi Ave 1 # 01-05

Policy No:

Claim No:

SSM007HM

Sum Insured:

Excess:

\$ 500.00

Make of Vehl:

D.O.A. 27042018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 02052018 5:07pm

Person Contacted:

Don

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	arrange survey when estimate done
	SDV 271H - NBA / INC15011174/e1	DA: 020713
7/5 -	Revert via menimen	
7/5 @ 2:40pm	authorise by Richard Ang.	
7/5 @ 5:11pm	inform Don authorise repair	
06/6/18 @ 11:19am	Informed Writase, we have received supplementary \$1037.27 & 8 Hs consistent and economical for repair via Smart Claims.	



Service Request Details

Claim

S8M00FHM

Reference

None 

Loss Date

April 27, 2018

Request Date

May 2, 2018

Due Date

May 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDV2271H

Make

BMW

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , 408933

Primary Contact/Insured

POH SENG WEE

560 UPPER EAST COAST ROAD, #02-02, 466580, Singapore

96876787

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

EXCESS - \$500 NO ESTIMATES

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

New Message

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , 408933

Primary Contact/Insured

POH SENG WEE
560 UPPER EAST COAST ROAD, #02-02, 466580, Singapore
96876787

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions
EXCESS - \$500 NO ESTIMATES

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

5/7/18 2:40 PM

FROM

ANG Richard

SUBJECT

Re:IA and estimate UPLOADED

BODY

Hi Denise, please proceed to authorise repairs. Th...



TYPE



SENT

5/7/18 2:18 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (OD)



SUPPLEMENTARY LIST OF VEHICLE SDV 2271H UPLOADED.

Type

🔗 Question

Message

Dear Winnie, we have received supplementary of \$1,032.27 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. - Shiau Chan

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 7/5/18

Survey Details:

Date of loss	27-Apr-18
Date of appointment	4-May-18
Date of survey	4-May-18
Location of survey	McWell @ Ubi Ave 1

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SDV 2271H
Make and Model	BMW 528i GT
Date of registration	28/4/2015
Excess	500
Market Value	\$155,000
Part Rebate	\$99,528
Nett Loss	\$55,472

Repair details:

Initial Estimate	14,746.98
------------------	-----------

Proposed/Revised repair cost:

Parts	\$7,198
Check items (estimate)	\$1,478
Labour	\$1,070
Total	\$9,746
Lump Sum(if applicable)	

Number of days for repair	5
---------------------------	---



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGE CONSISTENT, REPAIR COST ECONOMICAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/04/2018 14:55
Date Of Accident	27/04/2018 17:10
Exact Location Of Accident	MCE EXITING TO ECP (CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDV2271H
Insured/Policyholder	
Name Of Registered Owner	POH SENG WEE (FU CHENGWEI)
NRIC No	S7102441E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96876787
Alternative Phone No	OTHERS-96876787

Vehicle Particulars

Manufacturer	BMW
Model	528I-2.0 L (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1766736
Cover Note Number	

Driver

Name of Driver	POH SENG WEE (FU CHENGWEI)
NRIC No	S7102441E
Date Of Birth	30/01/1971
Occupation	INDOOR
Date Of Driving Pass	13/10/1989
Driving Experience	28 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96876787
Fax Number	
Contact Number	OTHERS-96876787
Email Address	NOEMAIL

Address	560 UPPER EAST COAST ROAD #02-02 SINGAPORE
Postcode	466580
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGQ6063G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

28/4/18
2:23PM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Perwen

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 Apr 2018, at about 5:10 pm, I was travelling on MCE and exiting to ECP (Changi). It was raining and the traffic was congested and slow. At the exit, I was behind a white car (SGQ 60636) following at about one car length. The car in front suddenly jammed brake and I was not able to brake in time. As a result, my car (SDV 22711) collided with the rear bumper of the white car.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated time frame from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature: *[Signature]*

Date & Time: 2:23pm

Signature: *[Signature]*

28/4/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature: *[Signature]*

Name:

NRIC/FIN No.:

[Signature]
PETHEN

Common Statement

ACCIDENT STATEMENT (Part I)

Reporting Centre: Progressive Automotive Pte Ltd

This is NOT an admission of blame / liability, but a summary of identities and facts which will speed up the settlement of claims.

1 Date of accident Time 1710		2 Exact location of accident MCE Exiting to ECP (Changi)		3 Injuries even if slight No ☒ Yes ☐	
4 Material damage To vehicles other than vehicles A and B No ☒ Yes ☐		To objects other than vehicles No ☒ Yes ☐		5 Witness' name, address and tel no. (to be underlined if helpful) Is passenger in vehicle A or vehicle B?	
				Vehicle Video Camera Available Yes ☐ No ☐	

Registration No. (VEHICLE A) **SDV2271H**

6 Insured / policyholder (see insurance cert.)
Name **Phn Song Wnr**
 (capital letters) **(Fu Chengwei)**

Address

NRIC / Passport no **S7102441E**

Tel no. (from 5am till 5pm)

HP **9687 6787**

7 Vehicle
Make, type **BMW 528i GT**
20

8 Insurance company
AAA ☒ C ☐ TPFT ☐ TPO

Does the policy cover damage to vehicle A?
 No ☐ Yes ☒

Policy No. **P1766736**

9 Driver ☒ Driver in Charge

Name
 (capital letters)

NRIC / Passport no.

Class of licence **3**

HP

Gender Male ☐ Female ☐

12 CIRCUMSTANCES
 Put a cross (X) in each of the relevant boxes applicable to your vehicle

☐	1 Collided into Bicycle
☐	2 Collided into Motorcyclist
☐	3 Collided into Parked Vehicle
☐	4 Collided into Pedestrian
☐	5 Collided into Property
☐	6 Collision - Change/Cross Lane
☐	7 Collision - Cross Junction
☐	8 Collision - Head on Collision
☐	9 Collision - Head to Rear
☐	10 Collision - Motor/Vehicle Hit
☐	11 Collision - Crossing Door of Vehicle
☐	12 Collision - Rear End
☐	13 Collision - In Turn
☐	14 Drink Driving / Drug Influence
☐	15 Fire, Explosion or Lightning
☐	16 Flood
☐	17 Hit and Run / Vandalism / Damaged whilst Parked
☐	18 Hit by Fallen Tree / Other Objects
☐	19 No Collision
☐	20 Tails Sweep
☐	21 Theft

State TOTAL number of boxes marked with a cross

Registration No. (VEHICLE B) **SFQ60634**

6 Insured / policyholder (see insurance cert.)
Name
 (capital letters)

Address

NRIC / Passport no

Tel no. (from 5am till 5pm)

HP

7 Vehicle
Make, type

8 Insurance company
☐ C ☐ TPFT ☐ TPO

Does the policy cover damage to vehicle B?
 No ☐ Yes ☐

Policy No. (if available)

9 Driver (See driving licence)
 (if different from insured B above)

Name
 (capital letters)

NRIC / Passport no.

Class of licence

HP

Gender Male ☐ Female ☐

10 Indicate the point of initial impact with an arrow (→)

11 Sketch of accident when impact occurred

Please indicate: 1. layout of the road - 2. the direction of vehicles A and B with arrows - 3. their positions at the time of impact - 4. the road signs - 5. names of the streets or roads

REFER TO ATTACHED

Obtain only glass mark reference to one of the punches on page 4

10 Indicate the point of initial impact with an arrow (→)

13 Visible damage to vehicle A

14 My remarks

15 Signatures of drivers

A

B

13 Visible damage to vehicle B

14 My remarks

* In the event of injuries or in the event of damage to property other than to vehicles A and B, give information overleaf

Do not alter anything in the statement after signing. Subsequently, each driver should take one copy

For insured's Individual Statement (Part II) see overleaf →

Individual Statement

Reporting Centre: Progressive Automotive Pte Ltd

INDIVIDUAL STATEMENT (Part II)		Own Workshop Email / Fax (if any)												
To be completed and submitted within 24 hours to your insurer or Idac or appointed workshop (Use a separate sheet of paper where necessary)														
Insured	1 Occupation (if more than one, state all)		Email: <u>patph@gmail.com</u>											
	2 Vehicle registration no.	<u>C.C.</u>	If commercial vehicle, state permissible carrying capacity											
	3 Is driver the owner?	Yes ☒ No ☐ If no, state relationship of driver with owner	state the vehicle number and name of owner of driver's own vehicle (where applicable)											
	4 Exact purpose for which vehicle was being used at time of accident	☐ Private use ☐ Commercial use ☐ Hire & reward ☐ Private Hire ☐ Others - please specify:												
	5 Is the vehicle still in use?	Yes ☐ No ☐ If no, state where it is at present	Tel no: _____											
Of which vehicle are you the owner?	6 Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ No ☐ <u>PMU</u>													
	If no, state action to be taken ☐ Third Party ☐ Reporting Only ☐ Third Party (Own Workshop)													
Driver or person in charge of vehicle at the time of accident (including insured)	7 Date of birth	Occupation	Date of license pass											
	<u>30/1/71</u>	<u>Indoor</u>	<u>13/10/89</u>											
	8 Give details of any pre-existing impairment of sight or hearing and of any other disability		Was vehicle driven with the insured's permission? Yes ☒ No ☐											
	9 Full details of all driving convictions including pending prosecutions in the last 36 months		Was driver an employee of the insured's company? Yes ☐ No ☒											
	<table border="1"> <thead> <tr> <th>Date</th> <th>Offence</th> <th>Penalty</th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> </tbody> </table>			Date	Offence	Penalty								
Date	Offence	Penalty												
Injured persons	10 Name(s), address(es) and approximate age(s)	Injuries sustained	If vehicle occupants, state in which vehicle											
Damage to property & vehicles (other than vehicles A and B)	11 Name(s) and address(es) of owner(s)	Vehicle registration no. or details of property	Nature of damage											
Police action	12 Was the accident reported to the Police? Yes ☐ No ☒													
	If yes, please state which Police station													
	13 Was notice of intended prosecution given? Yes ☐ No ☒													
	If yes, against whom?													
Accident details	14 Weather conditions	Clear ☐ Raining ☒ Others ☐												
	15 Road surface	Wet ☒ Dry ☐ Others ☐												
	16 Speed of vehicles	A ☐ km/hr B ☐ km/hr												
	17 What warnings were given by driver or other party?													
	18 Were street lights illuminated? Yes ☐ No ☐													
	19 What lights were displayed on your vehicle/the other vehicle(s)?													
	20 If your vehicle is commercial, state weight of load carried at time of accident													
	21 State how accident happened, width of roads, speed limits, etc. (Refer to attached)													
	22 State number of Passengers (including Driver) <u>0</u>													
Declaration	I/We declare the foregoing particulars are true in every respect													
	Policyholder's signature	<u>CP</u>	Date <u>28/4/18 2:23pm</u>											
	Driver's signature (if driver is not the policyholder)		Date											

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2441E
Vehicle Details	
Vehicle No.:	SDV2271H
Vehicle to be Exported:	No
Intended De-registration Date:	07 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	528i GT AT D/AB DSC LED SR NAV
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	B3121092N20B20A
Chassis No.:	WBASZ62020DZ35976
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$49,632.00
Original Registration Date:	28 Apr 2015
First Registration Date:	28 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$61,485.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2025
PARF Rebate Amount:	\$46,113.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$78,000.00
COE Rebate Amount:	\$53,415.00
Total Rebate Amount:	\$99,528.00

The information contained herein is correct as at 07 May 2018

OK

AXA INSURANCE PTE LTD
 8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Service Centre #B1-01
 Tel:(65)63387288 Fax:(65)63382522
 Website:www.axa.com.sg
 GST Registration Number: 199903512M
 customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO.	: VPA/P1766736	Account No. :	13854
Coverage	: Comprehensive		
Sum Insured	: Market Value At The Time Of Loss		
Name of Policy Holder	: POH SENG WEE		
Vehicle Registration No.	: SDV2271H		
Period of Insurance	: From 28/04/2017 To 27/04/2018 (Both Dates Inclusive)		

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
 The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
- (b) Any other person who is driving on the Policyholder's order or with his permission
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : SGD 500.00

An Additional Excess is applicable as follows:
 S\$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver.
 S\$5,000.00 for Undeclared Young and Inexperienced Driver.
 (Please refer to your policy on the terms & conditions)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SG0VCBP on 09/03/2017

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

DRIVER NRIC & LICENSE Pg. 1



Vehicle No. : SDV2271H
 Make/Model : BMW 528i GT
 Chassis No. : WBASZ62020DZ35976

No.	QTY	ITEMS	AMOUNTS (\$\$)
-----	-----	-------	----------------

PARTS LIST

1	1 pc	Bonnet			Repair	
2	1 pc	Bonnet center seal			\$	92.80
3	1 pc	Headlamp (Adaptive LED) RH			\$	4,304.00
4	1 pc	Frt fog lamp (LED) RH			\$	400.60
5	1 pc	Frt grille RH			\$	155.50
6	1 pc	Frt emblem			\$	71.20
7	1 pc	Frt bumper			\$	1,334.90
8	1 pc	Frt bumper tow cover			\$	42.70
9	2 pcs	Frt PDC sensor		\$ 381.20	\$	762.40
10	1 pc	Frt bumper nozzle cover RH			\$	48.36
11	1 pc	Frt bumper nozzle cover spring RH			\$	14.50
12	1 pc	Frt bumper nozzle spray			\$	140.10
13	1 pc	Frt bumper nozzle spray hose			\$	34.40
14	1 pc	Frt bumper nozzle spray hose joint			\$	36.90
15	2 pcs	Frt bumper side guide R/L		\$ 14.70	\$	29.40
16	2 pcs	Frt bumper bracket R/L		\$ 64.10	\$	128.20
17	1 pc	Frt bumper center grille			\$	90.30
18	1 pc	Frt bumper fog lamp garnish			\$	83.10
19	1 pc	Frt bumper fog lamp garnish chrome			\$	62.30
20	1 pc	Frt bumper absorber			\$	72.70
21	1 pc	Frt bumper carrier			\$	715.50
22	2 pcs	Frt bumper carrier bracket R/L		\$ 119.10	\$	238.20
23	2 pcs	Frt bumper bracket adapter R/L		\$ 62.80	\$	125.60
24	1 pc	Frt bumper lower beam			\$	184.30
25	1 pc	Frt support cover RH			\$	75.70
26	1 pc	Frt air duct cooler			\$	343.60
27	1 pc	Frt supprt upper joint front			\$	181.80
28	1 pc	Frt supprt upper joint rear			\$	208.80
29	1 pc	Frt headlamp support RH			\$	139.60
30	1 pc	Frt radiator support top			\$	61.20
31	2 pcs	Frt radiator support side R/L		\$ 88.62	\$	177.24
32	1 pc	Frt brake air duct RH			\$	60.30
33	1 pc	Frt air duct RH			\$	60.30
34	1 pc	Auxiliary radiator RH			\$	594.50
35	1 pc	Horn, high pitch			\$	101.50
36	1 pc	Horn, low pitch			\$	101.50
37	1 pc	Frt fender RH			\$	803.90
38	1 pc	Frt fender cowl RH			\$	148.80
39	1 pc	Frt fender cowl lower RH			\$	43.80
					\$	12,270.50
					Less 5%	\$ 613.53
					List Parts Sub-Total :	\$ 11,656.98

1	1 set	Frt no.plate			S/N	\$	50.00
2	1 pc	Radiator coolant			S/N	\$	80.00

Labour Charge

- 1 To check front affected electrical system and repair wire harness.
- 2 To remove and reinstall intercooler for necessary repair.
- 3 To remove and reinstall a/c condenser for necessary repair.
- 4 To remove and reinstall radiator assy for necessary repair.
- 5 To remove and reinstall RH auxiliary radiator for necessary repair.
- 6 To remove, replace/transfer front PDC sensor.
- 7 To straighten, repair, realign on affected area and replace damaged parts.
- 8 To spray painting on affected area.
- 9 To inspection, diagnose, reset and perform coding programming on:-
Front PDC control unit.
Calibrate/focus headlamp.

\$ ~~80.00~~ 30

\$ 60.00 *

\$ 120.00 *

\$ 100.00 *

\$ 60.00 *

\$ 40.00 ✓

\$ ~~1,200.00~~ 500

\$ ~~1,000.00~~ 500

\$ ~~300.00~~ 100

Total : \$ 14,746.98

15279.28

Adrian King.

P/P 04/05/18.

05 Days.

96893735

Supplementary: 1032.27

total: 10645 (P/P)

05 Days

Att: Catharine.

Vehicle No. : SDV2271H
Make/Model : BMW 528i GT
Chassis No. : WBASZ62020DZ35976

Supplementary parts

ESTIMATE COST OF REPAIRS TO VEHICLE SDV2271H.

No.	QTY	ITEMS	AMOUNTS (S\$)
-----	-----	-------	---------------

PARTS LIST

1	1 pc	Bonnet Lock <i>Damaged.</i>	\$ 184.00 ✓
2	1 pc	PDC wiring <i>snapped.</i>	\$ 104.95 ✓
3	1 pc	Nozzel cover bracket <i>Damaged.</i>	\$ 11.00 ✓
4	1 pcs	LED corner light <i>Damaged.</i>	\$ 786.65 ✓
			\$ 1,086.60
Less			5% 54.33
			\$ <u>1,032.27</u>

Service Request Details

Claim	S8M00FHM	Vehicle Information	
Reference	CS/ASM18008022/Attb Loss Date	Incident Vehicle	SDV2271H
		Registration #	51 Ubi
		Make	BMW
		Model	528I GT AT D/AB
			DSC LED
			Avenue 1 #01-25 Paya Ubi, , ,
			408933
		Primary Contact/Insured	
		POH SENG WEE	
		560 UPPER EAST COAST ROAD,	
		#02-02, 466580, Singapore	
		96876787	

Actions

Next Step

Finish the work

Complete Work

More

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
INVOICE & DV.msg	Forms / Claim Documents	Others	KUMAR Shailendra	June 25, 2018
RESURVEY PHOTO2.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	June 21, 2018
RESURVEY PHOTO.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	June 21, 2018
SDV2271 SUPPLEMENTARY.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	June 6, 2018
SDV 2271H photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	May 7, 2018
SDV 2271H MARKED ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	May 7, 2018
PRELI ADVISED SDV 2271H.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	May 7, 2018
GIA SGQ6063G TP.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	April 30, 2018

<<

Service Request Details

Claim	S8M00FHM	Vehicle Information	
Reference		Incident Vehicle	SDV2271H
CS/ASM18008022/AttLoss Date		Registration #	Make Service Address
			BMW 51 Ubi
April 27, 2018	Request Date	Model	528i GT AT D/AB DSC LED
May 9, 2018	Due Date	Avenue 1 #01-25 Paya Ubi, , , 408933	
May 2, 2019	Vendor Name	Primary Contact/Insured	
LKK AUTO CONSULTANTS PTE Loss LTD (OD)		POH SENG WEE 560 UPPER EAST COAST ROAD, #02-02, 466580, Singapore 96876787	
Own Damage	Services		

Actions

Next Step

Finish the work

Complete Work

More



SERVICE REQUESTS

MESSAGES

CLAIMS

◀◀ Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

General Details

Involving
1 2015 BMW 528I GT AT D/AB DSC LED (SDV2271H)

Date of Loss
April 27, 2018

Time of Loss
17.10

Loss Description
SDV2271H (INSD) HIT REAR OF SGQ6063G (TP)

Comment

Workshop Details

Total Rebate Amount

99528

Nett Loss Amount
\$55,472.00

Assigned Workshop
LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

05/09/2018 

Days of work completion *

7



SERVICE REQUESTS

MESSAGES

CLAIMS

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (OD) ▾



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SDV2271H

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

04/28/2015



Mileage

46959

Age of Vehicle

2

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT... 2015

CATEGORY Driver Name

ASSESSMENT INFO... 2015

FNOL INFORMATI... POH SENG WEE

POST SURVEY INF...

ASSESSMENT INFO... WBASZ62020DZ35976

CATEGORY	Engine No
POLICY INFORMAT...	B3121092N20B20A
ASSESSMENT INFO...	B3121092N20B20A

CATEGORY	Engine Capacity
POLICY INFORMAT...	
ASSESSMENT INFO...	1997 cc

CATEGORY	Sum Insured
POLICY INFORMAT...	0
ASSESSMENT INFO...	0

CATEGORY	Market Value
POLICY INFORMAT...	0
ASSESSMENT INFO...	155000

FNOL INFORMATI...	8
POST SURVEY INF...	
CATEGORY	Driver License #
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	License Type
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	License Issue Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy

CATEGORY	License Expiration Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy

CATEGORY	Address
----------	---------

POST SURVEY INF ...



SERVICE REQUESTS

MESSAGES

CLAIMS

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (OD) ▾



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

CONTINENTAL 6mm

Rear left side

CONTINENTAL 6mm

Front right side

CONTINENTAL 6mm

Rear right side

CONTINENTAL 6mm

SERVICE REQUESTSMESSAGESCLAIMS

<< Assessment Details

General & Workshop Details										Vehicle & Driver Details				Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
Act		Approve		Deny																					
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR / BTRK%	DISC CUNT%	SALV AGE%	PART PRICE(NET)	ACT (PART)											
	1	1			BONNET (NPA)			Repair	0		0		0	Rev											
	2	1			BONNET CENTER SEAL			Serviceable	0		0		0	Rev											
	3	1			HEADLAMP (ADAPTIVE LED) RH (DISC 5%)			Cracked	4088.8		0		4088.8	Rev											
	4	1			FRT FOG LAMP (LED) RH			Serviceable	0		0		0	Rev											
	5	1			FRT GRILLE RH (DISC 5%)			Cut	147.72		0		147.72	Rev											
	6	1			FRT EMBLEM (DISC 5%)			Necessary	67.64		0		67.64	Rev											
	7	1			FRT BUMPER (DISC 5%)			Damaged	1268.15		0		1268.15	Rev											
	8	1			FRT BUMPER TOW COVER			Serviceable	0		0		0	Rev											

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BITR%	DISC OUNIT%	SALV AGE%	PART PRICE(NET)	ACT (PAF)
	 18	1			FRT BUMPER FOG LAMP GARNISH			Serviceable	0		0		0	Rev
	 19	1			FRT BUMPER FOG LAMP GARNISH CHROME			Serviceable	0		0		0	Rev
	 20	1			FRT BUMPER ABSORBER (DISC 5%)			Cracked	69.06		0		69.06	Rev
	 21	1			FRT BUMPER CARRIER (DISC 5%)			Bent	679.72		0		679.72	Rev
	 22	1			FRT BUMPER CARRIER BRACKET R/L (O/S) (DISC 5%)			Damaged	113.15		0		113.15	Rev
	 23	1			FRT BUMPER BRACKET ADAPTER R/L (O/S) (DISC 5%)			Cracked	59.66		0		59.66	Rev
	 24	1			FRT BUMPER LOWER BEAM			Serviceable	0		0		0	Rev
	 25	1			FRT SUPPORT COVER RH (DISC 5%)			Cracked	71.92		0		71.92	Rev
	 26	1			FRT AIR DUCT COOLER			Serviceable	0		0		0	Rev

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACT (PAF)
	38	1			FRT FENDER COWLING RH			Serviceable	0		0	0	0	Rev
	39	1			FRT FENDER COWLING LOWER RH			Serviceable	0		0		0	Rev
	40	1			BONNET LOCK (DISC 5%)			Damaged	174.8		0		174.8	Rev
	41	1			PDC WIRING (DISC 5%)			Snapped	99.7		0		99.7	Rev
	42	1			NOZZLE COVER BRACKET (DISC 5%)			Damaged	10.45		0		10.45	Rev
	43	1			LED CORNER LIGHT (DISC 5%)			Damaged	747.32		0		747.32	Rev

Labour

Add Approve Deny			SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
			1		TO CHECK FRONT AFFECTED ELECTRICAL SYSTEM AND REPAIR WIRE HARNESS.	30	0	0	Reviewing	
			2		TO REMOVE AND REINSTALL INTERCOOLER FOR NECESSARY REPAIR.	0	0	0	Reviewing	
			3		TO REMOVE AND REINSTALL A/C CONDENSER FOR NECESSARY REPAIR.	0	0	0	Reviewing	
			4		TO REMOVE AND REINSTALL RADIATOR ASSY FOR NECESSARY REPAIR.	0	0	0	Reviewing	

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR	Reviewing	5		
		2	SET FRT NO. PLATE	Reviewing	50	BENT	
		3	RADIATOR COOLANT	Reviewing	0	NOT NECESSARY	

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$10,145.00	Claim Amount	\$10,145.00	

CATEGORY

ESTIMATE

REVISED AMOUNT

Labour

\$1,170.00

\$1,170.00

Miscellaneous

\$50.00

\$50.00

Excess

-\$500.00

-\$500.00

Submit for Review