

22/03/2002

ASS. REC. BY:

REF: CS3 / SM018008037 / G24621 Special Instruction:

Surveyor:

GID

ASSIGNMENT (Office)

From (Person):

Graue Ted

of

Gmo

Date/Time:

02052018 8:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 3027A

Insured:

SJA 76H

at Workshop m/s

J&E Automobile

Tel:

9457 1616

of

Bllc 9002 Tampines

Ind Park A #01-44

Policy No:

Claim No:

CMTD 1801839 / NSW

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3042018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

02052018 9:22am

Person Contacted:

Jimmy

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJU 3027A - X

SJA 76H - X

Dismantle part : 02.05.2018


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STU 3027A Yr Regn: Aug / 2009
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota Vios C.C. 1497
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 200168 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MR053HY9305141309

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 / 60 R 15
 R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front 5 mm R/Bal. 5 mm
 L/Bal. 5 mm
 D.O.A. 21.04.2018
 Survey held at J & E Automobile.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
Estimate repair range \$5,000 - \$6,000. (Bryan)

RECEIVED 19 JUL 2018

Date/Time. File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2Survey Fee: 100

Transportation: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

) \$ + RS \$

) Photos

) Others

Report Format: PRQ

Lump Sum / I.B.B. (\$)

TOTAL

100

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 2 May, 2018 8:45 AM
To: Mdm Ling; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Ngo, Sau Wei Shawn; Choo, Thelma; Ye, Yong Kang Melvin; lhling@tcmg.com.sg
Subject: CMTD1801839/NSW - PRI/ Accident invlg SJA76H & SJU3027A ON 29.04.2018
Attachments: TCMG.pdf

Our Reference: CMTD1801839/NSW

Your Reference: TCMG/ SJU3027A /0418/J&E

Without Prejudice

Date: 2nd May 2018

Attention:
M/S TOMMY CHOO, MARK GO LLC

Dear Mdm Ling,

ACCIDENT INVOLVING SJA76H & SJU3027A ON 29.04.2018

We refer to your email reply dated 30/04/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Mdm Ling [mailto:mdmling@tcmg.com.sg]

Sent: Monday, April 30, 2018 5:51 PM

To: Teo, Grace

Cc: Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; lhling@tcmg.com.sg

Subject: RE: CMTD1801839/NSW - PRI/ Accident invlg SJA76H & SJU3027A ON 29.04.2018

WITHOUT PREJUDICE

Dear Sirs,

We refer to the above matter and to your mail of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

Yours faithfully,

Mdm Ling

Tommy Choo Mark Go LLC

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Monday, April 30, 2018 5:07 PM

To: lhling@tcmg.com.sg; mdmling@tcmg.com.sg

Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1801839/NSW - PRI/ Accident invlg SJA76H & SJU3027A ON 29.04.2018

Our Reference: CMTD1801839/NSW

Your Reference: TCMG/ SJU3027A /0418/J&E

Date: 30th April 2018

Without Prejudice
EMAIL ONLY

Attention:

M/S TOMMY CHOO, MARK GO LLC

Dear Mr. Ling,

ACCIDENT INVOLVING SJA76H & SJU3027A ON 29.04.2018

We refer to your Notice of Accident dated 30/04/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18008037/Gz4be2		
50 RAFFLES PLACE #05-01/06		Date: 19-07-2018		
SINGAPORE LAND TOWERSINGAPORE 048623				
Code: SMO				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJA 76H	Veh. Inspected	SJU 3027A	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801839/NSW	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305141309	Colour	SILVER	
Odometer	200168 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	MICHELIN	5 mm	
L/H Front Tyre	185/60 R15	MICHELIN	5 mm	
R/H Rear Tyre	185/60 R15	MICHELIN	5 mm	
L/H Rear Tyre	185/60 R15	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	29/04/2018	Inspect Date / Time	02/05/2018 (05:33 PM)	
Survey held at	J & E AUTOMOBILE SERVICES 9002 TAMPINES INDUSTRIAL PARK A #01-44 SINGAPORE 528836			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/SMO18008037/Gz4be2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.