

INS. CASE OWNER:

CC 4/ASM1800

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lin:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

200

(\$

x 4 days)

Loss of Income (LOI):

SS

3

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

ABWIN SERVICE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:

X

3/12/18

REF: ASM (AXA)

8048 (unaz)

ASSIGNMENT

Front: Date: 03052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 7971U

at Workshop mis

Abwin Sernie

of

8 Kaka Bukit Ave 4

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Afternoon

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAR Accident Report:

Consistent? : Yes or No

O/S / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lump Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKX 79714 Yr Regn: 1215

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Honda Fit

cc 1317

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

43442

T/Radio: Insured / Std / NI / NA

Eng/No:

GK311.1 8937

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / A/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUNLOP / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front:

Rear:

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

28/4/18

D.O.I:

4/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: 5/5/18 Action/Instruction: confirmed LTA 49354 with Lmd. \$2200 1,600

photo 95040482 rear bumper

95040478 sport rim tyre

R (16,089.72/73%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) S + RS \$

1) Photos

1) Other

1)

TOTAL

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18008048/Uua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 02-05-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKB 262U	Veh. Inspected	SKX 7971U	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00FPM	Excess (\$)	0.00	
Assign From		Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/04/2018	Inspection Date	04/05/2018	
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 論輝

Date : 30/04/2018
TP Vehicle No. : SKB- 262-U
To : AXA INSURANCE SINGAPORE PTE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : HO WAI MUN
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5076478044-02
Vehicle No. : SKX-7971-U
Make & Model : HONDA FIT 1.3 G F-PACKAGE A

Accident Date: 29/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR BUMPER <i>Repair Decent</i>	\$710.30	X
1	REAR BUMPER RETAINER RH <i>11</i>	\$25.60	X
1	REAR BUMPER RETAINER LH <i>11</i>	\$25.60	X
10	REAR BUMPER CLIPS <i>new</i>	\$50.00	✓
1	REAR FENDER LH <i>2</i>	\$635.60	X
1	REAR FENDER INNER SHIELD LH <i>11</i>	\$35.60	X
10	REAR FENDER INNER SHIELD CLIPS LH <i>11</i>	\$50.00	X
1	REAR DOOR LH <i>20 / 1/2nd</i>	\$799.40	✓
1	LH REAR DOOR HINGE BOTTOM <i>11</i>	\$50.60	X
1	LH REAR DOOR WEATHERSTRIP <i>11</i>	\$85.00	X
1	LH REAR DOOR HINGE UPPER <i>11</i>	\$48.50	X
1	LH REAR DOOR CHECKER <i>11</i>	\$48.50	X
1	LH REAR DOOR PILLAR <i>NS</i>	\$709.60	X
1	LH REAR AXLE BEAM <i>11</i>	\$959.70	X
1	LH REAR AXLE BEAM BEARING <i>11</i>	\$281.90	X
1	LH REAR SHOCK ABSORBER MOULDING <i>11</i>	\$95.60	X
1	LH REAR SHOCK ABSORBER <i>11</i>	\$356.90	X
	Sub Total	\$4,968.40	
	Discount 20% on Parts	(\$993.68)	
		\$3,974.72	

Special Nett

1	LH REAR FENDER SEALANT <i>11</i>	\$65.00	X
	Sub Total	\$65.00	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00	550
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	800
TO TRANSFER AND REFIX DOOR FIXTURE	\$250.00	60
TO CONDUCT 4 WHEEL ALIGNMENT	\$250.00	60

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 30/04/2018
TP Vehicle No. : SKB- 262-U
To : AXA INSURANCE SINGAPORE PTE LTD
Attn : Motor Claim Department

Owner : HO WAI MUN
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5076478044-02
Vehicle No. : SKX-7971-U
Make & Model : HONDA FIT 1.3 G F-PACKAGE A

Accident Date: 29/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO REMOVE AND INSTALL TYRE AND BALANCING	11 \$150.00	X
	TO APPLY UNDERCOATING FOR RUST ROOFING	\$250.00	50
	TO CARRY OUT UNDERCARRIAGE REPAIR	11 \$350.00	X
	Sub Total	\$4,250.00	
	Sub Total	\$8,289.72	
	GST 7%	\$580.28	
	Total	\$8,870.00	

2109.52
415-17505

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 7/5/2018

Survey Details:

Date of loss	29-Apr-18
Date of appointment	2-May-18
Date of survey	4-May-18
Location of survey	Abwin Service Pte Ltd - Kaki Bukit

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKX 7971U
Make and Model	HONDA FIT 1.3G
Date of registration	29-Dec-15
Excess	
Market Value	\$ 68,000.00
Parf Rebate	\$ 49,354.00
Nett Loss	\$ 18,646.00

Repair details:

Initial Estimate	\$ 8,289.72
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,247.76
Check items (estimate)	\$ -
Labour	\$ 1,520.00
Total	\$ 2,767.76
Lump Sum(if applicable)	\$ 2,200.00

Number of days for repair	4 days
---------------------------	---------------

JKX 7971U

<<

DAMAGES

Type

 Question

Message

LOOKING AT INSPECTION PHOTOS PG 5, THE DAMAGES ON THE LEFT SIDE BUMPER DOES NOT SEEMS LIKE DEEP CUT BUT RATHER SCRATCHES. PLS CONFIRM AND UPLOAD PHOTOS SHOWING THE 'DEEP CUT'.

Reply

<< Re:Seeking for Mandate approval S8M00FPM

Type

🔔 Question

Message

PLS PROCEED AS RECOMMENDED

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/11/2018

Survey Details:

Date of loss	29-Apr-18
Date of appointment	2-May-18
Date of survey	4-May-18
Location of survey	Abwin Service Pte Ltd - Kaki Bukit

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SKX 7971U
Make and Model	HONDA FIT 1.3G
Date of registration	29-Dec-15
Excess	
Market Value	\$ 68,000.00
Part Rebate	\$ 49,354.00
Nett Loss	\$ 18,646.00

Repair details:

Initial Estimate	\$ 8,289.72
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 679.40
Check items (estimate)	\$ -
Labour	\$ 1,520.00
Total	\$ 2,199.40
Lump Sum(if applicable)	\$ 1,750.00

Number of days for repair	<u>4 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Ol confirmed that she was stationary inside the parking lot and waiting for other car park and TP passed by and graze against her vehicle. She have no evidence. We have uploaded voice recoded in SMART. We have not authorized repairs.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	1,712.00
Loss of use	\$	200.00 4 days x \$ 50
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	2.00
Others		
Proposed Total	\$	1,914.00

Your Ref:
Our Ref: AC18040031

20/11/2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Attn: Motor Claims Department

Dear Sirs,

ACCIDENT ON 29/04/2018 INVOLVING SKX-7971-U & SKB- 262-U BLK 423 JURONG WEST STREET 42 OPEN CARPARK

We are authorised repair workshop for the owner of vehicle, SKX-7971-U, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorised us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, SKB- 262-U, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repair	\$1,712.00
2. 0 days Car Rental x \$0.00	-
3. Loss of Use (4 x \$200.00)	\$800.00
4. Survey Fees	-
5. LTA Fees	-
6. TP/GIA Fees	\$2.00
7. Medical Fees	-
8. Others	-
(E&OE)	\$2,514.00

We enclose the following documents to support the claims:-

<input checked="" type="checkbox"/> Repair/Excess Bill	<input type="checkbox"/> GIA/Police Report(s)	<input type="checkbox"/> Power of Attorney	<input type="checkbox"/> Medical Bill
<input type="checkbox"/> Surveyor Report	<input checked="" type="checkbox"/> GIA/TP Search	<input type="checkbox"/> Car Rental Bill	<input type="checkbox"/> Witness Statement
<input type="checkbox"/> Coloured Photographs	<input type="checkbox"/> Insurance Certificate	<input type="checkbox"/> Others: _____	

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully,
ABWIN SERVICE PTE LTD



LINDA LIAO
Claims Department
E-mail: lindaliao@abwin.com.sg
DID: 67139417



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

24 MAY 2018

GONG XIUE

33 JURONG WEST STREET 41

#04-41

SINGAPORE 649413

Dear Sir/Madam,

OUR REF : CC4/ASM18008048/Uua3

YOUR REF : SKB 262U

**ACCIDENT INVOLVING SKB 262U AND SKX 7971U ALONG JURONG WEST AVE 1
CARPARK ON 29/04/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s **ABWIN SERVICE PTE LTD** acting on behalf of the owner of SKX 7971U against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 07 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to thinthin@lkkauto.com within 07 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at thinthin@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

THIN THIN HLAING
LKK Auto Consultants Pte Ltd
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

Cc AXA Insurance Pte Ltd
(Motor Claims Dept)

Date: 03/29/18From: HO WAI MUN (Name of Policyholder)My Vehicle No.: SKX-7971-UOther Vehicles: SKB-262-UAccident Date: 29/04/2018Location: BLK 423 JURONG WEST STREET 42 OPEN CARPARK**LETTER OF AUTHORISATION**To: AXA INSURANCE SINGAPORE PTE LTD (Third Party and/or Third Party Insurer)

I have authorised ABWIN SERVICE PTE LTD to proceed with the repairs to my accident damaged vehicle and to proceed with 3rd Party Insurance Claims against Third Party and / or its Insurer on my behalf for property damages, costs, and expenses, including loss of use, loss of rental, medical fees and legal costs.

To have absolute discretion to agree to any settlement of compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).

As ABWIN SERVICE PTE LTD will be handling the entire 3rd Party Claims, which includes signing / submission of all relevant documents and negotiation of my claims on my behalf, kindly forward and make payable all proceeds of my claims to **ABWIN SERVICE PTE LTD**.

I confirm that the payment of any negotiated settlement with and accepted by ABWIN SERVICE PTE LTD will serve as an effectual discharge of my claims against the Third Party and / or its Insurer for the damage caused.

ABWIN 論輝

ABWIN SERVICE PTE LTD
8 Kaki Bukit Avenue 4 #07-48
Premier @ Kaki Bukit Gate 2
Singapore 415875
Tel: 67139400 Fax: 65 67139415

Policyholder's Signature / Company's Stamp (if applicable)

Name: Ho Wai MunNRIC No./ROC No.: S1687100A

Designation: _____

Witness's Signature

Name: LindaNRIC No.: S8188387D



redefining / insurance

CLAIM REF : S8M00FPM
INSURED : GONG XIUE

DISCHARGE VOUCHER

We/I HO WAI MUN, NRIC NO. S1687100A hereby agree to accept the sum of dollars One Thousand and Nine Hundred Only (S\$ 1,900.00) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for ~~personal injuries~~ and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SKB262U as a result of an accident along BLK 423 JURONG WEST STREET 42 OPEN CARPARK on 29/04/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SKX7971U.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SKB262U in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SKB262U.

Dated this 26TH day of November 2018

Claimant's Signature

[Signature]

NRIC no./ Company Stamp

S1687100A

Occupation/ Business

Engineer

Address

BLK 475 #06-388, Jurong West 8441, S640475

Telephone No.

96951441

Witness's Name

Linda Liao

Witness's Signature

[Signature]

Witness's NRIC No.

S8188387D

TAX INVOICE**INV18110012****To:** AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811**Date:** 20/11/2018
Vehicle No.: SKX-7971-U
Make: HONDA
Model: FIT 1.3 G F-PACKAGE A**Attention:****Date of Accident:** 29/04/2018

S/N	DESCRIPTION	QTY	AMOUNT (\$\$)
1	BEING SUCCESSFUL CLAIM FOR VEHICLE NO. SKX-7971-U ACCIDENT ON 29/04/2018 AS FOLLOWS :-		
2	REPAIR COSTS	1.000	\$1,600.00

SUB TOTAL \$1,600.00
7% GST \$112.00
TOTAL \$1,712.00**Remarks:**Payment by cheque should be crossed and made payable to **ABWIN SERVICE PTE LTD.**

For ABWIN SERVICE PTE LTD



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-065014
Date of Request: 30/04/2018

Your Ref No: Online Purchase

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Dear Sir/Madam,

Enquiry Date: 30/04/2018
Enquiry By: Linda Liao
TP Vehicle No.: SKB262U
Accident Date: 29/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKB262U	AXA Insurance Pte Ltd	17/09/2017-16/09/2018	8338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

SKX 79714
SR48960

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-085014
Date of Request: 30/04/2018

Your Ref No: Online Purchase

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Dear Sir/Madam,

Enquiry Date 30/04/2018
Enquiry By Linda Liao
TP Vehicle No. SKB262U
Accident Date 29/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKB 262U (Insd veh)	Model:	HONDA FIT (A)
	SKX 7971U (TP veh)		
Date of Accident:	29/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	8,870.00
Final Repair Cost	:	\$	1,712.00
Loss of Use	:	\$	200.00
Rental (if any)	:	\$	4days at \$50.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	1,900.00

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	ABWIN SERVICE PTE LTD	:	\$ 1,900.00

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

05/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008048/Uja3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 05-12-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 262U	Veh. Inspected	SKX 7971U
Policy No.	GA121668	Coverage (\$)	0.00
Claim No.	S8M00FPM	Excess (\$)	0.00
Assign From		Assign Date	02/05/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT (A)	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	GK31118937	Colour	WHITE
Odometer	43442	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	DUNLOP	7 mm
L/H Front Tyre	175/70 R14	DUNLOP	7 mm
R/H Rear Tyre	175/70 R14	DUNLOP	7 mm
L/H Rear Tyre	175/70 R14	DUNLOP	7 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	29/04/2018	Inspection Date	04/05/2018
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 7971U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEEP CUT	710.30	710.30
1	REAR BUMPER RETAINER RH (CONSISTENT)	NOT NECESSARY	25.60	-
1	REAR BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	25.60	-
10	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	635.60	-
1	REAR FENDER INNER SHIELD LH (CONSISTENT)	NOT NECESSARY	35.60	-
10	REAR FENDER INNER SHIELD CLIPS LH (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR DOOR LH (CONSISTENT)	DENTED / BENT	799.40	799.40
1	LH REAR DOOR HINGE BOTTOM (CONSISTENT)	NOT NECESSARY	50.60	-
1	LH REAR DOOR WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	85.00	-
1	LH REAR DOOR HINGE UPPER (CONSISTENT)	NOT NECESSARY	48.50	-
1	LH REAR DOOR CHECKER (CONSISTENT)	NOT NECESSARY	48.50	-
1	LH REAR DOOR PILLAR (CONSISTENT)	NO SUCH PARTS	709.60	-
1	LH REAR AXLE BEAM (CONSISTENT)	NOT NECESSARY	959.70	-
1	LH REAR AXLE BEAM BEARING (CONSISTENT)	NOT NECESSARY	281.90	-
1	LH REAR SHOCK ABSORBER MOULDING (CONSISTENT)	NOT NECESSARY	95.60	-
1	LH REAR SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	356.90	-
	LESS 20% DISCOUNT		-993.68	-311.94
			3,974.72	1,247.76
SPECIAL NETT ITEMS				
1	LH REAR FENDER SEALANT (SN) (CONSISTENT)	NOT NECESSARY	65.00	-
			65.00	-
LABOUR				
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.		1,500.00	550.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,500.00	800.00
	TO TRANSFER AND REFIX DOOR FIXTURE.		250.00	60.00
	TO CONDUCT 4 WHEEL ALIGNMENT.		250.00	60.00
	TO REMOVE AND INSTALL TYRE AND BALANCING.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING FOR RUST ROOFING.		250.00	50.00

Report Ref No. CC4/ASM18008048/Uja3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT UNDERCARRIAGE REPAIR.	NOT NECESSARY	350.00	-
			4,250.00	1,520.00
GRAND TOTAL			8,289.72	2,767.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CC4/ASM18008048/Uja3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SBA000FTM
Reference	CC4/ASH18006046/0ja3c2
Loss Date	29 April 2018
Request Date	2 May 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	S007971U
Make	TPVO HONDA
Model	FT1-1.3 (A)
Service Address	
...	
Primary Contact/Insured	
GONG XIUE 33 JURONG WEST STREET #1, #04-41, 649413, Singapore	
alexchua757@gmail.com	
Claim Handler	
CHAN Kian Chuan 6568804269 kianchuan.chan@axa.com.sg	

Additional InstructionsNON-REPORTED















MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes







Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice-1 (4).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 LETTER TO O.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2018
 RE-INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 November 2018
 Immediate Advice and Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2018
 LOD AXA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 November 2018
 Immediate Advice.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 November 2018
 WhatsApp Audio 2018-07-08 at 11.23.mp4	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 November 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPDATED
 Mark Estimate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 November 2018
 Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 May 2018
 Estimate marking.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 May 2018
 LKK Inspection Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 May 2018
 EMAIL RECIEVED FROM WORKSHOP WITH ESTIMATE AND GIA REPORT.png	Other	Other	DHAWA Namrata	2 May 2018
 OI GIA REPORT.pdf	Reports & Statement	GIA Report	CHAN Kian Chuan	2 May 2018