

ASS. REC. BY:

REF:

CS/EG118008074 / Mitben

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Yee Pei Li of EG1 Date/Time: 03052018 11:40am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLA 851m Insured: G88 4125mat Workshop m/s Borneo Motor Tel: 9847 6171of 2 Pandan CrescentPolicy No: _____ Claim No: G884125m/SL/pl

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26042018
(Client's Record)CA / REV / REP. / REV 24 HRS 'DS' 14-052018 @ 10am-12pmDate/Time: 03052018 1:04pm H.O.D. Endorsement: _____Person Contacted: Thomas Vehicle: IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SLA 851m - X</u>
	<u>G88 4125m - X</u>
	<u>Part by Part \$3549.75 (Red. 117.20 !24%)</u>

REF: ETL

ASSIGNMENT

From: Date: 14052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 881M

at Workshop m/s

of

Borneo motor
2 Pandan crescent

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Thomas

10am - 12pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'OS'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLA 881M, Yr Regn: FEB 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA AURA

C.C. 1598

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading:

45807

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WRO3REH164544601

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55/16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sumi

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 22 JUN 2018

Date/Time. File Pass to?

22/6 Typist

Date/Time. File Return to?



Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + PS \$

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum (B.I) (\$ 3549.75)

250

250

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 3 May, 2018 11:40 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GBB4125M / TP : SLA851M/LKK / DOA : 26/04/2018
Attachments: GBB4125M - SAS.pdf; SLA851M - SAS.pdf; SLA851M - ESTIMATE.pdf; SLA851M - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **INCHCAPE - BORNEO MOTORS (S) PTE LTD**,

ADDRESS : 2 PANDAN CRESCENT
INCHCAPE CENTRE LEVEL 4
SINGAPORE 128462

PERSON TO CONTACT : THOMAS PANG @ 9847 6171 / 6631 1860

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop..

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and Third Party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBB4125M/SL/pl

Date:22/5/2018

Our Ref: CS/EGI18008074/M1tb

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SLA 851M .

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 14/5/2018 at the premises of M/s Borneo Motors and have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,721.25</u>
Revised Estimate Amount	: S\$ <u>3,549.25</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
At rear portion.



Repair days: 3 Days

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Ma CF
Automotive Assessor

ERGO

Date: 02.05.2018
Our Reference: GBB 4125M/SL/pl
Your Reference: SLA 851M

Sent via Fax

or

Email

Siti.Nabilah@inchcape.com.sg

To: **INCHCAPE - BORNEO MOTORS (S) P/L**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLA 851M
Insured's Vehicle: GBB 4125M
Date Of Accident: 26.04.2018

We acknowledge receipt of your request for PRS on: 30.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.


* LKK AUTO

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☐ Our Insured's driver has not reported the accident to us todate.

✓

Others: **We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - STEVE LIM**

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 22 May 2018 2:45 PM
To: Admin-D (LKKAUTO); 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; assignments
Subject: RE: GBB4125M / TP : SLA851M/LKK / DOA : 26/04/2018
Attachments: PRELI ADVISED SLA 851M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLA 851M**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 3 May 2018 1:05 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: GBB4125M / TP : SLA851M/LKK / DOA : 26/04/2018

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Thursday, 3 May, 2018 11:40 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBB4125M / TP : SLA851M/LKK / DOA : 26/04/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **INCHCAPE - BORNEO MOTORS (S) PTE LTD,**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/04/2018 14:51
Date Of Accident	26/04/2018 18:30
Exact Location Of Accident	SLIP RD OF WOODLANDS RD TWD SENJA WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA851M
Insured/Policyholder	
Name Of Registered Owner	LIN LAN
NRIC No	S2660976C
Email Address	LINLAN@JEL.COM.SG
Mobile Phone No	(LOCAL) +65-96162901
Alternative Phone No	OFFICE-96162901

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPAP2031651
Cover Note Number	

Driver

Name of Driver	LIN LAN
NRIC No	S2660976C
Date Of Birth	31/10/1967
Occupation	INDOOR
Date Of Driving Pass	05/02/2004
Driving Experience	14 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96162901
Fax Number	
Contact Number	OFFICE-96162901
EEmail Address	LINLAN@JEL.COM.SG

Address	BLK 32 SEGAR RD #15-23
Postcode	677722
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB4125M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YE KYAW THU
NRIC/Passport Number	G5891711M
Contact Number	
Address	
Postcode	
Insurance Company Name	ERGO INSURANCE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

Sketch Plan



Describe Circumstances of the Accident

My vehicle was stationary along Slip Road of woodlands Road towards Senja Ways to wait for oncoming vehicle to clear. While there is no oncoming vehicle, I proceed to move. Suddenly a vehicle G1313 4125m hit my vehicle from behind.

Witnessed by Reporting Centre
Personnel



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 8631 1188

Account Detail	Account No	Customer Detail
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICN13 Document No 0 Document Date 27/04/2018	Mdm Lin Lan 32 Segar Road #15-23 Singapore 677722 Mobile: 96162901

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	22/02/2016	SLA0851M	0	30715 72/DS/SLA0851M
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104544601	12RX548318	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:ERGO INSURANCE TP VEH:GGB4125M DATE OF ACC:26.04.2018				100.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N ETT)				154.00
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET T)				154.00
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				616.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1272.00
6	B	BP-RES RESPRAY ACC AFFECTED AREAS				1012.00
7	1	SPZ061-12021 76 BACK SENSOR 1F9 310A	1.00	159.75		159.75
8	2	S52159-02904 COVER, RR BUMPER	1.00	539.90		539.90
9	3	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70		105.70
10	4	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30		58.30
11	5	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70		105.70
12	6	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30		58.30
13	7	S52023-02190 REINFORCEMENT, RR	1.00	386.60		386.60
14	8	S52161-OK040 PIECE, RR BUMPER	10.00	3.90		39.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	LKK Auto Consultants hence notify the Repairer of the following • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	4,721.25 GST 7.00% 330.49 Less 0.00 Amount Due 5,051.74

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME
27/04/2018
17:27

VEHICLE NO
SLA0851M

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462

Tel no.: 6631 1188
Customer Detail

ESTIMATE

Account Detail	Account No	
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICN13 Document No 0 Document Date 16/05/2018	Mdm Lin Lan 32 Segar Road #15-23 Singapore 677722 Mobile: 96162901

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	22/02/2016	SLA0851M	42716	30715 72/DS/SLA0851M
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MR053REH104544601 1ZRX548318 60 Thomas Pang W T 14/05/2018 8.00 16/05/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:ERGO INSURANCE TP VEH:GBB4125M DATE OF ACC:26.04.2018 BY:LKK @ 14.05.2018 03 WORKING DAYS				50.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N 29 ETT)				154.00
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET 29 T)				154.00
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT) 18				616.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS 29 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				616.00
6	B	BP-RES RESPRAY ACC AFFECTED AREAS *				506.00
7	1	SP2061-12021 76 BACK SENSOR 1F9 310A	1.00	159.75		159.75
8	2	S52159-02904 COVER, RR BUMPER	1.00	539.90		539.90
9	3	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70		105.70
10	4	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30		58.30
11	5	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70		105.70
12	6	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30		58.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3668390

TO SECURITY GUARD

3668390

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 16/05/2018
13:45

VEHICLE NO

SLA0851M

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICNI3 Document No 0 Document Date 16/05/2018	Mdm Lin Lan 32 Segar Road #15-23 Singapore 677722 Mobile: 96162901

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	22/02/2016	SLA0851M	42716	30715 72/DS/SLA0851M
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MRO53REH104544601	1ZRX548318	60	Thomas Pang W T	14/05/2018	8.00	16/05/2018	18.00
-------------------	------------	----	-----------------	------------	------	------------	-------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	7	S52161-OK040	10.00	3.90		39.00
14	8	S52023-02190	1.00	386.60		386.60
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour 1,453.25 Materials 2,096.00 Lubrication/Fluid 0.00 Others 0.00	3,549.25
			GST 7.00% 248.45 Less 0.00 Amount Due 3,797.70

PLEASE TEAR ALONG PERFORATED LINE

3668391

3668391

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/05/2018
TIME 13:45

VEHICLE NO

SLA0851M

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EG18008074/M1tbe2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 29-06-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 4125M	Veh. Inspected	SLA 851M	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBB4125M/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	03/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104544601	Colour	GREY	
Odometer	45807	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	8 mm	
L/H Front Tyre	205/55 R16	DUNLOP	8 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	8 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2018	Inspection Date	14/05/2018	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 851M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRY (SN)	NECESSARY	100.00	50.00
1	BACK SENSOR 1F9 310A (SN)	NECESSARY	159.75	159.75
1	COVER, RR BUMPER (SN)	NECESSARY	539.90	539.90
1	RETAINER, RR BUMPER L (SN)	NECESSARY	105.70	105.70
1	RETAINER, RR BUMPER L (SN)	NECESSARY	58.30	58.30
1	RETAINER, RR BUMPER R (SN)	NECESSARY	105.70	105.70
1	RETAINER, RR BUMPER R (SN)	NECESSARY	58.30	58.30
1	REINFORCEMENT, RR (SN)	NECESSARY	386.60	386.60
10	PIECE, RR BUMPER @\$3.90 (SN)	NECESSARY	39.00	39.00
			1,553.25	1,503.25
LABOUR				
	DRILL HOLE AND INSTALL REVERSE SENSOR.		154.00	154.00
	CHECK WIRING AND CONDUCT WATER TEST.		154.00	154.00
	TO RESET ECU AND REPROGRAMME.		616.00	616.00
	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN ACC AFFECTED AREAS.		1,232.00	616.00
	RESPRAY ACC AFFECTED AREAS.		1,012.00	506.00
			3,168.00	2,046.00
GRAND TOTAL			4,721.25	3,549.25
RECOMMENDED COST OF REPAIRS				3,549.25

Report Ref No. CS/EG18008074/M1tbe2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.