

ASS. REC. BY:

REF: CS/FC118008078/Urb22

Special Instruction:

Surveyor

Marcus

ASSIGNMENT (Office)

From (Person): (WS Luene Jan)

of

FCL

Date/Time: 03052018 1129am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 1362L

Insured:

SHB 3468J

at Workshop m/s

Ben Hook Hin

Tel:

of

No. 6 Defu Lane 4

Policy No:

Claim No:

D18003627MTSH

Sum Insured:

Excess:

D.O.A. 21042018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

'api

04052018

H.O.D. Endorsement:

Date/Time:

03052018 1pm

Person Contacted:

Raymond

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

FBL 1362L - x

SHB 3468J - PC4 / AXA / 7015749 / Klwb342

DET: 110317

07/5/18 @ 4.53pm revised to Luene by email.

(08/11/13) Wef
ASS. REC. BY: *Marcus*

REF:

FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *F3L 1362L*

at Workshop m/s *SMH*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *9500*

IDAC Accident Report: _____ Consistent? : Yes or No

GA / PR Seen: *2* Consistent? : Yes or No

Est. Repairs: *3* days Res.: Yes or No

Lum Sum: *131* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction *LTA 5126*

15/5/18 confirmed final by 528.60 with Raymond
checked by 2006.70, 7901.2

Veh No: *F3L 1362L* Yr Regn: *6 18*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Yamaha 4BR25* c.c. *124*

Colour: *Red* A/C: Insured / Std / NI / NA

Sp. Reading: *92081* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *L3PRE 101000057362*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *2.75-18*

R: *3.00-18*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *metre*

Front *6* mm Rear *6* mm

R/Bal. *6* mm L/Bal. *6* mm

L/Bal. *6* mm D.O.I. *4/5/18*

D.O.A. *21/4/18* Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

LH, 0153.5

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

11/5/18

Date/Time, File Return to?

2)

☐ : Prel. Report

☐ : Final Report

Days Of Repair: *3*

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS. SI

Photos

Others

TOTAL

110

50

50

46

256

Report Format: *TP*

Lump Sum / I.B.I. (\$) *528.60*

MOTOR SURVEY ASSIGNMENT

Date	02-05-2018	Our Ref No. D18003427MFSH
Accident Date	21-04-2018	Claim Type. Third Party
Insured Vehicle	SHB3468J	Third Party Vehicle. FBL1362L
Survey Location	NO. 6 DEFU LANE 4	
Contact Person.	RAYMOND	
Contact No.	62816520/ 62816520	Fax No. 62812830
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BAN HOCK HIN CO. PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 7 May 2018 4:53 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003427MFSH/1
Attachments: CSFCI18008078Uqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of FBL 1362L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 3 May 2018 1:02 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003427MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 3 May, 2018 11:29 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003427MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003427MFSH

Date: 07 May 2018

Our Ref: CS/FCI18008078/Uqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBL 1362L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/05/2018 at the premises of M/s BAN HOCK HIN, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,290.00 .
Revised Estimate Amount	: S\$ 452.10 .
"Check" Items Amount	: S\$ 1,489.50 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front portion & o/s body.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0288K

Vehicle Details

Vehicle No.:	FBL1362L
Vehicle to be Exported:	No
Intended De-registration Date:	04 May 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	E3F5E042526
Chassis No.:	LBPREF101000057362
Maximum Power Output:	-
Open Market Value:	\$1,883.00
Original Registration Date:	23 Jun 2016
First Registration Date:	23 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$283.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	22 Jun 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,303.00
COE Rebate Amount:	\$5,126.00
Total Rebate Amount:	\$5,126.00

The information contained herein is correct as at 04 May 2018

OK

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	FBL1362L		
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	YAMAHA		
Vehicle Model:	YBR125		
Chassis No.:	LBPREF101000057362		
Propellant:	Petrol		
Engine No.:	E3F5E042526		
Engine Capacity:	124 cc		
Maximum Power Output:	-		
Maximum Laden Weight:	320 kg		
Unladen Weight:	114 kg		
Year Of Manufacture:	2016		
Original Registration Date:	23 Jun 2016		
Lifespan Expiry Date:	-		
COE Category:	D - Motorcycle		
Quota Premium:	\$6,303.00		
COE Expiry Date:	22 Jun 2026		
Road Tax Expiry Date:	22 Jun 2018		
Inspection Due Date:	22 Jun 2019		
Intended Transfer Date:	04 May 2018		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 22 Jun 2018. You may renew the road tax from 23 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 22 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 23 Jun 2018 to 22 Dec 2018)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			32.00
Nett Road Tax Amount (After Offsetting Over Payment):	32.00		57.00
Total Amount Payable:			
Amount Payable (From 23 Jun 2018 to 22 Jun 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			64.00
Nett Road Tax Amount (After Offsetting Over Payment):	64.00		89.00
Total Amount Payable:			

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/04/2018 14:11
Date Of Accident	21/04/2018 15:10
Exact Location Of Accident	ALONG COMPASSVALE BOW OUTSIDE OF BLK 264B
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL1362L
Insured/Policyholder	
Name Of Registered Owner	BAN HOCK HIN COMPANY PRIVATE LIMITED
Co Reg No	197000288K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82626668

Vehicle Particulars

Manufacturer	YAMAHA
Model	YBR125
Exact Purpose for which vehicle was being used at time of accident	MOTORCYCLE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	AVFMSB0000591702
Cover Note Number	

Driver

Name of Driver	WANG GANGPING
Passport No/FIN	G2852676N
Date Of Birth	12/05/1989
Occupation	OUTDOOR
Date Of Driving Pass	28/03/2017
Driving Experience	1 YEAR AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82626668
Fax Number	
Contact Number	
Email Address	SKRV@SG.MCD.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was traveling along Compassvale Bow when a taxi SHB3468J came out from Blk 264B carpark making a right turn. I brake but due to wet road surface, i could not stop on time and collided onto the taxi right rear side. I then fell to the right side.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB3468J
Vehicle Make/Model/Colour	HYUNDAI/i40 1.7L CRDI AT ABS AIRBAG 4DR/YELLOW
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	AH SENG
NRIC/Passport Number	S1775809H
Contact Number	82016286
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
 I understand, acknowledge, agree and consent that:
 (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 (ii) investigating the accident and/or my claims;
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS**REPORTING OFFICER**

Muhammad Faizal

Bin Pabila

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel**Sketch Plan**

ACCIDENT STATEMENT (2000 characters)

I was traveling along Compassvale Bow when a taxi SHB3468J came out from Blk 264B carpark making a right turn. I brake but due to wet road surface, i could not stop on time and collided onto the taxi right rear side. I then fell to the right side.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

22 April 2018 at 11:12 AM

Date/Time:

22 April 2018 at 11:12 AM

MOTOR CYCLE R

CERTIFICATE OF INSURANCE

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189) OF THE REPUBLIC OF SINGAPORE
THE ROAD TRANSPORT ACT 1987 OF MALAYSIA
THE AGREEMENT BETWEEN THE MINISTER FOR FINANCE (SINGAPORE) AND THE MOTOR INSURERS' BUREAU OF SINGAPORE DATED 22 FEBRUARY 1975
THE AGREEMENT BETWEEN THE MINISTER OF TRANSPORT (MALAYSIA) AND THE MOTOR INSURERS' BUREAU OF WEST MALAYSIA DATED 15 JANUARY 1968
ANY SUBSEQUENT REVISIONS TO THE ABOVE ACTS AND AGREEMENTS

MYH
E SB
A593SD0
Cov.Type: T
KSXT3SB

CERTIFICATE No.

AVFMSB0000591601

ChaNo: LBPRI01000057362

1. Index Mark and Registration
Number of Vehicle

FBL 1362 L

2. Name of Policyholder

BAN HOCK HIN CO PTE LTD

3. Effective Date of Commencement of Insurance
for the purposes of the Ordinance

25 June 2016

09 April 2017

4. Date of Expiry of Insurance

5. Persons or Classes of Persons entitled to drive* (For certificate references MX1 and MX4, see overleaf)

ANY PERSON WHO IS UNDER THE POLICYHOLDER &/OR HIRER'S EMPLOYMENT AND IS DRIVING ON THEIR ORDER OR WITH THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use* (For certificate reference MX1, see overleaf)

USE ONLY FOR THE POLICYHOLDER &/OR HIRER'S BUSINESS OR PROFESSION.

THE POLICY DOES NOT COVER:

1. USE FOR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING.
2. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING (OTHER THAN FOR REWARD) OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.
3. USE FOR THE CARRIAGE OF PASSENGERS FOR HIRE OR REWARD BY ANY PERSON TO WHOM THE VEHICLE IS HIRED.

Type of Cover : Third Party

* Limitations rendered inoperative by Section 79 of the Road Traffic Ordinance 1958 (Malaysia) or Section 7 of the Motor Vehicle (Third-Party Risks and Compensation) Ordinance 1960 (Republic of Singapore) are not to be included under the headings.

I/WE HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and The Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Republic of Singapore)



Approved Insurers

Examined By



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

NO. : 32568

- Rev. 1

DATE : 02/05/2018
CLAIM NO. : 11136
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

VEHICLE NO. : FBL1362L
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY / FRAME P/N: 29844 - REAR BODY	Repair	1.00	\$70.00	70.00
2	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00
3	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00	55.00
4	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	4.00	\$35.00	140.00
5	LAMP SIGNAL REAR RH P/N: 45419	REPLACE	1.00	\$63.00	63.00
6	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$20.00	20.00
7	MIRROR RH P/N: 26503	REPLACE	1.00	\$15.00	15.00
8	PIPE EXHAUST ASSY P/N: 50025	REPLACE	1.00	\$1,655.00	1,655.00
9	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
10	SPRAY PAINTING (RH Tail Cover)	Spray	1.00	\$28.00	28.00
11	TRANSPORT CHARGES P/N: 07169 - TOW BACK BIKE FOR ACCIDENT REPAIR.	Supply/Install	1.00	\$35.00	35.00

SUB TOTAL
GST @ 7 %

\$2,290.00
\$160.30



P-299

P-384
345-60



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830. (Spare Parts) +65 6285 7530. (Insurance/Project) +65 6284 2969. (Accounts) +65 6281 6759

CERT NO: 23024-0303
ISO 9001: 2008

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL					\$2,450.30

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

NO. : 32612

Supplementary 1 To QTN: 32568

DATE : 14/05/2018
CLAIM NO. : 11136
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

VEHICLE NO. : FBL1362L
MAKE/MODEL : YAM / YBR125

S/N	Description	Action	Qty	Unit Price	Amount
1	PROTECTOR EXHAUST P/N: 55580	Replace	1.00	\$85.00	85.00
SUB TOTAL					\$85.00
GST @ 7 %					\$5.95
GRAND TOTAL					\$90.95

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0303
ISO 9001: 2008



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18008078/Uqbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3468J	Veh. Inspected	FBL 1362L
Policy No.		Coverage (\$)	0.00
Claim No.	D18003427MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	03/05/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHA YBR125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	LBPREF101000057362	Colour	RED
Odometer	92081	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	2.75-18	METZELER	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.00-18	METZELER	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/04/2018	Inspection Date	04/05/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 1362L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	CRASH BAR	BENT	195.00	195.00
1	FOOT REST 1	BENT	55.00	55.00
1	LAMP SIGNAL REAR RH	SERVICEABLE	63.00	-
1	LEVER BRAKE	CUT	20.00	20.00
1	MIRROR RH	CUT	15.00	15.00
1	PIPE EXHAUST ASSY	TO REPAIR SEE LABOUR	1,655.00	-
1	RUBBER FOOTREST FRONT	TORN	14.00	14.00
1	PROTECTOR EXHAUST (ADDITIONAL)	DISTORTED	85.00	85.00
	LESS 10% DISCOUNT		-	-38.40
			2,102.00	345.60
	<u>LABOUR</u>			
	ALIGNMENT BODY/FRAME-REAR BODY.	NOT NECESSARY	70.00	-
	LABOUR INCLUSIVE OF THE REPAIR OF PIPE EXHAUST ASSY.		140.00	120.00
	SPRAY PAINTING (RH TAIL COVER).	RESPRAY	28.00	28.00
	TRANSPORT CHARGES -TOW BACK BIKE FOR ACCIDENT REPAIR.		35.00	35.00
			273.00	183.00
	GRAND TOTAL		2,375.00	528.60
RECOMMENDED COST OF REPAIRS				528.60

Report Ref No. CS/FC118008078/Uqbe2

CHUA KANG SENG

Licensed Appraiser

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.