

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SLW5145U

Tan Siao Yuen (chen Xiaoyan)

53 Hume Avenue #04-05 Singapore 598751 Vehicle & Document Information

WIP No

Reg No/Reg Date

23297

SLW5145U / 19/02/2018

Date In/Mileage

Chassis No

WDD2050402R360133

Engine No

27491031236818

Make/Model Colour/Trim

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A 021 197 Obsidian B1/ 041 118 ARTICO Leat

Account No Terms Date/Time Printed CSE Operator WCV34166 **CRDVCH** 02/05/2018/ 18:36 YK 395 / Yik Chan Hoe

Description of Goods / Services Qty Unit Price Disc% M. BPNSUN POLICY NO/ACC DATE : 1800014762 // 02/05/2018 : 02/05/2018 // TP VEH NO SBM520Z LONPAC DRIVE IN EXCESS DATE IN/DATE SURVEY: BY/AUTHRIZED ON A BPILAB 1200.00 PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH. **BPIRES**

FÖR

LEAKAGE.NETT

RESPRAY REAR BUMPER USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESEL MEMORY STANDARD SETTINGS.

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER REAR BUMPER LOWER CHROME MOULDING

A BPILAB

М

0.10 380.00

120.00

Amount

750.00

1.00 1676.05 00.00 1676.05 1.00 245.09 00.00 245.09 1.00 208.27 00.00 208.27

Cycle & Carriage Industries Pre Ltd Yik Chan Hoe Body Care & Kepair Center

Bioly Care & Kepair Center

Biolity Charles and Commission Co J: 0111 4333 FIF. 7100 3107 Fax. 001212 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

REAR BUMPER LOWER

Nett

4,579.41

7% GST on 4579.41 320.56

Total Payable

4.899.97

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be

required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

 Date Of Report
 02/05/2018 13:33

 Date Of Accident
 02/05/2018 07:20

Exact Location Of Accident CLEMENTI RD BEFORE ENTERING SLIP RD

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLW5145U

Insured/Policyholder

Name Of Registered Owner TAN SIAO YUEN

NRIC No S7627617Z
Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-92252253
Alternative Phone No OFFICE-92252253

Vehicle Particulars

Manufacturer MERCEDES-BENZ

Model C180

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1800014762

Cover Note Number

Driver

Name of Driver TAN SIAO YUEN

 NRIC No
 \$7627617Z

 Date Of Birth
 04/09/1976

 Occupation
 INDOOR

 Date Of Driving Pass
 01/06/1996

Driving Experience 21 YEARS AND 11 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-92252253

Fax Number

Contact Number OFFICE-92252253

EMail Address NOEMAIL

Address

53 HUME AVE #04-05

Postcode

598751

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: UNKNOWN

GENDER:

: MALE

Passenger 2

NAME:

: UNKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

MY CAR WAS STAIONARY ON THE LEFT LANE AS THE TRAFFIC WAS HEAVY. CAR B (SBM520Z) CAME FROM THE BACK AND KNOCKED INTO THE BACK OF MY CAR.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SBM520Z

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

JEREMY TAN GHEE LIN

NRIC/Passport Number

S7509043I

Contact Number

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations treating to the claims:
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and (d) management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law Cycle Body Care & Repair Center Cycle & Carriage Industries Fre Ltd

 Cycle & Carriage Repair Center: 6872 1272

 Cycle & Care & Repair Centrage aconses

 6771 4353 FF. 9186 Sycleouthage aconses

 Ethania chamboe, jik (2007) enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time


Driver's Signature (If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDE

My car was stationary on the left lane as the traffic was heavy. Can 3 cause from the bade and knewed into the bade of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

OID: 671 4353 HP. vik@cyclecatriage.com.se (Please contact your insurance company for any further details) in Charles Repair Center Carriage Repair Center 6 Carriage Repair Center 6 Carriage Repair Center 6 Carriage Repair Center 6 Repair 6 Fax: 6 Carriage Repair 5: 6771 4353 HP: 9186 3109 rax; 0012 121

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name:

NRIC/FIN No .: