

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9150R

MAKE :

MODEL : HYUNDAI i40

DATE 2/5/2018

EQ Ins (P)

LKK - Kalvin

TS

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid ✓			\$ 1,681.40	
	Boot Lid 'H' Emblem ✓			\$ 27.20	
	Boot Lid CRDI Plate ✓			\$ 41.00	
	Boot Lid Lamp (LH) ✓			\$ 556.80	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	Rear Bumper Reflector Lamp (LH) ✓			\$ 32.00	
	Tail Lamp (LH) ✓			\$ 565.60	
	Rear Panel ✕			\$ 592.30	
	Rear Panel Garnish ✕			\$ 57.70	
	Rear Panel Lower Panel ✕			\$ 495.50	
	Exhaust Pipe Insulator, LH ?			\$ 58.55	
	Exhaust Silencer, LH ✓			\$ 954.00	
	Exhaust Pipe Hanger, LH ?			\$ 58.55	
	Exhaust Pipe Centre ?			\$ 1,150.30	
	SUB TOTAL			\$ 8,227.25	
	LESS 20%			\$ 1,645.45	
	DISCOUNTED TOTAL			\$ 6,581.80	
	Boot Lid City Cab Logo & Tel No. Sticker ✓			\$ 30.00	Nett
	Rear Bumper Reverse Sensor ✕			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 215.70	
	Labour Charge				
	Panel Beating			\$ 600.00	
	Spray Painting Charge			\$ 850.00	
	Wiring Charge			\$ 600.00	400
	Tuff Kote			\$ 50.00	20
	Remove/Refix Reverse Sensor			\$ 50.00	20
	Remove/Refix Exhaust Pipe			\$ 120.00	20
				\$ 150.00	50
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 8,617.50	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to quotation
- Third party survey on a "no fault" basis
- No illegal modification to the vehicle and
- Supplemental charges are subject to quotation

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

ESTIMATE TOTAL

Kalvin (LKK)
2/5/18
3 Rtn.
P/P Before Paint p/le