

ASS. REC. BY:

REF: C93/ASM18008088/N24621

Special Instruction:

Surveyor

N02

ASSIGNMENT (Office)

Smart claim

From (Person):

Cynthia Loh

of

ASM

Date/Time: 03/05/2018 9.16am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBJ 11234P

Insured:

SKX 6324U

at Workshop m/s

Asia Motorsport

Tel:

6745 3811

of

568 Aeylang Rd

Policy No:

Claim No:

98 M100BTX

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1

04052018

H.O.D. Endorsement:

Date/Time:

03/05/2018 1052am

Person Contacted:

Mr. WOO

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBJ 11234P - X
	SKX 6324U - X

PRS
NAZ

REF: ASM

ASIA MOTORSPORT

From: Date: 04/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FBJ 4234P

at Workshop mis

Asia Motorsport

of

568 Geylang Rd

Insured.

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: FBJ 4234P

Tr Page:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

YAMAHA

CC

Colour

BLACK

A/C:

Insured / Std / NI / NA

Sp Reading

N/A

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110 / 70 R17

R:

140 / 70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

4/5/18 @ 1:02PM

Survey held at

ASIA MOTORSPORT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

SWINGARM BROKE

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/5/18 Submit PRS Report

RECEIVED 10 MAY 2018

Date/Time: File Pass to:



: Preli. Report



: Final Report

Date/Time: File Return to:

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Inspection

1 - 45 / 0

1 - 100

1 - 100

Report Format:

Lump Sum / L.B.F. / S

Add Fee:



: Site Insp. / S



: Interview / S



: Tech. Insp. / S



: Check and / S

100
100



Service Request Details

Claim

S8M00BIY

LKK AUTO CONSULTANTS PTE LTD (TP) ▼

Reference

None 

Loss Date

March 21, 2018

Request Date

May 3, 2018

Due Date

May 10, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

FBJ4234P

Make

TPVD

Service Address

...

Primary Contact/Insured

QU YINGHUA

BLK 65 TAMPINES AVE 1, #04-02, 529778, Singapore

93802610

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)