

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.05.2018

REPAIR ESTIMATE

Time: 15:53:15

Page: 1

EQ (4S)

Lxx-kalvin

1/2 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305155547
REGN NO : SHB2079E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 23.03.2012
DATE/TIME IN : 02.05.2018 12:50
ACCIDENT DATE : 01.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0094-G	WING MIRROR RH	1	545.50	20.00	436.40	✓
0002 04-01-0101-0017-A	FRT FENDER RH	1	593.00	20.00	474.40	✓
0003 03-01-0101-0002-G	FRT WHEEL CAP RH	1	145.00	20.00	116.00	X

Frt Bumper x repair

SUB-TOTAL : 1,026.80

JOB NATURE

0000 20-05	Frt Fender Adv.Sticker RH	100.00	✓
0001 L	PANEL BEATING	400.00 200	
0002 23-502	SPRAYPAINT AFFECTED AREA	500.00 450	
0003 17-01	CHECK ALL LIGHTING	20.00 X	
0004 20-00	TUFF COAT ON AFFECTED PARTS.	40.00 20	
0005 L	WHEEL ALIGNMENT	120.00 X	

SUB-TOTAL : 1,180.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.05.2018

REPAIR ESTIMATE

Time: 15:53:15

Page: 12 TS

EQ (4S)

LKK-Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305155547
REGN NO : SHB2079E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 23.03.2012
DATE/TIME IN : 02.05.2018 12:50
ACCIDENT DATE : 01.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,206.80

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalvin LKK
2/5/18 1600h.
2 Rep,
4/s
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: