

INS. CASE OWNER:

Richard Ernest

CC 4 / AXA 1800 8096, UWB37

LKK: IDAC:

Surveyor: Marcus

DOI: ASSIGNMENT 7/5/18

Date / Time: 3/5/18 Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: SKG 6233M  
 Name of Insured: LOY ANN HENG  
 Insured Tel No.: HP: 81665382  
 Excess Sec II :SS D.O.A: 30/4/18

Claim No.: S8MOOFPL / 4467  
 Policy No.: GA069029  
 Make / Model: BMW  
 Place of Accident: SERAYA LANE

Is driver the owner? (YES /  NO) Nature of Accident:  
 If NO, Driver Name / Age: HENG SHI TIE  
 Driver Tel No.: (V/L:  YES / NO)

OI GIA REPORT:  YES / NO ; TP GIA REPORT:  YES / NO  
 Insured Liability: % Final ? Yes / No

SKL 7627R



INSRS: WSP: ALPHONS  
 Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
3/5/18 viniam	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
	Documentation Check List:	Handler Typist
3/5/18	Notification ltr (if non-pickup): After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
28/6/18	Confirm accident details, inform TP claim, agree to settle and letter send out	
16/11/18	File pass to typist type report	
20/11/18	Seek nodate via SMART	
	nodate approve via SMART.	
	RECEIVED 20 JUN 2018	
	RECEIVED 05 DEC 2018	

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm with:	Confirm by:
<b>FINALIZATION</b>	Date/Time:	Confirm with:	Confirm by:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Repair Cost:	SS	( days) Reduction:	%	
<b>FINAL SETTLEMENT</b>	Date/Time: 3/12/18	Confirm with: Sharon	Confirm by:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	SS 100	(Agreed / Assessed) BOLA S/N No.:	NIL	If NO or B 28, Ass. Lia:
Repair Cost:	SS 4387.00			
Loss of Rental (LOR):	SS 535.60	( 8 days) x 66.95		
Loss of Use (LOU):	SS	( 3 x 8 days)		
Loss of Income (LOI):	SS 400.00	(50 x 8 days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	<input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search:	SS 7.49			
Medical:	SS			1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS	(e.g. Tow/Independent)		2) Report Format:
Legal Cost:	SS			3) Survey fee:
<b>Total:</b>	SS 5330.09	<b>Global Sum SS:</b>		
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Confirm by:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 5330.09	Name 1:	Pegasis Engineering & Trading Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008096/Uwb3

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 03-05-2018



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SKG 6233M	Veh. Inspected	SLL 7627R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/05/2018

**2. Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	30/04/2018	Inspection Date	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

4x4

W

Enailed 30/04/2018

@ 185225

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

\* Alignment result

**From :**  
**PEGASUS ENGINEERING & TRADING PTE LTD**  
 C/O 51 DEFU LANE 10  
 SINGAPORE 539216  
 Officer in Charge : ALVIN LOW WAI LUN  
 Tel :  
 Email :

**Customer :**  
**GRAB RENTALS PTE LTD**  
 18 SIN MING LANE  
 #01-08 MIDVIEW CITY  
 SINGAPORE 573960  
 Attn :  
 Tel :  
 Fax :

*Take photo After repair*  
*Not aligned*  
*make*  
*1/55 4/100?*  
*4 days*  
*3/5/18*

Quotation No : QO18/04-1344	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLL7627R	Chassis No : JM6BN22ABH0144953	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEHICLE NO: SKG6233M, DATE OF ACCIDENT: 30.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	O/S HEADLAMP	1	1,020.0000	1,020.00
2	O/S FRONT FENDER	20/ 1	334.0000	334.00
3	O/S FRONT FENDER INNER COWLING	1	130.0000	130.00
4	O/S FRONT FENDER INNER COWLING CLIPS	6	5.0000	30.00
5	FRONT BUMPER	1	825.0000	825.00
6	O/S FRONT BUMPER INDICATOR LIGHT GARNISH	1	25.0000	X 25.00
7	O/S FRONT BUMPER INDICATOR LIGHT GARNISH EXTENSION	1	20.0000	X 20.00
8	O/S FRONT BUMPER LOWER CENTRE AIR GRILLE COVER	1	35.0000	X 35.00
9	FRONT BUMPER REINFORCEMENT	1	479.0000	X 479.00
10	FRONT BUMPER REINFORCEMENT COVER	1	67.0000	X 67.00
11	FRONT BUMPER REINFORCEMENT COVER CLIPS	4	5.0000	X 20.00
12	FRONT BUMPER AIR GUIDE	2	32.0000	X 64.00
13	FRONT BUMPER CLIPS	10	5.0000	50.00
14	FRONT BUMPER LOWER SPLASHIELD COVER	1	95.0000	X 95.00
15	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS	8	5.0000	X 40.00
16	FRONT BUMPER SIDE RETAINER	1	19.0000	19.00
17	RADIATOR GRILLE INNER SIDE BRACKETS	2	26.0000	X 52.00
18	RADIATOR GRILLE CHROME GARNISH INNER BASE	1	38.0000	X 38.00
19	WINDSCREEN WASHER TANK	1	105.0000	105.00
20	WINDSCREEN WASHER TANK MOTOR	1	68.0000	X 68.00
21	O/S FRONT <del>bumper</del> LOWER ARM	1	485.0000	485.00
22	O/S FRONT <del>bumper</del> KNUCKLE ARM	1	384.0000	384.00
23	STEERING RACK ASSY	1	916.0000	X 916.00

C/F 0.00



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

**From :**  
**PEGASUS ENGINEERING & TRADING PTE LTD**  
 C/O 51 DEFU LANE 10  
 SINGAPORE 539216  
 Officer in Charge : ALVIN LOW WAI LUN  
 Tel :  
 Email :

**Customer :**  
**GRAB RENTALS PTE LTD**  
 18 SIN MING LANE  
 #01-08 MIDVIEW CITY  
 SINGAPORE 573960  
 Attn :  
 Tel :  
 Fax :

Quotation No : QO18/04-1344	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLL7627R	Chassis No : JM6BN22A8H0144953	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEHICLE NO: SKG6233M, DATE OF ACCIDENT: 30.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
24	O/S FRONT WHEEL BEARING WITH HUB	1 <i>Set</i>	542.0000	542.00
25	O/S FRONT SHOCK ABSORBER	1 <i>Set</i>	287.0000	287.00
26	LESS 20% ITEM (1-25)	1	-1,226.2000	-1,226.20
27	O/S FRONT WHEEL RIM	1 <i>RD</i>	450.0000	450.00 <i>100 S.W</i>
28	O/S FRONT WHEEL TYRE <i>LP 200</i>	1 <i>2 in</i>	320.0000	320.00 <i>70% 140 SA</i>
29	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	120.0000	120.00 <i>60</i>
30	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00 <i>20</i>
31	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING	1	350.0000	350.00 <i>250</i>
32	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	900.0000	900.00 <i>520</i>
33	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	700.0000	700.00 <i>600</i>
34	TOWING	1	80.0000	80.00 <i>60</i>

*Set wheel key cap o/s car — 75*

LKK Auto Consultants hence notify the Repairer of the following:

- A survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Sub Total 7,884.80  
 GST(7.00%) 551.94  
 Total (SGD) 8,436.74

Please conduct the survey at  
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

*P- 4286*  
*202*  
*3428.80*  
*S.W 240*  
*1400 - 1510*  
*5178.80*  
*1143*

# CK MOTOR PTE LTD

No.10 #01-02 AMK Autopoint  
 Ang Mo Kio Industrial Park 2A  
 Singapore 568047

Phone Number: 6484-2555

Fax Number: 6484-2555

Customer:		Date:	5/6/2018 3:21 PM
Company:	TAN LIM	VIN	
License NO:	SLL 7627 R	Technician:	
Odometer:		Order NO:	

## VEHICLE ALIGNMENT REPORT

MAZDA, 3, 03-07, 1.3/1.6L Benzin

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6°02'	2°04'	4°04'	6°12'
		Right	6°06'	2°04'	4°04'	6°12'
	Camber	Left	-0°12'	-1°41'	0°19'	-0°06'
		Right	-0°36'	-1°41'	0°19'	-0°36'
	Toe	Left	0°48'	-0°05'	0°17'	0°18'
		Right	1°18'	-0°05'	0°17'	1°45'
Total		2°06'	-0°11'	0°33'	2°03'	
Rear	Camber	Left	-0°24'	-2°19'	-0°19'	-0°24'
		Right	-0°48'	-2°19'	-0°19'	-0°48'
	Toe	Left	0°03'	-0°05'	0°17'	0°03'
		Right	-0°03'	-0°05'	0°17'	-0°03'
		Total	0°00'	-0°11'	0°33'	0°00'
Thrust Angle		0°03'	---		0°03'	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13°51'	14°02'	14°02'	13°51'
	Right		14°02'	14°02'	14°02'	14°02'
Included Angle	Left		13°39'	---	---	13°45'
	Right		13°26'	---	---	13°26'
Toe Out On Turns	Left		---	---	---	---
	Right		---	---	---	---
Max Turn Inside	Left		---	36°48'	42°48'	---
	Right		---	36°48'	42°48'	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		-14mm	---	---	-14mm
	Rear		1mm	---	---	1mm
Track Width Diff.			11mm			11mm
Wheel Base Diff.			-15mm			-15mm
Front Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Rear Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Frame Angle						---

H/Phone : 9747-2555



PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Emailed 30.04.2018

@ 1852243

Quotation

\* Alignment result

**From :**  
**PEGASUS ENGINEERING & TRADING PTE LTD**  
 C/O 51 DEFU LANE 10  
 SINGAPORE 539216  
 Officer in Charge : ALVIN LOW WAI LUN  
 Tel :  
 Email :

**Customer :** *Toke pke Ather*  
**GRAB RENTALS PTE LTD**  
 18 SIN MING LANE  
 #01-08 MIDVIEW CITY  
 SINGAPORE 573960  
 Attn : *not Albert*  
 Tel : *Mark*  
 Fax : *2/55*  
*Hq.*  
*3/5/18*

Quotation No : QO18/04-1344	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLL7627R	Chassis No : JM6BN22A8H0144953	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
marks : TP INSURER: AXA, INSURED'S VEHICLE NO: SKG6233M, DATE OF ACCIDENT: 30.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	O/S HEADLAMP	1	1,020.0000	1,020.00
2	O/S FRONT FENDER	<i>DO/</i> 1 <i>Buc</i>	334.0000	334.00
3	O/S FRONT FENDER INNER COWLING	1 <i>To.1</i>	130.0000	130.00
4	O/S FRONT FENDER INNER COWLING CLIPS	6 <i>ner</i>	5.0000	30.00
5	FRONT BUMPER	1 <i>D.S</i>	826.0000	826.00
6	O/S FRONT BUMPER INDICATOR LIGHT GARNISH	1 <i>11</i>	25.0000	X 25.00
7	O/S FRONT BUMPER INDICATOR LIGHT GARNISH EXTENSION	1 <i>11</i>	20.0000	X 20.00
8	O/S FRONT BUMPER LOWER CENTRE AIR GRILLE COVER	1 <i>11</i>	35.0000	X 35.00
9	FRONT BUMPER REINFORCEMENT	1 <i>12</i>	479.0000	X 479.00
10	FRONT BUMPER REINFORCEMENT COVER	1 <i>11</i>	67.0000	X 67.00
11	FRONT BUMPER REINFORCEMENT COVER CLIPS	4 <i>11</i>	5.0000	X 20.00
12	FRONT BUMPER AIR GUIDE	2	32.0000	? 64.00
13	FRONT BUMPER CLIPS	10 <i>ner</i>	5.0000	50.00
14	FRONT BUMPER LOWER SPLASHIELD COVER	1	95.0000	? 95.00
15	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS	8	5.0000	? 40.00
16	FRONT BUMPER SIDE RETAINER	1 <i>one</i>	19.0000	19.00
17	RADIATOR GRILLE INNER SIDE BRACKETS	2 <i>11</i>	26.0000	X 52.00
18	RADIATOR GRILLE CHROME GARNISH INNER BASE	1	38.0000	? 38.00
19	WINDSCREEN WASHER TANK	1 <i>one</i>	105.0000	105.00
20	WINDSCREEN WASHER TANK MOTOR	1 <i>11</i>	68.0000	X 68.00
21	O/S FRONT BUMPER LOWER ARM	1 <i>11</i>	485.0000	X 485.00
22	O/S FRONT BUMPER KNUCKLE ARM	1	384.0000	? 384.00
23	STEERING RACK ASSY	1	916.0000	? 916.00

C/F 0.00

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

<b>Customer :</b>
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

<b>Quotation No :</b> QO18/04-1344	<b>Quotation Date :</b> 30/04/2018	<b>Terms :</b> 30 DAYS
<b>Vehicle No :</b> SLL7627R	<b>Chassis No :</b> JM6BN22A8H0144953	<b>Third Party Insurer :</b>
<b>Model :</b> MAZDA 3	<b>Date of Accident :</b>	
<b>Remarks :</b> TP INSURER: AXA, INSURED'S VEHICLE NO: SKG6233M, DATE OF ACCIDENT: 30.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	O/S FRONT WHEEL BEARING WITH HUB	1	542.0000	542.00
25	O/S FRONT SHOCK ABSORBER	1	287.0000	287.00
26	LESS 20% ITEM (1-25)	1	-1,226.2000	-1,226.20
27	O/S FRONT WHEEL RIM	1	450.0000	450.00
28	O/S FRONT WHEEL TYRE <i>LP 200</i>	1	320.0000	320.00 <i>QW</i>
29	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	1	120.0000	120.00
30	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00
31	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING.	1	350.0000	350.00
32	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	900.0000	900.00
33	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	700.0000	700.00
34	TOWING	1	80.0000	80.00

*Get wheel buy cap o/s one*

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

LKK Auto Consultants hence notify the Repairer of the following:

- Survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

<b>Sub Total</b>	7,884.80
<b>GST(7.00%)</b>	551.94
<b>Total (SGD)</b>	8,436.74

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLL7627R
Vehicle to be Exported:	No
Intended De-registration Date:	03 May 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520432301
Chassis No.:	JM6BN22A8H0144953
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,688.00
Original Registration Date:	09 Mar 2017
First Registration Date:	09 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$9,688.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Mar 2027
PARF Rebate Amount:	\$7,266.00
Intended COE Rebate Details	
COE Expiry Date:	08 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,401.00
COE Rebate Amount:	\$42,819.00
<b>Total Rebate Amount:</b>	<b>\$50,085.00</b>

The information contained herein is correct as at 03 May 2018

OK

## FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

## Post an Advertisement

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

## New 5 Years Coe Renewal Toyota Altis 1.6A



\$2800 Downpayment Monthly  
From \$688 Onwards. Lowest  
3.68%PA Add GV Cars Financing  
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by

5 vehicles

Mazda 3

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
<b>Search Selection</b>	<b>Mazda 3</b>		Any	Any	<b>2017</b>	Any	
	<b>Mazda 3 1.5A</b>		<b>\$72,800</b>	<b>\$7,600 /yr</b>	<b>17-Apr-2017</b>	<b>1,496 cc</b>	<b>15</b>
(Depreciation \$7,500) 1 Owner, (Warranty's By Mazda Agents), Always Parked Under Shelter, Well Kept, Original Good Condition. Sports Rims, Accident Fees.							
Posted: 03-May-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda							
	<b>Mazda 3 1.5A</b>		<b>\$79,800</b>	<b>\$8,260 /yr</b>	<b>26-May-2017</b>	<b>1,496 cc</b>	<b>7</b>
\$10K Down Payment. Most Popular Mazda Sedan For Your Family And Daily Usage. Fuel Consumption At 15Km/Litre. Very Non Smoker. Fuel Saving Yet Powerful Drive.							
SmartCars Boutique Pte Ltd							
Posted: 02-May-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda							
	<b>Mazda 3 1.5A</b>		<b>\$76,800</b>	<b>\$7,700 /yr</b>	<b>31-Aug-2017</b>	<b>1,496 cc</b>	<b>8</b>
Agent Unit! Come With 3 Years Agent Warranty! Lowest Depreciation! 2017 Model With G-vectoring And Nice Interior! Guaranteed High Loan Available. \$5000 Drive Away Possible. Trade In ...							
Posted: 25-Apr-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda							
	<b>Mazda 3 1.5A</b>		<b>\$77,900</b>	<b>\$8,290 /yr</b>	<b>15-Feb-2017</b>	<b>1,496 cc</b>	<b>15</b>
(We Assure 100% Genuine Mileage,) 100% Accident Free, 100% Original, No Modification. Super Low Mileage Only At 1 Year Warranty (3Yrs / 100K Km - Whichever Comes 1st)							
Posted: 06-Apr-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda							

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Compare

Mazda 3 1.5A

\$79,800

\$8,220 /yr

06-Mar-2017

1,496 cc

## ◀ Service Request Details

### Claim

S8M00FPL

### Reference

None 

### Loss Date

April 30, 2018

### Request Date

May 2, 2018

### Due Date

May 9, 2018

### Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

### Type of Loss

Third Party Vehicle Damage

### Services

Pending verification - Direct Settlement

02052018 @ 2.13pm  
Atom Vch in  
William Marcus  
Pegasus.

### Actions

---

#### Next Step

Agree to perform service

### Vehicle Information

---

#### Incident Vehicle Registration #

SLL7627R

#### Make

TPVD MAZDA

---

**Service Address**

---

...

---

**Primary Contact/Insured**

---

LOY AH ENG

65 KALLANG BAHRU, #12-323, 330065, Singapore

UNIQ304@SINGNET.COM.SG

---

**Claim Handler**

---

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

⏪ **Re:S8M00FPL- Mandate approval**

Type

🔔 Question

Message

Hi LKK, pls propose 8 days for the LOU & LOI. We agree to the COR. Thank you.

Reply



9A Lok Yang Singapore 628628  
c/o 51 Defu Lane 10 Singapore 539216

Tel: 6858 1846 / HP 9628 6508  
Fax: 6858 0877

Our Ref SLL 7627R  
Your Ref SKG 6233M

Date 27/06/2018

Claims Department - LKK - Vivian  
AXA

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SLL 7627R / SKG 6233M ON 30.07.2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- Original survey report / \_\_\_\_\_ copies of photographs \_\_\_\_\_
- Original Tax-invoice number L18/06-1049  police report / police result
- Certificate Of Insurance \_\_\_\_\_  Vehicle search result
- Authorization To Act - Owner/Hiper  Rental Tariff

\*Survey under insurance instruction / Independent surveyor / No survey.  
LKK

a)	Cost of repair (inclusive GST)	\$ <u>4,387.00</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>7.49</u>
d)	Loss of rental <u>8.5 days @ \$66.96</u>	\$ <u>569.08</u>
e)	Loss of earnings / rental fees <u>35 days @ \$150.00</u>	\$ <u>525.00</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g)	<u>5 days (incurred extra rental @ \$56.00 to mitigate loss on loss of earnings)</u>	\$ <u>280.00</u>
	Total	\$ <u>5,762.57</u>

\* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

**Sharon Ow**

Email: claims@pegasusengr.com.sg



09 May 2018

**LOY AH ENG**  
65 KALLANG BAHRU,  
#12-323,  
Singapore 330065

Dear Sir/ Mdm

**OUR REF : CC4/ASM18008096/Uwb3**  
**YOUR REF : SLL 7627R**

**ACCIDENT INVOLVING SLL 7627R & SKG 6233M ALONG SERAYA LANE ON  
30/04/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Pegasus Engineering & Trading Pte Ltd** acting on behalf of the owner of SLL 7627R against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd  
(Motor Claims Dept)

## AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER           9LL7607R          

ACCIDENT INVOLVING           9K66233M          

ALONG/AT           Haig Road to Seraya Lane                     ON 30.04.2018          

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals Pte Ltd

Co Reg No : 2016172006

Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact : 6655 0005

Date :           27.06.2018          

Signature



Owner



redefining / insurance



CLAIM REF : S8M00FPL  
INSURED : LOY AH ENG

**DISCHARGE VOUCHER**

We/I GRAB RENTALS PTE LTD hereby agree to accept the sum of dollars Five Thousands Three Hundred Thirty and Cents Nine Only (S\$ 5,330.09) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no SKG 6233M as a result of an accident along SERAYA LANE on 30/04/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLL 7627R.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SKG 6233M in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SKG 6233M.

Dated this 3 day of Dec 2018

Claimant's Signature : \_\_\_\_\_



NRIC no./ Company Stamp : \_\_\_\_\_

Occupation/ Business : Rental

Address : 18 Sin Ming Lane #01-04 Midview City (S 292960)

Telephone No. : 6695 0005

Witness's Name : Sharon

Witness's Signature : \_\_\_\_\_

Witness's NRIC No. : S7267527H



Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Vehicle Model : Mazda 3 Sedan 1.5  
Vehicle No : SLL7627R  
Chassis No : JM6BN22A8H0144953

GST / ROC Company No : 201101753C

Third Party Insurer : AXA  
Insured's Veh No : SKG6233M  
Date of accident : 30.04.2018

Tax Invoice No : IV18/06-1049  
Invoice Date : 22.06.2018

Pages : 1 of 1

DESCRIPTION	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR.	\$ 4,100.00
Sub Total	\$ 4,100.00
GST (7.00%)	\$ 287.00
Total	\$ 4,387.00

Cheques should be made payable to PEGASUS ENGINEERING & TRADING PTE LTD

PEGASUS ENGINEERING & TRADING PTE LTD

  
Authorised Signature (Company Stamp)



If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846  
Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216  
E-mail : claims@pegasusengr.com.sg

CONFIDENTIAL  
SCHEDULE TO VEHICLE RENTAL AGREEMENT

Date:	12/05/2017	Vehicle Rental Agreement No.	5380
<b>Renter Details</b>		<b>Additional Driver (if any)</b>	
<input checked="" type="checkbox"/> Name	Yeong Ming, Timothy Tan	<input checked="" type="checkbox"/> Name	ZiHong, Gilbert (Lin ZiHong, Gil
<input checked="" type="checkbox"/> Address	408 Yishun Avenue 5 #02-1264	<input checked="" type="checkbox"/> Address	Apt Blk 807A Chai Chee Road. #
<input checked="" type="checkbox"/> Date of Birth	08/12/1977	<input checked="" type="checkbox"/> Date of Birth	11/23/1984
<input checked="" type="checkbox"/> NRIC/Passport No.	S7723448I	<input checked="" type="checkbox"/> NRIC No.	
<input checked="" type="checkbox"/> Driving License No.	S7723448I	<input checked="" type="checkbox"/> Driving License No.	S9438283C
<input checked="" type="checkbox"/> Telephone No.	6593830733	<input checked="" type="checkbox"/> Telephone No.	6596223532
<input checked="" type="checkbox"/> Mobile No.	6593830733	<input checked="" type="checkbox"/> Mobile No	
<b>Vehicle Description</b>		<b>Additional Driver (if any)</b>	
<input checked="" type="checkbox"/> Vehicle No	SL17627R	<input checked="" type="checkbox"/> Name	
<input checked="" type="checkbox"/> Make/Model	MAZDA MAZDA3	<input checked="" type="checkbox"/> Address	
<b>Rental Period</b>		<input checked="" type="checkbox"/> Date of Birth	
<input checked="" type="checkbox"/> Minimum Rental Period	182	<input checked="" type="checkbox"/> NRIC No.	
<input checked="" type="checkbox"/> Date Checked Out	12/05/2017	<input checked="" type="checkbox"/> Driving License No.	
<input checked="" type="checkbox"/> No. of Days	171	<input checked="" type="checkbox"/> Telephone No.	
<input checked="" type="checkbox"/> Expected Date of Return	06/05/2018	<input checked="" type="checkbox"/> Mobile No	
<input checked="" type="checkbox"/> Actual Date of Return	05/25/2018		
<b>Rental Charges* &amp; Deposit</b>			
<input checked="" type="checkbox"/> ( ) RR Rental Charges/Day	Per day @ S \$72.00 Per week @ S \$503.00	Deposit Received	S \$1,500.00
<input checked="" type="checkbox"/> ( X ) ER Promotion Rental Charges/Day	Per day @ S \$56.00 Per week @ S \$392.01	Total Amount Received*	S \$9,418.40
<input checked="" type="checkbox"/> ( ) DD Promotion Rental Charges/Day	Per day @ S Per week @ S	* Inclusive GST	
Rental Period	182 days / 24 weeks	Total Rental Charges	S \$9,604.14

<b>Payment Method</b>			
<input checked="" type="checkbox"/> Driver Wallet		<input type="checkbox"/> Cash	SGS
<input type="checkbox"/> Credit Card		<input type="checkbox"/> Debit Account	
Type		Bank Name	
Card No.		Account No.	

CONFIDENTIAL

I, the Renter, agree that the Lessor may collect, use & disclose my personal data, as provided in this Schedule &/or pursuant to the Agreement from time to time, for the following purposes in accordance with the Personal Data Protection Act 2012 & the Lessor's group Privacy Policy (available at [www.grab.com/sg/privacy/](http://www.grab.com/sg/privacy/)):

- (a) administration of the vehicle rental under the Agreement;
- (b) for internal administrative purposes;
- (c) to communicate with me; &
- (d) for the Lessor to comply with its obligations under law.

Further, I understand that my personal data may be used for marketing purposes by the Lessor, its affiliated companies or their partners: & I hereby consent to receive marketing & promotional materials by telephone, SMS or e-mail.

**Additional Notes:**

Subject to Renter's fulfilment of Minimum Rental Period, Renter shall enjoy the following Discounts:

**Agreement**

The Renter has read, understood & agrees with all terms & conditions of this Agreement.



\_\_\_\_\_  
Renter's Signature/Stamp  
Date:



\_\_\_\_\_  
Authorised Signatory/Stamp  
Grab Rentals Pte Ltd

**Enquire Vehicle & Owner Information ( Vehicle No. SKG6233M As At 30 Apr 2018 / 13:20:00 )**

**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: PET(ALVIN)SLL7627R

**Current Owner Details**

Owner ID Type: Singapore NRIC

Owner ID: S0696205Z

Owner Name: LOY AH ENG

Registered Address Type: HDB / HUDC

Registered Block/House No.:65

Registered Street Name: KALLANG BAHRU

Registered Unit No.: # 12 - 323

Registered Building Name: -

Registered Postal Code: 330065

**Current Vehicle Details**

Vehicle No: SKG6233M

Make Description/Model: B.M.W. / 325i COUPE SR XL

Insurance Company Name: AXA INSURANCE PTE LTD

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	SKG 6233M ✓ (Insd veh)	<b>Model:</b>	MAZDA 3 (A)
	SLL 7627R ✓ (TP veh)		
<b>Date of Accident:</b>	30/04/2018 ✓		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	8,500.94	
Final Repair Cost	:	\$	4,387.00	
Loss of Use	:	\$	400.00	8days at \$50.00 per day
Rental (if any)	:	\$	535.60	8 days
LTA / GIA Search Fee	:	\$	7.49	

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	5,330.09

**Is Third Party Workshop GIA Registered?**  YES  NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

<b>Payment Instruction: Payee's Breakdown</b>			
1)	PEGASUS ENGINEERING & TRADING PTE LTD	:	\$ 5,330.09

\_\_\_\_\_  
JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
20/12/2018  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008096/Uwb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:RICHARD

Date : 20-12-2018



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 6233M	Veh. Inspected	SLL 7627R
Policy No.	GA049029	Coverage (\$)	0.00
Claim No.	S8M00FPL	Excess (\$)	0.00
Assign From		Assign Date	03/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0144953	Colour	GREY
Odometer	88897	Steering	AFFECTED
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	30/04/2018	Inspection Date	03/05/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7627R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	O/S HEADLAMP (CONSISTENT)	CRACKED	1,020.00	1,020.00
1	O/S FRONT FENDER (CONSISTENT)	DENTED / BUCKLED	334.00	334.00
1	O/S FRONT FENDER INNER COWLING (CONSISTENT)	TORN	130.00	130.00
6	O/S FRONT FENDER INNER COWLING CLIPS @\$5.00 (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT BUMPER (CONSISTENT)	DISTORTED	826.00	825.00
1	O/S FRONT BUMPER INDICATOR LIGHT GARNISH (CONSISTENT)	NOT NECESSARY	25.00	-
1	O/S FRONT BUMPER INDICATOR LIGHT GARNISH EXTENSION (CONSISTENT)	NOT NECESSARY	20.00	-
1	O/S FRONT BUMPER LOWER CENTRE AIR GRILLE COVER (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	479.00	-
1	FRONT BUMPER REINFORCEMENT COVER (CONSISTENT)	NOT NECESSARY	67.00	-
4	FRONT BUMPER REINFORCEMENT COVER CLIPS @\$5.00 (CONSISTENT)	NOT NECESSARY	20.00	-
2	FRONT BUMPER AIR GUIDE @\$32.00 (CONSISTENT)	NOT NECESSARY	64.00	-
10	FRONT BUMPER CLIPS @\$5.00 (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER SPLASHIELD COVER (CONSISTENT)	NOT NECESSARY	95.00	-
8	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS @\$5.00 (CONSISTENT)	NOT NECESSARY	40.00	-
1	FRONT BUMPER SIDE RETAINER (CONSISTENT)	CRACKED	19.00	19.00
2	RADIATOR GRILLE INNER SIDE BRACKETS @\$26.00 (CONSISTENT)	NOT NECESSARY	52.00	-
1	RADIATOR GRILLE CHROME GARNISH INNER BASE (CONSISTENT)	NOT NECESSARY	38.00	-
1	WINDSCREEN WASHER TANK (CONSISTENT)	DEFORMED	105.00	105.00
1	WINDSCREEN WASHER TANK MOTOR (CONSISTENT)	NOT NECESSARY	68.00	-
1	O/S FRONT LOWER ARM (CONSISTENT)	BENT	485.00	485.00
1	O/S FRONT KNUCKLE ARM (CONSISTENT)	BENT	384.00	384.00
1	STEERING RACK ASSY (CONSISTENT)	SERVICEABLE	916.00	-

Report Ref No. CC4/ASM18008096/Uwb3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	O/S FRONT WHEEL BEARING WITH HUB (CONSISTENT)	BENT	542.00	542.00
1	O/S FRONT SHOCK ABSORBER (CONSISTENT)	BENT	287.00	287.00
1	FRT WHEEL HUP CAP O/S (CONSISTENT)	CRACKED	75.00	75.00
	LESS 20% DISCOUNT		-1,241.20	-857.20
			4,964.80	3,428.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	O/S FRONT WHEEL RIM (SN) (CONSISTENT)	DENTED	450.00	100.00
1	O/S FRONT WHEEL TYRE (LOCAL PURCHASE) (70%) (\$200.00) (SN) (CONSISTENT) (LOCAL PURCHASE)	PUNCTURE	320.00	140.00
			770.00	240.00
	<b><u>LABOUR</u></b>			
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		120.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS ,REMOVE AND RENEWAL OF THE AFFECTED PARTS ,TO PERFORM FINAL CHECKING AND TESTING.		350.00	250.00
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		900.00	520.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		700.00	600.00
	TOWING.		80.00	60.00
			2,210.00	1,510.00
	<b>GRAND TOTAL</b>		<b>7,944.80</b>	<b>5,178.80</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,100.00</b>

Report Ref No. CC4/ASM18008096/Uwb3q2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim: S861007PL  
 Reference: CCAJASH180080994/Uak3q2  
 Loss Date: 30 April 2018  
 Request Date: 21 August 2018  
 Dam Date:  
 Vendor Name: LKK AUTO CONSULTANTS PTE LTD (TP)  
 Type of Loss: Third Party Vehicle Damage  
 Services: Pending verification - Direct Settlement

**Actions**

Next Step: Wait for Approve invoice

[Add Invoice](#)

**Vehicle Information**

Incident Vehicle Registration #: 5LL7627R  
 Make: TMVD MAZDA  
 Model: 3-1.5 SEDAN L SP 6EAT (A)  
 Service Address:  
 ...  
 Primary Contact/Insured:  
 LOY AH ENG  
 65 KALLANG BAHRU, #12-323, 330065, Singapore  
 UHQ004@SINGNET.COM.SG  
 Claim Handler:  
 ANG Richard  
 richard.ang@aia.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type:  Document SubType:

[Upload Documents](#)

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2018



NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
■ Immediate Advice-SLL 7627R.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 November 2018
■ LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 November 2018
■ Immediate Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	8 May 2018
■ EMAIL FROM WORKSHOP INCLUDING ESTIMATE & SLL7627R TP GIA.mxl	Letters and Correspondence	Others	NIKAM Samsiah Pandurang	7 May 2018
■ TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	7 May 2018
■ SLL7627R / TP.PDF	Reports & Statement	GIA Report	TAY Ernest	3 May 2018
■ SKG6233M/ INSD.PDF	Reports & Statement	GIA Report	TAY Ernest	3 May 2018
■ TP REQ SURVEY.mxl	Letters and Correspondence	Workshop	KAGIBI Muzien	2 May 2018