

ASS. REC. BY:

REF:

CS3/MSH1800913/G24be2

Special Instruction:

SURVEYOR

GR

## ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSLH

Date/Time:

03052018 205pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SJM 3386E

Insured:

SLB 7932L

at Workshop m/s

MJE motor

Tel:

9225 1391

of

Blk 7 Sin Ming Ind Est #01-82

Policy No:

MSD / VPCP / 17 - 001233 - 00

Claim No:

MSC / V / 18 - 000619

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30042018

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

03052018 205pm

Person Contacted:

Vehicle ☒ IN / OUT

| Date/Time | Action/Instruction ( X ) Estimate    |                         |
|-----------|--------------------------------------|-------------------------|
|           | SJM 3386E - CS3/MSH13001252/Cqm3cl-1 | DA: 12012013            |
|           | SLB 7932L - NGA / ALH18006332 / YL   | DA: 05042018            |
|           | Diamond: 4/5/2018                    |                         |
|           | <u>6000L</u>                         | Est range & repair day, |

PPS  
XHL

REF:

C 4751 W

(~2.18)

29 Dec 2008

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$36K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SIM 33866

Yr Regn:

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Rush

C.C 1495

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

143271

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J200 E 00 20 790

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim / STD A/Rim or

Tyre Size:

F:

215/55 R 17

R:

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

3/5/2018

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimate repair range \$5000 - \$6000.

RECEIVED 19 JUL 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

120

50

10

180

Report Format:

PRC

Lump Sum / I.B.I. (\$

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 02 May 2018 |               | 03 May 2018<br>14:05<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |  |
|-----------------------------|---|------------------------|--|
| Insured:                    | HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N  |                        |  |
| Main Claimant:              | VIDA & PARTNERS PTE LTD Co Reg, Co. Reg. No.: 201534751W  |                        |  |
| Vehicle Reg. No.:           | SJM3386E  | Date of Loss:          | 30/04/2018 10:00 - :59<br>[112 Months and 1 Days From LTA<br>Reg Date (Man Yr)]  |
| Claim Type:                 | TP / MSC/V/18-000619  | Policy/Cover Note No.: | MSD/VPCP/17-001233-00<br>(Comprehensive)<br>Coverage: 01/06/2017 -<br>31/05/2018 |
| Vehicle Reg. No. (Insured): | SLB7932L  | Policy No. (Claimant): |  |
|                             |   | Excess:                |  |
| Repairer:                   | Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:  |                        |  |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541] |                        |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/05/2018]                            |                        |  |
| Driver/Custodian (Insured): | MOHAMED YUSOFF BIN ISMAIL (), NRIC: S1503951E, Tel: +6586111210   |                        |  |
| Adj Asg. Remarks:           | TP DISAGREE SJE FOLLOW CHART - LKK CONSULTANTS  |                        |  |

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

> Back to OneMotoring

## Enquire Transfer Fee

Enquire Transfer Fee

| Vehicle Details  |  |                     |                           |
|--|--|---------------------|---------------------------|
| Vehicle No. :  | SJM3386E   |                     |                           |
| Vehicle Type :   | Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover |                     |                           |
| Vehicle Attachment 1 :   | No Attachment  |                     |                           |
| Vehicle Scheme :   | Normal   |                     |                           |
| Vehicle Make :   | TOYOTA   |                     |                           |
| Vehicle Model :  | RUSH 1.5X A  |                     |                           |
| Chassis No. :  | J200E0020790   |                     |                           |
| Propellant :   | Petrol   |                     |                           |
| Engine No. :   | 3SZ2076507   |                     |                           |
| Engine Capacity :  | 1495 cc  |                     |                           |
| Maximum Power Output :   | 80.0 kW ( 107 bhp )  |                     |                           |
| Maximum Laden Weight :   | 1425 kg  |                     |                           |
| Unladen Weight :   | 1150 kg  |                     |                           |
| Year Of Manufacture :  | 2008   |                     |                           |
| Original Registration Date :   | 29 Dec 2008  |                     |                           |
| Lifespan Expiry Date :   | -  |                     |                           |
| COE Category :   | E - Open Category  |                     |                           |
| Quota Premium :  | \$6,509.00   |                     |                           |
| COE Expiry Date :  | 28 Dec 2018  |                     |                           |
| Road Tax Expiry Date :   | 28 Dec 2018  |                     |                           |
| PARF Eligibility Expiry Date :   | 28 Dec 2018  |                     |                           |
| Inspection Due Date :  | 28 Dec 2019  |                     |                           |
| Intended Transfer Date :   | 18 Jul 2018  |                     |                           |
| CO2 Emission :   | -  |                     |                           |
| CO Emission :  | -  |                     |                           |
| HC Emission :  | -  |                     |                           |
| NOx Emission :   | -  |                     |                           |
| PM Emission :  | -  |                     |                           |
| Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.                        |  |                     |                           |
| Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. |  |                     |                           |
| Amount Payable   |  |                     |                           |
|  | Amount Before GST<br>(S\$)                                   | GST Amount<br>(S\$) | Amount After GST<br>(S\$) |
| Transfer Fee :   | 25.00  | -                   | 25.00                     |
| Total Amount Payable :   |  |                     | 25.00                     |

You may print this page for reference.

OK

Print

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                   |
|-------------------------------------|-------------------|
| <b>Vehicle Owner Particulars</b>    |                   |
| Owner ID Type:                      | Company           |
| Owner ID:                           | 4751W             |
| <b>Vehicle Details</b>              |                   |
| Vehicle No.:                        | SJM3386E          |
| Vehicle to be Exported:             | No                |
| Intended De-registration Date:      | 18 Jul 2018       |
| Vehicle Make:                       | TOYOTA            |
| Vehicle Model:                      | RUSH 1.5X A       |
| Primary Colour:                     | Silver            |
| Manufacturing Year:                 | 2008              |
| Engine No.:                         | 3SZ2076507        |
| Chassis No.:                        | J200E0020790      |
| Maximum Power Output:               | 80.0 kW (107 bhp) |
| Open Market Value:                  | \$15,732.00       |
| Original Registration Date:         | 29 Dec 2008       |
| First Registration Date:            | 29 Dec 2008       |
| Transfer Count:                     | 4                 |
| Actual ARF Paid:                    | \$15,732.00       |
| <b>Intended PARF Rebate Details</b> |                   |
| PARF Eligibility:                   | Yes               |
| PARF Eligibility Expiry Date:       | 28 Dec 2018       |
| PARF Rebate Amount:                 | \$7,866.00        |
| <b>Intended COE Rebate Details</b>  |                   |
| COE Expiry Date:                    | 28 Dec 2018       |
| COE Category:                       | E - Open Category |
| COE Period(Years):                  | 10                |
| QP Paid:                            | \$6,509.00        |
| COE Rebate Amount:                  | \$274.00          |
| <b>Total Rebate Amount:</b>         | <b>\$8,140.00</b> |

The information contained herein is correct as at 18 Jul 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                  |
|----------------------------|----------------------------------|
| Date Of Report             | 02/05/2018 10:33                 |
| Date Of Accident           | 30/04/2018 11:30                 |
| Exact Location Of Accident | QUEENSWAY TOWARDS ALEXANDRA ROAD |
| Country/State of Loss      | SINGAPORE                        |

### DETAILS OF OWN VEHICLE

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | SJM3386E                |
| <b>Insured/Policyholder</b> |                         |
| Name Of Registered Owner    | VIDA & PARTNERS PTE LTD |
| Co Reg No                   | 201534751W              |
| Email Address               | NOEMAIL                 |
| Mobile Phone No             |                         |
| Alternative Phone No        | OFFICE-86846321         |

### Vehicle Particulars

|  |              |
|--|--------------|
| Manufacturer   | TOYOTA       |
| Model  | RUSH-1.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident           | WORK PURPOSE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO           |
| If No, Please state action to be taken                                       | THIRD PARTY  |
| Vehicle Category   | PRIVATE HIRE |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | THIRD PARTY                            |
| Fleet Policy              | NO                                     |
| Policy Number             | 5078366681-02                          |
| Cover Note Number         |  |

### Driver

|                      |                              |
|----------------------|------------------------------|
| Name of Driver       | HALIMATUSA'ADIAH BINTE LAMRI |
| NRIC No              | S7912284Z                    |
| Date Of Birth        | 25/04/1979                   |
| Occupation           | OUTDOOR                      |
| Date Of Driving Pass | 15/02/2013                   |
| Driving Experience   | 5 YEARS AND 2 MONTHS         |
| Gender               | FEMALE                       |
| Mobile Number        | (LOCAL) +65-86846321         |
| Fax Number           |                              |
| Contact Number       |                              |
| Email Address        | NOEMAIL                      |

|   |   |
|---|---|
| Address   | BLK 55 LENGKOK BAHRU #02-395<br>SINGAPORE |
| Postcode  | 151055                                    |
| Was driver an employee of the Insured's Company     | NO  |
| If No, Relationship of the Driver with the Insured  | OTHER - HIRER                             |
| Vehicle Registration Number of Driver's Own Vehicle | -   |
|   | -   |
|   | -   |
| Insurance Company of Driver's Own Vehicle           | -   |
|   | -   |
|   | -   |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles involved in the accident   | 2   |
| Was any body injured in the Accident?   | YES |
| Was any injured conveyed to hospital by ambulance?  | NO  |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 2   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                           |
|-------------------------------------|---------------------------|
| Vehicle Registration Number         | SLB7932L                  |
| Vehicle Make/Model/Colour           |                           |
| Details Of Properties               |                           |
| Vehicle Category                    | PRIVATE CAR               |
| Name of Driver                      | MOHAMED YUSOFF BIN ISMAIL |
| NRIC/Passport Number                | S1503951E                 |
| Contact Number                      |                           |
| Address                             |                           |
| Postcode                            |                           |
| Insurance Company Name              |                           |
| Nature Of Damage                    |                           |
| No. Of Passenger (Including Driver) |                           |

#### DETAILS OF INJURED PERSON 1

|      |                              |
|------|------------------------------|
| Name | HALIMATUSA'ADIAH BINTE LAMRI |
|------|------------------------------|

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

CHEST PAIN & GIDDY

SJM3386E



## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation of withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicles(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, law or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/04/18 at about 1130 hrs I was driving along ~~the~~ Queensway towards Alexandra Road in lane 2. Approaching the above junction, the traffic light was red, I slow down & stopped. As the green arrow lit up, I proceeded with my right turn keeping in my lane. After I completed the turn I felt an impact on the rear of my vehicle. Vehicle B, SLV 7932 L, collided into the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)

  
 Reporting Centre Personnel's Signature  
 Name:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |             |   |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 02 May 2018 |               | 03 May 2018<br>14:05<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference   | Claim Details          | Documents  | Show All |         |             |              |            |       |
|---|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>  |   |                        |  |          |         |             |              |            |       |
| Insured:  | <b>HITACHI CAPITAL ASIA PACIFIC PTE LTD</b> , Co. Reg. No.: 199400399N  |                        |  |          |         |             |              |            |       |
| Main Claimant:  | <b>VIDA &amp; PARTNERS PTE LTD Co Reg</b> , Co. Reg. No.: 201534751W  |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SJM3386E</b>   | Date of Loss:          | 30/04/2018 10:00 - :59<br>[112 Months and 1 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | <b>TP / MSC/V/18-000619</b>   | Policy/Cover Note No.: | MSD/VPCP/17-001233-00 (Comprehensive)<br>Coverage: 01/06/2017 - 31/05/2018   |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>SLB7932L</b>   | Policy No. (Claimant): |  |          |         |             |              |            |       |
|   |   | Excess:                |  |          |         |             |              |            |       |
| Repairer:   | <b>Mje Motor (HQ)</b> BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:   |                        |  |          |         |             |              |            |       |
| Handling Insurer:   | <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]       |                        |  |          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 04/05/2018] |                        |  |          |         |             |              |            |       |
| Driver/Custodian (Insured):   | MOHAMED YUSOFF BIN ISMAIL (), NRIC: S1503951E, Tel: +6586111210   |                        |  |          |         |             |              |            |       |
| Adj Asg. Remarks:   | TP DISAGREE SJE FOLLOW CHART - LKK CONSULTANTS  |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |   |                        |  |          |         |             |              |            |       |
| There are no mail for this case.  |   |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |   |                        |  |          |         |             |              |            |       |
| Due Date  | Priority  | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |   |                        |  |          |         |             |              |            |       |

## Claim Documents

\*SJM3386E (MSC/V/18-000619)

[SLB7932L]

TP

VIDA & PARTNERS PTE LTD Co Reg

Apr 30 2018 10:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Mje Motor

















[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** [View in Browser](#)

| Assessment Reports |                |   | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|------------|-------------------------------------|
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ)   | Thumbnail  | Print                               |
| 1                  | 03/05/18 14:01 | <b>Accident Statement</b><br>From: SC - Reg. No: SLB7932L, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD | Load HTM   | <input type="checkbox"/>            |

| Photos/Images |                 |                                   | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 2             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 3             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 4             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 5             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 6             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 7             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 8             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 9             | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 10            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 11            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 12            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 13            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 14            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 15            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 16            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 17            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 18            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 19            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 20            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 21            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 22            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 23            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 24            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 25            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 26            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 27            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 28            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 29            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 30            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 31            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 32            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 33            | 18/07/18 12:45  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |

| Assessment Reports |                |   | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail  | Print                               |
| 34                 | 18/07/18 12:45 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 18/07/18 12:45 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 18/07/18 12:45 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 18/07/18 12:45 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 18/07/18 12:45 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 18/07/18 12:45 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 53                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 54                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 55                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 56                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 57                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 19/07/18 12:32 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation      |                |   | 1 per page   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail  | Print                               |
| 1                  | 03/05/18 14:01 | TPD SJM3386E GIA REPORT.PDF               |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008113/GZ4BE2

Date: 20/07/2018

## REFERENCE

|                       |                                      |                      |                       |
|-----------------------|--------------------------------------|----------------------|-----------------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | MSD/VPCP/17-001233-00 |
| Claimant Vehicle No : | SJM3386E                             | Insured Vehicle No : | SLB7932L              |
| Date of Loss:         | 30/04/2018                           | Nature of Claim:     | TP                    |
|                       |                                      | Claim No:            | MSC/V/18-000619       |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SJM3386E</b>                   | Engine No:  | 3SZ2076507   |
| Make & Model:               | TOYOTA RUSH, 1.5 X (A)            | Chassis No: | J200E0020790 |
| Reg. Date:                  | 29/12/2008 (Man. Year: 2008)      | Odometer:   | 143271 km    |
| Colour:                     | Black                             |             |              |
| Engine Capacity:            | 1495 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/55 R17    | Rear Tyre Size:  | 215/55 R17    |
| Front Left Side:  | Michelin 5 mm | Rear Left Side:  | Michelin 5 mm |
| Front Right Side: | Michelin 5 mm | Rear Right Side: | Michelin 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

|                             |            |               |   |
|-----------------------------|------------|---------------|---|
| Date of Assignment:         | 03/05/2018 |               |   |
| Date Inspected:             | 03/05/2018 | Inspected At: | Mje Motor (HQ)<br>BLK 7 SIN MING SECTOR C, #01-82<br>Singapore 575642 |
| Estimated Period of Repair: | 0.0 days   |               |   |

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

07

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00



## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 20 Jul 2018)  |
| <b>Parts:</b> M1-SUV   | TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SJM3386E) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >