



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD (SGF255S)

Date of Loss

30 April 2018

Time of Loss

0.00

Loss Description

GBD4892X (INSD) C/W SGF255S(TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

11/06/2018



Days of work completion *

39



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SGF255S

Registration State

SINGAPORE

Mileage

212903

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2005

CATEGORY

Make

Purchase Date

dd/mm/yyyy



Registration Date *

29/03/2006



Age of Vehicle

12

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

POST SURVEY INF...

POLICY INFORMAT... TPVD

ASSESSMENT INFO...

VOLKSWAGEN

CATEGORY

Model

POLICY INFORMAT...

ASSESSMENT INFO...

GOLF GTI

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...



CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

WVWZZZ1KZ6U018240

CATEGORY

Date of Birth

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Age

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

POST SURVEY INF...



CATEGORY

Driving Experience

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Driver License #

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... AXX059038

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1984

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI...
POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI...

FILE IN SYSTEM

POST SURVEY INF...

▼

CATEGORY

Gender

FNOL INFORMATI...

POST SURVEY INF...

▼

CATEGORY

Marital status

FNOL INFORMATI...

POST SURVEY INF...

▼

CATEGORY

Identification #

FNOL INFORMATI...

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

04/05/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/40ZR18

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

225/40ZR18

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes No

Save



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN : CHAN KIAN CHUAN

Ref: CS3/ASM18008117/Nz4be2

Date: 21-05-2018



Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBD 4892X	Veh. Inspected	SGF 255S
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00FLC	Excess (\$)	0.00
Assign From	CHAN KIAN CHUAN	Assign Date	03/05/2018


2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GTI	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	WWWZZZ1KZ6U018240	Colour	BLACK
Odometer	212903 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40Z R18	MICHELIN	6 mm
L/H Front Tyre	225/40Z R18	MICHELIN	6 mm
R/H Rear Tyre	225/40Z R18	MICHELIN	6 mm
L/H Rear Tyre	225/40Z R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.	
--	---

5. General Information

Accident Date	30/04/2018	Inspect Date / Time	04/05/2018 (12:01 PM)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/ASM18008117/Nz4be2

Inspected By

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.