

ALG

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.05.2018

REPAIR ESTIMATE

Time: 12:15:59

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305155474
REGN NO : SHA4724T
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 30.12.2016
DATE/TIME IN : 02.05.2018 07:45
ACCIDENT DATE : 30.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 04-01-0302-0898-G PRIG4 COVER OUTER MIRROR	1		107.40	25.00	80.55
0002 04-01-0302-0594-G PRIG4 MIRROR ASSY OUTER R	1		1,374.00	25.00	1,030.50
Front (RH) Rear Glass cut					
SUB-TOTAL :					1,111.05

JOB NATURE

JOB NATURE	QTY	UNIT-PRICE	DISC%	AMOUNT
0000 L LABOUR		120.00	50	
0001 23-502 SPRAYPAINT ON AFFECTED AREA		120.00	50	
0002 17-01 WIRING CHARGE		50.00	20	
SUB-TOTAL :				290.00

TOTAL : 1,401.05

Larry Ng

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kohli (KKA)
2/5/18 1505
1 Day.
PIP
After Repair ill.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date