

22/03/2002

ASS. REC. BY:

REF:

CS/MSH18008140 / Urbez

Special Instruction:

Survivor

Mumu

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSH

Date/Time:

03052018 4:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 5134U

Insured:

YP 3162R

at Workshop m/s

Tan Lim Motor

Tel:

6858 5151

of

51 Dehu Lane 10

Policy No:

A28 780304 MKC

Claim No:

55 6483

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24042018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

04052018 @ 12pm

H.O.D. Endorsement:

Date/Time:

03052018 5:05pm

Person Contacted:

William

Vehicle IN / OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

YN 5134U - CS/MSH17007796 / R/bbm2

RA: 160417

YP 3162R - X

Revrt thm memmen

REF: msh

MORRIS  
MORRIS

MORRIS

From Date: 04/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 5134U  
at Workshop m/s Tan Lim Motor  
of 51 Defu Lane 10

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GA / PR Seen Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 1/N 5134U Yr Pagn: 3.14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A.)

Make: mt center FEBU cc 2998

Colour: wh. ll A/C Insured / Std / NI / NA

Sp. Reading: 390306 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. mm

L/Bal. mm

D.O.A. 24/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/5/18 confirmed find of 1905.50 with willian

Red: 626.00, 25%

RECEIVED 11 MAY 2018

Date/Time File Pass to?

1: typist

Date/Time File Return to?

2:

Report Format:

Lump Sum / L.B.H. IS

☐ : Preli. Report☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Insp. (\$)☐ Workshop (\$)

Survey Fee:

Transportation

1. 3-PC

2. Photos

3. 100%

Total:

200

10

210

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2018 19:34 Sendback Est	24 Apr 2018 19:40 S\$2,531.50	03 May 2018 16:07 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	Atwin Marine Engineering Pte Ltd, Co. Reg. No.: 198803323W								
Main Claimant:	HOCKFULL CONSTRUCTION, Co. Reg. No.: 52860424D								
Vehicle Reg. No.:	YN5134U	Date of Loss:	24/04/2018 06:00 - :59 [48 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556483	Policy/Cover Note No.:	A28780304MKC (Comprehensive) Coverage: 23/06/2017 - 22/06/2018						
Vehicle Reg. No. (Insured):	YP3162R	Policy No. (Claimant):	5099035207						
		Excess:	S\$850.00						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/05/2018]								
Driver/Custodian (Insured):	Hasan A B M Kamrul (), NRIC: G2521544W, Tel: +6598725087								
Adj Asg. Remarks:	ON WP. Survey on 04/05/18(Fri), 12pm. Owner waiting. Please contact us ASAP if you are not able to attend this assignment.								
<b>ASSOCIATED MAIL RECEIVED</b>									
There are no mail for this case.									
<div>View All</div> <div>Compose Case Mail</div>									
<b>ALL ASSOCIATED TASKS</b>									
<div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 11 May 2018

## **Preliminary Advice**

Insured Vehicle : YP3162R  
No

TP Vehicle No : YN5134U

Make : MITSUBISHI CANTER

Date of : 04/05/2018

Inspection

Inspection At : TAN LIM MOTOR PTE LTD (DEFU)  
51 DEFU LANE 10  
SINGAPORE 539216

Accident Date : 24/04/2018

Assignment Date : 03/05/2018

Est. Duration of : 3.00  
Repair

## **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,531.50
Revised Amount	:S\$	1,905.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,905.50

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

## **Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/04/2018 17:35
Date Of Accident	24/04/2018 05:45
Exact Location Of Accident	TUAS ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN5134U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HOCKFULL CONSTRUCTION
Co Reg No	52860424D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62947251

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER-3.0 D FEB21ER3SDEB (CBU) (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099035207
Cover Note Number	23/03/2018 TO 31/03/2019

### Driver

Name of Driver	VADIVEL KARTHIK
Passport No/FIN	G3314123N
Date Of Birth	13/07/1995
Occupation	OUTDOOR
Date Of Driving Pass	06/03/2017
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94478293
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLOCK 85 KALLANG AVENUE #01-04
Postcode	339418
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	9
Passenger 1	NAME: : UNKNOWN - ADULT GENDER: : MALE
Passenger 2	NAME: : UNKNOWN - ADULT GENDER: : MALE
Passenger 3	NAME: : UNKNOWN - ADULT GENDER: : MALE
Passenger 4	NAME: : UNKNOWN - ADULT GENDER: : MALE
Passenger 5	NAME: : UNKNOWN - ADULT GENDER: : MALE
Passenger 6	NAME: : UNKNOWN - ADULT GENDER: : MALE
Passenger 7	NAME: : UNKNOWN - ADULT GENDER: : MALE
Passenger 8	NAME: : UNKNOWN - ADULT GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ROCHOR NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 11 KAMPONG KAPOR ROAD , POSTCODE: 208678 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2949999 - FAX NO: 63918583

Was notice of intended Prosecution given?

NO

If Yes, against whom?

**Circumstances of Accident**

Refer to Police Report:-T/20180424/2051

**Attachment(s)**

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

YP3162R

Vehicle Make/Model/Colour

MITSUBISHI CANTER

Details Of Properties

LORRY

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

HASAN A B M KAMRUL

NRIC/Passport Number

G2521544W

Contact Number

9872 5087

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT PORTION

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 24/04/2018 07:50h

Reporting Centre Personnel's Signature  
Name: Lam Wei Sheng  
NRIC/FIN No.: G6866052R



# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report: - T/20180424/2051

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time: 24/04/16 @ 7:50h

Reporting Centre Personnel's Signature

Name: Lam Wai Shun

NRIC/FIN No.: 66864052R

## Police Report Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180424/2051

1 of 3

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

Report No. T/20180424/2051

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 24/04/2018 14:16	Vide Report No.:	Station Diary No.: 80
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: VADIVEL KARTHIK	Address: APT BLK 85 KALLANG AVENUE #01-04 SINGAPORE 339418		
ID Type / ID No.: FIN NO / G3314123N	Contact No.: Home/Office: Mobile: 94478293		
Nationality: INDIAN	Email:		
Sex: Male	Age: 22	Date of Birth: 13/07/1995	Type of Informant: Driver
Race: Indian	Language: English		Institution / School Name:
Occupation: OPERATIONS ASSISTANT	Driving Licence Information: Class: 2B,3,4 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/04/2018 05:45	Type of Location: Straight Road
Location: Along Road 1 TUAS ROAD				
Opposite Tuas Fire Station, towards PIE Changi, 2nd Lane.				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
YN5134U	Lorry	MITSUBISHI	CANTER FEB21ER3S DEB	White	Slightly Damaged	8
YP3162R	Lorry	MITSUBISHI	CANTER FEB71ER4S DEC	White	Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180424/2051

2 of 3

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

Report No. T/20180424/2051

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	VADIVEL KARTHIK		ID No. G3314123N
Related Vehicle	YN5134U (Lorry)		Contact No. 94478293
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	HASAN A B M KAMRUL		ID No. G2521544W
Related Vehicle	YP3162R (Lorry)		Contact No. 98725087
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 24/04/2018 at around 0545hrs, I was along Tuas Road driving my vehicle bearing license plate no. YN5134U. I was on the 2nd lane. I was in front of the traffic light. When the traffic light turned green, I moved off slowly. There was vehicle bearing license plate no. YP3162R that collided into the rear of my vehicle. No one was injured. My rear bumper suffered some dents. The other vehicle suffered some dents in the front of the bumper. Traffic Police came. We decided for private settlement.

As such, I am lodging this report for insurance claims. That is all.



**SINGAPORE  
POLICE FORCE**



T/20180424/2051

3 of 3

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

Report No. T/20180424/2051

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: A / Sgt 2 GLENN CHEAH YONG QUAN <i>gcy</i>
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMMAD ABDILLAH BIN PALIL Contact No.: 65476246 <i>SN 12</i>

Signature Of Informant: <i>[Signature]</i>
Date/Time: 24/04/2018 14:16
Classification Of Case:

Authentication Stamp  
NP168

*gcy*  
Singapore Police Force

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:Business

Owner ID:0424D

Vehicle Details

Vehicle No.:YN5134U

Vehicle to be Exported:No

Intended De-registration Date:24 Apr 2018

Vehicle Make:MITSUBISHI

Vehicle Model:CANTER FEB21ER3SDEB

Primary Colour:White

Manufacturing Year:2013

Engine No.:4P10B04559

Chassis No.:FEB21EA00225

Maximum Power Output:-

Open Market Value:\$27,908.00

Original Registration Date:31 Mar 2014

First Registration Date:31 Mar 2014

Transfer Count:2

Actual ARF Paid:\$1,396.00

Intended PARF Rebate Details

PARF Eligibility:No

PARF Eligibility Expiry Date:-

PARF Rebate Amount:\$0.00

Intended COE Rebate Details

COE Expiry Date:30 Mar 2024

COE Category:C - Goods Vehicle & Bus

COE Period(Years):10

PQP Paid:\$20,598.00

COE Rebate Amount:\$12,220.00

Total Rebate Amount:\$12,220.00


The information contained herein is correct as at 24 Apr 2018

OK

Not Affected  
LKK

Chapman's Workshop  
4/5/18

3 Lg.



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)  
Atwin Marine Engineering Pte Ltd  
2 Gul Lane  
Singapore 629403

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

04/05/18 @ 152h  
Marcus - LKK

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP022042018
Policy No:		Date of Loss:	24/04/2018
Vehicle Reg. No.:	YN5134U	Driveable?	YES
Part at Fault:	UNKNOWN		
Driver (TP):	VADIVEL KARTHIK	Driver (Insured):	HASAN A B M KAMRUL

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)	Vehicle Reg. Date:	31/03/2014
Vehicle Colour:	WHITE	Gen Condition:	GOOD
Engine No:	4P10B04559	Chassis No:	FEB21EA00225
Odometer:	0 KM		

Paint Type:  
Total Loss? NO  
Est. Duration of Repair (day) 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Description of Accident/Loss: REFER TO POLICE REPORT:-T/20180424/2051  
Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS	Amount
Parts	1,541.50
Miscellaneous Items	0.00
Labour	490.00
Paintwork Labour	500.00
Towing	0.00
Gross Total (\$\$)	2,531.50
+ GST 7.00% (\$\$)	177.21
Nett Amount (\$\$)	2,708.71

This claim is handled by: LAM WEI SHONG

## Reference

**Further info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

<b>Total Parts (S\$)</b>	<b>1,541.50</b>
--------------------------	-----------------

P- 920

$$\begin{array}{r} 152 \\ \hline 1115.50 \end{array}$$

S.N - 70

$$\begin{array}{r} 1000 - 720 \\ \hline 1905.50 \end{array}$$

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>			
1	Putty and spray painting of the affected portion.	New 300	500.00
<b>Labour Items</b>			
2	To check electrical lighting concerned.	New 20	40.00
3	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same and repair tailgate lid.	New 400	450.00
Gross Labour Cost (S\$)			990.00

Tan Lim Motor Pte Ltd/YN5134U/24/04/2018 19:40. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216  
Tel : 6858 5151 (24 hours) Fax : 6858 0877  
email@tlmotor.com.sg www.tlmotor.com.sg  
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2





Ng Wah Hong  
Enterprises Pte Ltd  
Office & Workshop  
52 Defu Lane 9,  
Singapore 539292  
07 Defu Lane 9,  
Singapore 539249  
T (65) 6487 1491  
F (65) 6487 1493  
nwh.com.sg  
GST Reg.: 199902575E

300T/077  
Messrs TAN LIM MOTOR PTE LTD  
51 DEFU LANE 10  
SINGAPORE 539216

Attn MR TAN/MR LAI:HP9116-0051

## TAX INVOICE E1800719

Quotation No.  
Your P/O No.  
Date 05/05/2018  
Terms C.O.D  
Salesman GERALD  
Page 1

S/N	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Make & Model : MIT 14FT			
	Vehicle No : YN5134U			
1	To supply & install (01) rear under run bumper	1	850.00	850.00

SINGAPORE DOLLARS : NINE HUNDRED NINE AND CENTS FIFTY ONLY

<div>1. Please pay 40% of total quote upon confirmation. 2. Full payment upon collection. 3. Deposit is not refundable. 4. Goods sold is not returnable. 5. All orders executed within 3 months of confirmation. 6. The company accepts no liability for any loss, damage, however caused. 7. The company reserves the right to change delivery date and time. 8. Unless full payment is received, the company reserves the right to reclaim/re-possess products and/or services supplied to the customer.</div>	Sub-Total	850.00
	Discount 0.00 %	0.00
	GST 7 %	59.50
	Total	909.50
	Less Deposit :	0.00
AMOUNT DUE : S\$		909.50

Received above mentioned goods in good order and condition

for NG WAH HONG ENTERPRISES PTE LTD

Received by

Signature, Company Stamp & Date

AUTHORISED SIGNATURE(S)



友興汽車零件有限公司  
**YEW HENG AUTO PARTS PTE LTD**

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708  
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858  
Email: yewheng@yewhengauto.sg  
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

**TAX INVOICE**

NO: **YLI1205932**  
PAGE: 1  
DATE: 05/05/2018  
A/C CODE: LYTL001  
TERMS: 30 DAYS  
P/O NO: YN5134U

TO: **TAN LIM MOTOR PTE LTD**

51 DEFU LANE 10  
SINGAPORE 539216

*P/O 90412*

*TP 201804022*

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
JMK580766	LAMP ASSY, COMB, RR RH	YDS	1	120.00	120.00
TOTAL QUANTITY			1	TOTAL	SIN 120.00
				ADD GST @ 7%	8.40
				GRAND TOTAL	<b>SIN 128.40</b>

DELIVERY

POSTED 07 MAY 2018

*90412*

*YN 51344*

*TP 022042018*

Printed / KOHZY / 05/05/2018 10:23:10 AM

LESMAN: KOHZY

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E & O E

GOODS RECEIVED BY



# 友興汽車零件有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708  
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858  
Email: yewheng@yewhengauto.sg  
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

## TAX INVOICE

NO: YLI1205940  
PAGE: 1  
DATE: 05/05/2018  
A/C CODE: LYTL001  
TERMS: 30 DAYS  
P/O NO: YN5134U

TAN LIM MOTOR PTE LTD

51 DEFU LANE 10  
SINGAPORE 539216

P/O 90412

TP 2018040622

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
JMK580765	LAMP ASSY, COMB, RR LH	1F-1A	1	120.00	120.00
TOTAL QUANTITY:			1	TOTAL	SIN 120.00
				ADD GST @ 7%	8.40
				GRAND TOTAL	<b>SIN 128.40</b>

DELIVERY

POSTED 07 MAY 2018

90412

YN5134U

~~TP00~~ TP0022042018

nt / KXM / 05/05/2018 11:19:10 AM

LESAN: KXM

is document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Apr 2018 19:34 <a href="#">Sendback Est</a>	24 Apr 2018 19:40 <b>S\$2,531.50</b>	03 May 2018 16:07 <a href="#">Edit Adj Rpt</a>	<b>S\$1,905.50</b> <a href="#">Edit Estimates</a>	<b>S\$1,905.50</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS	
Insured:	<b>Atwin Marine Engineering Pte Ltd</b> , Co. Reg. No.: 198803323W
Main Claimant:	<b>HOCKFULL CONSTRUCTION</b> , Co. Reg. No.: 52860424D
Vehicle Reg. No.:	<b>YN5134U</b>
Date of Loss:	24/04/2018 06:00 - :59 [48 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 556483</b>
Policy/Cover Note No.:	A28780304MKC (Comprehensive) Coverage: 23/06/2017 - 22/06/2018
Vehicle Reg. No. (Insured):	<b>YP3162R</b>
Policy No. (Claimant):	5099035207
Excess:	S\$850.00
Repairer:	<b>Tan Lim Motor Pte Ltd (Defu)</b> 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 02/06/2018]
Driver/Custodian (Insured):	Hasan A B M Kamrul (), NRIC: G2521544W, Tel: +6598725087
Adj Asg. Remarks:	ON WP. Survey on 04/05/18(Fri), 12pm. Owner waiting. Please contact us ASAP if you are not able to attend this assignment.

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.


































#### ALL ASSOCIATED TASKS














[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**YN5134U (556483)**  
**[YP3162R]**  
**TP**  
**HOCKFULL CONSTRUCTION**  
**Apr 24 2018 6:00AM**  
**[Atwin Marine Engineering Pte Ltd]**  
**Tan Lim Motor Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	24/04/18 17:58	<b>Accident Statement</b>	 Load HTM	<input type="checkbox"/>
2	24/04/18 19:40	<b>Repalrer Estimates</b>	 Load HTM	<input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/04/18 08:46	<b>Accident Statement</b> From: SC - Reg. No: YP3162R, Claimant: ATWIN MARINE ENGINEERING PTE LTD	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 10:46	<b>Adjuster Immediate Advice</b>	 Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/05/18 10:35	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
2	05/05/18 10:35	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
3	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	05/05/18 10:35	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
30	05/05/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/05/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/05/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/05/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/05/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/05/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/05/18 08:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/05/18 08:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/05/18 08:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/05/18 08:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/05/18 08:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/04/18 08:46	<b>POLICY DOCUMENTS</b> From: SC - Reg. No: YP3162R, Claimant: ATWIN MARINE ENGINEERING PTE LTD	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/05/18 10:35	Parts Invoice	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com,assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008140/URBE2

Date: 14/05/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28780304MKC  
 Claimant Vehicle No: YN5134U Insured Vehicle No: YP3162R  
 Date of Loss: 24/04/2018 Nature of Claim: TP Claim No: 556483

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: YN5134U  
 Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) Engine No: 4P10B04559  
 (M)  
 Reg. Date: 31/03/2014 (Man. Year: 2013) Chassis No: FEB21EA00225  
 Colour: White Odometer: 390306 km  
 Engine Capacity: 2998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/85R15 Rear Tyre Size: 195/85R15  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,541.50	1,185.50	356.00	23.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	490.00	420.00	70.00	14.29
Paintwork Labour	500.00	300.00	200.00	40.00
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,531.50</b>	<b>1,905.50</b>	<b>626.00</b>	<b>24.73</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>177.21</b>	<b>133.39</b>	<b>43.82</b>	<b>24.73</b>
<b>Nett Amount (S\$)</b>	<b>2,708.71</b>	<b>2,038.89</b>	<b>669.82</b>	<b>24.73</b>

## INSPECTION

Date of Assignment: 03/05/2018 Present Location: Tan Lim Motor Pte Ltd (Defu)  
 Date Inspected: 04/05/2018 Inspected At: 51 Defu Lane 10  
 Singapore 539216  
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 14 May 2018)  
**Parts:** N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for YN5134U)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*rear bumper under-run with stay end serial no. (WCP)	Bent	1,000.00 FS	*850.00 F
2	1		*rear bumper under-run with reflective sticker	Necessary	50.00 FS	*50.00 FS
3	1		*rear lamp (O/s Cracked)(WCP)	N/s Cracked/O/s Not Consistent	360.00 FS	*120.00 F
4	1		*rear lamp holder brackets	Not Necessary	50.00 FS	*- FS
5	1		*tailgate lid mitshubishi sticker	Not Necessary	30.00 FS	*- FS
6	1		*tailgate lid 60 km/h sticker	Necessary	20.00 FS	*10.00 FS
7	1		*tailgate lid 22 pax sticker	Necessary	20.00 FS	*10.00 FS
8	2		*tailgate lid rubber stopper (WCP)	Not Necessary	10.00 F	*- F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>1,540.00</b>	<b>1,040.00</b>
<b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b>	<b>1.50</b>	<b>145.50</b>
<b>Total Parts (\$\$)</b>	<b>1,541.50</b>	<b>1,185.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	Putty and spray painting of the affected portion.	New	500.00	300.00
<b><u>Labour Items</u></b>				
2	To check electrical lighting concerned.	New	40.00	20.00
3	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same and repair tailgate lid.	New	450.00	400.00
Gross Labour Cost (\$\$)			990.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >