

ASS. REC. BY:

REF: CS3 / AG18008141 / R124627 Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person):

Julie

of

AGI

Date/Time:

03/05/2018 4pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKR 7526D

Insured:

FBK 96798

at Workshop m/s

Xin Yun Auto

Tel:

9839 1555

of

Blk 8 Kaki Bukit Ave 4 #05-23

Policy No:

Claim No:

C20001957 / AH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30012018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp

H.O.D. Endorsement:

Date/Time:

03/05/2018 5:03pm

Person Contacted:

Yi Xin

Vehicle-IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKR 7526D - NA / INC17013016 / 13

QA: 03/07/17

FBK 96798 - X

Estimate Range & Repair

4/5/18

After Repair

Form

REF:

AGI

3711C

ASSIGNMENT

From:

Date: 9/5/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 7526D

at Workshop m/s Xin Yun Auto

of BLK 8 Kaki Bukit #05-23

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res: Yes or No

Lum Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKR 7526D

Yr Regn:

2015 MAR

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru XV 1.6 I

C.C. 1600

Colour:

BLUG

A/C: Insured / Std / NI / NA

Sp. Reading:

048465

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JP14P3XCSEA146842

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ in order / Jammed / Leaked / Burnt or

Brake: ☒ in order / Jammed / Leaked / Burnt or

Modi: Nil ☒ / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIE / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

30/04/18

D.O.I:

09/05/18 @ 4:49

Survey held at

Xin Yun Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

PRS

* Repair Estimate : S\$ 7000 - 8000

* 4 days

16/5/18 Submit PRS Report

RECEIVED 17 MAY 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S & P S

Phone

Other

TOTAL

Add Fee:

☐

Site Insp: /\$

☐

Interview: /\$

☐

Tech. Insp: /\$

☐

Weekend: /\$

100

60

160

Report Format:

Lump Sum / I.B.I: /\$

Catherine Chong (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Thursday, 3 May, 2018 4:00 PM
To: 'SUR'; assignments@lkkauto.com
Cc: Albert Hong
Subject: FW: 2nd Notice to Conduct Pre-Repair Survey - Claim ref; C20001557/AH
Attachments: PRS 2 - SKR 7526D.PDF

Sent on behalf of Albert

Hi Team

Please accept PRI survey request and survey on a without prejudice basis.

Attached is the workshop details.

Thank you,
-Julie

From: Julie Mangubat
Sent: Thursday, 3 May, 2018 3:53 PM
To: accident@kscgp.com
Cc: motor@kscgp.com; Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: RE: 2nd Notice to Conduct Pre-Repair Survey - Your ref: FBK 9679B ; C20001557 | Our ref: SKR 7526D/XY/sy/ms

Without Prejudice

Hi Myra

We are not agreeable to your list of surveyors.

We will proceed to send our surveyor and liaise with your workshop accordingly.

Thank you.

Best Regards,
Julie Mangubat
Executive, Claims

T +65 6540 2181
F +65 6725 0853
E julie.m@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: accident@kscgp.com <accident@kscgp.com>
Sent: Thursday, 3 May, 2018 3:41 PM
To: Julie Mangubat <julie.m@budgetdirect.com.sg>
Cc: motor@kscgp.com; Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: 2nd Notice to Conduct Pre-Repair Survey - Your ref: FBK 9679B ; C20001557 | Our ref: SKR 7526D/XY/sy/ms

Dear Julie,

We are instructed to reply to you as enclosed.

Thank you.

Regards,
Myra
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Julie Mangubat [<mailto:julie.m@budgetdirect.com.sg>]
To: accident@kscgp.com
Cc: motor@kscgp.com, albert.hong@budgetdirect.com.sg
Sent: Thu, 3 May 2018 06:39:39 +0000
Subject:

Without Prejudice

Dear Sir

We refer to your notice of PRS on even date.

Please find the list of your surveyors to choose from.

1. Calvin Ang LKK Auto Consultant Pte Ltd
2. Bryan Ang LKK Auto Consultant Pte Ltd

3. Xing Guo Qiang LKK Auto Consultant Pte Ltd
4. Mohammed Rasul LKK Auto Consultants Pte Ltd
5. Mohamad Taufihk LKK Auto Consultants Pte Ltd
6. Simon Ho LKK Auto Consultants Pte Ltd
7. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
8. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd
9. Lim Say Koon FormTeam Adjusters Pte Ltd
10. Ng You Han FormTeam Adjusters Pte Ltd
11. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd
12. Chow Bo Xiong FormTeam Adjusters Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thank you,
-Julie

From: accident@kscgp.com <accident@kscgp.com>

Sent: Thursday, 3 May, 2018 12:48 PM

To: Motor Claims <motorclaims@budgetdirect.com.sg>

Cc: motor@kscgp.com

Subject: Notice to Conduct Pre-Repair Survey - Your insured's vehicle: FBK 9679B Our ref: SKR 7526D/XY/sy/ms

Dear Sir/Mdm,

Please find enclosed the Notice to Conduct Pre-Repair Survey.

Thank you.

Regards,

Myra

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Your ref : FBK 9679B ; C20001557
Our client's vehicle / ref: SKR 7526D ; XY/sy/ms
Date : 3 May 2018

Auto & General Insurance (Singapore) Pte Limited

By Email Only

Dear Sirs,

DATE OF ACCIDENT: 30 APRIL 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Chang Fuh Keong, Dave	Sincere Appraisal Services
2.	Ang Guea Kiang	CA Appraiser Pte Ltd
3.	Ong Poh Meng	Aeon Auto Consultant LLP
4.	Lee Kok Weng	Lee Automobile Appraisers Services
5.	Ong Ah Keng, Kent	KTO Automobile Assessors

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected on **Monday, 7 May 2018** at:

Workshop : Xin Yun Auto Pte Ltd
Address : Block 8 Kaki Bukit Avenue 4
#05-23 Premier @ Kaki Bukit Singapore
Singapore 415875 (Gate 2)
Contact : Mr. Fabian (h/p: 9839 1666)
Ms Yi Xin (h/p: 9839 1555)

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,



Your ref : FBK 9679B ; C20001557

Our client's vehicle / ref: SKR 7526D ; XY/sy/ms

Date : 3 May 2018

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as
follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (after dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (party by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2018 11:57
Date Of Accident	30/04/2018 08:25
Exact Location Of Accident	SUBARU WORKSHOP AT LENG KEE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR7526D
Insured/Policyholder	
Name Of Registered Owner	PNG CHIN HONG
NRIC No	S7023711C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91289558
Alternative Phone No	OTHERS-91289558

Vehicle Particulars

Manufacturer	SUBARU
Model	XV-1.6 I-S AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA043727/1
Cover Note Number	

Driver

Name of Driver	PNG CHIN HONG
NRIC No	S7023711C
Date Of Birth	20/07/1970
Occupation	INDOOR
Date Of Driving Pass	01/10/1993
Driving Experience	24 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91289558
Fax Number	
Contact Number	OTHERS-91289558
Email Address	NOEMAIL

Address	129 LORONG L TELOK KURAU #04-10
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	FBK9679B
Vehicle Make/Model/Colour	YAMAHA MT-03 ABS (MTN320-A)
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

A SKR7526D

B FOK9679B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I start to move my car when B vehicle FOK9679B drove through the car park pocket on my left and hit onto my left side of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: Subin
NRIC/FIN No: S8042377A

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to sample claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 
Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: J. & G. N.
NRIC/Fin No. 60401710




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
AUTO & GENERAL INSURANCE (S) PL		Ref:	CS3/AGI18008141/R1z4be2
(BUDGET DIRECT INSURANCE)190 CLEMENCEAU AVENUE #03-01 S S C SINGAPORE 239924		Date:	17-05-2018
		Code:	AGI
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	FBK 9679B	Veh. Inspected	SKR 7526D
Policy No.		Coverage (\$)	0.00
Claim No.	C20001557/AH	Excess (\$)	0.00
Assign From	JULIE	Assign Date	03/05/2018
2. Vehicle Particulars & Condition			
Make & Model	SUBARU XV 1.6I	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JF1GP3KC5EG146842	Colour	BLUE
Odometer	48465 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	PIRELLI	6 mm
L/H Front Tyre	225/55 R17	PIRELLI	6 mm
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION			
5. General Information			
Accident Date	30/04/2018	Inspect Date / Time	09/05/2018 (04:49 PM)
Survey held at	BLK 8 KAKI BUKIT AVE 4 #05-23		
Repairer	XIN YUN AUTO PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/AGI18008141/R1z4be2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.