

Your Ref: MSC/MCGL/17-000048

Date: 11th May 2018

Our Ref: CS1/MSG18008145/T1rbs2

M/s MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay
#24-01 Hong Leong Bldg
Singapore 048581
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
S 1067CD INSURED VEHICLE: Public Liability**

We thank you for your instruction on 02/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of S 1067CD from M/s Performance Motors Ltd.
- b) Final Repair Bill of S 1067CD from M/s Performance Motors Ltd.
- c) Colour damaged vehicle photographs of S 1067CD.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -
Registration Number : S 1067CD
Make & Model : BMW 320IA/4
Year of Registration : 2013
Chassis Number : NP47245
2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.