


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1568H  
 Ref. No : BUS/05/17/7027  
 Reg. Date : 01/01/1900  
 Vehicle Type : BUS -12M  
 Make : MAN  
 Model : MAN  
 Name of Driver : Ng Kheng Kee  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 20/05/2017 11:47:00 AM  
 Accident Reported Date / Time : 22/05/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : AXA  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC,if any :  
 FRONT LEFT PORTION.  
 TP: SHB7765A  
 Prepared Date : 23/05/2017 03:08:47 PM



**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudices" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Sebastian.  
 3/5/18.  
 - hump  
 - Sun Repair  
 - Photo After Paint.

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

### Summary of Repair Estimates

|                              | Quotation from ARC       | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges         | : 795.00                 | 0.00                                |
| Total Spray Painting Charges | : 538.00                 | 0.00                                |
| Total Material Charges       | : 0.00                   | 0.00                                |
| Other Charges                | : 0.00                   | 0.00                                |
| <b>TOTAL</b>                 | <b>: 1,333.00</b>        | <b>0.00</b>                         |
| <b>Lum Sum Total</b>         | <b>: 0.00</b>            | <b>0.00</b>                         |
| No. of Repair Days           | : 2.00                   | <del>0.00</del>                     |
| Prepared / Adjusted By       | :                        | 1 day.                              |
| Arc / Surveyor Sing Off Date | : 13/06/2017 11:48:43 AM | 01/01/1900 12:00:00 AM              |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/06/2017 11:48:43 AM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

|                  |                 |
|------------------|-----------------|
| Quotation No :   | Invoice No :    |
| Quotation Date : | Invoice Date :  |
| Invoice Amount : | Prepared Date : |

**Part 1 - Labour Works**

| Job Scope                  | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------------|--------------------|-------------------------------------|
| TO REPAIR LH FRONT PORTION | 795.00             | <del>0.00</del> 530                 |
| <b>Total Labour</b>        | <b>795.00</b>      | <b>0.00</b>                         |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope   | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | 538.00             | <del>0.00</del> 400                 |
| <b>Total Spray Painting &amp; Panel Beating</b>                     | <b>538.00</b>      | <b>0.00</b>                         |

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

| Job Scope                | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------|--------------------|-------------------------------------|
| <b>Total Other Costs</b> |                    |                                     |

**Part 4 - Spare Parts / Material Usage**

| Part Number                 | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommended | Surveyor Approved | Photos Attached |
|-----------------------------|---------|----------|-----------|-----|-----------------|--------------|------------------|-----------------|-------------------|-----------------|
| TOTAL MATERIALS             |         |          |           |     |                 |              |                  |                 |                   |                 |
| TOTAL MATERIALS(Discounted) |         |          |           |     |                 |              | 0.00             | 0.00            |                   |                 |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number                   | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS |         |           |     |                 |              |                  |           |                |          |