

EDIT	S/N	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACT (PAR
☐	☐	8	1		FRONT BONNET LOCK LOWER - RH			Serviceable	0				0	Rev
☐	☐	9	1		FRONT BUMPER			Deformed	650				650	Rev
☐	☐	10	1		HEADLAMP NOZZLE COVER - LH			Cut	18				18	Rev
☐	☐	11	1		HEADLAMP NOZZLE COVER - RH			Cut	18				18	Rev
☐	☐	12	1		RADIATOR GRILLE - LH			Necessary	75				75	Rev
☐	☐	13	1		RADIATOR GRILLE - RH			Cracked	75				75	Rev
☐	☐	14	1		RADIATOR GRILLE AIR GUIDE			Cracked	85				85	Rev
☐	☐	15	1		RADIATOR SUPPORT PANEL			Deformed	400				400	Rev
☐	☐	16	1		EXPANSION TANK BYPASS HOSE			Cut	50				50	Rev
☐	☐	17	1		AIR INTAKE DUCT			Cracked	65				65	Rev
☐	☐	18	2		AIR INTAKE DUCT CLIP			Necessary	1.5				3	Rev
☐	☐	19	1		BRACE PANEL			Repair	0				0	Rev

Detailed Assessment

Inspection Date *

05/04/2018



Condition of Vehicle at time of survey

General condition

Fair

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

500

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/45ZR17

Rear Tyre Size

225/45ZR17

POST SURVEY INF...

CATEGORY	Gender
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	Marital status
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	Identification #
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Make	Date of Birth
POLICY INFORMAT...	BMW	FNOL INFORMATI...
ASSESSMENT INFO...	B.M.W.	POST SURVEY INF... 
CATEGORY	Model	Age
POLICY INFORMAT...	325 I CABRIOLET	FNOL INFORMATI...
ASSESSMENT INFO...	325I CONVERTIBLE	POST SURVEY INF...
CATEGORY	Type	Occupation
POLICY INFORMAT...		FNOL INFORMATI...
ASSESSMENT INFO...		POST SURVEY INF...
CATEGORY	Type of Paint	Education Qualification
POLICY INFORMAT...		FNOL INFORMATI...
ASSESSMENT INFO...		POST SURVEY INF...
CATEGORY	Chassis No	Driving Experience
POLICY INFORMAT...	WBAWL12050PD76401	FNOL INFORMATI...
		POST SURVEY INF...
		CATEGORY

Accelerated survey
and authorize

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

▼

Additional Instructions

Wkshop: Ah Lim @ Sin Ming Excess: \$500

Document SubType

▼

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
PARTS INVOICE.pdf	Invoice	Spare Part / Accessories Supplier	LKK AUTO CONSULTANTS PTE LTD (OD)	June 8, 2018
FINAL INV - SKQ2299Y- 06042018112711.pdf	Invoice	Repairer	AH LIM MOTOR CO (Sin Ming)	June 4, 2018