

ASS. REC. BY:

REF:

CS/CT18008201/Ag bnz

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Sharon Han

of

CT

Date/Time: 04052018 338pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 1886C

Insured:

GZ 7572A

at Workshop m/s

Autolution

Tel:

96450079

of

19 Ubi Rd 4

Policy No:

DMCVSN 3013921800

Claim No:

SNM1800205102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19042018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

04052018 353pm

Person Contacted:

Hamzah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 1886C - 003/ALH13000609/Dwb302

D/A: 03012018

GZ 7572A - x

16/10/18 2:20pm confirmed with Hamzah from Ag 81923-52, 3 days.
(Red 6837.52, 30%.)

REF: CTI

murmen

ASSIGNMENT

From: Date: 07/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 1886C

at Workshop m/s

of

Autolution
19 Ubi Rd 4

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

HamZah

(Policy Condition)

3pm

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 hrs days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKW1886C Yr Reg: 2015 / oct

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai. o.c. 1197

Colour: Brown. A/C: Insured / Std / NI / NA

Sp. Reading: 37825 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ~~SN~~ SINFEAJ1161472235Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SiRim / STD A/Rim or

Tyre Size: F: 215/60R17-

R: 215/60R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 07/05/18

Survey held at Tan Chong Cubic.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TR China.

RECEIVED 16 OCT 2018

Date/Time, File Pass to?

1) 16/10 10:15

Date/Time, File Return to?

2)

☐
☐

Preli. Report

Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Wier-TP

1923.52

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 May 2018		04 May 2018 15:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHAO JUN ELECTRICAL PTE LTD, Co. Reg. No.: 201313151K		
Main Claimant:	JUAY KANGJIE, EDMUND (RUI KANGJIE, EDMUND), ID: S8308206B		
Vehicle Reg. No.:	SKW1886C	Date of Loss:	19/04/2018 14:00 - :59
Claim Type:	TP / SNM18D02051C02	Policy/Cover Note No.:	DMCVSN3013921800 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GZ7572A	Policy No. (Claimant):	2100434392-02
		Excess:	S\$0.00
Repairer:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2018]		
Driver/Custodian (Insured):	LI CHAOCHAO (24 / Male), NRIC: S9373698B, Tel: +6598276005		
Adj Asg. Remarks:	EST \$2761.04 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 16 October 2018 2:20 PM
To: Hamzah
Cc: SUR
Subject: RE: SKW1886C - Final repair copy

Dear Hamzah,

WITHOUT PREJUDICE

Confirm final fig \$1,923.52 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hamzah <hamzah_saad@tanchong.com>
Sent: Tuesday, 16 October 2018 11:43 AM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: Re: SKW1886C - Final repair copy

Hi,

Kindly assist on this claim.

I've send final repair copy last month and kindly revert for invoicing.

Regards

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/04/2018 09:07
Date Of Accident	19/04/2018 14:50
Exact Location Of Accident	PAYA LEBAR - AIR BASE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW1886C
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	JUAY KANGJIE, EDMUND (RUI KANGJIE, EDMUND)
NRIC No	S8308206B
Email Address	VERSA83@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98370578
Alternative Phone No	OTHERS-98370578

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-1.2 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100434392-02
Cover Note Number	

Driver


Name of Driver	JUAY KANGJIE, EDMUND (RUI KANGJIE, EDMUND)
NRIC No	S8308206B
Date Of Birth	24/03/1983
Occupation	INDOOR
Date Of Driving Pass	12/05/2005
Driving Experience	12 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98370578
Fax Number	
Contact Number	OTHERS-98370578
Email Address	VERSA83@YAHOO.COM.SG



Details Of Properties

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LI CHAO CHAO
NRIC/Passport Number	S9373696B
Contact Number	98276005
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

42



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The vehicle was parked at Paya Lebar Air Base. When my colleague and I ~~were~~ were about to alight ~~at~~ the car, the lorry reversed straight into my ~~static~~ stationary vehicle. The lorry reversed with acceleration and hit straight to the ~~back of the~~ ^{back} left door. A huge dent was noticeable at the left ~~back~~ door.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Reddy
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

AM
AUTOLUTION INDUSTRIAL PTE LTD
Reporting Centre Personnel's Signature
NSIR ROAD
SINGAPORE 408623
TEL: 650 9665 FAX: 6546 7483

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0240/18

DATE : 20-APR-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : MR JUAY KANGJIE, EDMUND (RUI KANGJIE, EDMUND)

ADDRESS : BLK 987A BUANGKOK GREEN

#06-07

S(531987)

TELEPHONE NO : 96370578

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SKW1886C

MODEL CODE : FRLARBZJ11UEA--A--

MODEL/YEAR : NISSAN QASHQAI 1:2

ENGINE NO : HRA2201249A

CHASSIS NO : SJNFEA11U1472235

MILEAGE : 37160 KM

DATE IN : 20/04/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 19/04/2018

96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW1886C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO RENEW LH REAR DOOR.	600.00	390 /
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	350.00	290 /
3 ZZ/003	LABOUR CHARGES TO REMOVE AND INSTALL LH REAR DOOR MECHANISM.	80.00	✓
TOTAL LABOUR CHARGES		1030.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW1886C

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES <i>Ne</i>	NPN		50.00 <i>20</i>
2	REAR WHEEL ARC MLOG LH <i>Ne</i>	93829-4EA0A	483.00	<i>X</i>
3	REAR DOOR PVC MLOG LH <i>Del</i>	82871-4EA0A	264.80	<i>/</i>
4	REAR DOOR TOP MLOG LH <i>Ne</i>	82821-4EA0A	188.90	<i>X</i>
5	REAR DOOR TAPE LH <i>Ne</i>	82819-4EA0A	29.90	<i>/</i>
6	REAR DOOR TAPE LH <i>Ne</i>	82813-4EA0A	29.90	<i>/</i>
7	DOOR-REAR LH <i>Disturbed</i>	H2101-4EAMA	1104.80	<i>/</i>
SUB TOTAL			2101.30	0.00 50.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			420.26	0.00 0.00
GRAND TOTAL			1681.04	0.00 50.00
OVERALL TOTAL			1731.04	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKW1896C

TOTAL LABOUR CHARGES	1030.00
TOTAL SPARE PARTS CHARGES	1731.04
GRAND TOTAL	2761.04 *

* All charges do2 not include GST.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Adrian Lim
07/05/18.

96893735.
03Days.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Adrian

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
15 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7487

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/HV/0240/18
DATE : 20-APR-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63696111
FAX : 62247175

OWNER'S NAME : MR JUAY KANGJIE, EDMUND (RUI KANGJIE, EDMUND)
ADDRESS : BLK 987A BUANGKOK GREEN
#06-07
S(531987)
TELEPHONE NO : 98370578

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SKW1006C
MODEL CODE : FRLARBZJ11UEA-A++
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2201249A
CHASSIS NO : SJNFEAJ11U1472235
MILEAGE : 38623 KM
DATE IN : 20/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HANZAH
ACCIDENT DATE : 19/04/2018

3 days

- 96450079

AUTOLUTION INDUSTRIAL PTE. LTD.

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGN1886C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO RENEW LH REAR DOOR.	600.00	390.00
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	350.00	290.00
3 ZZ/003	LABOUR CHARGES TO REMOVE AND INSTALL LH REAR DOOR MECHANISM.	80.00	80.00
TOTAL LABOUR CHARGES		1030.00	760.00

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW1886C

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			20.00	OK
2	REAR WHEEL ARC MLDG LH	93829-4EA0A	483.00			X
3	REAR DOOR PVC MLDG LH	82871-4EA0A	264.80			OK
4	REAR DOOR TOP MLDG LH	82821-4EA0A	188.90			X
5	REAR DOOR TAPE LH	82819-4EA0A	29.90			OK
6	REAR DOOR TAPE LH	82813-4EA0A	29.90			OK
7	DOOR-REAR LH	H2101-4EAWA	1104.80			OK
SUB TOTAL			1429.40	0.00	20.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			285.88	0.00	0.00	
GRAND TOTAL			1143.52	0.00	20.00	
OVERALL TOTAL			1163.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKH1886C

NETT ITEM	1429.40
LESS 20.00%	-285.88
NETT AMOUNT	1143.52

LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	20.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	20.00

TOTAL LABOUR CHARGES	760.00
TOTAL SPARE PARTS CHARGES	1163.52

TOTAL CHARGES	1923.52
ADD 7 % GST	134.65

GRAND TOTAL	2058.17
-------------	---------

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18008201/AQBN2

Date: 16/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3013921800
Claimant Vehicle No :	SKW1886C	Insured Vehicle No :	GZ7572A
Date of Loss:	19/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D02051C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW1886C	Engine No:	HRA2201249A
Make & Model:	NISSAN QASHQAI, 1.2 (A)	Chassis No:	SJNFEAJ11U1472235
Reg. Date:	21/10/2015 (Man. Year: 2015)	Odometer:	37825 km
Colour:	Brown		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,731.04	1,163.52	567.52	32.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	760.00	270.00	26.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,761.04	1,923.52	837.52	30.33
+ GST 7.00/7.00% (S\$)	193.27	134.65	58.62	30.33
Nett Amount (S\$)	2,954.31	2,058.17	896.14	30.33

INSPECTION

Date of Assignment:	04/05/2018		
Date Inspected:	07/05/2018	Inspected At:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2018)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW1886C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL ARC MLDG LH	Not Necessary	483.00 FN	*- FN
2	1		*REAR DOOR PVC MLDG LH	Deformed	264.80 FN	*264.80 FN
3	1		*REAR DOOR TOP MLDG LH	Not Necessary	188.90 FN	*- FN
4	1		*REAR DOOR TAPE LH	Necessary	29.90 FN	*29.90 FN
5	1		*REAR DOOR TAPE LH	Necessary	29.90 FN	*29.90 FN
6	1		*DOOR-REAR LH	Distorted	1,104.80 FN	*1,104.80 FN
7	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
					Sub Total (S\$)	2,151.30
					- Nett Item Discount on N Items 20.00/20.00% (S\$)	420.26
					Total Parts (S\$)	1,731.04
						1,163.52

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO RENEW LH REAR DOOR	New	600.00	390.00
2	CHARGES TO SPRAY PAINTING SAME	New	350.00	290.00
3	LABOUR CHARGES TO REMOVE AND INSTALL LH REAR DOOR MECHANISM	New	80.00	80.00
Gross Labour Cost (S\$)			1,030.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >