

NS. CASE OWNER:

CC 4 / ASM1800

8233, Aua32

LKK:

IDAC:

43363

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Muhammad Saiful Bin Abdul Razak

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost: Cash-in-lieu

S\$

1700.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

300.00 x 50 x 6 days

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

2000.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

2000.00

Name 1:

AUTOLUTION INDUSTRIAL PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 31 AUG 2018

COPY SENT 31/8/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

REF: ASM(AXA)

8233 (Ana) - (U)

ASSIGNMENT

06/10/08

2008 Oct

From:

Date: 07052018

Veh No:

SJK1195M.

Yr Regn:

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJK 1195M

at Workshop m/s

Autolution

of

19 Ubi Rd 4

Make:

Nissan Sylphy.

C/G

1498

Colour:

Blue.

A/C

Insured / Std / NI / NA

Sp. Reading

135816.

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JN1BAAG1120106864

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Humzah

Modi: Nil S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 195/65R15

R: 195/65R15.

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lump Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

07/05/18

Survey held at

Tan Chong (Ubi)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP AXA.

MV: 12.8K
 PV: 9.3K
 Nett: 3.5K

LIS - \$ 3750.00
 check item - \$ 172.20

offer cash-in-lieu - \$ 1700.00 with 6 day

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee:

☐

Site Insp (\$

S + RS + SI

☐

Interview (\$

1 Photos

☐

Tech. Invs (\$

1 Other

☐

Week-end (\$

1

TOTAL

Report Format:

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008233/ua3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 05-05-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 325Z	Veh. Inspected	SJK 1195M	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00B29	Excess (\$)	0.00	
Assign From		Assign Date	01/01/1900	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/03/2018	Inspection Date		
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0175/18

DATE : 13-MAR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : PANG LIM KWEE
ADDRESS : BLK 604 BEDOK RESERVOIR RD
#05-590
S(470604)
TELEPHONE NO : 93697270/90934751

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SJK1195H
MODEL CODE : BDUARCA11EHJ-----
MODEL/YEAR : SYLPHY 1.5 4A/T SEDAN (MC)
ENGINE NO : HR150327318
CHASSIS NO : JN1BAAG11Z0106864
MILEAGE : 135400 KM
DATE IN : 13/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 12/03/2018

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO. SJK1195M

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR FENDER, RENEW REAR PANEL, TRUNK LID & REAR BUMPER,	1300.00	750
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1200.00	1000
3 ZZ/003	TRANSFER TRUNK LID MECHANISM,	80.00	/
4 ZZ/004	RENEW REVERSE SENSOR.	55.00	✓
5 ZZ/005	APPLY SEALANT TO REAR PANEL.	100.00	X.
6 ZZ/006	PERFORM RUST PROOFING TO REAR PANEL.	120.00	X.
7 ZZ/007	SUPPLY REAR LICENCE PLATE.		
	TOTAL LABOUR CHARGES	2855.00	

1885
57
1290 73

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK1195M

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			100.00	?
2	REAR LICENCE PLATE <i>new</i>	RLP			60.00	+
3	REAR PANEL <i>Repaired</i>	79110-EW000	438.70	+		
4	L/R LAMP PACKING ?	26558-EW00A	17.60	?		
5	R/R LAMP PACKING ?	26553-EW00A	17.60	?		
6	L/R TRUNK LAMP <i>cut</i>	26555-EW01A	109.90	✓		
7	R/R TRUNK LAMP <i>new</i>	26550-EW01A	109.90	+		
8	REAR COMB LAMP LH <i>new</i>	26555-EW00A	219.80	+		
9	REAR COMB LAMP RH <i>cut</i>	26550-EW00A	219.80	✓		
10	CARPET-TRUNK FLOOR <i>new</i>	84902-EW01A	511.00	+		
11	TRUNK LID INNER CENTRE FINISHER <i>new</i>	84966-EW00A	148.90	+		
12	TRUNK TOP PLATE MASK <i>new</i>	84994-EW00A	4.20	✓		
13	TRUNK TOP PLATE <i>cut</i>	84921-EW01A	192.00	✓		
14	EMBLEM REAR SYLPHY <i>new</i>	84895-EW000	87.00	✓		
15	EMBLEM REAR NISSAN <i>new</i>	84890-EW000	46.10	✓		
16	W/STRIP-TRUNK LID <i>new</i>	84830-EW000	106.30	+		
17	STRIKER-TRUNK LID <i>new</i>	84621-ED400	63.70	+		
18	LOCK ASSY-TRUNK <i>new</i>	84631-EW000	112.00	+		
19	TRUNK LID LOWER MLDG <i>cut</i>	84860-EW000	152.70	✓		
20	TRUNK LID TOP MLDG <i>cut</i>	84810-EW005	270.60	✓		
21	LID TRUNK <i>Repaired</i>	H430M-EX1MA	796.70	✓		
22	SENSOR-REVERSE <i>new</i>	SENSOR			200.00	+
23	REAR BUMPER REFLECTOR LH <i>new</i>	26565-EW00A	55.00	+		
24	REAR BUMPER REFLECTOR RH <i>new</i>	26560-EW00A	55.00	+		
25	REAR BUMPER MLDG <i>new</i>	85072-EW000	162.80	✓		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJK1195M

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 ENERGY ABSORBER REAR BUMPER ?	B5090-EW000	37.00	?	
27 REAR BUMPER SIDE BRKT LH ?	B5227-EW000	36.60	✓	
28 REAR BUMPER SIDE BRKT RH ?	B5226-EW000	36.60	✓	
29 CLIP REAR BUMPER @ \$1.20 EACH ?	01553-10501	7.20	✓	
30 REAR BUMPER FASCIA Dehd	B5022-EW025	660.60	✓	
SUB TOTAL		4675.30	0.00	360.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		935.06	0.00	0.00
GRAND TOTAL		3740.24	0.00	360.00
OVERALL TOTAL		4100.24		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

218280
20%
2226.24
5%
2114.92
1790.75
3905.67

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJK1195M

TOTAL LABOUR CHARGES	2855.00
TOTAL SPARE PARTS CHARGES	4100.24
GRAND TOTAL	6955.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Adrian Ling	86893735.
SURVEYED DATE	:	07/03/18.	
AUTHORIZED DATE	:		
EXCESS CLAUSE	:	0.00	06 days.
LIABILITY	:	0.00	
REMARKS	:		

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



Service Request Details

Claim

S8M00B29

Reference

None

Loss Date

March 12, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▼

Request Date

May 4, 2018

07/05/2018 @ 11:10am

Hamzah veh not in

Due Date

May 11, 2018

arrange @ 3pm

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJK1195M

Make

TPVD NISSAN

Service Address

51 LENTOR AVENUE, , , 786876

Primary Contact/Insured

THE LENTOR RESIDENCE PTE LTD
51 LENTOR AVENUE, 786876, Singapore
64576300

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE



SENT

5/4/18 2:07 PM

FROM

LOH Cynthia

SUBJECT

PROCEED DS

BODY

ID-H2R



Thin Thin (LKKAUTO)

From: Hamzah <hamzah_saad@tanchong.com>
Sent: Friday, 8 June 2018 9:04 AM
To: Thin Thin (LKKAUTO); Mei Kwan (LKKAUTO)
Cc: Vivian Lau (LKKAUTO); Admin A
Subject: Re: S8M00B29 / Accident involving SJK1195M and your insured SKP325Z on 12.3.2018
*** LKK REF: CC4/ASM18008233/ua3

Dear Thin Thin,

My client intend to sell the vehicle without being repair and if this is confirm will you be able to reimbursement to my client.

You may offer my client less that the actual repair cost for him to reconsider.

Kindly revert.

Regards

Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S408623
TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483
Hp: +65 96450079 Email: hamzah_saad@tanchong.com

From: Thin Thin (LKKAUTO) <thinthin@lkkauto.com>
Sent: Tuesday, May 15, 2018 2:27:39 PM
To: Mei Kwan (LKKAUTO); Hamzah
Cc: Vivian Lau (LKKAUTO); Admin A
Subject: RE: S8M00B29 / Accident involving SJK1195M and your insured SKP325Z on 12.3.2018 *** LKK REF: CC4/ASM18008233/ua3

"Without Prejudice"

Dear Hamzah,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

<< Service Request Details

Claim S8M00B29

Reference CC4/ASM18008233/Aua3 

Loss Date March 12, 2018

Request Date May 4, 2018

Due Date May 7, 2019

Vendor Name LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss Third Party Vehicle Damage

Services Pending verification - Direct Settlement

Actions

Next Step Finish the work

Complete Work

More

Vehicle Information

Incident SJK1195M

Vehicle Registration #

Make TPVD NISSAN

Model SYLPHY-1.5 4AT (A)

Service Address

51 LENTOR AVENUE, , 786876

Primary Contact/Insured

THE LENTOR RESIDENCE PTE LTD
51 LENTOR AVENUE, 786876, Singapore
64576300

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE	SENT	FROM	SUBJECT	BODY	
	8/30/18 10:42 AM	LOH Cynthia	Re:RE: Request for Mandate approval	Mandate approved	
	8/28/18 6:48 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Request for Mandate approval	OI rear-ended to TP vehicle. Informed TP claim and...	
	8/15/18 5:08 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Request for Mandate approval	OI rear-ended to TP vehicle. Informed TP claim and...	
	7/27/18 10:50 AM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Request for Mandate approval	OI rear-ended to TP vehicle. Informed TP claim and...	

TYPE	SENT	FROM	SUBJECT	BODY	
?	7/25/18 1:51 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Request for Mandate approval	OI rear-ended to TP vehicle. Informed TP claim and...	↩
?	7/18/18 1:15 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	Request for Mandate approval	OI rear-ended to TP vehicle. Informed TP claim and...	↩
?	5/4/18 2:07 PM	LOH Cynthia	PROCEED DS	ID-H2R	↩



SERVICE REQUESTS

MESSAGES

CLAIMS

**RE: Request for Mandate approval**

Type

Question

Message

OI rear-ended to TP vehicle. Informed TP claim and he agree to settle the claim. TP vehicle did not repair and offer cash-in-lieu. TP vehicle was trade in to the dealer. Please refer to the uploaded document. Proposed Total \$3,000.00 - cash-in-lieu. Thanks. Best Regards, Thin Thin Hlaing | Case Handler, LKK Auto Consultants Pte Ltd

[Reply](#)



HUA YANG CREDIT PTE LTD

159, SIN MING ROAD, #04-04 AMTECH BUILDING, SINGAPORE 575625
TEL: 6458 5111 FAX: 6459 5111 RCB NO: 198404112-G



PURCHASE AGREEMENT

PA No: B 21884

REF: A01 NG ☒ Tan Chong ☐ Motor Image SA No: _____ Date: 10/4/18

Seller Name: <u>Fong Lim Kwee</u>	I/C/P No.: <u>212242436</u>
Address: <u>604 BODEN ROAD #01-01 RD #01-01</u>	Tel (HP): _____
Postal Code: _____	Tel (OR): _____

Registration No: SK 1195 M No. Retention: Yes () / No () Agent: Yes () / No ()
 Make / Model: Nissan Sunny 1.6 Year of Manufacture: 2007 Engine Capacity: 1.6
 First Registration Date: 16 Feb 2008 Colour / Upholstery: Blue
 Engine No: HR16030732 Chassis No: 3113AAG 112010664
 No of Transfer: 0 (With PARF / Non PARF) R/Tax Expiry Date: _____ Mileage: _____
 Delivery Date / Time No Later Than: 3 July 18 COE No: _____ COE Expiry: _____
 Original Paint: Yes () / No () Accident Free: Yes () / No () OPC: Yes () / No () Warranty Expiry Date: _____

Note: Car must come with minimum (2/3) Keys, owner's manual, service booklet.

Special Conditions: Car related Rd tax (related)

*If any repair under special conditions the cost will be borne by the seller.

Agreed Price: <u>3788 (3.1.118)</u>	FOR OFFICE USE Finance Co: _____ Due Date: _____ Insurance Co: _____
Deposit Paid: _____	
Outstanding Finance: _____	
Balance: _____ Full Payment On: _____	

Important:

- The seller warrants that at the time of delivery, the vehicle will be in the same condition and will correspond to the description as found on the day of the signing of the purchase agreement.
- The property in the vehicle passes upon delivery. The vehicle delivered is to be free from all encumbrances whatsoever. In the event that any encumbrances are discovered after the signing of this agreement and/or after the delivery of the vehicle that were created prior to the signing of this agreement and/or prior delivery of the vehicle, the seller shall indemnify the buyer against all cost of removing such encumbrances and/or damages resulting from the said encumbrances.
- The purchase price is inclusive of COE and road tax, expiring on the dates stated herein. If seller is a GST registered company/business, the price stated is also inclusive of GST. Further, the seller agrees, if it is a GST registered company that shall not issue any tax invoices for the price, and further authorises HYC to issue to it self billing invoices for the price on its behalf.
- In this agreement, the time and the delivery of the vehicle is of the essence of the agreement. The seller shall be liable for all losses and damages arising from late delivery. Without prejudice to any other right or remedy of HYC, the seller agrees to compensate HYC two (2) times the deposit amount or ten percent (10%) of the purchase price - whichever is higher - should the seller fail to fulfill this purchase agreement.
- Notwithstanding that this agreement may have been signed by HYC representative, this agreement is not binding on HYC, unless approved and accepted by a duly authorized officer of HYC.
- The seller shall further indemnify the buyer against all claims by the customers of buyers arising out of any breach of this purchase agreement.
- With reference to the seller's purchase of the new car in the SA number above, if there is any breach or cancellation of this purchase agreement by the seller, the seller will not be entitled to the trade-in discount (if any) given to him as stated in the above SA number.

The seller has read and understood the contents herein and the Terms and Conditions printed above, all of which form part of this agreement, and further confirm that there is no other verbal or written agreements, representations or promises made to seller by any person (whether a servant, employee or otherwise) relating to this agreement.

Signed by, or for and on behalf of
the seller

2 keys, engine & gear box, air con
to be delivered in working
condition upon delivery,
if not subjected to price changes.

Accepted on behalf of
HUA YANG CREDIT PTE LTD

Name: _____
NRIC / Co. Reg No: _____

Name: Ng Jia Hui
NRIC: 383231241

FULL PAYMENT

Cash / Cheque: _____ Dollars: _____

White Copy : Company Blue Copy : Customer Yellow Copy : Sales Executive Pink : Purchaser

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKP 325Z (Insd veh)	Model:	NISSAN
	SJK 1195M (TP veh)		SYLPHY 1.5 4AT
Date of Accident:	12/03/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	0.00
Cash-in-Lieu	:	\$	1,700.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	300.00 6 days
LTA / GIA Search Fee	:	\$	

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	2,000.00

Is Third Party Workshop GIA Registered?	[X] YES	[] NO	(Kindly indicate below)
---	-----------	--------	-------------------------

A) For Non GIA Registered Workshop:	Agreed Liability _____(%)
-------------------------------------	---------------------------

B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	_____27_____
BOLA Liability: _____100_____ (%)	Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks	TOTAL LOSS – CASH-IN-LIEU
---------	---------------------------

Payment Instruction: Payee's Breakdown			
1)	AUTOLUTION INDUSTRIAL PTE LTD	:	\$ 2,000.00

NUR SHAQILAH BTE ABDOL
WAHAB

03/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim

SBM00629

Reference

CC4/ASM18006233/Aua3s2  Loss Date

Request Date

March 12, 2018

Due Date

May 4, 2018

Vendor Name

May 7, 2019

Type of Loss

LKK AUTO CONSULTANTS PTE LTD (TP)

Services

Third Party Vehicle Damage

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SJK1195M

Make

TPVD NISSAN

Model

51

Service Address

SYLPHY-1.5 4AT (A)

LENTOR AVENUE, .

786876

Primary Contact/Insured

THE LENTOR RESIDENCE PTE LTD

51 LENTOR AVENUE, 786876, Singapore

64576300

Document Type

Document SubType

Upload Documents

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SJK1195M	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	10/06/2008
Mileage	135816	Age of Vehicle	9

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		2008
Make	TPVD NISSAN	NISSAN
Model	SYLPHY-1.5 4AT (A)	SYLPHY 1.5 4AT
Type		
Type of Paint		
Chassis No		JN1BAAG11Z0106864
Engine No		HR15032731B
Engine Capacity		1498 cc

CATEGORY	PNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	PANG CHOON HOW (PENG JUNHAO)	
Date of Birth		mm/dd/yyyy
Age	0	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	05/07/2018	General condition	Good
Total Loss	Yes No	Steering (Serviceable)	Yes No
Towing Charges	0	Footbrake (Serviceable)	Yes No
Voluntary Excess	0	Handbrake (Serviceable)	Yes No
Compulsory Excess	0	Engine Modification	Yes No
Young/Inexperienced/Unarmed Driver Excess	0	Pre-accident condition	Good
Other Excess			

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	195/65R15	Rear Tyre Size	195/65R15
Front left side	MICHELIN 6mm	Rear left side	MICHELIN 6mm
Front right side	MICHELIN 6mm	Rear right side	MICHELIN 6mm