

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/05/2018 13:49
Date Of Accident	02/05/2018 23:00
Exact Location Of Accident	LOWER DELTA FLYOVER TWDS LOWER DELTA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC2187K
Insured/Policyholder	
Name Of Registered Owner	SOO, LIP KIAN EDWARD
NRIC No	S7729031A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98558108
Alternative Phone No	OTHERS-98558108

Vehicle Particulars

Manufacturer	FORD
Model	GALAXY 2.0 GHIA ECOBOOST
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00319730/01
Cover Note Number	

Driver

Name of Driver	SOO, LIP KIAN EDWARD
NRIC No	S7729031A
Date Of Birth	06/10/1977
Occupation	INDOOR
Date Of Driving Pass	27/05/2014
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98558108
Fax Number	
Contact Number	OTHERS-98558108
E-Mail Address	NOEMAIL

Address	BLK 40 TANGLIN HALT ROAD #10-153
Postcode	143040
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLOUDY
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HONG KAH NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 370 BUKIT BATOK STREET 31 , POSTCODE: 650370 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5679999 - FAX NO: 65652508
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20180503/2113 / T/20180503/2125

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MANICKAM PADHMANABAN
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ126B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SOO, LIP KIAN EDWARD

Approximate Age

Injuries Sustain SLIGHT

Injured person in which vehicle? SKC2187K

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 04/05/2018


Driver's Signature
(If driver is not the policyholder)
Date & Time: 04/05/2018


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.
T/20180503/2113
T/20180503/2125

DECLARATION

I/We declare the foregoing particulars are true in every respect.

GPR
Policyholder's Signature
Date & Time: 04/05/2018

GPR
Driver's Signature
(If driver is not the policyholder)
Date & Time: 04/05/2018

:- 4/5/2018
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20180503/2113

2 of 4

Report No. T/20180503/2113

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKC2187K	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT/00319730/01	26/07/2016	29/07/2018

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Driver			
Name	SOO LIP KIAN EDWARD	ID No.	S7729031A
Related Vehicle	SKC2187K (Car)	Contact No.	98558108
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	03/05/2018	Date Discharge	03/05/2018
No. of Days granted Medical Leave	10	Degree of Injury	Slight
Driver			
Name	GAN BOON PENG	ID No.	G8005023U
Related Vehicle	NIL	Contact No.	87999456
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/05/2018 at about 2300hrs, I was traveling in my vehicle of reg: V1) SKC2187K along AYE (Exit), traffic junction at Lower delta flyover, I was on the extreme left lane of a 3 lane road, I stopped my vehicle at the traffic light junction as it was red. One vehicle of reg v3) GX4700C which was traveling on the middle lane also stopped at the traffic junction. When the traffic light turns green, I advance my vehicle to make a right turn onto Lower Delta Road towards Telok Blangah direction. Suddenly, I saw a bright light coming from my right side, I then immediately stepped on the brakes to stop my vehicle. I then felt a heavy impact and heard a loud sound. I was then in a shock and I saw V2) GZ126B which was lorry was swirling on the road and subsequently then come to a stop. I then alighted from my vehicle. The driver of V3, Pahdu hp: 93444294 then came to assist me, he wrote down his name and contact details as he claims he had witness the accident. I then call for police assistances. I observed the driver of v2 and one other passenger were smoking at a distance. The traffic police then arrived. The paramedics also was at scene however no one was conveyed.

There is no In-Cam installed in my vehicle. I observed there is In-Cam installed in V2 however the driver

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20180503/2113

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

3 of 4
Report No. T/20180503/2113

CONTINUATION OF REPORT

informed that there is no SD card in the camera as his boss had already retrieve it and left the scene.

On 03/05/2018 I went to Singapore General Hospital as I was not feeling well. I felt pain my neck and back area and also weakness on my right shoulder area. I was given 10 days of MC dated on 03/05/2018 to 12/05/2018.

Individual Statement



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999



T/20180503/2125

2 of 3

Report No. T/20180503/2125

CONTINUATION OF REPORT

Brief Details.

I am lodging this report as a witness.

On 02/05/2018 at about 2300hrs, I witness a accident that took place at the traffic junction of Lower Delta Road. I was traveling in my vehicle of reg: V1) GX4700C along AYE (Exit) towards Lower Delta Road, I was on the middle lane of a 3 lane road. While at the traffic junction, I came to a stop as the traffic light was red. I noticed there is one blue colored vehicle stopped at the stop line of the traffic junction on the extreme left lane. When the traffic light was green, I started to advance my vehicle to make a right turn onto Lower Delta Road. I was advancing slowly, the vehicle on my left was also advancing slowly. Suddenly I saw one lorry from the right, The lorry was traveling very fast and the left side of the lorry collided into the front side of the blue coloured vehicle. I saw the lorry was swirling on the road and subsequently came to a stop. I alighted from my vehicle to make a check on the driver of the blue coloured vehicle and if he need any assistances. I observed the driver to be in a shock state and advised him to call for the police and he did so.


I observed the driver and the passenger of the lorry alighted from the driver side of vehicle and then make a check on the vehicle. Both of them did not approached the other driver. I wrote my name and contact details and passed to the driver of the blue coloured vehicle. I then left the scene.

There is no In-cam installed in my vehicle.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



**SINGAPORE
POLICE FORCE**



T201805092113

1 of 4

Report No. T201805092113

Police Station Of Origin
Hong Kah North NPT
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5879559

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/05/2018 15:47	Video Report No.:	Station Diary No. 15
--	-------------------	-------------------------

Informant's Particulars

Name of Informant: SOO LIP KIAN EDWARD		Address: APT BLK 40 TANGLIN HALL ROAD #10-153 SINGAPORE 143043	
ID Type / ID No. NRIC NO / S7728031A		Contact No. Home/Office:	Mobile: 98550108
Nationality SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 40	Date of Birth: 06/10/1977	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Project Executive		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury Attended by Police	Drink Driver: No	Date/Time of Accident: 02/05/2018 23:00	Type of Location: Flyover
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE exit towards lower stella road, Traffic Junction			
Weather: Cloudy	Road Surface: Wet	Road Speed Limit:	
Traffic Flow:	Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GZ126B	Lorry	TOYOTA		White	Seriously Damaged	1
SKC2187K	Car	FORD	GALAXY 2.0 GHIA ECOBOST	Grey	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date

Accident Photo



**SINGAPORE
POLICE FORCE**



T201805032115

3 of 4

Report No: T201805032113

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5678889

CONTINUATION OF REPORT

Details of Vehicle Insurance			
Vehicle No.	Insurance Company	Insurance No.	Effective / Expiry Date
SKC2187K	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT00318730/01	26/07/2018 / 26/07/2018

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Driver			
Name	SOO LIP KIAN EDWARD	ID No.	S7729031A
Related Vehicle	SKC2187K (Car)	Contact No.	98558108
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	03/05/2018	Date Discharge	03/05/2018
No. of Days granted Medical Leave	10	Degree of Injury	Slight
Driver			
Name	GAN BOON PENG	ID No.	G8005023U
Related Vehicle	NIL	Contact No.	87669458
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/05/2018 at about 2300hrs, I was traveling in my vehicle of reg: V1) SKC2187K along AYE (Exit) traffic junction at Lower delta flyover. I was on the extreme left lane of a 3 lane road, I stopped my vehicle at the traffic light junction as it was red. One vehicle of reg v3) GX4700C which was traveling on the middle lane also stopped at the traffic junction. When the traffic light turns green, I advance my vehicle to make a right turn onto Lower Delta Road towards Telok Blangah direction. Suddenly, I saw a bright light coming from my right side. I then immediately stepped on the brakes to stop my vehicle. I then felt a heavy impact and heard a loud sound. I was then in a shock and I saw V2) GZ126B which was lorry was swerving on the road and subsequently then come to a stop. I then alighted from my vehicle. The driver of V3, Pandu Ho; 93444294 then came to assist me, he wrote down his name and contact details as he claims he had witness the accident. I then call for police assistances. I observed the driver of v2 and one other passenger were smoking at a distance. The traffic police then arrived. The paramedics also was at scene however no one was conveyed.

There is no In-Cam installed in my vehicle. I observed there is In-Cam installed in V2 however the driver

Accident Photo



**SINGAPORE
POLICE FORCE**



T201800032113

3 of 4

Report No. T201800032113

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No. 1800-6679988

CONTINUATION OF REPORT

informed that there is no SD card in the camera as his boss had already retrieve it and left the scene.

On 02/05/2018 I went to Singapore General Hospital as I was not feeling well. I felt pain my neck and back area and also weakness on my right shoulder area. I was given 10 days of MC dated on 03/05/2018 to 12/05/2018.

Accident Photo



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Bahk Street 31 #01-201
SINGAPORE 860370
Tel No: 1800 5679999



T2018050302113

2 of 4

Report No. T2018050302113

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report
J.J.
Sgt 1 NIMROD GOH TIAN JIN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
JE / QJ
Sgt 2 LIM HONG LEE SN 116
No: 65476438

Investigation Stamp
Singapore Police Force

Signature Of Informant:

Date/Time:
03/05/2018 15:47

Classification Of Case:

Accident Photo



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999



T/20180603/212B

2 of 3

Report No: T/20180603/212B

CONTINUATION OF REPORT

Brief Details.

I am lodging this report as a witness.

On 02/05/2018 at about 2300hrs, I witness a accident that took place at the traffic junction of Lower Delta Road. I was traveling in my vehicle of reg: V1) GX4700C along AYE (Exit) towards Lower Delta Road. I was on the middle lane of a 3 lane road. While at the traffic junction, I came to a stop as the traffic light was red. I noticed there is one blue colored vehicle stopped at the stop line of the traffic junction on the extreme left lane. When the traffic light was green, I started to advance my vehicle to make a right turn onto Lower Delta Road. I was advancing slowly, the vehicle on my left was also advancing slowly. Suddenly I saw one lorry from the right. The lorry was traveling very fast and the left side of the lorry collided into the front side of the blue coloured vehicle. I saw the lorry was swirling on the road and subsequently came to a stop. I alighted from my vehicle to make a check on the driver of the blue coloured vehicle and if he need any assistances. I observed the driver to be in a shock state and advised him to call for the police and he did so.

I observed the driver and the passenger of the lorry alighted from the driver side of vehicle and then make a check on the vehicle. Both of them did not approached the other driver. I wrote my name and contact details and passed to the driver of the blue coloured vehicle. I then left the scene.

There is no In-cam installed in my vehicle.

Accident Photo



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999



T12018050302125

3 of 3

Report No: T12018050302125

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 85474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

Sgt 1 NIMROD GOH TIAN JIN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
03/05/2018 16:45

Officer In Charge Of Case:
TP / GIT /
Sgt 2 LIM HONG LEE
Contact No.: 85478438

Classification Of Case:

Authentication Stamp
NPTD

Singapore Police Force