

22/03/2002

ASS. REC. BY:

REF: CS/CT18008283 / Kvbck Special Instruction:

Surveyor: Kenneth
Maimen

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTL Date/Time: 07052018 1:25pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 9069H Insured: YN 1435C

at Workshop m/s Ding Auto Tel:

of Blk 10 Sin Ming Ind Est #01-20

Policy No: DMCVGN 3023651800 Claim No: SNM180 02290C02.

Sum Insured: Excess:

Make of Veh: D.O.A. 30042018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp: 08052018 @ 11am H.O.D. Endorsement:

Date/Time: 07052018 1:55pm Person Contacted: Alex Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 9069H - X
	YN 1435C - CS/MSG/9003759/Std3 DIA: 230218
19/7/18	@ 4:44pm Alex said TP already has private settle with OI
20/7/18	Submit preli report

REF: **en**

Signature

merimen**ASSIGNMENT**From: _____ Date: **08052018**

Estimated Cost: _____

OD / **TP** / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: **SKT 9069H**

at Workshop m/s

of

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

11am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: **06** days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: **SKT 9069H**Yr Regn: **06 / 15**Type: **M** / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toy / Harrier**

C.C

Colour: **M. Black**

A/C

Insured / Std / NI / NA

Sp. Reading: **73839**

T/Radio

Insured / Std / NI / NA

Eng/No: _____

C/No: **ESU 60****0043292**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **In order** / Jammed / Leaked / Burnt orBrake: **In order** / Jammed / Leaked / Burnt orModi: **Nil** / S/Rim / STD A/Rim orTyre Size: **F:****R:****235/55R19**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **9** mmR/Bal. **9** mmL/Bal. **9** mmL/Bal. **9** mmD.O.A. **30/4/18**D.O.I. **8/5/18**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Acc
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/5 Mile per 11 to Catherine**RECEIVED 20 JUL 2018**

Date/Time, File Pass to?



Preli. Report



Final Report

1) _____

Date/Time, File Return to?

2) **2017 - typist**Days Of Repair: **6**Resurvey No. of Trip: **-**Survey Fee: **220**

Transportation: _____

) S+RS \$

) Photos

) Others

Report Format: **merimen**

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐

Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018		07 May 2018 13:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:		
Main Claimant:	IBRAHIM BIN ATAN	
Vehicle Reg. No.:	SKT9069H	Date of Loss: 30/04/2018 00:00 - :59
Claim Type:	TP / SNM18D02290C02	Policy/Cover Note No.: DMCVSN3023651800
Vehicle Reg. No. (Insured):	YN1435C	Policy No. (Claimant):
		Excess: S\$0.00
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/05/2018]	
Adj Asg. Remarks:	EST \$5610.63, ASSIGN KENNETH KONG AS SJE.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS								View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?		
No results.											

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2018 19:11
Date Of Accident	30/04/2018 20:50
Exact Location Of Accident	CTE EXITING TOWARDS BRADDELL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT9069H
Insured/Policyholder	
Name Of Registered Owner	IBRAHIM BIN ATAN
NRIC No	S1262236H
Email Address	IBRAHIM@F1-RECREATION.COM.SG
Mobile Phone No	(LOCAL) +65-97903117
Alternative Phone No	OFFICE-68467666

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER 2.0-2.0 PREMIUM AT AIRBAG 2WD (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	71542213 QMY
Cover Note Number	

Driver

Name of Driver	IBRAHIM BIN ATAN
NRIC No	S1262236H
Date Of Birth	17/09/1957
Occupation	INDOOR
Date Of Driving Pass	19/05/2003
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97903117
Fax Number	
Contact Number	OFFICE-68467666
EEmail Address	IBRAHIM@F1-RECREATION.COM.SG

Address	APT BLK 418 SERANGOON CENTRAL
Postcode	550418
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SON
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please Refer to Circumstance of Accident Thank you.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN1435C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	002334401B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driving along CTE heading towards Braddell Road was on left lane when all of a sudden heard a banging from the back of my car. Stop immediately and to check the car to found out there deep scratch on the rear side of my car. The driver of the lorry whom stop behind was saying sorry for this to happen. The driver was a foreign worker whom drive the company Lorry. Appendix is the particulars of the driver and its company

Name Sundaran Saravanan

Licence No 97619773 W

Co's Name: Stew Engineering Services (S) Pte Ltd
4025 Ang Mo Kio Industrial Park 1
#01-285 Singapore 569636

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

DING AUTO PTE LTD

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle:	SKT9069H
Model:	TOYOTA HARRIER 2.0 PREMIUM 2WD CVT
Chassis:	ZSU600043292

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	REAR BUMPER ASSY	1	\$ 1,495.60	25%	\$ Bu 1,121.70	✓
2	REAR BUMPER SIDE RETAINER RH	1	\$ 69.70	25%	\$ Bu 52.28	✓
3	REAR FENDER RH	1	\$ 1,102.70	25%	\$ Bu 827.03	✓
4	TAILLAMP RH	1	\$ 479.80	25%	\$ Bu 359.85	X
5	REAR FENDER INNER SHIELD RH	1	\$ 102.80	25%	\$ Bu 77.10	X
6	REAR WHEELHOUSE PANEL RH	1	\$ 527.50	25%	\$ Bu 395.63	X
TOTAL:					\$ 2,833.58	

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
7	REAR TYRE RH	1	\$ Bu 500.00	X
8	SEALANT	1	\$ Bu 60.00	Join
9	REAR BUMPER SENSOR RH	Bu 1	\$ 150.00	X
SPECIAL NETT			\$ 710.00	

	LABOUR	PRICE	SURVEYOR MARKING
10	PANEL BEAT ACCIDENT AREAS	\$ 750.00	600
11	R & R SPARE TYRE BOARD, CARPET & TRIM	\$ 80.00	} 1000
12	R & R SEATS & CARPETS TO ASSIST REPAIR	\$ 80.00	
13	R & R R/H/R QUARTER GLASS	\$ 80.00	
14	CHECK & REPAIR WIRING SYSTEM	\$ 60.00	200
15	RESpray REAR BUMPER, REAR FENDER RH & REAR WHEELHOUSE PANEL RH	\$ 650.00	600
TOTAL:		\$ 1,700.00	

PARTS	\$ 2,833.58
LABOUR	\$ 1,700.00
SPECIAL NETT	\$ 710.00
TOTAL	\$ 5,243.58
GST 7%	\$ 367.05
FINAL TOTAL	\$ 5,610.63

Not Notified
1. B1, 1.1 Lmp 8?

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018		07 May 2018 13:25 Edit Adj Rpt	S\$3,391.00 Edit Estimates	S\$3,391.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	IBRAHIM BIN ATAN								
Vehicle Reg. No.:	SKT9069H	Date of Loss:	30/04/2018 00:00 - :59 [34 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02290C02	Policy/Cover Note No.:	DMCVSN3023651800						
Vehicle Reg. No. (Insured):	YN1435C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/05/2018]								
Adj Asg. Remarks:	EST \$5610.63, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT9069H (SNM18D02290C02)
[YN1435C]
TP
IBRAHIM BIN ATAN
Apr 30 2018 12:00AM
[-]
Ding Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Documentation							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	07/05/18 13:25	REPAIR EST					Load PDF		
2	07/05/18 13:25	TP GIA REPORT					Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18008283/KVBE2

Date: 01/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3023651800

Claimant Vehicle
No : SKT9069HInsured Vehicle
No : YN1435C

Date of Loss: 30/04/2018

Nature of Claim: TP

Claim
No: SNM18D02290C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9069H**

Make & Model: TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A) Engine No: 3ZRB547737

Reg. Date: 25/06/2015 (Man. Year: 2015) Chassis No: ZSU600043292

Colour: Metallic Black Odometer: 73839 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19

Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,543.57	2,031.00	1,512.57	42.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,360.00	340.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,243.57	3,391.00	1,852.57	35.33
+ GST 7.00/7.00% (S\$)	367.05	237.37	129.68	35.33
Nett Amount (S\$)	5,610.62	3,628.37	1,982.25	35.33

INSPECTION

Date of Assignment: 07/05/2018

Date Inspected: 08/05/2018 Inspected At:

Ding Auto Pte Ltd (HQ)
Blk 10, #01-20, Sin Ming Industrial Estate
Sector C
Singapore 575645

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Aug 2018)	
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9069H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Bent	1,495.60 FL	*1,495.60 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Distorted	69.70 FL	*69.70 FL
3	1		*REAR FENDER RH	Bent	1,102.70 FL	*1,102.70 FL
4	1		*TAILLAMP RH	Serviceable	479.80 FL	*- FL
5	1		*REAR FENDER INNER SHIELD RH	Serviceable	102.80 FL	*- FL
6	1		*REAR WHEELHOUSE PANEL RH	Repair	527.50 FL	*- FL
7	1		*REAR TYRE RH	Serviceable	500.00 FS	*- FS
8	1		*SEALANT	Necessary	60.00 FS	*30.00 FS
9	1		*REAR BUMPER SENSOR RH	Serviceable	150.00 FS	*- FS
					Sub Total (S\$)	4,488.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	944.53
					Total Parts (S\$)	3,543.57
						2,698.00
						2,031.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT ACCIDENT AREAS	New	750.00	600.00
2	R & R SPARE TYRE BOARD, CARPET & TRIM }	New	80.00	100.00
3	R & R SEATS & CARPETS TO ASSIST REPAIR }	New	80.00	0.00
4	R & R R/H/R QUARTER GLASS	New	80.00	40.00
5	CHECK & REPAIR WIRING SYSTEM	New	60.00	20.00
6	RESPRAY REAR BUMPER, REAR FENDER RH & REAR WHEELHOUSE PANEL RH	New	650.00	600.00
Gross Labour Cost (\$\$)			1,700.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >