

22/03/2002

S.S. REC. BY:

REF:

CS/CTU18008287 / Altbn2

Special Instruction:

Surveyor:

Rusli

ASSIGNMENT (Office)

From (Person):

Chung Soon Sen

of

CTI

Date/Time: 07052018 116pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 8441J

Insured:

SJH 3621C

at Workshop m/s

Borneo Motors

Tel:

9221 3150

of

2 Pandan Crescent

Policy No:

DMPC SN3015231708

Claim No:

SNM18D0228J002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04052018

CA / REV / REP. / REV 24 HRS 'wp'

08052018

H.O.D. Endorsement:

Date/Time:

07052018 130pm

Person Contacted:

Raymond

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 8441J - X

SJH 3621C - CS3/CTU12024109/Zcd1

Df: 131212

Part by Part \$7908.42 : (Red: 3993.65 :33%)

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

D.O.A.

04/05/18

D.O.I.

08/05/18

Survey held at

Borneo Motors

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 JUN 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 28/6 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format:

TP

Lump Sum / I.B.I: (\$ 7908.42)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$