



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2006 HONDA AIRWAVE 1.5 (SGQ3438D)

Date of Loss

29 April 2018

Time of Loss

0.30

Loss Description

SGQ3438D (INSD) C/W SLB4726K (TP)

Comment

Workshop Details

Total Rebate Amount

18597

Nett Loss Amount

\$9,403.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

31/07/2018



Days of work completion *

85



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SGQ3438D

Registration State

SINGAPORE

Mileage

125613

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2006

ASSESSMENT INFO...

2006

Purchase Date

dd/mm/yyyy



Registration Date *

11/01/2007



Age of Vehicle

11

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

RICARDO LEE MING SHU

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... AIRWAVE 1.5

ASSESSMENT INFO... AIRWAVE 1.5 A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... GJ11115193

CATEGORY Date of Birth

FNOL INFORMATI... 15 November 1990

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 27

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... L15A5118799

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 5

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2013

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 129 LORONG AH SOO, #13-342,
530129, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S9043981B

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

07/05/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

800

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

185/60R14

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

185/60R14

Front left side

YOKOHAMA6mm

Front right side

YOKOHAMA6mm

Rear left side

YOKOHAMA6mm

Rear right side

YOKOHAMA6mm



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
<input type="checkbox"/>		1	1			HEADLAMP RH			Cracked	625.8		20		500.64	Review
<input type="checkbox"/>		2	1			HEADLAMP LH			Cracked	625.8		20		500.64	Review
<input type="checkbox"/>		3	1			BONNET			Bent	750		20		600	Review
<input type="checkbox"/>		4	1			BONNET CHROME			Damaged	240.9		20		192.72	Review
<input type="checkbox"/>		5	1			BONNET HINGE RH			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		6	1			BONNET HINGE LH			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		7	1			BONNET LOCK			Bent	70		20		56	Review
<input type="checkbox"/>		8	1			FENDER LH			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		9	1			FENDER RH			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		10	1			FRT SUPPORT			Bent	550		20		440	Review
<input type="checkbox"/>		11	1			HEADLAMP BRACKET RH			Necessary	48.3		20		38.64	Review
<input type="checkbox"/>		12	1			HEADLAMP BRACKET LH			Necessary	48.3		20		38.64	Review
<input type="checkbox"/>		13	1			GRILLE			Cracked	265.8		20		212.64	Review
<input type="checkbox"/>		14	1			GRILLE BASE			Cracked	235		20		188	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
<input type="checkbox"/>		15	1			GRILLE LOGO			Necessary	32		20		25.6	Review
<input type="checkbox"/>		16	1			RADIATOR			Cracked	1450.5		20		1160.4	Review
<input type="checkbox"/>		17	1			CONDENSER			Bent	880		20		704	Review
<input type="checkbox"/>		18	1			FANCROWL ASSY			Cracked	110		20		88	Review
<input type="checkbox"/>		19	1			FRT BUMPER			Deformed	945.2		20		756.16	Review
<input type="checkbox"/>		20	1			BUMPER RETAINER RH			Necessary	22.5		20		18	Review
<input type="checkbox"/>		21	1			BUMPER RETAINER LH			Necessary	22.5		20		18	Review
<input type="checkbox"/>		22	10			BUMPER CLIPS			Necessary	3.8		20		30.4	Review
<input type="checkbox"/>		23	1			BUMPER BRACKET RH			Necessary	48.3		20		38.64	Review
<input type="checkbox"/>		24	1			BUMPER BRACKET LH			Necessary	48.3		20		38.64	Review
<input type="checkbox"/>		25	1			SPOILER			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		26	1			REINFORCEMENT			Bent	320.8		20		256.64	Review
<input type="checkbox"/>		27	1			BUMPER LOWER GRILLE			Cracked	220.5		20		176.4	Review
<input type="checkbox"/>		28	1			SPARE TANK			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		29	1			BONNET INSULATOR			Deformed	145.2		20		116.16	Review
<input type="checkbox"/>		30	10			BONNET INSULATOR CLIPS			Necessary	3.8		20		30.4	Review

EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
	31	1			ENGINE LOWER COVER			Serviceable	0	0	0	0	0	Deny
	32	1			BUMPER LOWER RUBBER			Deformed	29.4		20		23.52	Review
	33	1			WHEEL ARC DUST COVER RH			Serviceable	0	0	0	0	0	Deny
	34	1			AIRDUCT			Serviceable	0	0	0	0	0	Deny

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
	1		LABOUR	800	0	0	Reviewing		1
	2		SPRAY PAINTING	800	0	0	Reviewing		1
	3		DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	30	0	0	Reviewing		1
	4		REMOVE AND REPLACE AIR-CON RADIATOR AND TOP UP COOLANT	100	0	0	Reviewing		1
	5		REMOVE AND REPLACE AIR-CON CONDENSER, PIPES AND VACUUM AIR-CON SYSTEM ABD REFILL GAS }	120	0	0	Reviewing		1
	6		REMOVE AND REINSTALL AIR-CON SYSTEM AND BLOWER UNIT }	0	0	0	Reviewing		1
	7		ANTI-RUST COATING	40	0	0	Reviewing		1

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
	8		REMOVE AND REPLACE SPARE TANK FIXTURE AND ATTACHMENT	0	0	0	Deny		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
<input type="checkbox"/>		2	NO. PLATE W/COVER	Reviewing	45	BENT	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$7,383.88

Claim Amount \$7,383.88

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,890.00	\$1,890.00
Miscellaneous	\$45.00	\$45.00
Excess	-\$800.00	-\$800.00

Submit for Review

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	6500	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$5,700.00

Claim Amount \$5,700.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$6,500.00	\$6,500.00
Excess	-\$800.00	-\$800.00