

INSURER

CASE OWNER

R. Edward Ernest

CC 4 ASM AXA 1800 8290, T1W639

LKK IDAC

Surveyor

Tanfich

DOI

11/5/18

Date / Time

7/5/18

Registered in Merimen

Pre-assign / CCU / FTE



Insured Vehicle No.

SFE 87AAD

Name of Insured

TAN HONG MUI

Insured Tel No.

HP

Excess Sec II :SS

D.O.A

11/5/18

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age

TAN YAN LIN

Driver Tel No. :

(V/L) YES / NO

Claim No.

SBM00F4H/02189

Policy No.

GA7642911

Make / Model

TOYOTA

Place of Accident :

WORTH BELONG VISA RD

OI GIA REPORT YES / NO

YES

TP GIA REPORT YES / NO

YES

Insured Liability :

SS

Final ? Yes / No

SGV7804



INSRS: WSP: Tel: Liability: RMKS:

performance



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

| Date/Time | STAGE | DATE / PIC |
|-----------|-----------------------------------|-------------------------------------|
| 8/15/18 | Non-Reporting ltr (1st): | |
| | Non-Reporting ltr (2nd): | |
| | Non-Reporting ltr (Final): | |
| | Notification ltr (if non-pickup): | |
| | Call OI: | |
| | After call ltr to OI: | |
| | Documentation Check List: | Handler Typist |
| | Notification ltr (if non-pickup) | <input type="checkbox"/> |
| | After call ltr to OI: | <input checked="" type="checkbox"/> |
| | Authorisation To Act: | <input checked="" type="checkbox"/> |
| | Release Voucher: | <input checked="" type="checkbox"/> |
| | Final Repair Bill: | <input checked="" type="checkbox"/> |
| | Car Rental Invoice: | <input type="checkbox"/> |
| | Towing Invoice | <input type="checkbox"/> |
| | LTA / CIA : | <input checked="" type="checkbox"/> |
| | Medical Bill: | <input type="checkbox"/> |
| | PIR: | <input type="checkbox"/> |
| | Mandate/Reject Instruction: | <input checked="" type="checkbox"/> |
| | LOD | <input checked="" type="checkbox"/> |
| | Payment Breakdown Form: | <input type="checkbox"/> |
| | Post-Repair Photos: | <input type="checkbox"/> |
| | Others: | <input type="checkbox"/> |

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 30/11/18 Confirm with: Corolme Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: > 7

Repair Cost: SS 3210.39

Loss of Rental (LOR): SS (days)

Loss of Use (LOU): SS 180.00 (560 x 3 days)

Loss of Income (LOI): SS (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS 2.00

Medical: SS

Disbursement: SS (e.g. Tow/Independent)

Legal Cost: SS

Total: SS 3392.39 **Global Sum SS:**

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 3392.39 Name 1: Performance Motors Ltd

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

COPIES SENT 11/12/18

RECEIVED 03 DEC 2018

Signature: *Tauphin*

REF: AXA

8250 / w63

ASSIGNMENT

From: _____ Date: **15/5/18**

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SGV 780 H**

at Workshop mis **Performance Motors**

of **303 Alexandra Rd**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: **3** days Res: Yes or No

Lum Sum: **100.0** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **lump**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SGV 780H** Yr Regn: **2016, Que.**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Bmw 318i** cc **1499**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp. Reading: **25486** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WBA8E36020NT89544**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: **275/50R17**

R: **-**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

| | | | |
|--------|----------|--------|--------------------|
| Front | 6 | Rear | 6 |
| R/Bal. | mm | R/Bal. | mm |
| L/Bal. | mm | L/Bal. | mm |
| D.O.A. | | D.O.I. | 16/5/18 0/0 |

Survey held at **pm**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
|-------------|----------------------|

16/5/18 Confirm 2.R. -> \$3000.36 with 3 working days.

(Red - \$1599.58 30%)

Date/Time: File Pass to? : Preli. Report

1) : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

| | |
|-----------------|--|
| Survey Fee: | |
| Transportation: | |
| S-RC: | |
| Photos: | |
| Others: | |
| TOTAL: | |

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format : _____

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|---|--|---------------------------|---|
| AXA INSURANCE PTE LTD | | Ref : CC4/ASM18008290/wb3 | |
| 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 | | Date : 07-05-2018 |  |
| | | Code : ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SFE 8799D | Veh. Inspected | SGV 780H |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 07/05/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 01/05/2018 | Inspection Date | |
| Survey held at | PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

16/5/18 @ 10am
Taufik
92495749

Taufik

Taufik @ lkkauto.com
03 days

| | | |
|--------------------|---|-----------------|
| Labour 1 | : | 2,570.00 |
| Parts | : | 1,728.95 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 7% | : | 300.93 |
| Grand Total | : | 4,599.88 |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Service Request Details

Claim

S8M00FUH

Reference

None 

Loss Date

May 1, 2018

Request Date

May 4, 2018

Due Date

May 11, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*04052018 @ 10:16am
Caroline veh not in
Email to her.*

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGV780H

Make

TPVD BMW

Service Address

...

Primary Contact/Insured

TAN HONG MUI
BLK 465 SEGAR ROAD, #04-154, 670465, Singapore
92257970

Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

 **Re:S8M00FUH-mandate approval**

Type

 Question

Message

Hi LKK, pls confirm if the COR is at \$3,392.39 as the mandate IA indicated the COR is more. Also do engage insured on the TP's claim. If the COR is confirmed at \$3,392.39, pls proceed as per mandate. Thank you.

[Reply](#)



(V.V.)

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

"Without Prejudice"

Your Ref :

Our Ref :

Date:

Subject:

09 October 2018

ACCIDENT INVOLVING VEHICLES SGV780H & SFE8799D ON 01.05.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

| | | |
|-----------------|-------|-----------------------------|
| Cost of repair | : S\$ | 3210.39 |
| Loss of use | : S\$ | 180.00 (S\$ 60.00 x 3 days) |
| GI A search fee | : S\$ | 2.00 |
| Total | : S\$ | 3392.39 |

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GI A search slip
3. Copy of Certificate Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales
6319 0527
Fax 6479 6624

260
Kampong Arang Rd
East Coast Centre
Singapore 438160
Tel AfterSales
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No.
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint



09 May 2018

TAN HONG MUI
BLK 465 SEGAR ROAD,
#04-154,
Singapore 670465

Dear Sir/ Mdm

OUR REF : CC4/ASM18008290/wb3
YOUR REF : SFE 8799D

**ACCIDENT INVOLVING SFE 8799D & SGV 780H ALONG NORTH BUONA VISTA RD
ON 01/05/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Performance Motors Limited** acting on behalf of the owner of SGV 780H against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd
(Motor Claims Dept)

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SGV780H & SFE8799D ON 01/05/18.

I, Mr Benedict Yap Hsien-Min owner of Vehicle Registration No. SGV780H hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:


Name: BENEDICT YAP (Date) 02/05/18
NRIC No.: HSIEN-MIN
57621143D

In the presence of:


Name: _____ (Date) 02/05/18
NRIC No.: _____



redefining / insurance



CLAIM REF : SSM00FUH
INSURED : TAN Hong mul

DISCHARGE VOUCHER


We/I [BENEDICT YAP HSIEN-MIN , NRIC NO. S7621143D] hereby agree to accept the sum of dollars [Three Thousand Three hundred Ninety Two And Cents Thirty Nine Only (S\$ 3392.29) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SFE8799D] as a result of an accident along [North Buona Vista Rd] on [01/05/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SGV780H].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SFE8799D] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SFE8799D].

Dated this 30 day of Nov 2018

Claimant's Signature : 
NRIC no./ Company Stamp : S7621143D
Occupation/ Business : Civil Servant
Address : 15 Farrer Dr, #02-01, SC259296
Telephone No. : 81257657

Witness's Name : HAN KWAN YONG
Witness's Signature : 
Witness's NRIC No. : _____

| |
|--|
| HAN KWAN YONG Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941 |
|--|

301, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190520 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1267957**Date IN : **16/05/2018**Cust. Svc. Advisor: **Han Kwan Yong**Page No. : **1 of 2**Invoice Number : **2016163 / WSB**Invoice Date : **08/10/2018**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan****- CUSTOMER INFORMATION -****Mr Benedict Yap Hsien-Min (Ye XianMing)**
15 Farrer Drive
#02-01 Pollen & Bleu**Singapore 259296****- INVOICE TO - 238****AXA Insurance Pte Ltd**
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|-----------|---------|
| SGV780H | NT89544 | 21/06/2016 | 318IA/4DR | 25486 |

--- LABOUR ---To replace rear bumper and attachments including knock
out dented area caused by the accident.

To respray rear bumper.

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 01.05.2018. 3RD PARTY CAR : SFE8799D.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON
16.05.2018 AT 10AM. AUTHORISED REPAIR BY MS VIVIAN LAU
FROM LKK AUTO ON 08.05.2018 VIA EMAIL.PROPOSE LOSS OF USE = \$60x3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

Retail

Price

DISC%

NETT

850.00 10.00 765.00

934.00 10.00 840.60

150.00 10.00 135.00

80.00 0.00 80.00

0.00 0.00 0.00

0.00 0.00 0.00

0.00 0.00 0.00

Total Labour 1: 1,820.60**--- PARTS ---**

(DG/SL) ADHESIVE SET K6

REAR BUMPER PANEL PRIMED (LINES)

SET MOUNTING PDC/PMA SENSOR REAR

Retail

Qty

Price

DISC%

NETT

1 53.05 3.00 51.46

1 1,100.25 3.00 1,067.24

1 62.95 3.00 61.06

Total Parts : 1,179.76

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64767770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 62190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**

| | |
|--|---|
| Repair Order No. : B1 1267957 | Page No. : 2 of 2 |
| Date IN : 16/05/2018 | Invoice Number : 2016163 / WSB |
| Cust. Svc. Advisor: Han Kwan Yong | Invoice Date : 08/10/2018 |
| | Payment Terms : 30 Days From Invoice |
| | Invoice By : Toh Jing Xuan |

| | |
|----------------------------------|--|
| Labour Charges : 1,740.60 | Total Labour & Parts Charges : S\$ 3,000.36 |
| Parts Charges : 1,179.76 | Less Insurance Excess : S\$ 0.00 |
| Lubricant/Misc : 80.00 | Invoice Total Amount Exclude GST : S\$ 3,000.36 |
| | GST @ 7% : S\$ 210.03 |
| | Invoice Total Amount Include GST : S\$ 3,210.39 |

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 3,210.39**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-065970
Date of Request: 02/05/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 02/05/2018
Enquiry By: Han Kwan Yong
TP Vehicle No.: SFE8799D
Accident Date: 01/05/2018

| DESCRIPTION | AMOUNT (S\$) |
|----------------------------------|--------------|
| TP Insurer Enquiry | 1 |
| GST Amount | 0 |
| Total Amount Due (GST Inclusive) | 2 |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-065970
Date of Request: 02/05/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 02/05/2018
Enquiry By: Han Kwan Yong
TP Vehicle No.: SFE8799D
Accident Date: 01/05/2018

Enquiry Result

| TP Vehicle No. | Insurer | Period of Insurance | Insurer Tel. No. |
|----------------|-----------------------|-----------------------|------------------|
| SFE8799D | AXA Insurance Pte Ltd | 05/12/2017-27/11/2018 | 6338 7288 |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the report or their images.

This is a computer generated document and requires no signature.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008290/T1wb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Date : 13-12-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------|----------------|------------|
| Insured Veh. | SFE 8799D | Veh. Inspected | SGV 780H |
| Policy No. | GA076429/1 | Coverage (\$) | 0.00 |
| Claim No. | S8M00FUH | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 07/05/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|------------|
| Make & Model | B.M.W. 318i | c.c | 1499 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | WBA8E36020NT89544 | Colour | BLACK |
| Odometer | 25486 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|-------------|---------|
| R/H Front Tyre | 225/50 R17 | BRIDGESTONE | 6 mm |
| L/H Front Tyre | 225/50 R17 | BRIDGESTONE | 6 mm |
| R/H Rear Tyre | 225/50 R17 | BRIDGESTONE | 6 mm |
| L/H Rear Tyre | 225/50 R17 | BRIDGESTONE | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 01/05/2018 | Inspection Date | 16/05/2018 |
| Survey held at | PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941 | | |

5a. Remarks

| |
|---|
| A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|---|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 780H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | SUNDRIES (SN) (CONSISTENT) | NECESSARY | 80.00 | 80.00 |
| 1 | REAR BUMPER CARRIER (ECE) (SN) (CONSISTENT) | NOT NECESSARY | 432.90 | - |
| 1 | REAR BUMPER BLACK TRIM STRIP (SN) (CONSISTENT) | NOT NECESSARY | 79.80 | - |
| 1 | REAR BUMPER PANEL PRIMED (LINES) (SN) (CONSISTENT) | DEFORMED | 1,100.25 | 1,067.24 |
| 1 | SET MOUNTING PDC/PMA SENSOR REAR (SN) (CONSISTENT) | NECESSARY | 62.95 | 61.06 |
| 1 | (DG/SL) ADHESIVE SET K6 (SN) (CONSISTENT) | NECESSARY | 53.05 | 51.46 |
| | | | 1,808.95 | 1,259.76 |
| LABOUR | | | | |
| | TO REPLACE REAR BUMPER & ATTACHMENT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT. | | 1,275.00 | 765.00 |
| | TO RESPRAY REAR BUMPER. | | 1,038.00 | 840.60 |
| | TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION. | | 177.00 | 135.00 |
| | | | 2,490.00 | 1,740.60 |
| GRAND TOTAL | | | 4,298.95 | 3,000.36 |
| RECOMMENDED COST OF REPAIRS | | | | 3,000.36 |

Report Ref No. CC4/ASM18008290/T1wb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim: SM100FUH

Reference: CCA/ASAM1800296UT1w36q2

Loss Date: 1 May 2018

Request Date: 21 August 2018

Dum Date:

Vendor Name: LIXX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss: Third Party Vehicle Damage

Services: Pending verification - Direct Settlement

Actions

Next Step: [Wait for Approve Invoice](#)

[Add Photos](#)

Vehicle Information

Incident Vehicle Registration #: 5GV780H

Make: TPUD BMW

Model: 318i

Service Address:

...

Primary Contact/Insured

TAN HONG MUJ
BLK 465 SEGAR ROAD, #01-154, 670465, Singapore
92257970

Claim Handler

ANG Richard
richard.ang@lixx.com.sg

Additional Instructions

Messages | Invoices | History | Documents | Assessment | Metrics | Notes

Document Type:

[+ Upload Documents](#)

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|------------------|---------------------|------------|---------|---------------|
| SPF8799D INS CIA | Reports & Statement | GIA Report | Meimien | |

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---------------------------------|----------------------------|----------------------------------|-----------------------------------|------------------|
| LK1Invoice1 (5).pdf | Invoice | Surveyor/ Assessor expense | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| Payment breakdown.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| LOO.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| LK1Inspection (4).pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| LK1Adjustment La (7).pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| GIA SEARCH.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| DISCHARGE VOUCHER.pdf | Forms / Claim Documents | Satisfaction / Discharge Voucher | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| AUTHORISATION TO ACT FORIRM.pdf | Forms / Claim Documents | POA / Authority Letter | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| WORKSHOP INVOICE.pdf | Invoice | Repairer | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| LETTER TO OI.pdf | Letters and Correspondence | Policy Holders / Insured | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 December 2018 |
| MARKED ESTIMATE.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 November 2018 |
| GIA SEARCH.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 November 2018 |
| LK1 Inspection Photos.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 November 2018 |
| Immediate Advice-SCV 710H.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 November 2018 |

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---|---------------------|----------------------|-----------------------------------|---------------|
| TP ESTIMATE- MARKED.pdf | Reports & Statement | Estimate / Quotation | LIX AUTO CONSULTANTS PTE LTD (TP) | 22 May 2018 |
| EMAIL WITH PT GIA SGV78181 & ESTIMATE.png | Reports & Statement | GIA Report | KUNJAR Shalendra | 4 May 2018 |