



Our Ref: T0518/SHC2076H/WT(ck) ComfortDelGro Engineering Pte Ltd 22.5.18 Date: **CDGE Taxi Claims** 59 Loyang Drive Axa Insurance Pte Ltd Facsimilie +65 6280 9755 4th Floor 8 Shenton Way Singapore 508969 #24-01 Axa Tower Singapore 068811 Workshops Without Prejudice c/o LKK Auto Consultants Dear Sir ACCIDENT INVOLVING OUR TAXI SHC2076H YOUR INSURED SKJ5888P ON Sin Ming We are the authorised repair workshop for Comfort Transportation Pte Ltd and Pandan 45 Pandan Road SHC2076H which was involved in the CityCab Pte Ltd, the owner of motor taxi captioned accident with your insured's vehicle. The taxi owner and driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the taxi. Senoko As the accident was caused by the negligent act of your insured driving SKJ5888P we are submitting these claims for your consideration on behalf of the claimants. Sungei Kadut TAXI OWNER'S CLAIM Sungei Kadut Way 1,310.64 1) Cost of Repair 501.60 4.0 days Loss of Rental @ \$ 125.40 per day Singapore 768732 3) Surveyor Report fees 7.49 4) LTA search fees 5) Accident Search/Report fees Towing/Medical/Transportation/Misc Fees Sub-Total \$ 1,819.73 HIRER'S CLAIM 320.00 per day 1) 4.0 days Loss of Income @ \$ 80.00 \$ 2,139.73 **TOTAL CLAIM** We enclosed herewith the following documents to support the claims: a) Original repair/survey bill/report/photographs SKJ5888P b) LTA search slip/s of SHC2076H c) Accident/Police report/s of d) Letter of authority from owner/ hirer/operator e) Rental rate letter/Mileage record 5 pcs f) Scene Photographs

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

Motor Claims Specialist

**CDGE Claims Department** 

Tel: 62148737 Fax: 62141843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.









LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING TOYOTA PRIUS SHC2076H , SKJ5888

ON 03-May-18 18:30

ALONG

CENTRAL BOULEVARD X BAYFRONT AVE

I / We

NG TECK HOCK

(Hirer) NRIC No.: **S1422440H** 

and/or

(Relief) NRIC No .:

Taxi Number

SHC2076H

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

04-May-2018

Name of Hirer

NG TECK HOCK

Hirer NRIC

S1422440H

Signature:

Address

**89 TAMPINES LINK** 

528743

Contact No.

90221427



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

## TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

450.00

COMPANY REG. NO.: 199506048W

801000	10 NSURANCE PTE LTD		VKHCLK SHC2076		INV. NO/D 91372037 1	ATE 1.05.2018
#24-0	1 8 SHENTON WAY PORE SG 068811		MAKE		<b>JOB NO.</b> 305156745	
	CT NO: 63387288		MODEL PRIUS H	YBRID(G4)	ODOMETER	RKADING
			DATE 01 28.09.		DATE/TIME 03.05.201	IN 8 23:10
Descr	iption : 3P 03.0	05.2018	CHASSI:	S CODE U903564923		
S/No	Part No.		Qty	Unit Price	*Disc	Net.
PART	REQUISITION					
0001	04-01-0302-2282	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0002	04-01-0302-228	PRIG4 GUARD-REAR BUMPER C	1.	552.60	25.00	41.4.45
0003	04-01-0302-226	PRIVE BUMPER PLECE	10	2.20	25.00	16.50
			SUB-TOTAL	:	7	74.90
JOB N	IATURE					
0001	L	PANEL BEATING	20	0.00	200.00	)
0002	23-502	SPRAYPAINT ON AFFECTED AREA	1.8	80.00	180.00	)
0003	L	REMOVE/REFTX REVERSE SENSOR	2	20.00	20.00	)
0004	L	Rear Bumper Rubber Mat.	5	60.00	50.00	)
						150 00

<sup>)</sup> WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS I RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED

SUB-TOTAL

OWNERS HISK.

CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GO NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS, OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTABLE OF THE COMPANY OF THE COMPLAINTS.

() INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO T COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR T

PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCHEPANCE WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE CORPECT AND BINDING.

## ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRQ

Head Office: 205 Braddell Road Singapore 579701 ACCOUNT No. INVOICE No. AMOUNT BANK/CHQ No. 8010010 91372037 1,310.64

Kindly note that no receipt shall be issued unless requested.

**CUSTOMER'S COPY** 



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Maintine + 65 6383 6280 Facsimile + 65 6280 9755

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

Page:

8010010

AXA INSURANCE PTE LTD

#24-01 8 SHENTON WAY AXA TOWER SINGAPORE SG 068811

CONTACT NO: 63387288

VEHCLE NO SHC2076H

INV. NO/DATE 91372037 11.05.2018

MAKE TOYOT'A

JOB NO. 305156745

MODEL. PRIUS HYBRID(G4) ODOMETER READING

DATE OF REG 28.09.2017

DATE/TIME IN 03.05.2018 23:10

CHASSIS CODE JTDKB3FU903564923

Items total

1,224.90

Add GST @

7,000 %

85.74

Invoice amount

1,310.64

KATHERINETAN 11.05.2018 10:34:09

Issued by : KATHERINETAN 11
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

## ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No. **AMOUNT** INVOICE No. ACCOUNT No. 1,310.64 91372037 8010010

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18050080

Date: 11 May 2018



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

03/05/2018 @ 18:30 hrs

ALONG

CENTRAL BOULEVARD X BAYFRONT AVE

INVOLVING

SKJ5888P

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC2076H (the "Taxi"). The Taxi was hired to NG TECK HOCK IC NO S1422440H a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.40 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

The state of the s						
H JE JOHN		MILEAGE	HOURS OPERATED (TIME)	ATED (TIME)	DATE	NAME O
DATE	MILEAGE READING	TRAVELLED (KM)	FROM	10		
	7 2 0 0 0	7-2470500	0200		-	
	t 0	108		6003		
<	000000	17/4-40530 1200	05 30	1200		
1000	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	6-1	1630	6512		
	でありつ	30 X10 84 30 XX	04 70	300	¥	
		190	1605	010 F		
100	7	2317 4.(0)00 1602	(0) oc	2001		
3-5-18 011400	7	リンド	1620	2303		
63-05-13 NG	0 7 0 0 1	Z	2510	(		
03.05.18 ALCIDENT		21.0	1630	-		
07.05.18 KEPBILL						
			The state of the s			

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time

Search Status

Insurance Company Code

Insurance Company Name

SKJ5888P

03 May 2018 / 18:30:00

Successful

A12

SHOWJOH

AXA INSURANCE PTE LTD

Previous OK









