

7/05/2018

ASS. REC. BY:

REF: CS / FCU 8 008342 / Uthbn2 | Special Instruction:

Surveyor

## ASSIGNMENT (Office)

From (Person): (WS) Serene Lee of FCI Date/Time: 07052018 522pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 9020C Insured: SHC 8479P

at Workshop m/s Pegasus Tel: 6858 1846

of 51 Defu Lane 10

Policy No: Claim No: D18003543mfsh

Sum Insured: Excess:

Make of Veh: D.O.A. 04052018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 16052018 @ 4:30pm H.O.D. Endorsement:

Date/Time: 07052018 558pm Person Contacted: Alvin Vehicle IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SLL 9020C - X
	SHC 8479P - NA / ALH 17012-FF / r3 OLA: 3006 H

REF: FCI

## ASSIGNMENT

From:

Date:

16/5/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLL 9020C

at Workshop m/s

Pegasus

of

51 Deftu Lane 10

Insured:

SHC 8478P

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 9.30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Rocker panel etc.

16/5/18 confirmed d/s @ 1900 with kermet. (Red: 2173.68 : 53%)

RECEIVED 22 MAY 2018

Date/Time. File Pass to?

1) 21/5 Typist

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 1900)-

☐

Preli. Report

☒

Final Report

Days Of Repair:

3

Resurvey No. of Trip:

-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

135
50
28
213

Veh No: SLL 9020C Yr Regn: 3, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Toyota Vios

C.C.

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

85 336

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MHFB29F360200770/

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5-

mm

R/Bal.

5-

mm

L/Bal.

5-

mm

L/Bal.

5-

mm

D.O.A.

4/5/18

D.O.I.

16/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s frt.

The U/C / Chassis frame / Body Structure affected due to collision.



Auto  
Consultants  
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003543MFSH

Date: 22/5/2018

Our Ref: CS/FCI18008342/Utb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLL 9020C.**

Please be informed that we had conducted the inspection of the abovementioned vehicle 16/5/18 at the premises of M/s Pegasus and have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,073.68</u>
Revised Estimate Amount	: S\$ <u>1,900.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>          </u>
LTA Reimbursement Value	: S\$ <u>          </u>
Nett Value	: S\$ <u>          </u>

**Description of Damage:**

The vehicle sustained damages at the n/s front portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully  
Marcus  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	07-05-2018	<b>Our Ref No.</b> D18003543MFSH
<b>Accident Date</b>	04-05-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC8479P	<b>Third Party Vehicle.</b> SLL9020C
<b>Survey Location</b>	51 DEFU LANE 10	
<b>Contact Person.</b>	ALVIN LOW	
<b>Contact No.</b>	68581846/ 68581846	<b>Fax No.</b> 64876070
<b>Survey Type</b>	WITHOUT PREJUDICE: EST. COR - \$4,358.84	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PEGASUS ENGINEERING & TRADING PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Accident Photo



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7200G

### Vehicle Details

Vehicle No.: SLL9020C

Vehicle to be Exported: Yes

Intended De-registration Date: 04 May 2018

Vehicle Make: TOYOTA

Vehicle Model: VIOS 1.5E CVT

Primary Colour: Silver

Manufacturing Year: 2017

Engine No.: 2NRX131948

Chassis No.: MHFB29F3602007701

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$12,946.00

Original Registration Date: 15 Mar 2017

First Registration Date: 15 Mar 2017

Transfer Count: 0

Actual ARF Paid: \$7,946.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Mar 2027

PARF Rebate Amount: \$5,959.00

### Intended COE Rebate Details

COE Expiry Date: 14 Mar 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,889.00

COE Rebate Amount: \$40,711.00

**Total Rebate Amount: \$46,670.00**

The information contained herein is correct as at 04 May 2018

OK

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	7200G

### Vehicle Details

Vehicle No.:	SLL9020C
Vehicle to be Exported:	No
Intended De-registration Date:	16 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NRX131948
Chassis No.:	MHFB29F3602007701
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,946.00
Original Registration Date:	15 Mar 2017
First Registration Date:	15 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$7,946.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2027
PARF Rebate Amount:	\$5,959.00

### Intended COE Rebate Details

COE Expiry Date:	14 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$44,901.00
<b>Total Rebate Amount:</b>	<b>\$50,860.00</b>

The information contained herein is correct as at 16 May 2018

OK

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

1/5 \$ 1900

**From :**  
PEGASUS ENGINEERING & TRADING PTE LTD  
C/O 51 DEFU LANE 10  
SINGAPORE 539216  
  
Officer in Charge : ALVIN LOW WAI LUN  
Tel :  
Email :

**Customer :**  
GRAB RENTALS PTE LTD  
18 SIN MING LANE  
#01-08 MIDVIEW CITY  
SINGAPORE 573960  
  
Attn :  
Tel :  
Fax :  
  
*Confirmed with Maray 16.05.2018*  
*Not Authorised*  
*3 days*  
*16/5/18*

Quotation No : QO18/05-1052	Quotation Date : 05/05/2018	Terms : 30 DAYS
Vehicle No : SLL9020C	Chassis No : MHFB29F3602007701	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: MS FIRST CAPITAL, INSURED'S VEH NO: SHC8479P, DATE OF ACCIDENT: 04.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	N/S FRONT FENDER <i>30d300</i>	1	612.5000	612.50
2	N/S FRONT FENDER INNER COWLING <i>70.1</i>	1	288.0000	288.00
3	N/S FRONT FENDER INNER COWLING CLIPS <i>mc</i>	6	4.3000	25.80
4	N/S FRONT DOOR MIRROR ASSY <i>n</i>	1	1,212.7000	1,212.70
5	N/S FRONT DOOR <i>10/300</i>	1	1,090.6000	1,090.60
6	LESS 20% <i>25%</i>	1	-645.9200	-645.92
7	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00
8	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	100.0000	100.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	1	80.0000	80.00
10	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	600.0000	600.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	650.0000	650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alteration/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

2016.90  
1512.67

2392.67  
1914.13

2-2016.9  
25%  
1512.67  
2392.67

Sub Total 4,073.68  
GST(7.00%) 285.16  
Total (SGD) 4,358.84






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008342/Utnb2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-05-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8479P	Veh. Inspected	SLL 9020C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003543MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	07/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MHFB29F3602007701	Colour	SILVER	
Odometer	85336	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	WEST LAKE	5 mm	
L/H Front Tyre	195/50 R16	WEST LAKE	5 mm	
R/H Rear Tyre	195/50 R16	WEST LAKE	5 mm	
L/H Rear Tyre	195/50 R16	WEST LAKE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/05/2018	Inspection Date	16/05/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9020C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	N/S FRONT FENDER	BADLY DENTED	612.50	612.50
1	N/S FRONT FENDER INNER COWLING	TORN	288.00	288.00
6	N/S FRONT FENDER INNER COWLING CLIPS @\$4.30	NECESSARY	25.80	25.80
1	N/S FRONT DOOR MIRROR ASSY	TO REPAIR SEE LABOUR	1,212.70	-
1	N/S FRONT DOOR	DENTED / BENT	1,090.60	1,090.60
	LESS 20% DISCOUNT		-645.92	-
	LESS 25% DISCOUNT		-	-504.23
			2,583.68	1,512.67
	<b>LABOUR</b>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	100.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		80.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF N/S FRONT DOOR MIRROR ASSY.		600.00	320.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		650.00	480.00
			1,490.00	880.00
	<b>GRAND TOTAL</b>		<b>4,073.68</b>	<b>2,392.67</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,900.00</b>

Report Ref No. CS/FCI18008342/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.