

ASS. REC. BY:

REF: CS3/EG718008389/724657

Special Instruction:

Surveyor

GL

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EG71

Date/Time:

08052018 1:30pm

Estimated Cost:

Bill to:

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 5505X

Insured:

XD 9916T

at Workshop m/s

Soon Kiang Motor

Tel:

9877 8805

of

81k 13 Delta Lane 10 # 01-430

Policy No:

XD 9916T

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02052018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

10052018 @ 11am

H.O.D. Endorsement:

Date/Time:

08052018 1:47pm

Person Contacted:

Mr. Lai

Vehicle-IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKE 5505X - X

XD 9916T - X

22/5/18

After Repair

Range 5,000 - 6,000fz

Repair days 6

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKE 5505X Yr Regn: 2012 / Feb 07Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Golf C.C. 1390Colour: White A/C: Insured / Std / NI / NASp. Reading: 104588 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZ1KZCK021978Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205 / 55 ZR16R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 02052018 D.O.I. 10052018 @ 12:30pmSurvey held at Soon Kiang


Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
1/8 Submit PRS report.

RECEIVED 01 AUG 2018



Date/Time, File Pass to?

 : Preli. ReportDays Of Repair: 6

1)

 : Final ReportResurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: : Site Insp (\$) \$ + RS \$: Interview (\$) Photos : Tech. Invs (\$) Other: : Weekend (\$)

TOTAL

Report Format: PRS-

Lump Sum / I.B.I: (\$)

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 8 May, 2018 1:30 PM
To: 'admin-d@lkkauto.com'
Subject: OI : XD9916T / TP : SKE5505X/LKK / DOA : 02/05/2018
Attachments: XD9916T - SAS.pdf; SKE5505X - SAS.pdf; RE: Your ref : CR.SKE5505.18.SK.DT / ERGO ref : XD9916T / DOA : 02.05.2018 (16.3 KB)

Dear Catherine,

We have rejected to their PRS list, please assist to conduct this survey from **C RAMESH LAW PRACTICE**,

ADDRESS : **SOON KIANG MOTOR**
BLK 13 DEFU LANE 10
#01-430
SINGAPORE 539194

PERSON TO CONTACT : MR LAI @ 9877 8805

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/05/2018 16:33
Date Of Accident	02/05/2018 15:20
Exact Location Of Accident	TWDS KJE (PIE TUAS) BRICKLAND ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE5505X
Insured/Policyholder	
Name Of Registered Owner	CHIN JIAYANG KENNETH
NRIC No	S8609554H
Email Address	KENNETHCHIN11@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94577411
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	GOLF CABRIOLET 1.4 TSI 5172Q5 W/O HID
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00001114-01
Cover Note Number	

Driver

Name of Driver	EVON TENG LAY HWA
NRIC No	S1286017Z
Date Of Birth	14/04/1958
Occupation	INDOOR
Date Of Driving Pass	31/05/1978
Driving Experience	39 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81217707
Fax Number	
Contact Number	
EMail Address	EVONTENGLH@GMAIL.COM

Address	42 PASIR PANJANG HILL #02-04
Postcode	118894
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG
Police Station Address	ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH AND POLICE REPORT (T/20180502/2195) ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD9916T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	THAVAMANI MANIKANDAN
NRIC/Passport Number	G2055758W
Contact Number	83429154
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

VEHICLE NO:

SKE 5505 X

ACCIDENT DATE:

2/5/18

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policyholder's Signature
Date & Time:



3/5/18
Driver Signature
(If Driver is not the policyholder)
Date & Time:

CHARN'S CUSTOMCRAFT
Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

SKE 5505X

2/5/18

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No
T/2018 0502/2194

OWN DAMAGE () 3RD PARTY CLAIM (/) REPORTING ONLY () OWN WORKSHOP (/)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

CHARN'S CUSTOMCRAFT
Reporting Centre/Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180502/2194

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

1 of 3

Report No. T/20180502/2194

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/05/2018 21:42		Vide Report No.:	Station Diary No.: 142
Informant's Particulars			
Name of Informant: EVON TENG LAY HWA		Address: 42 PASIR PANJANG HILL #02-04 SINGAPORE 118894	
ID Type / ID No.: NRIC NO / S1286017Z		Contact No.:	Mobile: 81217707
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 60	Date of Birth: 14/04/1958	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SELF EMPLOYED		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 02/05/2018 15:20	Type of Location: Straight Road
Location: Along Road 1 CHOA CHU KANG WAY TOWARDS KJE(PIE TUAS) Brickland Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKE5505X	Car	VOLKSWAGO N	GOLF TSI	White	Slightly Damaged	0
XD9916T	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180502/2194

2 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20180502/2194

CONTINUATION OF REPORT

Driver			
Name	EVON TENG LAY HWA		ID No. S1286017Z
Related Vehicle	SKE5505X (Car)		Contact No. 81217707
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	THAVAMANI MANIKANDAN		ID No. G2055758W
Related Vehicle	XD9916T (Lorry)		Contact No. 83429154
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

02/05/2018 at 1521hrs, I was driving my vehicle along Choa Chu Kang way towards KJE(PIE Tuas) Brickland road on the 2nd lane from the right. There was a lorry (XD9916T, Motor Tippri) on my right lane. As we were making right turn towards Brickland road, I felt a slight jerk and loud crackling sound outside of my vehicle. I then drove forward and stopped along the side of the road together with the lorry.

Initially when I prompted him to exchange our particulars, he did not provided me as he informed that his driving license was with his company. He then provided me with his supervisor namely: Ah Di HP:9040 1118. I then contacted his supervisor but however after waiting for 1hour, there was still no sight of him. After making a check on my vehicle, scratches, dent and cracks was observed on my right rear portion of my vehicle.

A moment later, I then observed LTA traffic officer namely: Thilagan HP: 83147336, FBC5412S and requested him for assistance. The lorry driver then subsequently provided his particulars to me with the help of the LTA traffic officer. At 1547hrs, I then called for the '999' for assistance but however subsequently at 1614hrs I called the police again to cancel the police for assistance as instructed by the LTA officer.

This first time such incident and I am lodging this report for police assistance and insurance purposes.



**SINGAPORE
POLICE FORCE**



T/20180502/2194

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

3 of 3



Report No. T/20180502/2194

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ CHEN SHIXIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/05/2018 21:42
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG -  Contact No.: 65476368	Classification Of Case:
Authentication Stamp NP168 	

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9554H
Vehicle Details	
Vehicle No.:	SKE5505X
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jul 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF CABRIOLET 1.4 TSI 5172Q5 W/O HID
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	CAV374483
Chassis No.:	WVWZZZ1KZCK021978
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$29,119.00
Original Registration Date:	07 Feb 2012
First Registration Date:	07 Feb 2012
Transfer Count:	1
Actual ARF Paid:	\$29,119.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Feb 2022
PARF Rebate Amount:	\$18,927.00
Intended COE Rebate Details	
COE Expiry Date:	06 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,112.00
COE Rebate Amount:	\$19,905.00
Total Rebate Amount:	\$38,832.00

The information contained herein is correct as at 20 Jul 2018

OK

MOTORCAR (Rear)

Rear Portion

Vehicle No: **SKE 5505 X**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: _____

Assessor: _____

Condition (CON)
 (0)1) Bent (2)2) Dented (3)3) Discolored (4)4) Cracked (5)5) Cut (6)6) Scratched
 (7)7) Deformed (8)8) Shifted (9)9) Buckled (10)10) Broken (11)11) Necessary (12)12) Missing
 (13)13) Torn (14)14) Unconfined (15)15) Not Working

ACTION (A/C)
 (1)1) Replace (✓) (2)2) Repair (R) (3)3) Check (T)
 (4)4) Not Consistent (INC)

Aug 2005

MOTOR CAR (RH)

Vehicle No: **SKE 5505X**

Right Portion			CON	AC	Qty
NAC	INC	Item			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			CUT ✓
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			BR ✓
1228	993456	Rear RH Fender			DD ✓
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items: _____ Assessor: _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18008389/Gz4bs2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVESINGAPORE 038985		Date: 17-08-2018	
		Code: EGI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	XD 9916T	Veh. Inspected	SKE 5505X
Policy No.	XD 9916T	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	08/05/2018
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN GOLF	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WWWZZZ1KZCK021978	Colour	WHITE
Odometer	104588 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55ZR16	HANKOOK	6 mm
L/H Front Tyre	205/55ZR16	HANKOOK	6 mm
R/H Rear Tyre	205/55ZR16	HANKOOK	6 mm
L/H Rear Tyre	205/55ZR16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
5. General Information			
Accident Date	02/05/2018	Inspect Date / Time	10/05/2018 (12:20 PM)
Survey held at	SOON KIANG MOTOR BLK 13 DEFU LANE 10 #01-430 SINGAPORE 539194		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000- \$6,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/EGI18008389/Gz4bs2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.