





| PRE-REPAIR INSPECTION REPORT | | | | |
|--|--|----------------------------|-------------------------|---|
| ERGO INSURANCE PTE LTD | | Ref: CS3/EG18008396/Gz4be2 | | |
| 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER | | Date: 11-09-2018 | |  |
| FIVE SINGAPORE 038985 | | Code: EGI | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | SLE 326S | Veh. Inspected | SLX 8256H | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | SLE326S/SL/sa | Excess (\$) | 0.00 | |
| Assign From | SITI | Assign Date | 08/05/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | LAMBORGHINI GALLARDO | c.c | 5204 | |
| Engine No. | HIDDEN | Year of Reg. | 2009 | |
| Chassis No. | ZHWGE54T19LA08583 | Colour | WHITE | |
| Odometer | 52684 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 235/35Z R19 | PIRELLI | 6 mm | |
| L/H Front Tyre | 235/35Z R19 | PIRELLI | 6 mm | |
| R/H Rear Tyre | 235/35Z R19 | PIRELLI | 6 mm | |
| L/H Rear Tyre | 235/35Z R19 | PIRELLI | 6 mm | |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. | | |  |
| 5. General Information | | | | |
| Accident Date | 02/05/2018 | Inspect Date / Time | 08/05/2018 (04:30 PM) | |
| Survey held at | D'S GRAFFITI CONCEPTS - 25 KAKI BUKIT RD 4 #08-26 | | | |
| Repairer | - | | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)THE REPAIR EST WAS NOT PRESENTED AT THE TIME OF INSPECTION.THE REPAIRER WAS TOLD TO PREPARE THE EST. C)ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE EST REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$90,000.00-\$110,000.00 | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 14 Working Days | |

Report Ref No. CS3/EG18008396/Gz4be2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.