



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD MERCEDES-BENZ E250-1.8 CGI (A) (SFM9779M)

Date of Loss

30 April 2018

Time of Loss

19.30

Loss Description

SKT2151Z (INSD) C/W SFM9779M (TP)

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *



Days of work completion *



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SFM9779M

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

23/09/2010



Mileage

72555

Age of Vehicle

7

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2010

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

NEO KEE CHOON THOMAS

CATEGORY

Make

POST SURVEY INF...

POLICY INFORMAT... TPVD MERCEDES-BENZ

ASSESSMENT INFO...

MERCEDES BENZ

CATEGORY

Model

POLICY INFORMAT...

E250-1.8 CGI (A)

ASSESSMENT INFO...

E250 CGI A

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

WDD2073472F046791

CATEGORY

Date of Birth

FNOL INFORMATI...

28 May 1962

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Age

FNOL INFORMATI...

56

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO...

27186030060137

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

1796

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO...

0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO...

0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY

Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Address

FNOL INFORMATI... 23 JALAN LIMAU MANIS, 468351,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S1524839D

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

09/05/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

235/40R18

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

235/40R18

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM18008397/Az4be2	
8 SHENTON WAY #24-01 AXA TOWER		Date: 08-06-2018	
SINGAPORE 068811			
ATTN : ERNEST TAY		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKT 2151Z	Veh. Inspected	SFM 9779M
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00G6E	Excess (\$)	0.00
Assign From	ERNEST TAY	Assign Date	08/05/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2073472F046791	Colour	GREY
Odometer	72555 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	235/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	235/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	235/40 R18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	30/04/2018	Inspect Date / Time	09/05/2018 (12:45 PM)
Survey held at	UNITED SG AUTOMOBILE - 53 UBI AVE 1 #01-56		
Repairer	-		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18008397/Az4be2

Inspected By

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.