



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 32580

Customer :

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

MOTOR CLAIMS DEPT

DATE : 04/05/2018

CLAIM NO. : 11138

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBK9679B

MAKE/MODEL : YAM / MT-03 ABS (MTN3)

*not about
the
telephone. After
repair
2 day.
8/5/18*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET 2	REPLACE	1.00	\$28.00	28.00
2	COOLANT RADIATOR (ANF 30) P/N: 45831	REPLACE	1.00	\$18.00	18.00
3	DUCT AIR P/N: 55151	REPLACE	1.00	\$18.00	18.00
4	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	3.00	\$35.00	105.00
5	MUDGUARD FRONT	REPLACE	1.00	\$75.00	75.00
6	PROTECTOR EXHAUST (R&G) AKRAPOVIC HEXAGON P/N: 46706	REPLACE	1.00	\$135.00	135.00
7	RADIATOR COMP.	REPLACE	1.00	\$320.00	320.00
8	SLIDER (MOTOVATION) ENGINE	REPLACE	1.00	\$128.00	128.00
SUB TOTAL					\$827.00
GST @ 7 %					\$57.89
GRAND TOTAL					\$884.89

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001: 2008

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	 RAYMOND				

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

